

# 2006-2007



Spark and glow plugs

Bougies d'allumage et de préchauffage

Bujías de encendido y de precalentamiento

Velas de ignição e de pré-aquecimento

Candele di accensione e candelette

Ontstekingsbougie en Voorgloeibougie

Zündkerzen und Glühkerzen

Świece zapłonowe i świece żarowe

Buji ve Isitma bujisi

Свечи зажигания и Свечи накаливания



**Valeo**




**SYMBOLS AND ABBREVIATIONS** SYMBOLES ET ABRÉVIATIONS **SIMBOLOS Y ABREVIATURAS** SÍMBOLOS E ABREVIATURAS

**SIMBOLI ED ABBREVIAZIONI** SYMBOLEN EN AFKORTINGEN **SYMBOLE UND ABKÜRZUNGEN** SYMBOLE I SKRÓTY **SIMGEVE KISALTMALAR**

	Vehicle	Véhicule	Vehículo	Veículo	Veicolo	Voertuig	Fahrzeug	Marka / Pojazd	Araç
	Engine	Moteur	Motor	Motor	Motore	Motor	Motor	Typ silnika	Motor
	Date of vehicle	Période de fabrication	Periodo de fabricación	Data de fabrico	Data di fabbricazione	Bouwjaar	Baujahr	Okres Produkcji	Üretim Tarihi
	Standard Reference	Référence Standard	Bujía de encendido	Vela de ignição	Candela di accensione	Ontstekingsbougies	Zündkerze	Świece Zapłonowe	Standart Referans
	Spark Plug 3+1	Bougie d'allumage 3+1	Bujía de Encendido 3+1	Vela de ignição 3+1	Candela di accensione 3+1	Ontstekingsbougies 3+1	Zündkerze 3+1	Świece Zapłonowe 3+1	Buji 3+1
	Electrode Adjustment	Réglage de l'électrode	Reglaje del electrodo	Regulação do electrodo	Regolazione elettrodo	Afstelling electrodenafstand	Einstellung der Elektrode	Przerwa Międzyelektrodowa	Elektrot Ayarı
	Glow Plug	Bougie de préchauffage	Bujía de Pre calentamiento	Vela de Pré-aquecimento	Candeletta	Voorgloeibougie	Glühkerze	Świece Żarowe	Isitma Bujisi
	Number of cylinders	Nombre de cylindres	Número de cilindros	Número de cilindros	Numero di cilindri	Aantal cylinders	Zylinderanzahl	Liczba Cylindrów	Silindir Sayısı
	Technical Code	Code Technique	Código Técnico	Código Técnico	Codice Tecnico	Technische Code	Technischer Code	Kod Techniczny	Teknik Kod

1



21

1.1

Valeo →



23

1.2



Valeo

25

1.3

CROSS



Valeo

139

2



143


2.1

Valeo →



145

2.2



Valeo

147

2.3

CROSS



Valeo

179

2.4

CROSS




Valeo

183



## PLUGS TECHNOLOGY

The identification is made by a technical code (e. g. : RF82HZ2Y) witch is in the application chapter and the corresponding commercial cross reference is : 2464900)



## SPARK PLUGS 3+1, POWER & PERFORMANCE

### 3+1 electrodes for :

#### \* Greater durability

Last upto 60 000 Km\*, with the combination of both technologies 2 large electrodes double copper and 3 small multi-ground electrodes.

#### \* More power

Optimum combustion for greater performance and catalytic converter protection.

#### \* Better starting

Made for all extreme climatic conditions, through the technologies of semi-surface spark, the 3+1 electrodes insure a better starting in every weather conditions.



#### \* Lower emissions


The 3 lateral ground electrodes produce more powerful spark which makes an ideal combustion and reduces the emissions.

#### \* Fuel Economy

The 3 small lateral electrodes propagate better spark which gives a better combustion in the cylinder chamber and decreases the medium consumption and reduces emissions.

With the 3+1 technologie, Valeo bring to the driver the result of OE research in order to improve the starting in all conditions through the powerful sparks. The " long life" technologies of the 3+1 produces an exceptional long life upto 60 000 Km\*.

\* Last upto 60 000 Km depending of the engines dirty and engine wear.



1

Spark plugs

Bougies d'allumage

Bujías de encendido

1.1

**Valeo**



**23**

Velas de ignição

1.2



**Valeo**

**25**

Candele di accensione

1.3



**Valeo**

**139**

Ontstekingsbougies


Zündkerzen

Świece zapłonowe

Вуји

Свечи зажигания

**Valeo**



1.1

Spark plugs

Bougies d'allumage

Bujías de encendido

Vela de ignição

Candele di accensione

Ontstekingsbougies

Zündkerzen

Świece zapłonowe

Буји

Свечи зажигания

**Valeo**




**Valeo**



<b>246021</b>	C60H						
<b>246170</b>	67HP						
<b>246173</b>	RF74H						
<b>246176</b>	RF80H						
<b>246178</b>	R64H						
<b>246179</b>	R76H						
<b>246180</b>	R84H						
<b>246181</b>	R90H						
<b>246182</b>	R92H						
<b>246184</b>	RF72H						
<b>246186</b>	RF82H						
<b>246189</b>	R88N						
<b>246190</b>	RC68H						
<b>246191</b>	RC72H						
<b>246195</b>	76H3E						
<b>246198</b>	R70H						
<b>246321</b>	RF80H3						
<b>246322</b>	RF72H3						
<b>246326</b>	RC72H11						
<b>246332</b>	RF74H11						
<b>246333</b>	RF72H11						
<b>246334</b>	RF64H11						
<b>246455</b>	RC68LPP						
<b>246486</b>	RF74HZ3YE						
<b>246487</b>	RF74HZDC						
<b>246488</b>	RF72HZDC						
<b>246490</b>	RF82HZ2Y						
<b>246492</b>	RF74HZ2Y						
<b>246511</b>	R74HZ3YE						
<b>246519</b>	RF80LZDC						
<b>246520</b>	RF74LZDC						
<b>246554</b>	F87 <b>3+1</b>						
<b>246555</b>	H79 <b>3+1</b>						
<b>246556</b>	F87-11 <b>3+1</b>						
<b>246557</b>	H60 <b>3+1</b>						
<b>246560</b>	RF74HZK						
<b>246562</b>	RV90LDC						
<b>246562</b>	RF80LZDC3						
<b>246563</b>	RV90LDC						
<b>246564</b>	H79-11 <b>3+1</b>						
<b>246565</b>	C60 <b>3+1</b>						
<b>246566</b>	C79 <b>3+1</b>						
<b>246567</b>	F59 <b>3+1</b>						





1.2

Spark plugs

Bougies d'allumage

Bujías de encendido

Velas de ignição

Candele di accensione


Ontstekingsbougies

Zündkerzen

Świece zapłonowe

Buji

Свечи зажигания





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## AC

### ME

3.0 V6			► 08.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--------	--	--	-----------	---------------	------	-----	---------------	-----

## ACURA

### INTEGRA

1.6 i 16V	D16 A1 Cat			<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	B18 A [DOHC]			<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	B18 C1/C5 VTEC [DOHC]					1.1	<b>246556</b>	F87-11

### LEGEND

2.5 i V6 24V	C25 A1			<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.7 i V6 24V	C27 A1 Cat			<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.2 i V6 24V	C32 A1 [SOHC]					1.1	<b>246556</b>	F87-11

## ALFA ROMEO

### 145

1.4 ie	33.501 [OHC]		04.1994 ► 11.1996	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.6 ie	33.201 [OHC]		04.1994 ► 09.1996	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie 16V	33.401 [DOHC]		04.1994 ► 11.1996			0.8	<b>246567</b>	F59

### 146

1.6 ie	33.201 [OHC]		12.1994 ► 09.1996	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
--------	--------------	--	-------------------	---------------	------	-----	---------------	-----

### 155

1.7 ie T.Sp	67.103 [OHC] Cat		02.1992 ► 04.1993			0.8	<b>246567</b>	F59
1.7 ie T.Sp	67.105		02.1992 ► 04.1996			0.8	<b>246567</b>	F59
1.8 ie T.Sp, Silverstone/L	67.101, 67.102 Cat		02.1992 ► 12.1996			0.8	<b>246567</b>	F59
2.0 ie T.Sp	67.201, 67.202		02.1992 ► 02.1995			0.8	<b>246567</b>	F59
2.0 ie Turbo 4x4	67.203		02.1992 ► 12.1997			0.8	<b>246557</b>	H60
2.0 Ti 16V Quadrifoglio 4	67.203 [OHC] Cat		02.1992 ► 12.1997			0.8	<b>246557</b>	H60
2.5 ie V6	67.301, 67.302, 67.303 Cat		02.1992 ► 12.1997	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.0 ie V6	64.304 Cat		02.1992 ►	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

### 156

1.6 ie T.Sp	32.101		01.2000 ►	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.6 ie T.Sp	32.101		11.1997 ► 12.1999			0.8	<b>246567</b>	F59
1.8 ie T.Sp	32.201		01.2000 ►	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.8 ie T.Sp	32.201		11.1997 ► 12.1999			0.8	<b>246567</b>	F59
2.0 ie T.Sp	32.301		01.2000 ►	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.0 ie T.Sp	32.301		11.1997 ► 12.1999			0.8	<b>246567</b>	F59

### 164


2.0 ie T.Sp	064.20, 64.103, 064.16		06.1987 ► 09.1992			0.8	<b>246567</b>	F59
2.0 ie Turbo	064.76		10.1987 ► 09.1992	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 ie V6 Turbo	64.102 Cat		10.1990 ► 09.1998	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.5 ie V6	66.201		09.1992 ► 09.1998	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.0 ie V6	64.305, 66.303, 064.10, 064.12		06.1987 ► 09.1992	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.0 ie V6 24V	66.301, 66.302		09.1992 ► 10.1998			0.8	<b>246567</b>	F59
3.0 ie V6 24V Quadrifoglio Verde	64.304 Cat		01.1993 ► 10.1998			0.8	<b>246567</b>	F59

### 166

2.0 ie V6 Turbo	34.102 [DOHC]		10.1998 ►	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-----------------	---------------	--	-----------	---------------	------	-----	---------------	-----

### 33

1.2	305.00		06.1983 ► 03.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.2	307.43		01.1990 ► 08.1991			0.9	<b>246555</b>	H79
1.3 ie Hit, Feeling, Tender, Flag, 4x4			02.1994 ►	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.35 AS	307.32		01.1990 ► 10.1994	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.35 DC	305.02		06.1983 ► 02.1990	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.35 DC, S, S Red	305.86, 305.87		06.1983 ► 12.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.35 S, S Sport Wagon...	301.68		06.1983 ► 12.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.35 S, S Veloce, Sprint	301.68		06.1983 ► 12.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.35 Sport Wagon	305.86, 305.87		06.1983 ► 12.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.35 V, VL, Sport Wagon, 4x4	307.32		01.1990 ► 10.1994	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.35 ie L, Imola, Sport Wagon	307.53		09.1991 ► 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.4	304.55		09.1991 ► 03.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.4 Sport Wagon	305.06		03.1988 ► 03.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.4 ie Sport Wagon, 4x4	307.55		09.1991 ► 03.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 4x4	305.08		10.1986 ► 03.1990	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 4x4	305.04		06.1983 ► 10.1984	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 AS	307.34		02.1990 ► 03.1994			0.8	<b>246557</b>	H60
1.5 Giardinetta 4x4	305.04		06.1983 ► 10.1984	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Quadrifoglio Verde	301.82		06.1984 ► 12.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60



3+1


**ALFA ROMEO** (.../...)

**33 (.../...)**

1.5 Sport Wagon, 4x4	305.08	10.1986 ▶ 03.1990	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti	305.04	06.1983 ▶ 10.1984	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti 4x4	305.20	06.1984 ▶ 10.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti Giardinetta 4x2, 4x4	301.46	06.1984 ▶ 03.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti Giardinetta 4x4, Quadrifoglio Oro	305.20	06.1984 ▶ 10.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti Sport Wagon 4x4, Ti Veloce	301.46	06.1984 ▶ 03.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 ie	307.50	06.1990 ▶ 10.1994			0.8	<b>246557</b>	H60
1.5 ie 4x4, Sport Wagon	307.51	06.1990 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.5 Ti	305.88	07.1987 ▶ 10.1989			0.8	<b>246557</b>	H60
1.7 Quadrifoglio Verde	305.50	09.1986 ▶ 10.1994			0.8	<b>246557</b>	H60
1.7 Sport Wagon, QV	305.50	09.1986 ▶ 10.1994			0.8	<b>246557</b>	H60
1.7 Sprint	305.50	09.1986 ▶ 10.1994			0.8	<b>246557</b>	H60
1.7 ie	307.36	01.1990 ▶ 03.1994			0.8	<b>246557</b>	H60
1.7 ie	307.37	10.1987 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie	307.40	04.1992 ▶ 10.1994	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.7 ie 4x4	305.58 Cat	10.1987 ▶ 03.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie 4x4	307.36	01.1990 ▶ 03.1994			0.8	<b>246557</b>	H60
1.7 ie 4x4	307.37	10.1987 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Quadrifoglio 4	307.37	10.1987 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Quadrifoglio Verde, Sport Wagon	305.58, 305.78	10.1987 ▶ 03.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Sport Wagon	305.58 Cat	10.1987 ▶ 03.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Sport Wagon	307.36	01.1990 ▶ 03.1994			0.8	<b>246557</b>	H60
1.7 ie Sport Wagon	307.37	10.1987 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Sport Wagon 4x4	305.58 Cat	10.1987 ▶ 03.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie Sport Wagon 4x4	307.36	01.1990 ▶ 03.1994			0.8	<b>246557</b>	H60
1.7 ie Sport Wagon 4x4	307.37	10.1987 ▶ 10.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 ie 16V Boxer Quadrifoglio Verde	M691AA.17.A	03.1990 ▶ 09.1994			0.8	<b>246567</b>	F59
1.7 ie 16V Elegante, Permanent, Quadrifoglio Verde Quadrifoglio 4, 4x4	307.46, 307.47	01.1990 ▶ 10.1994			0.9	<b>246567</b>	F59

**6**

2.0	019.32	01.1979 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.5	019.13	01.1979 ▶ 06.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.5 ie	019.28	09.1983 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**75**

1.6	061.00	05.1985 ▶ 09.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 ie	611.01	08.1989 ▶ 02.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.6 ie	611.02	08.1989 ▶ 02.1992	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 ie America, E	061.34, 062.02	02.1986 ▶ 08.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie HEL	062.02	05.1985 ▶ 09.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Indy	062.02, 612.01	05.1985 ▶ 09.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Scuderia	061.68	09.1988 ▶ 02.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Scuderia	062.02	05.1985 ▶ 09.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Turbo America	061.58	02.1986 ▶ 08.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Turbo E	061.58	02.1986 ▶ 08.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 ie Turbo Potenzziata, S Speciale	612.03	12.1988 ▶ 02.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0	062.12	05.1985 ▶ 10.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0 ie Twin Spark	061.66, 062.24	01.1986 ▶ 12.1992			0.8	<b>246567</b>	F59
2.5 ie V6	019.11, 016.46	09.1985 ▶ 02.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 V6 America, Milano	061.24, 061.20	01.1986 ▶ 02.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 V6 ES Coupé Zagato	615.01	03.1989 ▶ 02.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
3.0 V6 Potenzziata	615.03	02.1990 ▶ 02.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60

**90**

1.8 ie	062.02	10.1984 ▶ 01.1987	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0	062.12	10.1984 ▶ 06.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0 ie	017.13	10.1984 ▶ 01.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 ie V6	062.10	10.1984 ▶ 01.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.5 ie V6	019.11, 016.46	10.1984 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**ALFASUD**

1.2 Super	301.00, 301.04, 301.10	▶ 06.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.3 Ti Sprint Veloce	301.64	▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.35 Ti, Ti Sprint Veloce	301.68	▶ 12.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.5 Sprint	301.98	09.1976 ▶ 12.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.5 Sprint, Super, Ti, Ti Quadrifoglio	301.24, 301.28, 301.46, 301.98	09.1976 ▶ 12.1989	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.7 ie Sprint	305.58 Cat	10.1987 ▶ 12.1989	<b>246178</b>	R64H	0.8	<b>246557</b>	H60



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## ALFA ROMEO (.../...)

### ALFETTA

2.0	013.34		▶ 06.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 ie	017.13		▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.5 ie V6 L-Jetronic	016.46		▶ 12.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### ALFETTA GT

1.8 BN, GT	016.00, 016.08		▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 L, GTV 2000	016.23, 016.55		▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### ARNA

1.2	305.00, 310.00		▶ 12.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.3	310.10		▶ 12.1986	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.35 Ti	301.68		▶ 12.1986	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.5	305.20, 310.16		▶ 12.1986	<b>246178</b>	R64H	0.8	<b>246557</b>	H60

### F 12

1.3	140.20		01.1954 ▶ 10.1981	<b>246198</b>	R70H	0.6	<b>246557</b>	H60
-----	--------	--	-------------------	---------------	------	-----	---------------	-----

### GIULIA

1.3 Super			▶ 10.1978	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 Super			▶ 10.1978	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### GIULIETTA

1.3	016.44		▶ 04.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	016.00		▶ 04.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	016.78		▶ 04.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0	116.71, 016.55		▶ 04.1985	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

### GT

1.3			▶ 12.1977	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6			▶ 12.1977	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### GTA

1.3			▶ 12.1977	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
-----	--	--	-----------	---------------	------	-----	---------------	-----

### GTV

2.0	016.55		07.1978 ▶ 01.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0	062.12		01.1985 ▶ 12.1985	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0 ie V6 Turbo	16.202		04.1995 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 Turbo, Turbo Delta	116.42		05.1979 ▶ 12.1981	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.5 ie V6	016.46		11.1980 ▶ 08.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### JUNIOR ZAGATO

1.6			▶ 12.1976	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-----	--	--	-----------	---------------	------	-----	---------------	-----

### MONTREAL

2.6	AR 10832		12.1972 ▶ 03.1979	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
-----	----------	--	-------------------	---------------	------	-----	---------------	-----

### NUOVA GIULIA

1.3			▶ 12.1979	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6			▶ 12.1979	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### RZ

3.0 V6 Zagato	615.01		01.1992 ▶ 12.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
---------------	--------	--	-------------------	---------------	------	-----	---------------	-----

### SPIDER (105, 115)

1.3 Junior 1300	005.36		05.1968 ▶ 10.1978	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6	005.26, 015.63		11.1979 ▶ 12.1994	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 Junior 1600	005.26		06.1971 ▶ 10.1979	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0	005.15		04.1971 ▶ 12.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 ie	015.44, 015.88, 015.90		10.1981 ▶ 12.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 ie Veloce 2000	016.84		01.1972 ▶ 12.1980	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

### SPIDER (916S)

2.0 ie V6 Turbo	16.202		06.1998 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
3.0 ie V6	16.101, 19.199		04.1995 ▶ 05.1998	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### SZ

3.0 V6 Zagato	615.01		09.1988 ▶ 08.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
---------------	--------	--	-------------------	---------------	------	-----	---------------	-----

## ALPINA

### B10

3.5 L6	B11/3 Cat		04.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
3.5 L6 Coupé	B10 Cat		07.1985 ▶ 12.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

### B11

3.5 L6	B11/1-3 Cat		01.1987 ▶ 09.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
--------	-------------	--	-------------------	---------------	------	-----	---------------	-----

### B3

2.7	C2/2, C2/4 Cat		08.1987 ▶ 06.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	----------------	--	-------------------	---------------	------	-----	---------------	-----

### B6

2.8 L6	B6 Cat		09.1981 ▶ 01.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.8 L6	B6/2 Cat		03.1984 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79



										<b>ALPINA</b>	
<b>B6 (.../...)</b>											
3.5 L6	B10/2-3-4-5 Cat					11.1985 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
3.5 L6	B10/6 Cat					05.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>B9</b>											
3.5 L6 Coupé	B9, B9/1 Cat					11.1981 ▶ 12.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>C1</b>											
2.3 L6	C1, C1/1 Cat					04.1980 ▶ 11.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.5	C2/3 Cat					10.1986 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>C2</b>											
2.5	C2 Cat					07.1986 ▶ 11.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.7	C2/1-2-4 Cat					04.1986 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>ARO</b>											
<b>10</b>											
1.4	IAP 810-R-99					09.1988 ▶	<b>246189</b>	R88N	0.8		
1.6						09.1988 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
<b>SERIE 100</b>											
1.4 100, 101, 103, 104						01.1978 ▶	<b>246189</b>	R88N	0.8		
<b>ASIA</b>											
<b>ROCSTA</b>											
1.8 i 4x4	F8					01.1994 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
<b>ASTON-MARTIN</b>											
<b>DB6</b>											
4.0							<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>DB7</b>											
3.2 i L6 24V Tu	AJ6.4 Compressor [DOHC]					03.1994 ▶	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59
<b>LAGONDA</b>											
5.3 i V8 Bi-Turbo						01.1994 ▶			0.6	<b>246567</b>	F59
5.3 V8	[OHC] Cat					01.1976 ▶ 06.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>VIRAGE</b>											
5.3 i V8 32V	[DOHC]					10.1988 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
<b>ZAGATO</b>											
5.3 i V8	[OHC]					01.1986 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
<b>AUDI</b>											
<b>100</b>											
1.6 , Avant	YV, YM					08.1974 ▶ 02.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	ABB					08.1990 ▶ 07.1994	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8	ZU, ZM					08.1968 ▶ 07.1976	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8, Avant	DR					08.1982 ▶ 10.1986			0.9	<b>246555</b>	H79
1.8, Avant	DS					09.1982 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8, Avant	RS					08.1982 ▶ 12.1987			0.9	<b>246555</b>	H79
1.8, LS	ZZ					08.1968 ▶ 07.1976	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8, Quattro	JW					09.1982 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i Avant, Quattro	SF, NP, 4B, PH, SH					09.1982 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9	ZJ, ZL, ZY					08.1968 ▶ 07.1976	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.9 5S, Avant	WH					08.1980 ▶ 07.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 , Avant	WA					06.1976 ▶ 07.1980	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i	RT					01.1988 ▶ 12.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i, Avant	AAE					12.1990 ▶ 06.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i, Avant	KP					08.1984 ▶ 12.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i, Avant	SL					02.1986 ▶ 12.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i, Quattro	AAD					12.1990 ▶ 12.1992	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i E, E Avant	ABK					12.1990 ▶ 06.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Quattro	ADW					12.1993 ▶ 07.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V, Quattro	ACE					04.1992 ▶ 06.1994			0.9	<b>246567</b>	F59
2.0, Avant	WF					07.1977 ▶ 07.1978	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.1 i L5 5E	WC					03.1977 ▶ 07.1984			0.8	<b>246557</b>	H60
2.1 i L5 Avant	WG					01.1977 ▶ 07.1980	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.1 i Turbo Avant, Quattro	KH					08.1986 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.1 L5	WE					03.1977 ▶ 02.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.1 L5, Avant	KF					02.1982 ▶ 09.1984			0.8	<b>246557</b>	H60
2.1 L5 5S, Avant	WB					10.1977 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.2 i L5, Avant	KZ					08.1984 ▶ 09.1986	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## AUDI (.../...)

### 100 (.../...)

2.2 i L5, Quattro	KU	08.1984 ▶			0.8	<b>246557</b>	H60
2.2 i L5 E Quattro, E Quattro Avant	PX	08.1985 ▶ 07.1986	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i Turbo, Quattro	MC	08.1986 ▶ 11.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 L5, Quattro	HX	10.1983 ▶ 12.1990			0.8	<b>246557</b>	H60
2.3 i E, E Quattro	AAR	12.1990 ▶ 06.1994			0.9	<b>246555</b>	H79
2.3 i E, E Quattro	NF	11.1986 ▶ 11.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.6 i V6, Quattro	ABC	04.1992 ▶ 06.1994	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6, Quattro	ACZ	07.1993 ▶ 06.1994	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AAH	09.1991 ▶ 06.1994	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
4.2 i V8 32V, Quattro, S4	ABH	10.1992 ▶ 06.1994			1.6	<b>246566</b>	C79

### 200

2.1 i L5 5E	WC	08.1979 ▶ 07.1984			0.8	<b>246557</b>	H60
2.1 i Turbo	KH	08.1979 ▶ 07.1987			0.8	<b>246557</b>	H60
2.1 Turbo, Quattro	KG	08.1983 ▶ 01.1988			0.8	<b>246557</b>	H60
2.1 Turbo Quattro	KG	09.1983 ▶ 01.1988			0.8	<b>246557</b>	H60
2.1 Turbo Turbo Quattro	JY	08.1983 ▶ 07.1986			0.8	<b>246557</b>	H60
2.2 i L5	KU	08.1979 ▶ 07.1987			0.8	<b>246557</b>	H60
2.2 i Turbo, Quattro	1B, 2B	02.1988 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i Turbo, Quattro	MC	08.1985 ▶ 12.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.3 i	NF	11.1986 ▶ 09.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

### 50

1.1	HB, HD	08.1974 ▶ 07.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1	HC	08.1974 ▶ 07.1978	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

### 80

1.3	FY	05.1972 ▶ 07.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4	SE	08.1987 ▶ 08.1991			0.9	<b>246555</b>	H79
1.5	YJ, ZB, ZC	05.1972 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6	DT	08.1983 ▶ 07.1986			0.9	<b>246555</b>	H79
1.6	FS	02.1976 ▶ 08.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	JU	08.1983 ▶ 08.1991			0.9	<b>246555</b>	H79
1.6	PP	08.1987 ▶ 09.1991			0.9	<b>246555</b>	H79
1.6	RN	09.1986 ▶ 08.1991			0.9	<b>246555</b>	H79
1.6	RNA	08.1983 ▶ 08.1991			0.9	<b>246555</b>	H79
1.6	SA	08.1983 ▶ 08.1986			0.9	<b>246555</b>	H79
1.6	WP	08.1979 ▶ 01.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WV, WVA	08.1981 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WY, WZ	09.1979 ▶ 07.1983	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	YG	01.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YH	01.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YK	08.1977 ▶ 08.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YN	09.1975 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YP	09.1975 ▶ 02.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YT	09.1975 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YY	02.1979 ▶ 07.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 GLE, GTE	YS	01.1976 ▶ 07.1982	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 GLE, GTE	YZ	01.1976 ▶ 12.1986	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 GT	XX	10.1973 ▶ 08.1976	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 i	ABB	08.1990 ▶ 01.1996	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.6 i	ABM	09.1991 ▶ 12.1994			0.9	<b>246555</b>	H79
1.6 i	DTA	08.1983 ▶ 08.1991			0.9	<b>246555</b>	H79
1.6 i E	ADA	06.1993 ▶ 12.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.7	WT	08.1980 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 E, GTE	DS	08.1983 ▶ 08.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 E, GTE, GTE Quattro, Quattro	JN	09.1986 ▶ 07.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 E, GTE, GTE Quattro, Quattro	JV	08.1983 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 E, GTE, GTE Quattro, Quattro	MU	03.1985 ▶ 08.1986	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 S	JV	08.1983 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 S, S Quattro, CC Quattro	JN	09.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i	RU	10.1986 ▶ 01.1990			0.9	<b>246555</b>	H79
1.8 i, Quattro	SF	02.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i E, GTE, GTE Quattro, Quattro	NE, DZ	09.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i E, GTE, GTE Quattro, S, S Quattro	PM	09.1986 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTE, GTE Quattro	PV	08.1985 ▶ 07.1986	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i S, S Quattro	SF	09.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i S, S Quattro, CC Quattro	NE	09.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60



3+1


**AUDI** (.../...)

**80 (.../...)**

1.9 CD-5S	WN	09.1981 ▶ 08.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.9 i, Quattro	SD	09.1986 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 5E	HP	08.1983 ▶ 07.1985	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 5E	JL	08.1983 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	ABT	09.1991 ▶ 12.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	SK	▶ 07.1986	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i, Quattro	AAD	12.1990 ▶ 12.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i 5E, Quattro	JS	08.1983 ▶ 09.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i E	ABK	07.1992 ▶ 01.1996	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i E, E Quattro	ABK	08.1991 ▶ 12.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i E, Quattro, E Quattro	3A	08.1988 ▶ 07.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i Quattro	AAE	12.1990 ▶ 10.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Quattro	ADW	12.1993 ▶ 01.1996	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Quattro	PS	04.1987 ▶ 10.1991	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V, Quattro	6A	03.1990 ▶ 09.1991			0.9	<b>246567</b>	F59
2.0 i 16V, Quattro	ACE	04.1992 ▶ 12.1994			0.9	<b>246567</b>	F59
2.1 i L5 Quattro	KK	11.1982 ▶ 07.1984			0.8	<b>246557</b>	H60
2.1 L5 5E	WE	03.1977 ▶ 08.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.2 Quattro	KL	09.1982 ▶ 07.1984	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.3 i E, E Quattro	NG Cat	09.1991 ▶ 12.1994			0.9	<b>246555</b>	H79
2.6 i V6, Quattro	ABC	07.1992 ▶ 12.1994	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6 Quattro	ACZ	03.1993 ▶ 01.1996	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6 E, E Quattro	AAH	09.1991 ▶ 12.1994	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**90**

2.0	HP	10.1984 ▶ 03.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0	JL	10.1984 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	3A	09.1987 ▶ 10.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	JS	08.1984 ▶ 03.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	PS	07.1988 ▶ 09.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	SK	03.1986 ▶ 03.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i 20V, Quattro	NM	01.1988 ▶ 09.1991			0.9	<b>246567</b>	F59
2.2 i L5	HY	08.1984 ▶ 10.1991			0.8	<b>246557</b>	H60
2.2 i L5	KX	01.1985 ▶ 03.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5, E, E Quattro	KV	08.1984 ▶ 10.1991			0.8	<b>246557</b>	H60
2.2 i L5 E Quattro	JT	08.1985 ▶ 03.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.3 i E, E Quattro	NG Cat	04.1987 ▶ 12.1991			0.9	<b>246555</b>	H79
2.3 i 20V, Quattro	7A	06.1988 ▶ 09.1991			0.9	<b>246567</b>	F59
2.8 i V6 Quattro	AAH, AFC	01.1992 ▶ 06.1995	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**A2**

1.4 i 16V	AUA, BBY [DOHC]	02.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
-----------	-----------------	-----------	---------------	-----------	-----	---------------	-----

**A3**

1.4 i 16V	AFH	03.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AUA [DOHC]	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AEH [OHC]	09.1996 ▶ 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AKL	08.1997 ▶ 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	APF	03.1999 ▶ 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	APG [DOHC]	11.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V Ambiente, Attraction, Quattro	AGN [DOHC]	09.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AQA [DOHC]	08.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	ARY [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AUM [DOHC]	12.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AJQ, APP, AUQ [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	ARX [DOHC]	12.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	ARZ [DOHC]	08.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V Ambiente, Ambition, Quattro	AGU [DOHC]	12.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**A4**

1.6 i	ALZ [OHC]	07.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i, Pack Clim, Référence	ADP	01.1995 ▶ 10.1996	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i, Pack Clim, Référence	AHL	10.1996 ▶ 07.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i, Pack Clim, Référence	ANA, ARM	08.1998 ▶ 07.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V, Quattro	ADR	12.1995 ▶ 11.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V, Quattro	APT	02.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V, Quattro	ARG		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V Pack Clim, Quattro	AFY	04.1995 ▶ 11.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	ARK	07.1998 ▶ 07.1999	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## AUDI (.../...)

### A4 (.../...)

1.8 T 20V	AWT, AVV	► 09.2001	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AJL	01.1995 ► 11.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	ANB	07.1999 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	APU	02.1999 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V Pack Clim, Quattro	AEB [DOHC]	01.1995 ► 12.1998	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	ABT, ADW, ABK	01.1995 ►	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.4 i V6 30V Pack Clim	AFM	07.1995 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6, Quattro	ABC	01.1995 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6 Quattro	ACZ	01.1995 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AAH	09.1995 ► 07.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AFC	01.1995 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

### A6

1.6 i	ABB	06.1994 ► 03.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	AJP	06.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i	AQE	11.1998 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i	ARH	07.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	AFY	02.1998 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V, Quattro	ADR	12.1995 ► 12.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V, Quattro	AFY	05.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V Quattro	ADR	12.1995 ► 02.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AJL	12.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AEB [DOHC]	01.1997 ► 01.1999	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AJL	12.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	ANB, ARK	01.1999 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	APU	11.1998 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AWT	01.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	AAE, ABK	06.1994 ► 02.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	ADW	06.1994 ► 03.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V, Quattro	ACE	06.1994 ► 02.1997			0.9	<b>246567</b>	F59
2.3 i, Quattro	AAR	06.1994 ► 02.1997			0.9	<b>246555</b>	H79
2.4 i V6	ALW	08.1997 ► 01.1999	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.4 i V6	ARN	01.1999 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.4 i V6 30V	AFM	07.1995 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6	ACZ	06.1994 ► 02.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.6 i V6, Quattro	ABC	06.1994 ► 02.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AAH	06.1994 ► 02.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AEJ	08.1994 ► 02.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
2.8 i V6 Quattro	AFC	07.1994 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
3.7 i V8 40V, Quattro	AQG [DOHC]	03.1999 ►			1.6	<b>246554</b>	F87
4.2 i V8 32V S6 Quattro	AEC [DOHC]	06.1994 ► 02.1997			1.6	<b>246566</b>	C79

### A8

2.8 i V6, Quattro	AAH	06.1994 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AEJ	07.1995 ►	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
3.7 i V8 32V	AKJ [DOHC]	07.1995 ► 10.1998			1.6	<b>246566</b>	C79
3.7 i V8 32V, Quattro	AEW	07.1995 ► 10.1998			1.6	<b>246566</b>	C79
3.7 i V8 40V, Quattro	AQG [DOHC]	11.1998 ►			1.6	<b>246554</b>	F87
4.2 i V8, Quattro	AKG	04.1997 ► 09.1998			1.6	<b>246566</b>	C79
4.2 i V8 Quattro	ARU [DOHC]	02.1999 ►			1.6	<b>246554</b>	F87
4.2 i V8 32V	AGH	03.1995 ►			1.6	<b>246566</b>	C79
4.2 i V8 32V, Quattro	ABZ	03.1994 ► 07.1996			1.6	<b>246566</b>	C79
4.2 i V8 32V Quattro	AEM	06.1994 ► 07.1996			1.6	<b>246566</b>	C79
4.2 i V8 40V Quattro	AQF [DOHC]	11.1998 ►			1.6	<b>246554</b>	F87

### CABRIOLET

1.6 i	ADP	01.1997 ► 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	ADR	01.1997 ► 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i E	ABK	01.1993 ► 07.1998	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V	ACE	05.1995 ► 07.1996			0.9	<b>246567</b>	F59
2.3 i	NG Cat	05.1991 ► 07.1994			0.9	<b>246555</b>	H79
2.6 i V6	ACZ, ABC	01.1994 ► 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6	AAH, AFC	12.1992 ► 08.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

### COUPE

1.6	YN	09.1975 ► 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	DD	08.1981 ► 08.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 Quattro	DS, JV	09.1982 ► 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 S, GT, Quattro	JN	01.1985 ► 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60




**AUDI** (.../...)

**COUPE (.../...)**

1.8 i GT, Quattro	SF, PV	09.1982 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i S, GT, Quattro	DZ	01.1985 ▶ 07.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9 5S	WN	08.1980 ▶ 08.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 5E	JL, HP	08.1983 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	3A, AAD	05.1989 ▶ 07.1991	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 5E	SK, JS	08.1983 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i 16V	6A	03.1990 ▶ 07.1992			0.9	<b>246567</b>	F59
2.0 i 16V	ACE	01.1992 ▶ 12.1995			0.9	<b>246567</b>	F59
2.0 i 20V Quattro	NM	11.1988 ▶ 07.1991			0.9	<b>246567</b>	F59
2.1 i L5 5E	KE	09.1981 ▶ 08.1984			0.8	<b>246557</b>	H60
2.2	KL	09.1981 ▶ 08.1984			0.8	<b>246557</b>	H60
2.2 i L5	KX	01.1984 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5 Quattro	HY	09.1984 ▶ 10.1988			0.8	<b>246557</b>	H60
2.2 i L5 Quattro	JT	08.1984 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5 Quattro	KV	08.1984 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5 Quattro	KV	11.1988 ▶ 07.1991			0.8	<b>246557</b>	H60
2.3 i, Quattro	NG	01.1986 ▶ 10.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.3 i, Quattro	NG Cat	11.1988 ▶ 12.1996			0.9	<b>246555</b>	H79
2.3 i 20V, Quattro	7A	11.1988 ▶ 09.1991			0.9	<b>246567</b>	F59
2.6 i V6, Quattro	ABC	07.1992 ▶ 12.1996	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i V6, Quattro	AAH	08.1991 ▶ 12.1996	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**FOX**

1.6	YK -YG, YH	09.1974 ▶ 07.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	------------	-------------------	---------------	------	-----	---------------	-----

**QUATTRO**

2.2 i Turbo	1B	08.1987 ▶ 12.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 Turbo	MB	08.1987 ▶ 07.1989	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

**TT**

1.8 T 20V	AUM [DOHC]	10.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AUQ [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V, Quattro	AJQ [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V Quattro	ARY, APY [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**V8**

3.6 Quattro	PT	10.1988 ▶ 06.1994	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79
4.2 i V8 32V Quattro	ABH	10.1991 ▶ 02.1994			1.6	<b>246566</b>	C79

**AUSTIN, MORRIS**
**1100, 1300**

Tous modèles (all models)		▶ 12.1975	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
---------------------------	--	-----------	---------------	------	-----	---------------	-----

**1800, 2200**

Tous modèles (all models)		▶ 12.1975	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
---------------------------	--	-----------	---------------	------	-----	---------------	-----

**ITAL**

1.3 1300			<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7					0.7	<b>246566</b>	C79
1.8 1800			<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**ITAL VAN / PICK-UP**

		▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
--	--	-----------	---------------	------	-----	---------------	-----

**MARINA**

1.3 1300			<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7					0.7	<b>246566</b>	C79
1.8 1800			<b>246179</b>	R76H	0.7	<b>246555</b>	H79
Van, Pick-Up		▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**MINI**

Tous modèles (all models)		01.1959 ▶ 12.1971	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
Van, Pick-Up		▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**MINOR**

1.0			<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 Van, Pick-Up		▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**AUTOBIANCHI**
**A 112**

0.9 E, Junior, LX	A 112...	03.1973 ▶ 12.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 Elegant, Elite	A 112 B1...	11.1977 ▶ 02.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.05 Abarth	A 112 A	08.1977 ▶ 02.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**Y10**

1.0 Fire, Fire 4x4	156.A2.000	03.1985 ▶ 02.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
--------------------	------------	-------------------	---------------	-------	-----	---------------	-----



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## AUTOBIANCHI (.../...)

### Y10 (.../...)

1.0 ie Fire	156.A2.256	01.1989 ▶ 09.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.0 ie Fire, Fire 4x4	156.A2.100	10.1987 ▶ 09.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie Fire, Fire 4x4	156.A2.146	10.1987 ▶ 07.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie Fire, Fire 4x4	156.A3.000	09.1986 ▶ 12.1988	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.05 Touring	156.A.000	03.1985 ▶ 02.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 i, ie Fire ie, Selectronic ie, 4x4 ie	176.B2.000	02.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 ie Fire 4x4 ie, Fire LX ie	156.C.000	01.1989 ▶ 01.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.1 ie Fire ie, Selectronic ie, 4x4 ie	156.C.046 Cat	07.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.3 ie GTie, Elite	146.A5.046, 156.B.000	11.1987 ▶ 01.1995	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

## BEDFORD

### ASTRA

1.3	13 S [OHC]	01.1982 ▶ 10.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.4	14 NV [OHC]	09.1989 ▶ 12.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 SV [OHC]	01.1982 ▶ 12.1994	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### BEAGLE, HA VAN

1.3		01.1971 ▶ 12.1983			1.0	<b>246564</b>	H79-11
-----	--	-------------------	--	--	-----	---------------	--------

### BLITZ

2.0 230		01.1978 ▶ 04.1984	<b>246189</b>	R88N	0.7		
2.0 250		01.1978 ▶ 04.1984	<b>246189</b>	R88N	0.7		
2.0 280		01.1978 ▶ 04.1984	<b>246189</b>	R88N	0.7		
2.0 350		01.1978 ▶ 04.1984	<b>246189</b>	R88N	0.7		
2.3 CF 2		01.1984 ▶ 12.1987	<b>246326</b>	RC72H11	1.0		

### BRAVA

2.3 4x4		12.1988 ▶ 06.1994			1.0	<b>246564</b>	H79-11
---------	--	-------------------	--	--	-----	---------------	--------

### CHEVANNE

1.3		01.1976 ▶ 12.1982			1.0	<b>246564</b>	H79-11
-----	--	-------------------	--	--	-----	---------------	--------

### KB

1.6 25		01.1980 ▶ 01.1988	<b>246181</b>	R90H	0.8		
1.6 4, 26, 41		01.1980 ▶ 12.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### MIDI

1.8 2.0		02.1985 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------	--	-----------	---------------	------	-----	---------------	-----

### RASCAL

1.0 99170, 99180		02.1986 ▶ 06.1993	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
------------------	--	-------------------	---------------	------	-----	---------------	-----

## BENTLEY

### BROOKLANDS

6.8 i V8		09.1992 ▶	<b>246181</b>	R90H	0.8		
----------	--	-----------	---------------	------	-----	--	--

### CONTINENTAL

6.8 V8 Tous modèles (all models)		01.1984 ▶	<b>246182</b>	R92H	0.8		
----------------------------------	--	-----------	---------------	------	-----	--	--

### CORNICHE

6.8 V8		03.1971 ▶ 06.1984	<b>246182</b>	R92H	0.8		
--------	--	-------------------	---------------	------	-----	--	--

### EIGHT

6.8 V8		10.1980 ▶ 09.1992	<b>246182</b>	R92H	0.8		
--------	--	-------------------	---------------	------	-----	--	--

### MULSANNE

6.8 V8		01.1981 ▶ 08.1992	<b>246181</b>	R90H	0.8		
6.8 V8 Turbo		01.1981 ▶ 08.1992	<b>246181</b>	R90H	0.8		

### SERIES T

6.8 V8		03.1985 ▶	<b>246181</b>	R90H	0.8		
6.8 V8 Turbo		03.1985 ▶	<b>246181</b>	R90H	0.8		

## BERTONE

### FREECLIMBER

1.6 i	M40B16	02.1992 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
2.0 i 4x4	M20B20 Cat	01.1991 ▶			0.7	<b>246555</b>	H79

## BMW

### 1500-2000

1.5 1502		▶ 07.1977	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
----------	--	-----------	---------------	------	-----	---------------	-----

### M 5

3.5 i [E12]	M30B35	04.1980 ▶ 05.1981	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
-------------	--------	-------------------	---------------	------	-----	---------------	-----

### SÉRIE 3

315 : 1.6 [E21]	M10B16	08.1975 ▶ 03.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
316 : 1.6 [E21]	M10B16	08.1975 ▶ 08.1988	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
316 : 1.6 i [E30]	M40B16	09.1988 ▶ 04.1991	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87



3+1


**BMW** (.../...)

**SÉRIE 3 (.../...)**

316 : 1.6 i [E36]	M40B16	12.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i, Ci Coupé [E36]	M43B16	09.1993 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i, Ci Coupé [E46]	M43B16	02.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i Compact [E36]	M43B16	03.1994 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i Touring [E30]	M40B16	09.1991 ▶ 12.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i Touring [E36]	M43B16	02.1997 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316 : 1.6 i Worldline [E36]	M43B16	09.1993 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
316i : 1.8 i [E21]	M10B18	09.1980 ▶ 08.1988	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
318 : 1.8 [E21]	M10B18	▶ 08.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
318 : 1.8 i [E36]	M40B18, M43B18	12.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.8 i [E46]	M43B18	04.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.8 i Cabrio [E36]	M43B18	01.1994 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.8 i Touring [E30]	M40B18	09.1987 ▶ 12.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.8 i Touring [E36]	M43B18	07.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.8 i Worldline [E36]	M43B18	07.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.9 i [E46]	M43B19	04.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.9 i 16V S, Ti, Worldline [E36]	M44B19	12.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 : 1.9 i 16V Worldline [E36]	M44B19	12.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 Ti : 1.8 i 16V Compact [E36]	M42B18	10.1994 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318 Ti : 1.9 i 16V Compact [E36]	M44B19	12.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318iS : 1.8 i 16V [E30]	M42B18	09.1989 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318iS : 1.8 i 16V Coupé [E36]	M42B18	03.1992 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
318iS : 1.9 i 16V Coupé [E36]	M44B19	12.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 i [E30]	M20B20	09.1982 ▶ 05.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
320 : 2.0 i [E30]	M20B20 Cat	12.1986 ▶ 03.1993			0.7	<b>246555</b>	H79
320 : 2.0 i Touring [E30]	M20B20 Cat	01.1988 ▶ 08.1991			0.7	<b>246555</b>	H79
320 : 2.0 i 24V [E46]	M52B20	04.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 i 24V Cabrio, Coupé, Worldline [E36]	M52B20	09.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 i 24V Ci Coupé [E46]	M52B20	06.1999 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 i 24V Touring [E30]	M52B20	09.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 i L6 24V Cabrio, Coupé, Worldline [E36]	M50B20	09.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
320 : 2.0 L6 [E21]	M20B20, M10	09.1975 ▶ 08.1982	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
323 : 2.3 i [E21]	M20B23 Cat	01.1978 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
323 : 2.5 i 24V [E46]	M52B25 Cat	04.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
323 : 2.5 i 24V Cabrio, Coupé, Worldline [E36]	M52B25 Cat	06.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
323 : 2.5 i 24V Ci Coupé, Ti Compact [E46]	M52B25 Cat	04.1999 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
323 : 2.5 i 24V Touring [E36]	M52B25 Cat	06.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
325 : 2.5 i Touring [E30]	M20B25	07.1987 ▶ 10.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
325 : 2.5 i L6 24V Cabrio, Coupé, Worldline [E36]	M50B25	09.1990 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
325e : 2.7 i [E30]	M20B27 Cat	01.1985 ▶ 12.1988			0.7	<b>246555</b>	H79
325i : 2.5 i X [E30]	M20B25	09.1985 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
328 : 2.8 i 24V [E46]	M52B28	04.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
328 : 2.8 i 24V Cabrio, Coupé, Worldline [E36]	M52B28	01.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
328 : 2.8 i 24V Ci Coupé, Touring [E46]	M52B28	04.1999 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
328 : 2.8 i 24V Touring [E36]	M52B28	01.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87


**SÉRIE 5**

518 : 1.8 [E12]	M10B18	08.1975 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
518 : 1.8 i [E34]	M40B18	09.1989 ▶ 12.1995	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
518 : 1.8 i [E34]	M43B18	09.1989 ▶ 09.1996	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
518 i : 1.8 i [E12]	M10B18	08.1975 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
520 : 2.0 i [E28]	M20B20	▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
520 : 2.0 i [E28]	M20B20 Cat	▶ 12.1987			0.7	<b>246555</b>	H79
520 : 2.0 i [E34]	M20B20 Cat	01.1988 ▶ 08.1991			0.7	<b>246555</b>	H79
520 : 2.0 i 24V, Worldline [E39]	M52B20	01.1996 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
520 : 2.0 L6 [E12]	M20B20	09.1972 ▶ 05.1981	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
520 iS : 2.0 i L6 24V [E34]	M50B20	09.1989 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
523 : 2.5 i 24V [E39]	M52B25 Cat	07.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
525 : 2.5 [E12]	M30B25	09.1977 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
525 : 2.5 i [E34]	M20B25	01.1988 ▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
525 : 2.5 i 24V [E39]	M52B25 Cat	09.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
525 e : 2.7 i [E28]	M20B27 Cat	12.1986 ▶ 12.1987			0.7	<b>246555</b>	H79
525 eta : 2.7 i [E28]	M20B27 Cat	▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
525 i : 2.5 i [E28]	M30B25	09.1977 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
525 i : 2.5 i L6 24V X, Worldline [E34]	M50B25	09.1989 ▶ 09.1996	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
528 : 2.8 i 24V [E39]	M52B28	07.1995 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## BMW (.../...)

### SÉRIE 5 (.../...)

528 i : 2.8 i [E12]	M30B28	01.1975 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
528 i : 2.8 i [E28]	M30B28	06.1981 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
530 i : 3.0 i [E34]	M30B30	01.1988 ▶ 08.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
530 i : 3.0 i V8 32V [E34]	M60B30	09.1992 ▶ 09.1996	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
535 : 3.4 i [E28]	M30B35 Cat	09.1984 ▶ 12.1987			0.7	<b>246555</b>	H79
535 : 3.4 i [E28]	M30B35 Cat	09.1984 ▶ 12.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
535 : 3.5 i [E12]	M30B35	▶ 05.1981	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
535 i : 3.4 i [E34]	M30B35 Cat	01.1988 ▶ 04.1993			0.7	<b>246555</b>	H79
535 i : 3.5 i V8 32V [E39]	M60B35, M62B35 Cat	01.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
540 : 4.4 i V8 32V [E39]	M62B44 Cat	01.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
540 i : 4.0 i V8 [E34]	M60B40 Cat	09.1992 ▶ 09.1996	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
540 i : 4.0 i V8 [E39]	M60B40 Cat	11.1995 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87

### SÉRIE 6

628 : 2.8 i CSi [E24]	M30B28	09.1979 ▶ 08.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
630 : 3.0 i i, CSi [E24]	M30B30	04.1976 ▶ 08.1979	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
633 : 3.2 i CSi [E24]	M30B32	09.1979 ▶ 04.1982	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
635 : 3.4 i [E24]	M30B35 Cat	06.1978 ▶ 05.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
635 : 3.4 i CSi [E24]	M30B35 Cat	06.1987 ▶ 05.1989	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
635 : 3.5 i [E24]	M30B35	06.1978 ▶ 05.1987	<b>246180</b>	R84H	0.7	<b>246555</b>	H79

### SÉRIE 7

725 : 2.8 [E23]	M30B28	05.1977 ▶ 08.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
728 : 2.8 i 24V [E38]	M52B28	09.1995 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
728 i : 2.8 i [E23]	M30B28	05.1977 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
730 : 3.0 [E23]	M30B30	05.1977 ▶ 08.1979	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
730 : 3.0 i V8 32V [E32]	M60B30	09.1992 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
730 i : 3.0 i [E32]	M30B30	09.1986 ▶ 03.1994	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
730 i : 3.0 i V8 32V [E38]	M60B30	10.1994 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
732 i : 3.2 i [E23]	M30B32	05.1977 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
733 i : 3.2 i [E23]	M30B32	05.1977 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
735 : 3.5 i [E23]	M30B35	05.1977 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
735 i : 3.4 i [E23]	M30B35 Cat	05.1977 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
735 i : 3.4 i [E32]	M30B35 Cat	09.1986 ▶ 03.1994			0.7	<b>246555</b>	H79
735 i : 3.5 i V8 32V [E38]	M62B35 Cat	01.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
740 : 4.4 i V8 32V [E38]	M62B44 Cat	01.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
740 i : 4.0 i V8 [E32]	M60B40 Cat	04.1992 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
745 i : 3.2 i [E23]	M30B32	04.1980 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
745 i : 3.4 i [E23]	M30B35	04.1980 ▶ 08.1986	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
750 i : 5.0 i V12 [E32]	M70B50	09.1987 ▶ 10.1994			0.7	<b>246554</b>	F87
750 i : 5.0 i V12, iL [E32]	M70B50				0.7	<b>246554</b>	F87
750 i : 5.4 i V12 [E38]	M73B54	09.1994 ▶			0.8	<b>246554</b>	F87

### SÉRIE 8

840 : 4.0 i V8, Ci [E31]	M60B40 Cat	03.1993 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
840 : 4.4 i V8 32V, Ci [E31]	M62B44 Cat	01.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
850 : 5.0 i V12, Ci [E31]	M70B50	04.1990 ▶			0.7	<b>246554</b>	F87
850 : 5.0 i V12 Ci [E31]	M70B50				0.7	<b>246554</b>	F87
850 : 5.4 i V12, Ci [E31]	M73B54	03.1994 ▶			0.8	<b>246554</b>	F87
850 : 5.6 i CSi [E31]	M70B56	08.1992 ▶			0.8	<b>246554</b>	F87

### X5

4.4 i V8 32V [E53]	M62B44 Cat	05.2000 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
--------------------	------------	-----------	---------------	----------	-----	---------------	-----

### Z1

2.5 i	M20B25	09.1988 ▶ 06.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-------	--------	-------------------	---------------	------	-----	---------------	-----

### Z3

1.8 i	M43B18	▶ 10.1998	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
1.9 i	M43B19	07.1998 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
1.9 i 16V	M44B19	▶ 03.1999	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
2.8 i 24V	M52B28	11.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87

## BRISTOL

### 412

5.9 V8		09.1977 ▶ 12.1982	<b>246181</b>	R90H	0.9		
--------	--	-------------------	---------------	------	-----	--	--

### 603

5.9 V8 E, S		01.1977 ▶ 12.1983	<b>246181</b>	R90H	0.9		
-------------	--	-------------------	---------------	------	-----	--	--

### BEAUFIGHTER

5.9 V8 Turbo		01.1980 ▶ 12.1989	<b>246181</b>	R90H	0.9		
--------------	--	-------------------	---------------	------	-----	--	--



										<b>BRISTOL</b> (.../...)	
<b>BLLENHEIM</b>											
5.9 i V8						03.1994 ▶	<b>246181</b>	R90H	0.9		
<b>BRIGAND</b>											
5.9 V8 Turbo						01.1983 ▶	<b>246181</b>	R90H	0.9		
<b>BRITANNIA</b>											
5.9 V8						10.1982 ▶ 12.1989	<b>246181</b>	R90H	0.9		
<b>BUICK</b>											
<b>SKYHAWK</b>											
1.8 i Turbo	(J)					01.1984 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>SKYLARK</b>											
2.3 i Grand Sport						09.1991 ▶ 08.1994			1.1	<b>246556</b>	F87-11
<b>CATERHAM</b>											
<b>21</b>											
1.6 i 16V	16K series					10.1994 ▶	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
1.6 i 16V Superlight / Sport	16K series								0.7	<b>246567</b>	F59
<b>SUPER SEVEN</b>											
1.4 i 16V	K 16 series [DOHC]					01.1992 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.4 i 16V (6 vitesses, 6 Speed)	K 16 series [DOHC]					01.1994 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.6 GT	(S)					01.1981 ▶ 12.1991	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 GT Sprint, Twin Cam	(T)					01.1981 ▶ 12.1991	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
1.6 i 16V	16K series					10.1994 ▶	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
1.6 i 16V Superlight / Sport	16K series								0.7	<b>246567</b>	F59
2.0 i 16V HPC	Mot. Vauxhall					07.1991 ▶			0.7	<b>246567</b>	F59
<b>CHEVROLET</b>											
<b>ASTRO VAN</b>											
4.3 i V6	L35					04.1995 ▶	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
<b>BERETTA</b>											
2.3 i 16V GTZ	(D) [DOHC]					09.1990 ▶			1.1	<b>246556</b>	F87-11
<b>BLAZER</b>											
4.3 i V6	L35					03.1995 ▶	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
<b>CORVETTE</b>											
5.7 i V8 ZR-1	L98					06.1989 ▶ 08.1995	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
5.7 i V8 32V ZR-1	LT5					06.1989 ▶ 08.1995	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
<b>SPRINT</b>											
0.9 i Turbo	(2)					01.1987 ▶ 12.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>CHRYSLER</b>											
<b>CIRRUS</b>											
2.0 i 16V	ECB					01.1994 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
<b>COUPE</b>											
2.2 L6 Turbo						01.1987 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.5 L6 Turbo						01.1987 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>ES</b>											
2.2 i Turbo	EDR					01.1988 ▶	<b>246181</b>	R90H	0.9		
<b>GS</b>											
2.2 i Turbo	EDS					01.1988 ▶	<b>246181</b>	R90H	0.9		
<b>LE BARON</b>											
2.2 i Cabrio, GTS						01.1984 ▶ 08.1995	<b>246181</b>	R90H	0.9		
2.2 i Turbo	EDG					01.1984 ▶ 08.1995	<b>246181</b>	R90H	0.9		
2.2 i Turbo GTC Turbo						01.1984 ▶ 09.1990	<b>246181</b>	R90H	0.9		
2.5 i Turbo	TCi					01.1986 ▶ 08.1989	<b>246181</b>	R90H	0.9		
<b>NEON</b>											
1.8 i 16V [PL]	EBD					02.1998 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.0 i 16V [PL]	(C) [DOHC]					01.1994 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
<b>NEW YORKER</b>											
2.5 i	(K)					01.1985 ▶ 12.1987	<b>246182</b>	R92H	0.9		
<b>SARATOGA</b>											
2.0 i 16V						05.1995 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.5 i						09.1987 ▶			0.9	<b>246564</b>	H79-11
3.0 i V6						09.1987 ▶			1.1	<b>246564</b>	H79-11
<b>SEBRING</b>											
2.0 i 16V	[DOHC]					09.1994 ▶			1.1	<b>246556</b>	F87-11
2.5 i 24V						09.1994 ▶			1.1	<b>246556</b>	F87-11





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## CHRYSLER (.../...)

### STRATUS

2.0 i 16V [JA]	ECB	01.1994 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.5 i 24V [JA]	(H)	08.1995 ▶			1.1	<b>246556</b>	F87-11

### TOWN & COUNTRY

2.2 i Turbo	(A)		<b>246182</b>	R92H	0.9		
3.0 i V6	6G 72 [SOHC]	09.1989 ▶			1.1	<b>246564</b>	H79-11

### VOYAGER

2.0 i 16V [GS]		01.1996 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.4 i 16V [GS]	(X) [DOHC]	10.1995 ▶ 03.2001			1.1	<b>246556</b>	F87-11
2.5 i [ES]		09.1987 ▶ 12.1995	<b>246180</b>	R84H	0.9	<b>246555</b>	H79

## CITROEN

### AMI

8 : 1.0 Super			<b>246198</b>	R70H	0.6	<b>246557</b>	H60
---------------	--	--	---------------	------	-----	---------------	-----

### AX

1.1	TU1M [HDY]	10.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1	TU1M [HDY]	10.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1 i	TU1M [HDY] [HDZ]	10.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1M [HDY] [HDZ]	10.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A] TU3.2TR [K3B-K5A]	10.1986 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A] TU3.2TR [K3B-K5A]	10.1986 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 GT, GTS, TE, Volcane	TU3-N [K1B], TU3 S [K2A-K2B]	10.1987 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i	TU3M [KDX, KDY, KDZ]	06.1988 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3M [KDX, KDY, KDZ]	06.1988 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i GTi	TU3J2 [K6B, KFY, KFZ]	05.1991 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
10 : 1.0	TU9 [C1A, C1B, C3A]	10.1986 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
10 : 1.0 i	TU9M [CDY] [CDZ]	07.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
10 : 1.0 i	TU9M [CDY] [CDZ]	07.1992 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
11 : 1.1	TU1 [H1A, H3A, H1B, H1C, HAZ]	10.1986 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
11 : 1.1	TU1 [H1A, H3A, H1B, H1C, HAZ]	10.1986 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### AXEL

11, 12 : 1.1, R, RS, TRS, Entreprise		07.1984 ▶	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
--------------------------------------	--	-----------	---------------	-------	-----	---------------	-----

### BERLINGO


1.1 i	TU1JP-L4 [HFZ]	06.2000 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1JP-L4 [HFZ]	06.2000 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i X, SX, Familiale, type 600/800	TU3JP [KFX]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i X, SX, Familiale, type 600/800	TU3JP [KFX]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	09.2000 ▶	<b>246520</b>	RF74LZDC	0.9		
1.8 i	XU7 JB [LFX]	03.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i	XU7 JB [LFX]	03.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
475/600 : 1.1 i Familiale	TU1M+ [HDZ]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
475/600 : 1.1 i Familiale	TU1M+ [HDZ]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
600 : 1.4 Familiale	TU3.2 [K5A]	10.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
600 : 1.4 Familiale	TU3.2 [K5A]	10.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### BERLINGO MULTISPACE

1.1 i	TU1M+ [HDY] [HDZ] TU1JP-L4 [HFZ]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1M+ [HDY] [HDZ] TU1JP-L4 [HFZ]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3.2 [K2C-K2D-K5A]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3.2 [K2C-K2D-K5A]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i X, SX, Le Grand Bleu	TU3JP [K6C, KFX, K6C, KFX]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i X, SX, Le Grand Bleu	TU3JP [K6C, KFX, K6C, KFX]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	09.2000 ▶	<b>246520</b>	RF74LZDC	0.9		
1.8 i SX	XU7 JB [LFX]	05.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i SX	XU7 JB [LFX]	05.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### BX

1.9 i 16V GTi 16S	XU9 J4 [D6C]	07.1987 ▶ 09.1993	● <b>246322</b>	RF72H3	1.2		
11 : 1.1	TU1 [H1A, H1B, H1C, H3A, HAZ]	06.1987 ▶ 09.1993	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
11 : 1.1	XW7B2 [109LA]	05.1988 ▶ 09.1993	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
11 : 1.1	XW7B2 [109LA]	10.1982 ▶ 04.1988	<b>246190</b>	RC68H	0.9	<b>246566</b>	C79
14 : 1.4 Calanque, Olympique	TU3A [K1C-K1D-K1F-K1]	06.1987 ▶ 09.1993	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
14 : 1.4 E, RE	XY6 [150F]	07.1988 ▶ 06.1989	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
14 : 1.4 E, RE, TRE	XY6C, XY6D	05.1988 ▶ 09.1993	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
14 : 1.4 E, RE, TRE	XY6C, XY6D	10.1982 ▶ 04.1988	<b>246190</b>	RC68H	0.9	<b>246566</b>	C79
14 : 1.4 E, RE, TRE, TE, TGE, Entreprise	TU3.2-K [K2D]	07.1986 ▶ 09.1993	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87



3+1


**CITROEN** (.../...)

**BX (.../...)**

14 : 1.4 E, RE, TRE, TE, TGE, Entreprise	TU3A [K1C-K1D-K1F-K1]	06.1987 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87
14 : 1.4 Leader	XY7 [150D]	05.1986 ▶ 05.1988	246190	RC68H	0.6	246566	C79
14 : 1.4 i	TU3M [KDX, KDZ]	09.1988 ▶	246487	RF74HZDC	0.9	246554	F87
14 : 1.4 i	TU3M [KDX, KDZ]	09.1988 ▶	●246560	RF74HZK	0.9	246554	F87
15 : 1.6 RE, TGE, TRE, Image	XU51C [B1A]	07.1987 ▶ 06.1988	246190	RC68H	0.6	246566	C79
15 : 1.6 RE, TGE, TRE, Image	XU51C [B1A]	07.1988 ▶ 09.1993	●246560	RF74HZK	0.6	246554	F87
15 : 1.6 Tonic	XU51C-K [B1F]	07.1987 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87
16 : 1.6	171/A, XU5STR	10.1982 ▶ 03.1988	246190	RC68H	0.6	246566	C79
16 : 1.6	XU52C [B2C]	02.1988 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87
16 : 1.6 RS	XU5STR [171D]	02.1985 ▶ 03.1988	246190	RC68H	0.6	246566	C79
16 : 1.6 RS	XU5STR [171D]	04.1988 ▶ 09.1993	●246560	RF74HZK	0.6	246554	F87
16 : 1.6 RS, TRS	171/A	▶ 03.1988	246190	RC68H	0.6	246566	C79
16 : 1.6 RS, TRS	171/A	▶ 03.1988	●246560	RF74HZK	0.6	246554	F87
16 : 1.6 S, RS, TRS, TGS, TZS	XU5CP [BAZ]	09.1986 ▶ 10.1989	●246560	RF74HZK	0.9	246554	F87
16 : 1.6 S, RS, TRS, TGS, TZS	XU5S [171C-171Z]	07.1988 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87
16 : 1.6 i	XU5JA [B6D, B6E]	07.1987 ▶ 09.1993	246487	RF74HZDC	0.9	246554	F87
16 : 1.6 i	XU5JA [B6D, B6E]	07.1987 ▶ 09.1993	●246560	RF74HZK	0.6	246554	F87
19 : 1.9 Digit, GT	XU9 S [159A-159Z]	10.1984 ▶ 07.1986			0.6	246565	C60
19 : 1.9 Millesime, TGS, TRS, TZS	XU92 C [D2A-D2B-D2C]	07.1987 ▶ 09.1993	●246560	RF74HZK	0.6	246554	F87
19 : 1.9 Millesime, TGS, TRS, TZS	XU92 C [D2A-D2B-D2C]	09.1986 ▶ 07.1987			0.6	246565	C60
19 : 1.9 Millesime, TGS, TRS, TZS, Athena, 4x4	XU92 C+ [D2E-D2F]	02.1989 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87
19 : 1.9 Sport	XU9.4 [159B]	03.1985 ▶ 07.1987			0.6	246565	C60
19 : 1.9 i	XU9M, J1, J2, JA	07.1986 ▶ 09.1993	246487	RF74HZDC	0.9	246554	F87
19 : 1.9 i	XU9M, J1, J2, JA	07.1986 ▶ 09.1993	●246560	RF74HZK	0.9	246554	F87

**C1**

1.0 12v		09.2005 ▶	246520	RF74LZDC	0.9		
---------	--	-----------	--------	----------	-----	--	--

**C2**

1.1 i	TU1JP-L4 [HFZ]	09.2003 ▶	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1JP-L4 [HFZ]	09.2003 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	09.2003 ▶	246520	RF74LZDC	0.9		

**C3**

1.1 i	TU1JP [HFX]		246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1JP [HFX]		●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3JP [KFX]		246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3JP [KFX]		●246560	RF74HZK	0.9	246554	F87
1.4 i 16V	ET3		●246562	RV90LDC	0.9		
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]		246520	RF74LZDC	0.9		

**C4**

1.4 i 16V	ET3		●246562	RV90LDC	0.9		
1.6 i 16V	TU5 JP4-L4		246520	RF74LZDC	0.9		
2.0 i 16V	EW10 J4-L4		246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4		●246562	RF80LZDC3	0.9		

**C5**

1.8 i 16V	EW 7 J4 [6FZ]	03.2001 ▶	246519	RF80LZDC	0.9		
1.8 i 16V	EW 7 J4 [6FZ]	03.2001 ▶	●246562	RF80LZDC3	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	03.2001 ▶	246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	03.2001 ▶	●246562	RF80LZDC3	0.9		

**C8**

2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	04.2002 ▶	246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	04.2002 ▶	●246562	RF80LZDC3	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	04.2002 ▶	246519	RF80LZDC	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	04.2002 ▶	●246562	RF80LZDC3	0.9		

**CX**

2.0, RE, TRE	829.A5, J6R.A600	07.1979 ▶ 12.1992	246190	RC68H	0.6	246566	C79
2.3 i GTi, ie, ie Prestige	M23.622	07.1982 ▶ 06.1984	246189	R88N	0.6		
2000 : 2.0 Athena, Leader, Pallas, Reflex	829.A5	06.1979 ▶ 06.1984	246190	RC68H	0.6	246566	C79
2000 : 2.0 Confort, Pallas, Super	M20.616	07.1974 ▶ 06.1979	246189	R88N	0.6		
22 : 2.2 RS, TRS	J6T.A500	06.1982 ▶ 12.1992			0.6	246565	C60
2200 : 2.2	M22.617	01.1975 ▶ 07.1976	246189	R88N	0.6		
2400 : 2.4 i	M23	06.1977 ▶ 06.1982	246189	R88N	0.6		

**DS**

D Spécial, Spécial Super, Super			246189	R88N	0.6		
i DS / ID 19, 20, 21, 23			246189	R88N	0.6		

**EVASION**

1.8 i	XU7 JP [LFZ], [LFW]	09.1996 ▶	246487	RF74HZDC	0.9	246554	F87
-------	---------------------	-----------	--------	----------	-----	--------	-----



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## CITROEN (.../...)

### EVASION (.../...)

1.8 i	XU7 JP [LFZ], [LFW]	09.1996 ▶	●246560	RF74HZK	0.9	246554	F87
2.0 i	XU10 J2C [RFU]	06.1994 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i	XU10 J2C [RFU]	06.1994 ▶	●246560	RF74HZK	0.9	246554	F87
2.0 i 16V	EW10 J4-L3 [RFR]	05.2000 ▶	246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L3 [RFR]	05.2000 ▶	●246562	RF80LZDC3	0.9		
2.0 i 16V	XU10 J4R [RFV]	▶ 04.2000	246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	XU10 J4R [RFV]	▶ 04.2000	●246560	RF74HZK	0.9	246554	F87
2.0 i Turbo	XU10 J2TE [RGX]	06.1994 ▶	246487	RF74HZDC	0.9	246554	F87
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat		246519	RF80LZDC	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat		●246562	RF80LZDC3	0.9		

### GS

1015 : 1.0		08.1970 ▶ 06.1980	246198	R70H	0.6	246557	H60
1130 : 1.1, Spécial, G Spécial		08.1974 ▶ 06.1980			0.6	246565	C60
1130 : 1.1, Spécial, G Spécial		08.1974 ▶ 06.1980	246198	R70H	0.6	246557	H60
1220 : 1.2 Club, Club C-matic, Pallas Pallas C-matic		08.1974 ▶ 06.1980	246179	R76H	0.6	246555	H79
1300 : 1.3		08.1974 ▶ 06.1980	246198	R70H	0.6	246557	H60

### GSA

1.3 Pallas, Pallas C-matic		09.1979 ▶ 07.1986	246198	R70H	0.6	246557	H60
1015 : 1.0		08.1974 ▶ 06.1980	246198	R70H	0.6	246557	H60
1130 : 1.1		09.1977 ▶ 08.1983			0.6	246565	C60
1130 : 1.1		09.1977 ▶ 08.1983	246198	R70H	0.6	246557	H60
1220 : 1.2		08.1974 ▶ 12.1978	246198	R70H	0.6	246557	H60
1300 : 1.3		09.1979 ▶ 07.1986	246190	RC68H	0.6	246566	C79
1300 : 1.3		09.1979 ▶ 07.1986	246198	R70H	0.6	246557	H60

### LNA

0.7 LNA 652 cm_		11.1978 ▶ 06.1986			0.6	246565	C60
1.1		07.1982 ▶ 06.1986	246190	RC68H	0.6	246566	C79

### SAXO

1.0 i	TU9M [CDY] [CDZ]	01.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.0 i	TU9M [CDY] [CDZ]	01.1996 ▶	●246560	RF74HZK	0.9	246554	F87
1.1 i	TU1JP-L4 [HFZ]	06.2000 ▶	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1JP-L4 [HFZ]	06.2000 ▶	●246560	RF74HZK	0.9	246554	F87
1.1 i	TU1M+ [HDY] [HDZ]	01.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1M+ [HDY] [HDZ]	01.1996 ▶	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3JP [K6C, KFX]	01.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3JP [K6C, KFX]	01.1996 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i	TU5JP [NFZ]	01.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i	TU5JP [NFZ]	01.1996 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i 16V	TU5 J4 [NFX]	07.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	TU5 J4 [NFX]	07.1996 ▶	●246560	RF74HZK	0.9	246554	F87

### SM

Tous modèles (all models)			246180	R84H	0.6	246555	H79
---------------------------	--	--	--------	------	-----	--------	-----


### VISA

0.65 i Club, Spécial, II Club, II Spécial		▶ 03.1991			0.6	246565	C60
1.1 Super, Super E, Super E 5, Super X		▶ 03.1991	246190	RC68H	0.6	246566	C79
1.2 i L, Super E, Super X, II Super X		▶ 03.1991	246190	RC68H	0.6	246566	C79
1.4 Chrono, Super X	156/5A	07.1982 ▶ 03.1991			0.6	246565	C60
1.6 GTi		06.1987 ▶ 03.1991	246184	RF72H	0.6	246567	F59
1.6 GTi		09.1978 ▶ 05.1987			0.6	246565	C60
10 : 1.0 i E, II E, Challenger		▶ 03.1991	246190	RC68H	0.6	246566	C79
11 : 1.1 i E, RE, L, II L, II Super E		▶ 03.1991	246190	RC68H	0.6	246566	C79
14 : 1.4 GT		09.1978 ▶ 03.1991			0.6	246565	C60
14 : 1.4 RS, TRS, L, Super E		▶ 03.1991	246190	RC68H	0.6	246566	C79

### XANTIA

1.6 i	XU5JP-Z [BFZ]	03.1993 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i	XU5JP-Z [BFZ]	03.1993 ▶	●246560	RF74HZK	0.9	246554	F87
1.8 i	XU7 JP [L6A] [LFZ] [LFW]		246487	RF74HZDC	0.9	246554	F87
1.8 i	XU7 JP [L6A] [LFZ] [LFW]		●246560	RF74HZK	0.9	246554	F87
1.8 i 16V	XU7 JP4 [LFY]	08.1994 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i 16V	XU7 JP4 [LFY]	08.1994 ▶	●246560	RF74HZK	0.9	246554	F87
2.0 i	XU10 J2C [RFX] [R6D] [RFZ]		246487	RF74HZDC	0.9	246554	F87
2.0 i	XU10 J2C [RFX] [R6D] [RFZ]		●246560	RF74HZK	0.9	246554	F87
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		●246562	RF80LZDC3	0.9		





3+1


**CITROEN** (.../...)

**XANTIA (.../...)**

2.0 i 16V Activa, Athéna, Audace, Exclusive	XU10 J4R [RFV]	08.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V Activa, Athéna, Audace, Exclusive	XU10 J4R [RFV]	08.1994 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V Athéna, Audace, VSX	XU10 J4RS-L3 [RFS]	06.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V Athéna, Audace, VSX	XU10 J4RS-L3 [RFS]	06.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V VSX	XU10 J4D-L3 [RFT] [RFY]	03.1993 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V VSX	XU10 J4D-L3 [RFT] [RFY]	03.1993 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Turbo	XU10 J2TE [RGX- RGY]	08.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
3.0 i V6 24v	ES 9 J4-L3 [XFZ]	09.1996 ▶			0.9	<b>246554</b>	F87

**XM**

2.0	XU10.2C [R2A]	05.1989 ▶ 06.1994	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i	XU10 J2-Z [RFZ], XU10 J2 [R6A]	05.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 J2-Z [RFZ], XU10 J2 [R6A]	05.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i	XU10 M-Z [RDZ]	05.1989 ▶ 06.1994	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 M-Z [RDZ]	05.1989 ▶ 06.1994	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [RFV]	07.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [RFV]	07.1994 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Turbo	XU10 J2TE [RGX- RGY]	09.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
3.0 i V6 24v	ES 9 J4-L3 [XFZ]	07.1997 ▶			0.9	<b>246554</b>	F87

**XSARA**

1.4 i	TU3JP [KFX] [K6C] [KFW] [K6C]	09.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3JP [KFX] [K6C] [KFW] [K6C]	09.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ]	09.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ]	09.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	09.2000 ▶	<b>246520</b>	RF74LZDC	0.9		
1.8 i	XU7 JB [LFX], XU7 JP [LFW LFZ]	09.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i	XU7 JB [LFX], XU7 JP [LFW LFZ]	09.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i 16V	XU7 JP4 [LFY]	09.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i 16V	XU7 JP4 [LFY]	09.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		● <b>246562</b>	RF80LZDC3	0.9		
2.0 i 16V	XU10 J4R [RFV]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [RFV]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V VTS	XU10 J4RS-L3 [RFS]	01.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V VTS	XU10 J4RS-L3 [RFS]	01.1998 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

**XSARA PICASSO**

1.6 i	TU5JP-L3 [NFZ]	12.1999 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	TU5JP-L3 [NFZ]	12.1999 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i 16V	EW 7 J4 [6FZ]	12.1999 ▶	<b>246519</b>	RF80LZDC	0.9		
1.8 i 16V	EW 7 J4 [6FZ]	12.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9		

**ZX**

1.1	TU1-K [H1A, H1B]	02.1991 ▶ 08.1996	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1 i	TU1M+ [HDY]	04.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1M+ [HDY]	04.1994 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3.2 [K2C-K2D-K5A]	03.1991 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3.2 [K2C-K2D-K5A]	03.1991 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i	TU3JP [K6C, KFX], TU3M [KDX KDY]	08.1991 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3JP [K6C, KFX], TU3M [KDX KDY]	08.1991 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ], XU5JP [BFZ] XU5M [B4A, BDY]	03.1991 ▶ 06.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ], XU5JP [BFZ] XU5M [B4A, BDY]	03.1991 ▶ 06.1995	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i	XU7 JP [L6A] [LFZ]	07.1993 ▶ 06.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i	XU7 JP [L6A] [LFZ]	07.1993 ▶ 06.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i 16V	XU7 JP4 [LFY]	03.1997 ▶ 06.1998	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i 16V	XU7 JP4 [LFY]	03.1997 ▶ 06.1998	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.9 i Volcane	XU9 JA-Z [DFY], XU9 JA-K [D6E]	03.1991 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.9 i Volcane	XU9 JA-Z [DFY], XU9 JA-K [D6E]	03.1991 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Volcane	XU10 J2C [RFX] [R6D]	07.1994 ▶ 06.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i Volcane	XU10 J2C [RFX] [R6D]	07.1994 ▶ 06.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4RS-L3 [RFS]	06.1996 ▶ 06.1998	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4RS-L3 [RFS]	06.1996 ▶ 06.1998	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## CITROEN (.../...)

### ZX (.../...)

2.0 i 16V	XU10 J4-Z [RFT] [RFY]	07.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4-Z [RFT] [RFY]	07.1992 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

## CITROEN

### C15

1.0	TU9 [C1A]	07.1988 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.0	XV8 [108C]	11.1986 ▶ 09.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.1	E1A [M103]	07.1987 ▶ 09.1988	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	TU1-K [H1A]	07.1988 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	XW7 [109/5K]	10.1984 ▶ 07.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.3	G1A [M104]	07.1987 ▶ 12.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.3	G1A [M104]	10.1984 ▶ 06.1987	<b>246190</b>	RC68H	0.9	<b>246566</b>	C79
1.4	TU3.2-K [K2D], TU3A [K1G]	07.1987 ▶ 12.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A]	07.1987 ▶ 12.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A]	07.1987 ▶ 12.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	XY7 [150D]	10.1984 ▶ 05.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4	XY7 [150D], XY7CP [KAZ]	06.1988 ▶ 12.1997	● <b>246560</b>	RF74HZK	0.6	<b>246554</b>	F87
1.4 i	TU3M [KDY]	08.1991 ▶ 12.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3M [KDY]	08.1991 ▶ 12.1997	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### C25

25 : 1.8 E	XM7	11.1981 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
25 : 2.0 E	XN1T	09.1981 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79

### C32, C35

C 35 : 2.0 E		11.1973 ▶	<b>246189</b>	R88N	0.7		
--------------	--	-----------	---------------	------	-----	--	--

### H

1000 : 1.0			<b>246189</b>	R88N	0.6		
1500 :			<b>246189</b>	R88N	0.6		
1600 : 1.6			<b>246189</b>	R88N	0.6		
850 :			<b>246189</b>	R88N	0.6		

### JUMPER / RELAY

2.0 i	XU10 J2U [RFW]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 J2U [RFW]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### JUMPY / DISPATCH

1.6 i	1580 SPI	10.1995 ▶	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59
-------	----------	-----------	---------------	----------	-----	---------------	-----

## DACIA

### 1210

1.2		01.1977 ▶	<b>246189</b>	R88N	0.6		
-----	--	-----------	---------------	------	-----	--	--

### 1300 > 1325

1.3 / 1.4		01.1977 ▶	<b>246189</b>	R88N	0.75		
1.3 i / 1.4 i / 1.6 i		01.1983 ▶	<b>246189</b>	R88N	0.75		

### 1410

1.4		01.1977 ▶	<b>246189</b>	R88N	0.6		
-----	--	-----------	---------------	------	-----	--	--

### DUSTER

1.4 Duster 4x4		06.1984 ▶	<b>246189</b>	R88N	0.6		
----------------	--	-----------	---------------	------	-----	--	--

### LOGAN

1.4 i, 1.6 i	K7J, K7M	10.2004 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
--------------	----------	-----------	---------------	----------	-----	---------------	-----

### NOVA-SUPERNOVA

1.4		01.1996 ▶	<b>246189</b>	R88N	0.75		
1.4 i	C	01.1996 ▶	<b>246189</b>	R88N	0.75		
1.4 i	E7J	01.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i	C	05.1996 ▶	<b>246189</b>	R88N	0.75		

### SOLENZA

1.4 i	E7J	01.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
-------	-----	-----------	-----------------	---------	-----	---------------	-----

## DAEWOO

### ARANOS

1.8 i	[SOHC]	11.1994 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
-------	--------	-----------	---------------	------	-----	---------------	-----

### CIELO

1.5 i	G15MF [SOHC]	08.1994 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 i 16V	A15MF [DOHC]	08.1994 ▶			1.1	<b>246556</b>	F87-11

### DAMAS

0.8	F8CB	10.1991 ▶ 04.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	------	-------------------	---------------	------	-----	---------------	-----

### ESPERO

1.5 i	G 15 MF	04.1993 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 i 16V CLX, GLX, GLX Pack L	A15MF [DOHC]	09.1993 ▶			1.1	<b>246556</b>	F87-11



3+1

**DAEWOO** (.../...)

**ESPERO (.../...)**

1.8 i CD	C 18 NE [OHC]	09.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i CD, CD Pack L	C 20 LE, LZ	10.1990 ▶			1.1	<b>246564</b>	H79-11

**IMPERIAL**

3.0 i	C 30 NE	02.1989 ▶ 08.1993	<b>246189</b>	R88N	0.7		
-------	---------	-------------------	---------------	------	-----	--	--

**LANOS**

1.4 i	A14SMS [SOHC]	04.1997 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5 i SE, SX	A15SMS [SOHC]	11.1996 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 i 16V	A16DMS [DOHC]	11.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**LE MANS**

1.5	G 15 CF	01.1988 ▶ 12.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.5 i	G 15 SF, MF	09.1988 ▶ 03.1994	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.5 i 16V	A15MF [DOHC]	04.1993 ▶ 10.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i	G 16 SF	01.1988 ▶ 03.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	C 20 LZ	01.1990 ▶ 03.1993			1.1	<b>246564</b>	H79-11

**LEGANZA**

2.0 i 16V CDX, SX	X20SED [DOHC]	03.1997 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
-------------------	---------------	-----------	---------------	----------	-----	---------------	-----

**LEGEND**

3.2		09.1993 ▶	<b>246333</b>	RF72H11	1.1		
-----	--	-----------	---------------	---------	-----	--	--

**MATIZ**

0.8 i S, SE	F8CV	04.1998 ▶			1.1	<b>246564</b>	H79-11
-------------	------	-----------	--	--	-----	---------------	--------

**NEXIA**

1.5 i Aquarius, GL, GLE	G15MF [SOHC]	12.1994 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 i 16V GLX, GTX	A15MF [DOHC]	11.1994 ▶			1.1	<b>246556</b>	F87-11
1.8 i	C 18 LE [SOHC]	12.1995 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**NUBIRA**

1.6 i 16V SE, SX	A16DMS [DOHC]	06.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V CDX	X20SED [DOHC]	04.1997 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**PRINCE**

1.8 i 16V	[DOHC]	04.1996 ▶ 02.1997	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i Brougham, Super Salon	C 20 LE	01.1991 ▶ 03.1996			1.1	<b>246564</b>	H79-11
2.0 i 16V Brougham	T20 [DOHC]	01.1996 ▶ 02.1997	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.2 i 16V	[DOHC]	01.1996 ▶ 02.1997	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**RACER**

1.5 i		01.1988 ▶ 02.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-------	--	-------------------	---------------	------	-----	---------------	-----

**ROYAL**

1.5 Prince, Duke	G 15 CR	05.1987 ▶ 12.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 XQ	15 N	08.1982 ▶ 05.1986	<b>246189</b>	R88N	0.7		
1.5 i Prince	G 15 SR	01.1990 ▶ 12.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.9 Prince	H 19 CR	09.1980 ▶ 12.1987	<b>246189</b>	R88N	0.7		
1.9 i Prince	H 19 MR	01.1988 ▶ 12.1990	<b>246189</b>	R88N	0.7		
2.0 Prince, Salon	H 20 CR	09.1980 ▶ 12.1987	<b>246189</b>	R88N	0.7		
2.0 i Prince, Salon, Salon Super	H 20 MR	12.1985 ▶ 12.1990	<b>246189</b>	R88N	0.7		

**TACUMA / REZZO**

2.0 i		01.2000 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.0 i 16V	T20 [DOHC]	01.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**TICO**

0.8 SX	F8C	06.1991 ▶			1.1	<b>246564</b>	H79-11
--------	-----	-----------	--	--	-----	---------------	--------

**DAF**
**V 200**

1.7	Leyland-Daf	03.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0	Leyland-Daf	03.1988 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**DAIHATSU**
**APPLAUSE**

1.6 16V	HD-C [SOHC]	▶ 12.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i	HD-CF	06.1989 ▶ 08.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4x4	HD-E Cat	06.1989 ▶			1.1	<b>246556</b>	F87-11

**ARTEZ**

2.2 i 16V	5S-FE [DOHC] Cat	03.2000 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	---------------	---------	-----	---------------	--------

**CAB VAN, SPARCAR**

1.0 1000, S 75 V	CB41	01.1985 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
------------------	------	-----------	---------------	------	-----	---------------	-----

**CHARADE**

1.0 CS, CX	CB 36/37	01.1987 ▶ 01.1993			1.1	<b>246564</b>	H79-11
1.0 i	CB20, CB23 [OHC] Cat	10.1977 ▶			1.1	<b>246564</b>	H79-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## DAIHATSU (.../...)

### CHARADE (.../...)

1.0 i	CB90	11.1989 ▶			1.1	<b>246564</b>	H79-11
1.0 i GTi	CB70	03.1987 ▶ 01.1993			1.1	<b>246564</b>	H79-11
1.0 i Turbo GTi Twin Cam Turbo	CB80 [DOHC]	03.1987 ▶ 09.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.0 Turbo	CB23. CB 60/61	10.1983 ▶ 10.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 i 4x4	HC-E [OHC] Cat	06.1988 ▶ 10.1990			1.1	<b>246556</b>	F87-11
1.3 i 16V	HC-C [DOHC], HC-E [SOHC]	09.1988 ▶ 12.1992			1.1	<b>246556</b>	F87-11
1.5 i 16V	HE-E [SOHC] Cat	08.1993 ▶ 03.2000	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V GTi	HD-E Cat	01.1993 ▶ 03.2000	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### CHARMANT

1.3	4K, 4K-C	03.1978 ▶ 07.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	T	11.1973 ▶ 07.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	2T, 4A, 12T	03.1978 ▶ 07.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	3AU	01.1982 ▶ 12.1988			1.1	<b>246564</b>	H79-11

### CONSORTE

		01.1970 ▶ 12.1979	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
--	--	-------------------	---------------	------	-----	---------------	-----

### CUORE

0.5 550, Max	AB10	01.1976 ▶ 09.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.5 L55	AB30	10.1980 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.55 Turbo	EB-T	01.1988 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
0.6 L60	AD10	10.1980 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.8 850, 850 4x4	ED Cat	08.1985 ▶ 07.1994	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
0.8 i 12V 850	ED20	01.1995 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
0.8 i 6V 850, 850 4x4	ED10 [SOHC]	08.1985 ▶ 07.1994	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
0.9 900	Cat	11.1996 ▶			1.1	<b>246564</b>	H79-11
660	EF-CL	01.1990 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
660	EF-HL [SOHC]	01.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

### DELTA

1.2	3K-J	12.1975 ▶ 02.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 Wide	4K-J	01.1978 ▶ 10.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5 i Wide	5K-J	08.1990 ▶ 12.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 Wide	2Y-J [OHV]	08.1988 ▶ 11.1996	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 Wide	2Y-U [OHV]	11.1982 ▶ 12.1991			1.1	<b>246564</b>	H79-11
2.0 V69B-U	3Y	10.1986 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### DELTA WAGON / VAN

1.5 i	5K-J	11.1996 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i	7K	11.1996 ▶ 12.1999	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i	7K-E	01.2000 ▶			1.1	<b>246564</b>	H79-11
2.0 i 16V	3S-FE [DOHC] Cat	11.1996 ▶			1.1	<b>246556</b>	F87-11

### DOMINO

0.8	ED Cat	09.1985 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
0.8 i 12V	ED20	10.1996 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
0.8 i 6V	ED10 [SOHC]	09.1985 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.0 L		07.1993 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### F

1.6 20/25	12R	09.1976 ▶ 12.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 80/85	3Y	04.1984 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79

### FEROZA

1.6 16V 4x4	HD-C [SOHC]	10.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4x4	HD-E Cat	08.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### GRAN MOVE

1.5 i 16V	HE-E [SOHC] Cat	08.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	-----------------	-----------	---------------	---------	-----	---------------	--------

### HI ATRE 7

1.3 i 16V	K3-VE [DOHC] Cat	07.2000 ▶			1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	--	--	-----	---------------	--------

### HIJET

0.55 Climber, Jumbo	EB 60	09.1987 ▶ 04.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.55 HiJet, HiAtre	EB	10.1988 ▶ 04.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.55 HiJet, HiAtre	EB 60	09.1987 ▶ 10.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.8 850	CD	07.1986 ▶ 11.1992	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 1000	CB	12.1992 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.0 1000, 1000 4x4	CB	07.1986 ▶ 11.1992	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
660 i	EF-SE	01.1999 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### LEEZA

0.55	EB	12.1986 ▶ 08.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
660	EF-HL [SOHC]	08.1990 ▶ 12.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87


**DAIHATSU** (.../...)

<b>MIDGET</b>									
660 i	EF-CK		04.1996 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>MIRA</b>									
0.5 Turbo Mira Turbo	AB		10.1980 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
0.6 Mira 4x4	AB		10.1980 ▶ 09.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
0.8 i 6V	ED10 [SOHC]		11.1990 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79	
660	EF-CL		03.1990 ▶ 09.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
660	EF-FL [SOHC]		09.1994 ▶ 10.1998	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
660	EF-HL [SOHC]		03.1990 ▶ 09.1994	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
660	EF-KL		03.1990 ▶ 09.1994			1.1	<b>246564</b>	H79-11	
660 i	EF-SE		10.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
<b>MOVE</b>									
0.8 i 12V 850	ED20		01.1997 ▶			0.9	<b>246564</b>	H79-11	
0.8 i 6V 850	ED10 [SOHC]		01.1997 ▶			0.9	<b>246564</b>	H79-11	
660 i	EF-SE		10.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
660 i Turbo	JB-DET [DOHC] Cat		10.1998 ▶			1.0	<b>246554</b>	F87	
<b>OPTI</b>									
660	EF-KL		08.1992 ▶ 12.1998			1.1	<b>246564</b>	H79-11	
660 i	EF-SE		12.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
660 i Turbo	JB-DET [DOHC] Cat		12.1998 ▶			1.0	<b>246554</b>	F87	
<b>PYZAR</b>									
1.5 i 16V	HE-EG Cat		08.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
1.6 i 16V	HD-EP Cat		09.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
<b>ROCKY</b>									
1.6 i 16V	HD-E Cat		06.1990 ▶ 04.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
2.0 i 4x4	3Y		03.1987 ▶ 04.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
2.2 i 4x4	4Y		05.1993 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>SIRION</b>									
1.0 i 12V	EJ-DE Cat		04.1998 ▶			1.0	<b>246554</b>	F87	
1.3 i 16V, Gtvi	K3-VE [DOHC] Cat		09.2000 ▶			1.1	<b>246556</b>	F87-11	
<b>SPARCAR</b>									
0.5 550 S60, S65	AB20		03.1977 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
0.9 S70	CD20		09.1983 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>STORIA</b>									
1.0 i 12V	EJ-DE Cat		02.1998 ▶ 05.2000			1.0	<b>246554</b>	F87	
1.0 i 12V	EJ-VE [DOHC] Cat		05.2000 ▶			1.1	<b>246556</b>	F87-11	
1.3 i 16V	K3-VE [DOHC] Cat		05.2000 ▶			1.1	<b>246556</b>	F87-11	
<b>TAFT</b>									
1.6 4x4	12R		01.1976 ▶ 05.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>TERIOS</b>									
1.3 i 16V	HC-EJ		03.1997 ▶ 05.2000			1.0	<b>246554</b>	F87	
1.3 i 16V	K3-VE [DOHC] Cat		05.2000 ▶			1.1	<b>246556</b>	F87-11	
<b>VALERA</b>									
1.5 i 16V	HE-EG Cat		01.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
<b>WILDCAT, ROCKY</b>									
2.8 D	DL		02.1985 ▶ 03.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>YRV</b>									
1.0 i 12V	EJ-VE [DOHC] Cat		08.2000 ▶			1.1	<b>246556</b>	F87-11	
1.3 i 16V	K3-VE [DOHC] Cat		08.2000 ▶			1.1	<b>246556</b>	F87-11	

**DAIMLER LTD**

<b>DS</b>									
4.2 i L6 420	[OHC]		10.1984 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
4.2 L6 420	[OHC]		10.1984 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
<b>SOVEREIGN</b>									
3.4	XK [OHC]		09.1974 ▶ 08.1986	<b>246180</b>	R84H	0.9	<b>246555</b>	H79	
3.6			01.1986 ▶ 12.1989	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87	
4.0	AJ6 [DOHC] Cat		09.1989 ▶	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87	
4.2 L6	[OHC]		03.1979 ▶	<b>246179</b>	R76H	0.6	<b>246555</b>	H79	

**DINO**

<b>308</b>									
3.0 GT4			08.1973 ▶ 12.1981	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1




## DODGE

<b>600</b>									
2.2 i			01.1986 ▶ 12.1988	<b>246182</b>	R92H	0.9			
2.5 i	(K)		01.1986 ▶ 12.1988	<b>246182</b>	R92H	0.9			
<b>ARIES</b>									
2.2 i	(D)		01.1986 ▶ 12.1989	<b>246182</b>	R92H	0.9			
2.5 i	(K)		01.1986 ▶ 12.1989	<b>246182</b>	R92H	0.9			
<b>AVENGER</b>									
2.0 i	(Y) [DOHC]		09.1994 ▶ 08.1996	<b>246186</b>	RF82H	1.2	<b>246554</b>	F87	
2.5 i 24V	(H)		09.1994 ▶			1.1	<b>246556</b>	F87-11	
<b>CARAVAN</b>									
2.5 i			01.1988 ▶	<b>246181</b>	R90H	0.9			
<b>DAYTONA</b>									
2.2 i 16V Turbo IROC			08.1992 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79	
2.2 i Turbo			01.1986 ▶	<b>246182</b>	R92H	0.9			
2.5 i Turbo			01.1986 ▶	<b>246182</b>	R92H	1.1			
<b>DYNASTY</b>									
2.5 i	(K)		09.1987 ▶ 08.1993	<b>246182</b>	R92H	0.9			
<b>GRAND CARAVAN</b>									
2.5 i SE			01.1988 ▶	<b>246181</b>	R90H	0.9			
<b>KC</b>									
2.3				<b>246181</b>	R90H	0.8			
<b>LANCER</b>									
2.2 i Turbo	(A)		09.1986 ▶ 08.1989	<b>246181</b>	R90H	0.9			
2.5 i	(K)		09.1986 ▶ 08.1989	<b>246181</b>	R90H	0.9			
<b>MODELES IMP</b>									
			▶ 12.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>OMNI</b>									
1.6	(A)			<b>246182</b>	R92H	0.9			
2.2			01.1986 ▶ 12.1987	<b>246182</b>	R92H	0.9			
2.2 i			01.1986 ▶ 12.1990	<b>246182</b>	R92H	0.9			
<b>RAMCHARGER</b>									
5.2 i V8			01.1988 ▶ 12.1991	<b>246182</b>	R92H	0.9			
5.9 i V8			01.1993 ▶	<b>246182</b>	R92H	0.9			
5.9 i V8	(W)		01.1989 ▶ 12.1992	<b>246182</b>	R92H	0.9			
5.9 V8	(W)			<b>246182</b>	R92H	0.9			
<b>SERIES 1500, 2000, 2500</b>									
				<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>SERIES WALK-THRU</b>									
				<b>246182</b>	R92H	0.8			
<b>SHADOW</b>									
2.2 i ES	(D)		09.1986 ▶ 08.1994	<b>246182</b>	R92H	0.9			
2.5 i	(K)		08.1987 ▶ 08.1994	<b>246182</b>	R92H	0.9			
<b>SPACE VAN</b>									
				<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>SPIRIT</b>									
3.0 i V6	(3)		10.1988 ▶ 08.1995	<b>246182</b>	R92H	1.1			
<b>STEALTH</b>									
3.0 i Turbo	(K)		09.1992 ▶ 08.1997			1.1	<b>246556</b>	F87-11	
3.0 i V6			01.1991 ▶	<b>246186</b>	RF82H	0.9	<b>246554</b>	F87	
<b>STRATUS</b>									
2.0 i 16V	ECB		01.1994 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
2.5 i 24V	(H)		09.1994 ▶			1.1	<b>246556</b>	F87-11	

## FERRARI

<b>308 GTS</b>									
2.9 i 2.9 GTB, i, GTS, i, Quattrovalvole	F106B, F105A		07.1981 ▶ 08.1985	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
<b>400 I</b>									
4.8 i i Auto.	F101C010		10.1976 ▶ 04.1985	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
<b>412 I</b>									
4.9 i V12			03.1985 ▶ 12.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
<b>BB</b>									
512			08.1976 ▶ 12.1981	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
<b>MONDIAL</b>									
2.9			05.1980 ▶ 06.1982	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	


**3+1**

**FIAT**

**124**

1.4 Sport Coupé, Sport Spider			<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 Abarth Rallye		01.1973 ▶ 07.1975	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 Sport Coupé, Sport Spider		11.1969 ▶ 08.1973	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 Sport Coupé, Sport Spider			<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 Maratea		06.1983 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 Spider Europa Volumex		06.1983 ▶ 04.1985	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 ie Sport Spider 2000 ie	131 AB...	06.1979 ▶ 04.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
Berlina, Familiare, Special 1438			<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**126**

0.65 650	Lg filetage	07.1977 ▶ 09.1987	<b>246189</b>	R88N	0.7		
0.7 Bis, Up	126 A2...	09.1987 ▶ 06.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**127**

0.9 900 Brava, C, L, Spécial, Super		06.1971 ▶ 05.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.05 1050 C, CL, Panorama, Super, Top		04.1977 ▶ 12.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.05 1050 Sport		06.1978 ▶ 05.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.3 1300 Sport		06.1978 ▶ 05.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**128**

1.1 1100, S, SL, Sport, Sport Coupé		09.1969 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 1300, S, SL, Rallye, Sport, Sport Coupé		03.1969 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**131**

1.3 Mirafiori 1300, Super Mirafiori 1300		10.1974 ▶ 01.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 Mirafiori 1300, 1400, Panorama 1300, 1400		11.1980 ▶ 01.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 Super Mirafiori 1300, 1400		01.1981 ▶ 01.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 Mirafiori 1600, Super Mirafiori 1600		03.1978 ▶ 01.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 Mirafiori 1800		10.1974 ▶ 12.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 Abarth Rallye		01.1976 ▶ 12.1979	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 Brava, Mirafiori Sport, Racing, Super Brava		06.1978 ▶ 12.1981	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 Super Mirafiori 2000		06.1981 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 Super Mirafiori 2000	131.CC...	01.1981 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**132**

1.6 1600, GL, GLS		07.1979 ▶ 05.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 1800 GLS		05.1972 ▶ 02.1977	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 2000 Berlina (Nuova Fiat)		07.1979 ▶ 05.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 2000 ie		09.1979 ▶ 05.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**500**

0.5		▶ 12.1975	<b>246189</b>	R88N	0.6		
-----	--	-----------	---------------	------	-----	--	--

**900**

0.9 E Furgone	100 GF 000	12.1979 ▶ 12.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 T	100 GF 000	10.1977 ▶ 07.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**ARGENTA**

1.6 100, 1600	132.D, 132.FB	06.1981 ▶ 11.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 110	132.D1	06.1983 ▶ 11.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 SX, VX	132.E	03.1984 ▶ 11.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 120 ie	132.C	06.1983 ▶ 11.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 ie 2000, 2000 ie	132.FB, 132.GB	06.1981 ▶ 05.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**BARCETTA**

1.8 i, ie Lido, Riviera	183.A1.000	01.1995 ▶			1.0	<b>246554</b>	F87
-------------------------	------------	-----------	--	--	-----	---------------	-----

**BRAVA**

1.4 i 12V S, SX	182.A3-A5.000	08.1995 ▶ 10.1998			1.0	<b>246554</b>	F87
1.6 i, ie	182.A4.027	11.1998 ▶			1.0	<b>246554</b>	F87
1.6 i, ie EL, ELX, GT, HSX, SX	182.A4.000 Cat				1.0	<b>246554</b>	F87
1.6 i, ie ELX, SX	182.A6.000	08.1995 ▶			1.0	<b>246554</b>	F87
1.8 i, ie ELX, GT	182.A2.000	08.1995 ▶			1.0	<b>246554</b>	F87

**BRAVO**

1.6 i, ie	182.A4.027	11.1998 ▶			1.0	<b>246554</b>	F87
1.6 i, ie EL, ELX, GT, HSX, SX	182.A4.000 Cat				1.0	<b>246554</b>	F87
1.6 i, ie ELX, SX	182.A6.000	08.1995 ▶			1.0	<b>246554</b>	F87
1.8 i, ie ELX, GT	182.A2.000	08.1995 ▶			1.0	<b>246554</b>	F87
2.0 i 20V HGT	182.A1.000	08.1995 ▶ 10.1998			1.0	<b>246554</b>	F87

**CAMPAGNOLA**

2.0	6132 AZ 2000	06.1974 ▶ 10.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--------------	-------------------	---------------	------	-----	---------------	-----

**CINQUECENTO**

0.7 700 Clim, S, ED	170.A.000, 170.A.046	07.1991 ▶ 05.1998	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 900	170.A1.000	10.1991 ▶ 05.1998	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 i, ie	170.A1.046		<b>246179</b>	R76H	0.9	<b>246555</b>	H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## FIAT (.../...)

### CINQUECENTO (.../...)

0.9 i, ie 900	1170.A1.046	07.1991 ▶ 05.1998	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 i, ie Young	1170.A1.046	07.1991 ▶ 05.1998	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 i, ie Sporting Fire	176.B2.000, 176.A6.000	01.1994 ▶ 05.1998	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

### COUPE

1.8 i, ie	183.A1.000	02.1996 ▶			1.0	<b>246554</b>	F87
2.0 i 20V	182.A1-B3.000	09.1996 ▶			1.0	<b>246554</b>	F87
2.0 i, ie 16V	836.A3.000, 836.A3.011	02.1994 ▶ 12.1996	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 ie 20V Turb	175.A3.000	09.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 ie Turbo	175.A1.000	02.1994 ▶ 12.1996			0.8	<b>246557</b>	H60

### CROMA

1.6	154.A.048	12.1985 ▶ 06.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	153.C3.000	12.1992 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	154.A1.000	12.1985 ▶ 02.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	154.C2.000	12.1985 ▶ 06.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	154.C3.000	07.1990 ▶ 02.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	154.C3.046	07.1990 ▶ 02.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	154.C5.000	07.1990 ▶ 11.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	834.AB.000	12.1985 ▶ 11.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	834.B.048	12.1985 ▶ 11.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	834.B.146	10.1990 ▶ 02.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 16V	154.E1.000	01.1991 ▶ 02.1997	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 ie Turbo	154.A2-C4.000, 154.C4.046 834.C.146	12.1985 ▶ 02.1997			0.8	<b>246557</b>	H60
2.0 ie Turbo	175.A1.000	02.1994 ▶ 02.1997			0.8	<b>246557</b>	H60
2.5 ie V6	834.G.000	01.1993 ▶ 02.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### DUNA

1.1 60, 60 Weekend	146.A6.000	10.1986 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 70, 70 Weekend	146.A5.000	10.1986 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### MAREA

1.4 i S, SX	182.A3.000	09.1996 ▶ 02.1999			1.0	<b>246554</b>	F87
1.6 i 16V ELX, SX	186.A4.000	09.1996 ▶			1.0	<b>246554</b>	F87
1.6 i, ie ELX, SX	182.A4.000 Cat	09.1996 ▶			1.0	<b>246554</b>	F87
1.8 i, ie ELX, HLX	182.A2.000	09.1996 ▶			1.0	<b>246554</b>	F87
2.0 i 20V ELX, HLX	182.A1.000	09.1996 ▶ 02.1999			1.0	<b>246554</b>	F87

### MULTIPLA

1.6 i 16V 100 ELX	178.B3.000 [DOHC]	01.1999 ▶			1.0	<b>246554</b>	F87
1.6 i 16V 100, SX	186.A3-A4.000, 178.B3.000	01.1999 ▶			1.0	<b>246554</b>	F87
1.6 i, ie 100, SX	182.A4.000 Cat	01.1999 ▶			1.0	<b>246554</b>	F87

### PALIO

1.2 i 65	178.E2.000	01.2000 ▶			1.0	<b>246554</b>	F87
1.2 i 75	178.B5.000	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	178.B2.000	09.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.5 i	178.A5.011	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	SPI 8V	04.1996 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.6 i 16V 100	178.B3.000 [DOHC]				1.0	<b>246554</b>	F87

### PANDA

0.8 34, Young	M 020 BS	02.1981 ▶ 12.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 45, S, 903	146.A.000	02.1981 ▶ 03.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 ie L, CLX	1170.A1.046	04.1992 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 ie L, CLX	1170.A1.046	09.1995 ▶ 08.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.0 1000 Fire Europa, CL, CLX, Estival, Malicia, S Super	156.A2.000	01.1986 ▶ 12.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 48 4x4	A.112.B1.054	04.1983 ▶ 12.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 ie 1000, 4x4, Bluebay, Brio, Mod, Pop, Selecta	156.A2.146, 156.A2.246	10.1987 ▶ 05.1991	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.0 ie 1000, ie, ie 4x4, Selecta	156.A2.048	01.1986 ▶ 04.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie 4x4 Fire, CLX, Pop, Val d'Isère, Piste Noire	156.A2.100, 156.A3.000	01.1986 ▶ 12.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.1 i, ie 1100 ie, Selecta, 4x4 Val d'Isère Trekking, Country Club	176.B2.000	01.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 ie 1100 ie, Selecta, 4x4 Val d'Isère, Trekking Country Club	156.C.046 Cat	07.1990 ▶ 07.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 ie 1100 ie, Selecta, Trekking 4x4	156.C.000	10.1991 ▶ 03.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
750 : 0.8	156.A4.048, 156.A4.000	01.1986 ▶ 12.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
750 : 0.8 Fire	141.B.000	01.1986 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

### PENNY

1.1		01.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----




**FIAT** (.../...)

**PENNY (.../...)**

1.3		01.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

**PUNTO**

1.1 i 55 S, SX, "6 Speed"	176.A6.000	08.1993 ▶ 05.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.2 i 60 S, SX, Cabrio, Cult	176.A7.000	08.1993 ▶ 08.1999	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.2 i 75 SX, ELX, HSD	176.A8.000	08.1993 ▶ 08.1999	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.2 i Cabrio, Selecta, SX	176.B4.000	06.1995 ▶ 08.1999	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.2 i ELX, SX	188.A4.000	09.1999 ▶			0.9	<b>246554</b>	F87
1.2 i Selecta	176.B1.000	06.1994 ▶ 05.1997	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i Turbo GT Turbo	176.A4.000	08.1993 ▶ 05.1997			0.9	<b>246567</b>	F59
1.4 i Turbo GT Turbo	176.B6.000	06.1997 ▶ 08.1999			0.9	<b>246567</b>	F59
1.6 i 90, Cabrio, ELX, Sporting, SX	176.A9.000	01.1994 ▶ 05.1998	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.8 i, ie HGT	183.A1.000	09.1999 ▶			1.0	<b>246554</b>	F87

**REGATA**

1.1 60	146.4A	05.1985 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 70, S, ES, Strada, Weekend	138.B2, 149.A7, 149.A3, 149.C4	09.1983 ▶ 09.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 75	138.B3.048	09.1983 ▶ 03.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 75, S, Weekend	138.C3...	04.1985 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 85, 85 S	138.B3, 149.A5	09.1983 ▶ 12.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 ie 75 ie	149.C1.000 Cat	05.1987 ▶ 06.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 ie 75 ie, Weekend	138.C2... Cat	10.1985 ▶ 04.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 100S	149.A4.000	12.1984 ▶ 05.1986	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 85, 85S	149.A.000	01.1984 ▶ 09.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 ie 90 ie, Europa, Weekend, 100 S ie Weekend	149.C2, 149.C3	06.1986 ▶ 09.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
100S : 1.6 100S	149.A2...	09.1983 ▶ 11.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
100S : 1.6 100S	149.A2...	12.1984 ▶ 06.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**RITMO**

1.1 60, 60 ES		07.1978 ▶ 12.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 65, 70	138.B2, 149.A7	01.1978 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 75	138.C3.048	01.1978 ▶ 12.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 Super 75, Super 85, Cabriolet	138.AE, 138.B3, 149.A5	01.1981 ▶ 12.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 100	149.A4.000	05.1985 ▶ 12.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie 90 ie, 100 ie, 105 TC	149.C2, 149.C3	05.1981 ▶ 09.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 D	138.C...	05.1985 ▶ 12.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 105 TC, Abarth	138.AR...	09.1980 ▶ 07.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 125 TC Abarth	138.AR.1...	11.1981 ▶ 09.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 130 TC Abarth	138.AR.2...	11.1981 ▶ 09.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**SCUDO**

1.6 i	220.A2.000	10.1995 ▶	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59
1.8 i	XU7 JP [L6B]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

**SEICENTO**

0.9 i, ie	1170.A1.046		<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9 i, ie Citymatic, Clim, Hobby, S, SX, Young	170.A1.046	03.1998 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.1 i, ie Sporting, Sporting Abarth	176.B2.000	04.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

**SERIE 240**

1.4 237, 238, 241, 242		▶ 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
------------------------	--	-----------	---------------	------	-----	---------------	-----

**SPIDER**

2.0 Europa Volumex		▶ 12.1985	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i Europa		▶ 12.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**STILO**

1.6 16v	182 B6.000	10.2001 ▶			0.9	<b>246554</b>	F87
1.8 16v	192 A4.000	10.2001 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.4 20v	192 A2.000	10.2001 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

**TEMPRA**

1.4 ie S, SW	836.A4.000	10.1994 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.4 ie S, SX	159.A2.000	02.1990 ▶ 04.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 ie S, SX	160.A1.046	03.1992 ▶ 12.1996	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.4 ie Station Wagon	159.A2.000	02.1990 ▶ 04.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 ie SW, Pop	160.A1.046	03.1992 ▶ 12.1996	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6 ie HSD, Liberty, S, SX, SW, Perfect	835.C1.000	01.1993 ▶ 12.1996	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.6 ie S, SW, SX, Perfect, Selecta	159.A3.000	02.1990 ▶ 04.1993	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 ie SX Selecta, SRX Selecta	159.A3.046	06.1990 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie SX Selecta, SRX Selecta	159.A3.048	06.1992 ▶ 12.1996	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
1.8 ie SLX, ie SX, ie Station Wagon	159.A5.046, 159.A4.000	02.1990 ▶ 04.1993	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie SLX, ie SX, ie Station Wagon	835.C4.000, 159.A4.046	04.1993 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie 16V SLX, ie SX, ie Station Wagon	835.C2.000 Cat	04.1993 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## FIAT (…/…)

### TEMPRA (…/…)

2.0 ie SLX, Selecta, SX	159.A6.046	02.1990 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
<b>TIPO</b>							
1.1 Fire	160.A3.000	07.1987 ▶ 03.1993	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.4 ie Estival, Pop, Selecta, S, Sienna, SX	159.A2.000	01.1990 ▶ 10.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 ie Estival, Pop, Selecta, S, Sienna, SX	160.A1.046, 160.A1.000	07.1987 ▶ 10.1995	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.4 ie Estival, Pop, Selecta, S, Sienna, SX	160.A1.048	07.1987 ▶ 11.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 ie S, SW	836.A4.000	10.1994 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie	149.C2.046 [DOHC]	02.1988 ▶ 06.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 ie	160.A2.000	07.1987 ▶ 10.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie Selecta	835.C1.000	01.1993 ▶ 10.1995	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.6 ie SX, Perfect, Selecta	159.A3.000	04.1990 ▶ 10.1995	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 ie SX, Selecta	159.A3.046, 159.A3.048	03.1990 ▶ 10.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie SX, SLX	159.A4.000	06.1989 ▶ 03.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie 16V	160.A5.000	06.1989 ▶ 09.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie 16V GT, SX, SLX	835.C2.000 Cat	11.1991 ▶ 10.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i, ie 16V	836.A3.000 Cat	05.1991 ▶ 10.1995	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 ie 16V	160.A8.046	12.1990 ▶ 10.1995	<b>246198</b>	R70H	0.9	<b>246557</b>	H60

### ULYSSE

1.8 i S, EL	XU7 JP [LFW]	05.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i S, EL	XU7 JP [LFW]	05.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i S, EL	XU10 J2C [RFU]	07.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i S, EL	XU10 J2C [RFU]	07.1994 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	06.2002 ▶	<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	06.2002 ▶	● <b>246562</b>	RF80LZDC3	0.9		
2.0 i Turbo	XU10 J2TE [RGX]	07.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

### UNO

0.9 45, ES, Pop, S, Sting	146.A	01.1983 ▶ 09.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 Trend	146.B4.000	07.1990 ▶ 03.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 ie	146.C7.000	09.1993 ▶ 04.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 ie 45	156.A2.100, 156.A2.246 156.A2.048, 156.A2.146	06.1985 ▶ 12.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.1 55, S	138.B.000	01.1983 ▶ 04.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 60	146.C3.000	01.1993 ▶ 04.1994	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
1.1 60, S, Selecta, SL, Van CS	146.A6.000, 146.A4	05.1985 ▶ 10.1995	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.1 60, S, SX, Perfect	160.A3.000	09.1989 ▶ 09.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.1 ie 1.1 50 ie Fire, 60 ie Fire	160.A...	09.1989 ▶ 12.1993	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
1.1 ie 60, Hobby, S	156.C.046 Cat	09.1985 ▶ 10.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.3 70, S, SL, SX, Matic, Super	138.B2.000	01.1983 ▶ 12.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 70, S, SL, SX, Matic, Super	149 A7	05.1985 ▶ 08.1989	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.3 ie Turbo	146.A2.000, 146.A2.146 146.A2.246	04.1985 ▶ 03.1991			0.9	<b>246567</b>	F59
1.4 Racing	146.A8.046	09.1989 ▶ 03.1994			0.9	<b>246567</b>	F59
1.4 ie 70 ie, Selecta, ie Selecta, SX	160.A1.046, 146.C1.000	01.1985 ▶ 10.1995	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.4 ie Turbo	146.AB/A8.000	09.1989 ▶ 12.1993			0.9	<b>246567</b>	F59
1.5 ie 75 ie, S, SX	138.C2... Cat	01.1983 ▶ 10.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 ie 75 ie, S, SX, ie Selecta	149.C1.000 Cat	09.1987 ▶ 10.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### X 1/9

1.3 1300		01.1973 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 1500		01.1973 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

## FIAT

### CITIVAN

1.1		01.1989 ▶	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
-----	--	-----------	---------------	-------	-----	---------------	-----

### DAILY

2.0		01.1980 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-----	--	-----------	---------------	------	-----	---------------	-----

### DUCATO

10 : 1.8	XM7 T	09.1981 ▶ 12.1990	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
10 : 2.0	XN1T [170..]	09.1981 ▶ 12.1990	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
2.0 10, 13, 14, 18 Maxi	XN1T	09.1981 ▶ 02.1994	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
2.0 i 10, 14, 18	XU10 J2U [RFW]	03.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 10, 14, 18	XU10 J2U [RFW]	03.1994 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### FIORINO

0.9 900	903...	10.1977 ▶ 03.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 1050	127.A, M201	01.1980 ▶ 12.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 1100	146.A9.000	12.1987 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 1300	146.A5.000	12.1987 ▶ 10.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79



<b>FIAT</b> (.../...)									
<b>FIORINO (.../...)</b>									
1.4 ie	160.A1.046	01.1993 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79		
1.4 ie 1400 ie	146.C5, 146.D5	09.1993 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79		
1.5 ie 1500 ie	149.C1.000 Cat	01.1988 ▶ 12.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5 ie 1500 ie	149.C1.000 Cat	01.1990 ▶ 08.1993	<b>246198</b>	R70H	0.7	<b>246557</b>	H60		
1.6 ie 1600 ie	146.C6.000	09.1993 ▶	<b>246198</b>	R70H	0.9	<b>246557</b>	H60		
1.6 ie 1600 ie	146.D6.000	06.1995 ▶	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59		
<b>TALENTO</b>									
2.0	XN1T [170..]	07.1990 ▶	<b>246179</b>	R76H	0.6	<b>246555</b>	H79		
<b>FISSORE</b>									
<b>MAGNUM 4_4</b>									
2.0 Volumex	132 E.000	01.1986 ▶ 03.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60		
2.0 Volumex	132 GB...	07.1984 ▶ 12.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
2.5 ie V6 VIP	019.11 Cat	03.1986 ▶ 03.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
<b>RAYTON 4_4</b>									
3.5 ie		03.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>FORD</b>									
<b>A</b>									
2.0 0307, 0407, 0507	NX V4 ESX 1V	01.1986 ▶	<b>246179</b>	R76H	0.6	<b>246555</b>	H79		
3.0 V6 0310, 0510, 0610	HXB, HXC V6 ESX 1V	01.1986 ▶	<b>246179</b>	R76H	0.6	<b>246555</b>	H79		
<b>CAPRI</b>									
1.3	J1E, J2F, J2N, J3C, J3N, JSD	12.1968 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
2.0 V6	NYL HC / LC	05.1976 ▶ 07.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60		
2.3 V6	YYN HC	04.1969 ▶ 04.1987	<b>246178</b>	R64H	0.7	<b>246557</b>	H60		
2.8 i V6	RRN	11.1979 ▶ 04.1987	<b>246178</b>	R64H	0.7	<b>246557</b>	H60		
3.0 V6	HYF HC	12.1968 ▶ 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>CORTINA</b>									
1.3	KL 13 H, KL 13 L [OHV]	01.1969 ▶ 10.1982	<b>246198</b>	R70H	0.8	<b>246557</b>	H60		
2.3 V6	TV 23 H [OHV]	02.1977 ▶ 10.1982	<b>246198</b>	R70H	0.8	<b>246557</b>	H60		
<b>COUGAR</b>									
2.0 i 16V	EDBA Zetec [DOHC]	06.1998 ▶	<b>●246455</b>	RC68LPP	1.0				
2.0 i 16V	EDBC, EDBD Zetec [DOHC]	08.1998 ▶	<b>●246455</b>	RC68LPP	1.0				
2.0 i 16V	NGA Zetec [DOHC]	04.1998 ▶	<b>●246455</b>	RC68LPP	1.0				
<b>ESCORT</b>									
1.0 1000	KL 09 G [OHV]	12.1974 ▶ 08.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.1	GPA W	08.1980 ▶ 12.1985			0.7	<b>246567</b>	F59		
1.1 1100	KL 11 E/G/H/L [OHV]	08.1970 ▶ 08.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.1 C Affaire, Express, Express 35, Van 35, Van 55	GSE, GSG, GLB	08.1980 ▶ 07.1990	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79		
1.1 Express	GUC, GUF [HCS]	01.1986 ▶ 12.1994	<b>246326</b>	RC72H11	1.0				
1.1 Van 35, Van 55	GMA	08.1980 ▶ 12.1985	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59		
1.3	JGA	08.1980 ▶ 12.1985	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87		
1.3 1300, Combi, Van	KL 13 L [OHV]	08.1968 ▶ 08.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3 1300, GT	KL 13 G, KL 13 H [OHV]	08.1968 ▶ 08.1980	<b>246198</b>	R70H	0.7	<b>246557</b>	H60		
1.3 Affaire, CLX Melody, CLX Touring, Touring Turnier	JBB, JBD	01.1986 ▶ 12.1994	<b>246326</b>	RC72H11	1.0				
1.3 C, Turnier	JLA, JLB	01.1986 ▶ 07.1990	<b>246191</b>	RC72H	1.0	<b>246566</b>	C79		
1.3 Express 55, Van 35, Van 55	JPA	08.1980 ▶ 12.1985	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59		
1.3 i Affaire, CLX Melody, CLX Touring, Touring Turnier	JBA [HCS], JBE	01.1986 ▶ 12.1994	<b>246326</b>	RC72H11	1.0				
1.3 i CLX Melody, Express, Turnier	J6A [HCS]	07.1990 ▶ 12.1994	<b>246326</b>	RC72H11	1.0				
1.4 Cabrio, CL Affaire, Ghia/Salon, Scoop Touring/Salon, Turnier	FUA	01.1986 ▶ 07.1990	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59		
1.4 Cabrio, CLX, Express, GL, Turnier	FUC, FUH	01.1986 ▶ 12.1994	<b>246333</b>	RF72H11	1.0				
1.4 i Cabrio, CL Affaire, Ghia/Salon, Scoop Touring/Salon, Turnier	FUAA	01.1986 ▶ 07.1990	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59		
1.4 i Cabrio, Express, GL, Malibu, Turnier	F6F, F6G	07.1990 ▶ 12.1994	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11		
1.4 i Cabrio, Turnier	F6B, F6D Cat	01.1986 ▶ 07.1990	<b>246333</b>	RF72H11	1.0				
1.4 i Express 55/75, Sunset, Touring, Tropical Turnier	F4B	07.1990 ▶	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11		
1.6 Cabrio, CLX, Ghia/Salon, GL, Scoop, Success	LUD, LUG	01.1986 ▶ 12.1994	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59		
1.6 LX	LGA	08.1980 ▶ 12.1985	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87		
1.6 RS 1600	LC KL 16 G [OHV]	12.1974 ▶ 08.1980	<b>246198</b>	R70H	0.7	<b>246557</b>	H60		
1.6 Touring/Salon, Turnier, Van	LUD, LUG	01.1986 ▶ 12.1994	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59		
1.6 Turnier	LP1, LPA	08.1980 ▶ 07.1990			0.7	<b>246567</b>	F59		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## FORD (.../...)

### ESCORT (.../...)

1.6 i Cabrio, CLX, Ghia/Salon, GL, Scoop, Success	LUC, LUJ, LUK	01.1986 ▶ 12.1994	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 i Cabrio, i S, Turnier, XR3i	LJF, LJE	07.1990 ▶ 09.1992	<b>246333</b>	RF72H11	1.0		
1.6 i Cabrio, Turnier, XR3i	L4B	08.1980 ▶ 07.1990	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 i Ghia/Salon, XR3i, XR3i Salon	LR1, LR2, LRA, LRB	08.1980 ▶ 07.1990			0.8	<b>246567</b>	F59
1.6 i Touring/Salon, Turnier, Van	LUC, LUJ, LUK	01.1986 ▶ 12.1994	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 i Turnier	LP2	08.1980 ▶ 07.1990			0.7	<b>246567</b>	F59
1.6 i 16V Cabrio, CLX, L, LX, GHIA, GT, Sunset Tropical, Turnier, 4x4	L1E Zetec [DOHC]	08.1990 ▶	● <b>246455</b>	RC68LPP	1.0		
1.6 i 16V Cabrio, Turnier, XR3i Cabrio	L1H, L1K Zetec [DOHC]	08.1990 ▶	● <b>246455</b>	RC68LPP	1.0		
1.8 i 16V	RDA, RQB Zetec [DOHC]	02.1992 ▶	● <b>246455</b>	RC68LPP	1.0		
1.8 i 16V	RKA Zetec [DOHC]	03.1996 ▶	● <b>246455</b>	RC68LPP	1.0		
1.8 i 16V Turnier, XR3i Cabrio	RKC Zetec	01.1995 ▶	● <b>246455</b>	RC68LPP	1.0		
2.0 i 16V RS 2000, RS 2000 4x4	N7A [DOHC]	08.1990 ▶	<b>246333</b>	RF72H11	1.0		
XR3 : 1.6	LUA	08.1980 ▶ 12.1985			0.7	<b>246567</b>	F59
XR3 : 1.6 i i Hawaii/Tennis	LJB, LJA	01.1986 ▶ 07.1990	<b>246333</b>	RF72H11	1.0		

### FIESTA

1.0	TLB	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.0 Express	TKA, TKW, TKB, TLA	05.1976 ▶ 02.1989	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
1.0 Van	TKA, TKW	08.1981 ▶ 08.1983	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
1.1	GUB, GSH, GLC, GSF, GL1, GS1 GLA, GLW, GL	05.1976 ▶ 02.1989	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
1.1 Affaire, C Festival, CL, CLX, CTX, Fun, Melody Success	GUD, GUE	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.1 Claridge, Ghia, Super Festival, Urba	GUD, GUE	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.1 Van	GLA, GLW	08.1981 ▶ 08.1983	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
1.1 i Affaire, Claridge, CLX, Fun, Melody, Navy Newport	G6A Cat	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.3	J3E	07.1981 ▶ 08.1983			0.7	<b>246567</b>	F59
1.3	JLA	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.3	JPC	08.1983 ▶ 01.1987	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.3	KL 13 G [OHV]	08.1977 ▶ 06.1981	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.3 i	Endura-E	08.1995 ▶	<b>246326</b>	RC72H11	1.0		
1.3 i	J6B, JBC	03.1989 ▶ 06.1996	<b>246326</b>	RC72H11	1.0		
1.4 CLX, Ghia, Urba	FUB, FUF	08.1983 ▶ 06.1996	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.4 Ghia, Nordic Green	FUD, FUG, FUJ	02.1987 ▶ 06.1996	<b>246333</b>	RF72H11	1.0		
1.4 i	F6A, F6C Cat	10.1986 ▶ 07.1988	<b>246333</b>	RF72H11	1.0		
1.4 i	F6E, F4A Cat	03.1989 ▶ 06.1996	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11
1.6	LP3	08.1983 ▶ 02.1989			0.7	<b>246567</b>	F59
1.6	LUH	03.1989 ▶ 06.1996	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
1.8 i 16V RS 1800, XR2	RDA, RDB, RQC Zetec [DOHC]	02.1992 ▶ 06.1996	● <b>246455</b>	RC68LPP	1.0		
XR2 : 1.6	L3E	08.1981 ▶ 08.1983			0.7	<b>246567</b>	F59
XR2 : 1.6	LUB, LUD	08.1983 ▶ 02.1989			0.7	<b>246567</b>	F59
XR2 : 1.6 i i	LJD, LJC Cat	03.1989 ▶ 06.1996	<b>246333</b>	RF72H11	1.0		

### FOCUS

1.8 i 16V	EYDB, EYDC, EYDD, EYDE EYDF Zetec [DOHC]		● <b>246455</b>	RC68LPP	1.0		
2.0 i 16V	EDDB, EDDC, EDDD EDDF Zetec [DOHC]		● <b>246455</b>	RC68LPP	1.0		

### GALAXY

2.0 i	NSE	02.1995 ▶	<b>246488</b>	RF72HZDC	1.0	<b>246567</b>	F59
2.3 i 16V	Y5B	08.1996 ▶	<b>246487</b>	RF74HZDC	1.0	<b>246554</b>	F87
2.8 i V6	AAA	02.1995 ▶			1.6	<b>246554</b>	F87

### GRANADA

1.7 i Turnier	NWB, MYE	06.1979 ▶ 08.1981	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0	N8B, N8D [DOHC]	05.1985 ▶ 10.1994	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i	N9D, N9B, N9F [DOHC]	05.1985 ▶ 10.1994	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
2.0 V6 Turnier	NYU, NYP	▶ 08.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 V6	YYU, YYP	06.1979 ▶ 08.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 V6 Turnier	TV 23 H [OHV]	06.1979 ▶ 08.1985	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.4 i V6	ARC	05.1985 ▶ 10.1994	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
2.4 i V6	ARD	05.1985 ▶ 12.1994	<b>246326</b>	RC72H11	1.0		
2.6	TV 26 L	08.1977 ▶ 08.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.8 i	TV 28 I	▶ 08.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.8 i V6	PR4, PR3, PR2	04.1985 ▶ 10.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.8 i V6	PRD, PRC, PRE, PYU, PYA	08.1981 ▶ 08.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79





3+1

**FORD** (.../...)

**GRANADA (.../...)**

2.9 i V6	BRC	05.1985 ▶ 10.1994	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.9 i V6	BRD, BRE, BRF	05.1985 ▶ 10.1994	<b>246326</b>	RC72H11	1.0		

**KA**

1.3 i Déclic, Pack Electrique, Roller	J4D, J4K, JJA, JJB, JJD Endura-E	09.1996 ▶	<b>246326</b>	RC72H11	1.0		
1.7 i 16V	MHA SE Zetec [DOHC]	01.1998 ▶	<b>●246455</b>	RC68LPP	1.0		

**MAVERICK**

2.7 D	TD 27	06.1993 ▶ 04.1998	<b>246333</b>	RF72H11	1.1		
-------	-------	-------------------	---------------	---------	-----	--	--

**MONDEO**

1.6 i 16V	L1F, L1J Zetec [DOHC]	01.1993 ▶	<b>●246455</b>	RC68LPP	1.0		
1.6 i 16V	L1N, L1Q, L1L Zetec [DOHC]	05.1998 ▶	<b>●246455</b>	RC68LPP	1.0		
1.8 i 16V	RKA, RKB, RKH, RKF, RKJ RKK Zetec [DOHC]	07.1994 ▶	<b>●246455</b>	RC68LPP	1.0		
2.0 i 16V	NGA Zetec [DOHC]	01.1993 ▶	<b>●246455</b>	RC68LPP	1.0		
2.0 i 16V	NGB, NGC, NGD Zetec [DOHC]	08.1996 ▶	<b>●246455</b>	RC68LPP	1.0		

**ORION**

1.3	JLA, JLB	01.1986 ▶ 12.1988	<b>246326</b>	RC72H11	1.0		
1.3 Touring	JBB, JBD, JBE	01.1986 ▶ 12.1993	<b>246326</b>	RC72H11	1.0		
1.3 i	J6A [HCS]	08.1990 ▶ 12.1993	<b>246326</b>	RC72H11	1.0		
1.4 CL, Ghia/Salon, Scoop/Salon, Touring/Salon	FUA	01.1986 ▶ 07.1990	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.4 CLX, GL	FUH	01.1986 ▶ 12.1993	<b>246333</b>	RF72H11	1.0		
1.4 i	F6B, F6D Cat	01.1986 ▶ 07.1988	<b>246333</b>	RF72H11	1.0		
1.6	LUC, LUG, LUJ, LUK	04.1986 ▶ 12.1993	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 i	L4B	05.1983 ▶ 07.1990	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 i	LJA, LJB, LJE, LJF	01.1986 ▶ 07.1993	<b>246333</b>	RF72H11	1.0		
1.6 i	LR1 -LRA, LRB	05.1983 ▶ 07.1990			0.8	<b>246567</b>	F59
1.6 i 16V	L1E Zetec [DOHC]	08.1990 ▶ 12.1993	<b>●246455</b>	RC68LPP	1.0		
1.8 i 16V	RDA, ROB Zetec [DOHC]	08.1990 ▶ 12.1993	<b>●246455</b>	RC68LPP	1.0		

**PROBE**

2.0 i 16V	FS [A EFI] [DOHC]	08.1992 ▶	<b>246333</b>	RF72H11	1.1		
2.5 i V6 24V	KL [B EFI]	08.1992 ▶			1.1	<b>246556</b>	F87-11
3.0 i V6 GT	[U] Cat	02.1990 ▶	<b>246326</b>	RC72H11	1.1		

**PUMA**

1.7 i 16V	MHA, MHB, SE Zetec [DOHC]	04.1997 ▶	<b>●246455</b>	RC68LPP	1.0		
-----------	---------------------------	-----------	----------------	---------	-----	--	--

**SCORPIO**

2.0	N8D, N8B [DOHC]	05.1989 ▶ 02.1992	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i	N9D, N9B [DOHC]	05.1989 ▶ 12.1994	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
2.0 i	N9F, NSD [DOHC]	02.1992 ▶ 12.1998	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
2.0 i 16V	N3A	10.1994 ▶ 12.1998	<b>246487</b>	RF74HZDC	1.0	<b>246554</b>	F87
2.3 i 16V	Y5A	05.1996 ▶ 12.1998	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.4 i V6	ARC	05.1985 ▶ 06.1989	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
2.4 i V6	ARD	08.1988 ▶ 12.1994	<b>246326</b>	RC72H11	1.0		
2.9 i V6	BRD, BRE	05.1985 ▶ 10.1994	<b>246326</b>	RC72H11	1.0		
2.9 i V6 24V	BOB	10.1994 ▶ 12.1998	<b>246487</b>	RF74HZDC	1.0	<b>246554</b>	F87
XR4 : 2.8 i V6 i 4x4	PR3, PR4, PRE	04.1985 ▶ 10.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
XR4 : 2.9 i V6 i 4x4	BRC	05.1985 ▶ 02.1992	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
XR4 : 2.9 i V6 i 4x4	BRD, BRE, BRF	05.1985 ▶ 12.1994	<b>246326</b>	RC72H11	1.1		
XR4 : 2.9 i V6 i 4x4	BRG	10.1994 ▶ 12.1998	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11

**SIERRA**

1.6 i Turnier	L6B	10.1989 ▶ 02.1993	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11
1.8 i CL, CL Affaire, CLX, GL, Laser, Turnier	R6A, R2C, R2A	05.1988 ▶ 02.1993	<b>246332</b>	RF74H11	1.0	<b>246556</b>	F87-11
2.0 i CLX 4x4, Ghia, GL, GLS, S Pack, Turnier XR 4x4, 4x4	N9A, N9C, N9E	05.1989 ▶ 02.1993	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
2.0 i CLX, Ghia, GL, GT, Manhattan, Turnier	N8A, N8C	05.1989 ▶ 02.1993	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
2.0 V6 Turnier	NYT	08.1982 ▶ 01.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 V6 Turnier	YYT	08.1982 ▶ 01.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.8 i V6 4x4 Turnier, XR4, XR4 Turnier, XR 4x4	PR	03.1985 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.9 i V6 XR 4x4, Turnier 4x4	B4A	08.1988 ▶ 02.1993	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87

**TAUNUS**

2.0 V6	NWR, NYR	12.1975 ▶ 08.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 V6	YYR	08.1979 ▶ 08.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**FORD**
**COURIER**

1.3 Combi, Van	[HCS]	09.1991 ▶	<b>246326</b>	RC72H11	1.0		
1.3 i Combi, Van	J6B	09.1991 ▶	<b>246326</b>	RC72H11	1.0		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## FORD (.../...)

### TRANSIT

1.5 FT75, FT100	V4 Taunus	04.1971 ▶ 03.1978	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
1.7 FT100, FT120, FT130, FT160, FT175, FT190	V4 Essex	04.1971 ▶ 03.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 80, 100, 120, 150, 190	NSF, NSG	08.1994 ▶	<b>246488</b>	RF72HZDC	1.0	<b>246567</b>	F59
2.9 i V6	B4T	01.1986 ▶ 07.1991	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.9 i V6	BRT	01.1986 ▶ 10.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 V6	HX, HXC-LC	01.1978 ▶ 09.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

## FREIGHT ROVER

### SHERPA

1.6	[OHV]	01.1973 ▶ 12.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.7	[OHV]	01.1978 ▶ 12.1986	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79
1.7	[OHV]	01.1987 ▶ 12.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	[OHV]	01.1973 ▶ 12.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	[OHV]	01.1978 ▶ 12.1986	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79
2.0	[OHV]	01.1987 ▶ 12.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 V8		01.1986 ▶ 12.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

## FSO

### 125P

1.3		06.1968 ▶ 02.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5		06.1968 ▶ 02.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
125 Pick-up			<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### 126P

Bis		01.1987 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
P		01.1972 ▶ 12.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### 132P

1.6		▶ 12.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8		▶ 12.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

### CINQUECENTO

0.7	170.A.000, 170.A.046		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9	170.A1.000		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 i, ie	170.A1.046		<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.1 i	176.A6.000, 176.B2.000		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

### POLONEZ

1.3 Pick-Up, Truck		01.1978 ▶ 06.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 i 16V	K 16 series [DOHC]	01.1993 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.5 Pick-Up, Truck		01.1978 ▶ 06.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 i	Cat	07.1995 ▶	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.6		05.1987 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 i	Cat	07.1995 ▶	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0		01.1978 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

## GAZ

<b>3105</b>		01.1992 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-------------	--	-----------	---------------	------	-----	---------------	-----

### 3302 / GASELLE

2.5	ZMZ 4025.10, 4026.10	01.1993 ▶	<b>246189</b>	R88N	0.7		
2.5	ZMZ 4061.10	01.1993 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

### VOLGA

2.5 24		01.1973 ▶	<b>246189</b>	R88N	0.7		
2.5 2402		01.1973 ▶	<b>246189</b>	R88N	0.7		
2.5 3102	ZMZ 402.10		<b>246189</b>	R88N	0.7		
2.5 3102	ZMZ 4062.10		<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.5 31029	ZMZ 402.10		<b>246189</b>	R88N	0.7		
2.5 31029	ZMZ 4062.10		<b>246179</b>	R76H	0.7	<b>246555</b>	H79

## GEO

### METRO

1.0	3L [6]	08.1994 ▶			1.1	<b>246564</b>	H79-11
-----	--------	-----------	--	--	-----	---------------	--------

### PRIZM

1.6	4A-FE	01.1990 ▶			1.1	<b>246556</b>	F87-11
-----	-------	-----------	--	--	-----	---------------	--------



<b>GINETTA</b>									
<b>G21</b>									
1.7				08.1971 ▶ 02.1981	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
<b>G23</b>									
3.0				08.1980 ▶	<b>246198</b>	R70H	0.6	<b>246557</b>	H60
<b>G34</b>									
2.0 i Turbo	B 204 FT	Cat		03.1995 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
<b>HILLMAN</b>									
<b>AVENGER</b>									
1.3				01.1973 ▶ 12.1976	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1250, 1500, 1.6				01.1970 ▶ 12.1976	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
<b>HUNTER</b>									
1.5				01.1966 ▶ 12.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.7				01.1966 ▶ 12.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>HINDUSTAN</b>									
<b>AMBASSADOR</b>									
1.5				01.1991 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
<b>CONTESSA CLASSIC</b>									
1.5				03.1984 ▶ 09.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8				03.1984 ▶			1.1	<b>246564</b>	H79-11
<b>HOLDEN</b>									
<b>APOLLO</b>									
2.0 16V [JK, JL]	3SF [DOHC]			09.1989 ▶ 03.1993			1.1	<b>246556</b>	F87-11
2.0 i 16V [JK, JL]	3S-FE [DOHC] Cat			09.1989 ▶ 03.1993			1.1	<b>246556</b>	F87-11
2.2 i 16V [JM, JP]	5S-FE [DOHC] Cat			04.1993 ▶ 05.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
<b>ASTRA</b>									
1.6 i [TR]	C 16 SE [OHC]			08.1996 ▶ 09.1998	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i [TR]	C 16 SE [OHC]			08.1996 ▶ 09.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V [TS]	X 18 XE [DOHC]			09.1998 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
<b>BARINA</b>									
1.2 i City [SB]	C 12 NZ [OHC]			04.1994 ▶ 12.2001	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.2 i City [SB]	C 12 NZ [OHC]			04.1994 ▶ 12.2001	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i [MB, ML]	C 14 NZ [OHC]			01.1985 ▶ 01.1989	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i [MB, ML]	C 14 NZ [OHC]			01.1985 ▶ 01.1989	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i [SB]	C 14 SE [OHC]			08.1997 ▶ 12.2001	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i [SB]	C 14 SE [OHC]			08.1997 ▶ 12.2001	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i Cabrio [SB]	C 14 NZ [OHC]			04.1994 ▶ 12.2001	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i Cabrio [SB]	C 14 NZ [OHC]			04.1994 ▶ 12.2001	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V [SD, XC]	Z 14 XE [DOHC] Cat			01.2001 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i [SB]	C 16 XE [DOHC]			04.1994 ▶ 03.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V [SB]	X 16 XE [DOHC]			04.1995 ▶ 09.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
<b>CALIBRA</b>									
2.0 i [YE]	C 20 NE [OHC]				<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i [YE]	C 20 NE [OHC]				<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V [YE]	C 20 XE [DOHC]			▶ 08.1992	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.0 i 16V [YE]	C 20 XE [DOHC]			09.1992 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V [YE]	X 20 XEV [DOHC]				<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 [YE]	C 25 XE [DOHC]			08.1995 ▶ 07.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
<b>GEMINI</b>									
1.5 [RB]	4XC1			01.1985 ▶ 07.1987			1.1	<b>246564</b>	H79-11
1.6 [T_]	G161Z			01.1982 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
<b>NOVA</b>									
1.6 i 16V [LE, LF]	4A-FE [DOHC] Cat			06.1991 ▶ 10.1994			1.1	<b>246556</b>	F87-11
1.6 i 16V [LE, LF]	4A-FE [DOHC] Cat			08.1989 ▶ 06.1991			1.1	<b>246556</b>	F87-11
1.6 i 16V [LG]	4A-FE [DOHC] Cat			10.1994 ▶ 04.1997			1.1	<b>246556</b>	F87-11
1.8 i 16V [LE, LF]	7A-FE [DOHC] Cat			08.1989 ▶ 10.1994			1.3	<b>246556</b>	F87-11
1.8 i 16V [LG]	7A-FE [DOHC] Cat			10.1994 ▶ 04.1997			1.3	<b>246556</b>	F87-11
<b>PIAZZA</b>									
2.0 i Turbo [YB]	4ZC1T			01.1986 ▶			1.1	<b>246564</b>	H79-11
<b>VECTRA</b>									
2.0 i 16V [JR, JS]	C 20 SEL [DOHC]			06.1997 ▶			1.0	<b>246564</b>	H79-11
2.5 i V6 24V [JR, JS]	X 25 XE [DOHC]			06.1997 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## HONDA

### ACCORD

1.6	A16 A1	11.1985 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.6 Coupé	EL 16	06.1975 ▶ 08.1985	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6 12V Coupé	EZ 1/2	09.1983 ▶ 10.1985			1.1	<b>246564</b>	H79-11
1.8 12V Coupé	ET 1	09.1983 ▶ 10.1985			1.1	<b>246564</b>	H79-11
1.8 16V	F18 A2	09.1989 ▶			1.1	<b>246556</b>	F87-11
1.8 i S	F18 B2	01.1999 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V LS	F18 A3 Cat	09.1993 ▶			1.1	<b>246556</b>	F87-11
2.0 Aerodeck, Hatchback	A20 A1 Cat	08.1987 ▶ 12.1989			1.1	<b>246564</b>	H79-11
2.0 Aerodeck, Hatchback	A20 A2	11.1985 ▶ 12.1989			1.1	<b>246564</b>	H79-11
2.0 16V	F20 A2, A6	09.1988 ▶			1.1	<b>246556</b>	F87-11
2.0 i Aerodeck, Hatchback	A20 A3 Cat	09.1985 ▶ 12.1989			1.1	<b>246564</b>	H79-11
2.0 i Aerodeck, Hatchback	A20 A4	11.1985 ▶ 12.1989			1.1	<b>246564</b>	H79-11
2.0 i ES, LS	F20 B6	01.1999 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	B20 A [DOHC]	08.1986 ▶ 12.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 A [DOHC] Cat	09.1989 ▶ 02.1994			1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 A4 [SOHC] Cat	01.1990 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 A7 [SOHC] Cat	01.1992 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 B5	03.1998 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 Z1 [DOHC] Cat	01.1996 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 Z2 [SOHC] Cat	03.1993 ▶ 12.1995			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 A3, B5 [SOHC] Cat	01.1990 ▶			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 A7, A8 Cat	01.1990 ▶ 08.1994			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 B [SOHC] Cat	09.1993 ▶ 09.1997			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 Z2 VTEC	09.1995 ▶			1.1	<b>246556</b>	F87-11
2.2 i 16V	H22 A7	09.1993 ▶ 09.1997			1.1	<b>246556</b>	F87-11
2.3 i 16V	F23 Z5 Cat				1.1	<b>246556</b>	F87-11
2.3 i 16V	H23 A3 [DOHC] Cat	03.1993 ▶ 09.1995			1.1	<b>246556</b>	F87-11

### ACTY / STREET

0.66 i 12V	E07 A Cat	03.1990 ▶ 06.1999	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
------------	-----------	-------------------	---------------	---------	-----	---------------	--------

### ACTY TN

0.6 TN 550	EH	07.1978 ▶ 05.1988	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.0 2000, 2.5 2500	E200, E250	01.1983 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### ASCOT

2.0 i 16V, Inova	F20 A Cat	04.1992 ▶ 09.1997			1.1	<b>246556</b>	F87-11
------------------	-----------	-------------------	--	--	-----	---------------	--------

### BALLADE

1.5 EX, EXi		10.1986 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.5 i 12V EX, EXi		10.1986 ▶ 12.1989			1.1	<b>246564</b>	H79-11

### BEAT

650 : 0.66 i 12V	E07 A Cat	05.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
------------------	-----------	-----------	---------------	---------	-----	---------------	--------

### CAPA

1.6 i 16V	B16 A Cat	04.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	-----------	-----------	---------------	---------	-----	---------------	--------


### CITY

1.2	D12 A	09.1987 ▶ 03.1994			1.1	<b>246556</b>	F87-11
1.2	D12 A	11.1986 ▶ 08.1987			1.1	<b>246564</b>	H79-11
1.3	D13 C	09.1988 ▶ 04.1994			1.1	<b>246556</b>	F87-11
1.3 i	D13 C	09.1988 ▶ 04.1994			1.1	<b>246556</b>	F87-11

### CIVIC

1.2	D12 B1	10.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.2	EB 1, EB 2, EB 3	01.1972 ▶ 12.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.2	ZA 2	01.1985 ▶ 10.1987			1.1	<b>246564</b>	H79-11
1.3	EV 2	10.1983 ▶ 08.1988			1.1	<b>246564</b>	H79-11
1.3 Break	EN	09.1979 ▶ 08.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i	D13 B	10.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.3 i Hatchback	D13 B	09.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.3 i 16V	D13 B [SOHC]	10.1991 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.3 i 16V DX, BREEZE	D13 B [SOHC]	09.1988 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4	D14 A [SOHC]	01.1988 ▶ 09.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4	WD	08.1980 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.4 i	D14 A5	09.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4 i	D14 Z2 VTEC [SOHC] Cat	07.1998 ▶			1.1	<b>246556</b>	F87-11
1.4 i 16V	D14 A3, A4 [SOHC] Cat	10.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4 i 16V	D14 V1 Cat				1.1	<b>246556</b>	F87-11
1.4 i 16V iS	D14 A3, A4 [SOHC] Cat	09.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4 i 16V LS	D14 A2	09.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 4x4	EW 2	10.1983 ▶ 10.1987			1.1	<b>246564</b>	H79-11





3+1


**HONDA** (.../...)

**CIVIC (.../...)**

1.5 GL	EW 2	10.1983 ▶ 10.1987			1.1	<b>246564</b>	H79-11
1.5 i	D15 B	10.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i GT	EW 3	10.1983 ▶ 10.1987			1.1	<b>246564</b>	H79-11
1.5 i GT	EW 4	01.1986 ▶			1.1	<b>246564</b>	H79-11
1.5 i 16V	D15 B [SOHC] Cat	01.1988 ▶ 11.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i 16V	D15 Z1 VTEC [SOHC] Cat	10.1991 ▶ 09.1995			1.1	<b>246556</b>	F87-11
1.5 i 16V	D15 Z8 VTEC [SOHC] Cat	03.1998 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V DXi, LSi	D15 B [SOHC] Cat	10.1988 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i 16V LS	D15 Z3 VTEC Cat	09.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V LS	D15 Z8 VTEC [SOHC] Cat	01.1997 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	B16 A Cat	09.1989 ▶ 10.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	B16 A VTEC [DOHC] Cat	10.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A6, A9	10.1987 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A7	10.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 V1 Cat				1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 Y5 VTEC [SOHC] Cat	10.1995 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 Y8 VTEC [SOHC] Cat	11.1995 ▶ 02.2001	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 Z6 VTEC Cat	10.1987 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	ZC	09.1991 ▶ 09.1995	<b>246333</b>	RF72H11	1.1		
1.6 i 16V 4x4	B16 A VTEC [DOHC] Cat	10.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4x4	D16 A6, Z2 Cat	10.1987 ▶ 09.1991	<b>246333</b>	RF72H11	1.1		
1.6 i 16V 4x4	D16 Z6, Z7 VTEC Cat	10.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4x4, Realtime	D16 A, Z2	01.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V ESi	D16 Z6 VTEC Cat	01.1992 ▶ 12.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V ESi	D16 Z9 VTEC [SOHC] Cat	08.1993 ▶ 12.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V LS	D16 B2	09.1996 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V LS	D16 Y3 [SOHC] Cat	09.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V LS, SR	D16 Y6 VTEC [SOHC] Cat	09.1995 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V LS, SR	D16 Y7 VTEC [SOHC] Cat	09.1995 ▶ 04.2000			1.1	<b>246556</b>	F87-11
1.6 i 16V LS, SR	D16 Y8 VTEC [SOHC] Cat	09.1995 ▶ 04.2000			1.1	<b>246556</b>	F87-11
1.6 i 16V SR	D16 Y2 VTEC [SOHC] Cat	09.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V VTI	B16 A VTEC [DOHC] Cat	01.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.7 i 16v	D17 A8, A9 VTEC Cat	05.2001 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V VTI	B18 C [DOHC]	01.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**CONCERTO**

1.3 i 16V	D13 B [SOHC]		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.4 EX, GL	D14 A1	08.1989 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i 16V LXi, i S	D15 B [SOHC] Cat	08.1989 ▶ 09.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6	D16 Z1	01.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A6 Cat	08.1989 ▶ 12.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A9	01.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	ZC	08.1989 ▶ 10.1992	<b>246333</b>	RF72H11	1.1		
1.6 i 16V 4x4, EXi	D16 A8, Z2 [DOHC]	08.1989 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**CR-V**

2.0 i 16V	B20 B [DOHC] Cat	10.1995 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	B20 Z1	03.1999 ▶			1.1	<b>246556</b>	F87-11

**CRX**

1.4	D14 A [SOHC]	10.1989 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i	EW 3	10.1983 ▶ 12.1985			1.1	<b>246564</b>	H79-11
1.5 i 16V	D15 B [SOHC] Cat	10.1987 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A	10.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A [DOHC] Cat	10.1987 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A Cat	10.1987 ▶ 02.1992	<b>246333</b>	RF72H11	1.1		
1.6 i 16V	D16 A9	09.1987 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V Coupé	ZC	03.1986 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V ESi 16V	D16 Z5	10.1988 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V ESi 16V	D16 Z6 VTEC Cat	10.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V Targa	B16 A VTEC [DOHC] Cat	10.1987 ▶ 02.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V Targa	ZC	03.1992 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V Targa, VTI	B16 A VTEC [DOHC] Cat	03.1992 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**DOMANI**

1.6 i 16V	D16 A Cat	01.1997 ▶	<b>246333</b>	RF72H11	1.1		
1.6 i 16V	ZC	10.1992 ▶ 03.1998	<b>246333</b>	RF72H11	1.1		

**HR-V**

1.6 i Joy Machine	D16 W1 [SOHC]	02.1999 ▶			1.1	<b>246556</b>	F87-11
-------------------	---------------	-----------	--	--	-----	---------------	--------



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## HONDA (…/…)

### HR-V (…/…)

1.6 i 16V	D16 A Cat	03.1999 ▶	<b>246333</b>	RF72H11	1.1		
-----------	-----------	-----------	---------------	---------	-----	--	--

### INTEGRA

1.5 DX, LX	D15 A1	03.1985 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.6 i 16V	ZC	10.1991 ▶	<b>246333</b>	RF72H11	1.1		
1.6 i 16V EX, SX	D16 A2, A3, ZC	03.1985 ▶ 12.1989	<b>246333</b>	RF72H11	1.1		
1.8 i 16V	B18 A [DOHC]	01.1989 ▶ 09.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	B18 C VTEC [DOHC]	05.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### JAZZ

1.2	ER 1, ER 2, ER 3	10.1983 ▶ 10.1987			1.1	<b>246564</b>	H79-11
-----	------------------	-------------------	--	--	-----	---------------	--------

### LEGEND

2.5 i V6 24V	C25 A	01.1986 ▶ 04.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.7 i V6 24V	C27 A,A1 Cat	09.1987 ▶ 04.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### LIFE

0.66 i 12V	E07 A Cat	04.1997 ▶ 10.1998	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.66 i 12V	E07 Z [SOHC] Cat	10.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### LOGO

1.3 i	D13 B [SOHC]	10.1996 ▶			1.1	<b>246556</b>	F87-11
1.3 i 16V	D13 B [SOHC]	11.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### ORTHIA

2.0 i 16V	B20 B [DOHC] Cat	03.1996 ▶			1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	--	--	-----	---------------	--------

### PARTNER

1.3 i 16V	D13 B [SOHC]	03.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A Cat	03.1996 ▶	<b>246333</b>	RF72H11	1.1		

### PRELUDE

1.6	EL 16	01.1978 ▶ 10.1982	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.8 EX	ET 1	11.1982 ▶ 10.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 EX	ET 2/3/4	11.1983 ▶ 04.1987			1.1	<b>246564</b>	H79-11
2.0 EX	B20 A	04.1987 ▶ 01.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 12V	B20 A3 [SOHC]	09.1987 ▶ 12.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 12V	B20 A4 [SOHC]	04.1987 ▶ 09.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	B20 A [DOHC]	09.1984 ▶ 12.1988	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	B20 A5	04.1987 ▶ 12.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	B20 A9	09.1987 ▶ 12.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	F20 A4 [SOHC] Cat	10.1991 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V 4WS	B20 A7	04.1987 ▶ 12.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.1 i 16V	B21 A [DOHC]	10.1990 ▶ 09.1991			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 B [DOHC] Cat	11.1996 ▶			1.1	<b>246556</b>	F87-11
2.2 i 16V	F22 B [SOHC] Cat	09.1991 ▶			1.1	<b>246556</b>	F87-11
2.3 i 16V	H23 A2 [DOHC]	10.1991 ▶			1.1	<b>246556</b>	F87-11

### QUINT INTEGRA

1.5		02.1985 ▶			1.1	<b>246564</b>	H79-11
1.6 i	EW	02.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	B16 A Cat, ZC	02.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### QUINTET

1.6	EL	02.1980 ▶ 12.1984	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
-----	----	-------------------	---------------	------	-----	---------------	-----

### SHUTTLE

2.2 i 16V ES	F22 B8 [SOHC] Cat	12.1994 ▶			1.1	<b>246556</b>	F87-11
2.3 i 16V ES, LS	F23 A7 [SOHC] Cat	01.1998 ▶			1.1	<b>246556</b>	F87-11

### S-MX

2.0 i 16V	EL 18, EL 20	02.1980 ▶ 12.1984	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.0 i 16V 4WD	B20 B [DOHC] Cat	10.1996 ▶			1.1	<b>246556</b>	F87-11

### STEPWAGON

2.0 i 16V 4x4	B20 B [DOHC] Cat	05.1996 ▶			1.1	<b>246556</b>	F87-11
---------------	------------------	-----------	--	--	-----	---------------	--------

### STREAM

1.7 i 16V	D17 A2 Cat				1.1	<b>246556</b>	F87-11
-----------	------------	--	--	--	-----	---------------	--------

### TODAY

0.66 i 12V	E07 A Cat	03.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
600 : 0.6	EH	01.1986 ▶ 12.1992	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
660 : 0.66 i 12V	JA 4/5	01.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### Z

0.66 i 12V	E07 Z [SOHC] Cat	10.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
------------	------------------	-----------	---------------	---------	-----	---------------	--------



3+1


**HYUNDAI**

**ACCENT**

1.3	G4BG	09.1994 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.3 i 12V GLS, GS	G4EH Cat	07.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 12V GLS	G4EK Cat	07.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	G4FK Cat	08.1995 ▶			1.1	<b>246556</b>	F87-11

**ATOS**

1.0 i 12V	G4HC	11.1997 ▶			1.1	<b>246556</b>	F87-11
-----------	------	-----------	--	--	-----	---------------	--------

**COUPE**

1.8 i 16V SX, SFX	G4GM	06.1996 ▶			1.1	<b>246556</b>	F87-11
-------------------	------	-----------	--	--	-----	---------------	--------

**COUPE FX / TIBURON**

1.6 i 16V	G4GR	05.1996 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	Beta [DOHC]	03.1996 ▶			1.0	<b>246556</b>	F87-11
2.0 i 16V	G4GF	03.1996 ▶			1.1	<b>246556</b>	F87-11

**EXCEL**

1.3	4G13 Cat	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.3	G4DG	09.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.3 i 12V	G4EH Cat	07.1994 ▶			1.1	<b>246556</b>	F87-11
1.5	G15B	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.5 i	G4DJ, G15B	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.5 i 12V	G4EK Cat	07.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	G4FK Cat	11.1995 ▶			1.1	<b>246556</b>	F87-11

**EXCEL ( PONY )**

1.3	4G13 Cat	04.1986 ▶ 03.1989			1.1	<b>246564</b>	H79-11
1.3	G13B	01.1985 ▶ 03.1989			1.1	<b>246564</b>	H79-11
1.3	G4DG	01.1985 ▶ 09.1989			1.1	<b>246564</b>	H79-11
1.5	G15B	01.1985 ▶ 03.1989	<b>246179</b>	R76H	1.1	<b>246555</b>	H79

**GRANDEUR**

2.0 i	4G63 [SOHC]	07.1986 ▶ 08.1992			1.1	<b>246564</b>	H79-11
2.4 i	4G64 [SOHC]	07.1987 ▶ 03.1993			1.1	<b>246564</b>	H79-11
3.0 V6	6G 72	09.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11

**LANTRA**

1.5 i	G15B	10.1990 ▶ 04.1995			1.1	<b>246564</b>	H79-11
1.5 i GLi	G4DJ	10.1990 ▶ 12.1995			1.1	<b>246564</b>	H79-11
1.6 i 16V	4G61 [DOHC] Cat	10.1990 ▶ 04.1995			1.1	<b>246564</b>	H79-11
1.6 i 16V	G4CR	10.1990 ▶ 10.1995			1.1	<b>246564</b>	H79-11
1.8 i 16V	G4CN	06.1992 ▶ 12.1995			1.1	<b>246564</b>	H79-11

**LANTRA / ELANTRA**

1.5 i	Alpha	07.1996 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	G4GR	05.1995 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	G4GM	05.1995 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	G4GF	08.1996 ▶			1.1	<b>246556</b>	F87-11

**PONY**

1.2	Saturn	03.1974 ▶ 09.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	4G13 Cat	04.1986 ▶ 03.1989			1.1	<b>246564</b>	H79-11
1.3 GS, i	G4DG	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.3 LS, GLS	G4-M		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 i GS, i	G13B	10.1985 ▶ 03.1989			1.1	<b>246564</b>	H79-11
1.3 i 12V	G4EH Cat	07.1994 ▶			1.1	<b>246556</b>	F87-11
1.4	4G12	05.1982 ▶ 10.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	Saturn	03.1977 ▶ 09.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5, GLS	G15B	10.1985 ▶ 03.1989			1.1	<b>246564</b>	H79-11
1.5 i GLS	G4DJ, G15B	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.5 i GLSi	G4DJ-S	04.1989 ▶ 10.1994			1.1	<b>246564</b>	H79-11
1.6		01.1974 ▶ 12.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**S COUPE**

1.5 i	G15B	02.1990 ▶			1.1	<b>246564</b>	H79-11
1.5 i	G4DJ	02.1990 ▶ 08.1994			1.1	<b>246564</b>	H79-11
1.5 i	HMC Alpha	02.1990 ▶ 04.1992	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.5 i 12V	G4EK Cat	01.1992 ▶ 04.1995			1.1	<b>246556</b>	F87-11
1.5 i Turbo GT Turbo	G4EK-TC	04.1991 ▶ 04.1996	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

**SATELLITE**

2.4 i	G4CS	07.1994 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	G4CS Cat	07.1994 ▶			0.8	<b>246564</b>	H79-11

**SONATA**

1.8 i	4G62 Cat	06.1988 ▶ 10.1993			1.1	<b>246564</b>	H79-11
1.8 i	G4CM	07.1993 ▶ 08.1998			1.1	<b>246564</b>	H79-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## HYUNDAI (.../...)

### SONATA (.../...)

1.8 i	G62B	01.1989 ▶			1.1	<b>246564</b>	H79-11
2.0 i	4G63 [SOHC]	06.1988 ▶ 10.1993			1.1	<b>246564</b>	H79-11
2.0 i 16V	4G63 [DOHC] Cat	09.1990 ▶ 06.1993			1.1	<b>246564</b>	H79-11
2.0 i 16V	G4CP Cat	07.1993 ▶			1.1	<b>246564</b>	H79-11
2.0 i 16V	G4JP-G	05.1998 ▶			1.1	<b>246564</b>	H79-11
2.0 i 16V GLS	G4CP Cat	05.1996 ▶			1.1	<b>246564</b>	H79-11
2.4 i	4G64 [SOHC]	10.1988 ▶ 10.1993			1.1	<b>246564</b>	H79-11
2.4 i	G4CS	07.1993 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	G4CS Cat	07.1993 ▶			1.1	<b>246564</b>	H79-11

### SONICA

2.0 i 16V	G4CP	07.1993 ▶ 06.1996	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 16V	G4CP Cat	07.1993 ▶ 06.1996			1.1	<b>246564</b>	H79-11

### STAREX

2.4 i 4WD	G4CS	10.1997 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----------	------	-----------	---------------	------	-----	---------------	-----

### STELLAR

1.4	Saturn	09.1983 ▶ 12.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	4G32	09.1983 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.6	G32B	09.1983 ▶ 12.1989	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.8 i Prima	4G62 Cat	10.1985 ▶			1.1	<b>246564</b>	H79-11
2.0 Prima	4G63, G63B [SOHC]	09.1983 ▶ 12.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### XG

2.5 i V6	Delta [DOHC]	12.1998 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
----------	--------------	-----------	---------------	-------	-----	---------------	-----

## HYUNDAI

### H100

2.4 i	G4CS	07.1993 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	G4CS Cat	07.1993 ▶			0.8	<b>246564</b>	H79-11

## INNOCENTI

### ELBA

1.3	146.A5.000	01.1991 ▶ 08.1993	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.4 ie	146.C5.000, 146.D5.000	09.1993 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.5 ie	149.C1.000 Cat	03.1992 ▶ 08.1993	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie	146.C6.000	09.1993 ▶	<b>246198</b>	R70H	0.9	<b>246557</b>	H60

### INNOCENTI

0.55 550	EB	01.1987 ▶ 07.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.6 650	AD	01.1982 ▶ 04.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 990	CB	01.1982 ▶ 06.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 990 Matic	Z670	05.1986 ▶ 12.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 Tre	CB	04.1982 ▶ 04.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 Tre Mini Matic	Z670	06.1984 ▶ 04.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 ie 100 ie	146.C7.000	07.1994 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 Turbo 990 Turbo	G11	05.1986 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 Turbo De Tomaso	CB60, G11	01.1983 ▶ 04.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### KORAL

0.9 45, 1.1 55	100.GL.064, 128.A.064	10.1990 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 Cabrio	13CA.064	06.1991 ▶			1.1	<b>246564</b>	H79-11

### MILLE

1.0 ie	146.C7.000	01.1994 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
--------	------------	-----------	---------------	------	-----	---------------	-----

### MILLE CLIP

1.0 ie	146.C7.000	01.1995 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 ie	160.A1.046	01.1995 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### MINI

1.0 90, 1.3 120, De Tomaso	BLMC 99 H	10.1972 ▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
----------------------------	-----------	-------------------	---------------	------	-----	---------------	-----

### SMALL

0.6 500	E	07.1990 ▶ 12.1992	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 990	CB	07.1990 ▶ 12.1992	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

## ISUZU

### 117 COUPE

1.8 XC, XE, XG, XT	G 180	01.1968 ▶ 05.1981	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 XC, XE, XG, XT	G 200	01.1968 ▶ 05.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### ASKA

1.8	4ZB1	04.1983 ▶			1.1	<b>246564</b>	H79-11
1.8 i 16V	EJ18	06.1990 ▶ 03.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0	4ZC1	04.1983 ▶ 06.1990			1.1	<b>246564</b>	H79-11



3+1


**ISUZU** (.../...)

**ASKA (.../...)**

2.0	4ZC1 Cat	04.1983 ▶ 06.1990			1.1	<b>246564</b>	H79-11
2.0 i 16V	EJ20 [DOHC] Cat	06.1990 ▶ 03.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [SOHC] Cat	06.1991 ▶ 03.1994			1.1	<b>246556</b>	F87-11
2.0 i Turbo	4ZC1T	04.1983 ▶			1.1	<b>246564</b>	H79-11

**BELLET**

1300, 1500, 1600, 1800, 2000		▶ 12.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
------------------------------	--	-----------	---------------	------	-----	---------------	-----

**BIGHORN / RODEO / TROOPER**

2.0	G200Z	02.1981 ▶ 10.1991			0.8	<b>246564</b>	H79-11
2.3	4ZD1	01.1987 ▶			1.1	<b>246564</b>	H79-11
2.3	G230	01.1985 ▶ 10.1991	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.6 i	4ZE1 Cat	10.1987 ▶ 12.1991			1.1	<b>246564</b>	H79-11
3.2 i V6 24V	6 VD 1 Cat	10.1991 ▶ 02.1998	<b>246333</b>	RF72H11	1.1		

**CAMPO**

2300 : 2.3 i, 4WD	4ZD1 Cat	04.1988 ▶ 12.1993			1.1	<b>246564</b>	H79-11
-------------------	----------	-------------------	--	--	-----	---------------	--------

**ELF**

1.6 KAG, KA, 51	G161	01.1974 ▶ 10.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
100 : 2.0	NA20S	06.1995 ▶ 06.1999			1.1	<b>246564</b>	H79-11
100 : 2.0 i	KA 20 DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
250 : TLG	G201	01.1974 ▶ 10.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**FARGO**

2.0	4ZC1 Cat	12.1985 ▶			1.1	<b>246564</b>	H79-11
2.0	NA20S	08.1995 ▶			1.1	<b>246564</b>	H79-11
2.0 Turbo	4ZC1 Cat	01.1983 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 i	VG30E	08.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.3 i V6	VG33E Cat	10.1998 ▶			1.1	<b>246556</b>	F87-11

**FASTER**

2.3	4ZD1	01.1983 ▶ 12.1991	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.3	4ZD1 Cat	01.1983 ▶ 12.1991			1.1	<b>246564</b>	H79-11

**FLORIAN**

1.6 S, GT	G161Z	01.1976 ▶ 03.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 TS	G180Z	01.1976 ▶ 03.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**GEMINETTE**

1.6	EA71	09.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	------	-----------	---------------	------	-----	---------------	-----

**GEMINI**

1.5	4XC1	11.1984 ▶ 08.1993			1.1	<b>246564</b>	H79-11
1.5	4XC1	11.1984 ▶ 08.1993	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5	4XC1U Cat	11.1984 ▶ 08.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 i Turbo	4XC1UT	02.1988 ▶ 08.1993			1.1	<b>246564</b>	H79-11
1.6	G161Z	01.1974 ▶ 10.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 i 16V	4XE1-W	03.1990 ▶ 08.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	D16 A Cat	08.1993 ▶	<b>246333</b>	RF72H11	1.1		
1.6 i 16V	ZC	08.1993 ▶ 03.1998	<b>246333</b>	RF72H11	1.1		
1.6 i 16V GTi	4XE1	08.1988 ▶ 08.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8	G 180	06.1977 ▶ 10.1984			1.1	<b>246564</b>	H79-11

**KAG**

1.6 41, 51	G161	01.1985 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 KR 86	G161Z	01.1973 ▶ 10.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**MICROBUS**

2.0 4 cyl.		01.1983 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
------------	--	-----------	---------------	------	-----	---------------	-----

**MIDI**

2.0	4ZC1 Cat	07.1988 ▶			1.1	<b>246564</b>	H79-11
2.0	G200Z	07.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**MONTEREY**

3.2 i V6 24V	6 VD 1	06.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	--------	-----------	---------------	---------	-----	---------------	--------

**MU**

2.6 i	4ZE1 Cat	08.1990 ▶ 06.1998			1.1	<b>246564</b>	H79-11
3.2 i V6 24V	6 VD 1 Cat	08.1990 ▶	<b>246333</b>	RF72H11	1.1		

**NERO**

1.5	4XC1	05.1990 ▶ 09.1993			1.1	<b>246564</b>	H79-11
1.6 i 16V	4XE1	05.1990 ▶ 09.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	4XE1 Cat	02.1991 ▶ 09.1993	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

**PIAZZA**

2.0 i	G200W	06.1981 ▶			1.1	<b>246564</b>	H79-11
2.0 i	G200Z	06.1981 ▶			1.1	<b>246564</b>	H79-11
2.0 i Turbo	4ZC1 Cat	09.1985 ▶ 07.1991			1.1	<b>246564</b>	H79-11





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## ISUZU (.../...)

### PICK-UP

1.6 KB 10, KB 20, KB 25	G161Z	01.1981 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 KB 26, KB 41		09.1983 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 KB 30, KB 40	G161Z	01.1981 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 KB	G180Z	01.1981 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 KB 28, KB 43, KB 48	G200Z	02.1984 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### VEHICROSS

3.2 i V6 24V	6 VD 1 Cat	03.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------	-----------	---------------	---------	-----	---------------	--------

### WFR

1.8 11	4ZB1	06.1983 ▶ 02.1986	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 12	4ZC1 Cat	02.1986 ▶	<b>246179</b>	R76H	1.1	<b>246555</b>	H79

### WIZARD

3.2 i V6 24V	6 VD 1 Cat	06.1998 ▶	<b>246333</b>	RF72H11	1.1		
--------------	------------	-----------	---------------	---------	-----	--	--

## IVECO

### DAILY I

2.0 30-9, 35-9	6132 BZ 2CO	12.1981 ▶ 12.1987	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
----------------	-------------	-------------------	---------------	------	-----	---------------	-----

### GRINTA

2.0 30-9, 35-9	6132 BZ 2CO	12.1981 ▶ 12.1987	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
----------------	-------------	-------------------	---------------	------	-----	---------------	-----

## JAGUAR

### DAIMLER

3.6 i L6 24V	AJ6.4 [DOHC] Cat	10.1986 ▶ 08.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
4.0 i 24V	AJ6 [DOHC] Cat	09.1989 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

### E-TYPE

3.8		01.1961 ▶ 12.1980	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
4.2		01.1961 ▶ 12.1980	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
5.3 V12		03.1971 ▶ 04.1975	<b>246180</b>	R84H	0.6	<b>246555</b>	H79

### SOVEREIGN

3.2 24V	AJ6 [OHC]	09.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
3.6 i L6 24V	AJ6.4 [DOHC] Cat	10.1986 ▶ 08.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
4.0 i 24V	AJ6 [DOHC] Cat	09.1989 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
4.2 i	XK	01.1979 ▶ 12.1986	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### S-TYPE

3.4		01.1964 ▶ 12.1975	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
3.8		01.1964 ▶ 12.1975	<b>246180</b>	R84H	0.6	<b>246555</b>	H79

### XJ

XJ 12 : 5.3 i V12	[OHC]	01.1975 ▶ 12.1981	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
XJ 6 : 2.8	XK	10.1968 ▶ 12.1974	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
XJ 6 : 3.2 24V	AJ6 [OHC]	10.1990 ▶ 09.1997	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
XJ 6 : 3.4	XK [OHC]	01.1975 ▶ 12.1986	<b>246181</b>	R90H	0.9		
XJ 6 : 3.6 i L6 24V	AJ6.4 [DOHC] Cat	10.1986 ▶ 08.1989	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
XJ 6 : 4.0 i 24V	AJ6 [DOHC] Cat	09.1989 ▶ 09.1994	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
XJ 6 : 4.2	XK	01.1969 ▶ 12.1979	<b>246181</b>	R90H	0.7		
XJ 6 : 4.2 i	XK	01.1979 ▶ 12.1986	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
XJR : 4.0 i V6	AJ16 Compressor Supercharged	08.1994 ▶			0.9	<b>246567</b>	F59
XJR : 4.0 i V6 24V Supercharger	[DOHC]	01.1989 ▶ 09.1994	<b>246176</b>	RF80H	0.6	<b>246554</b>	F87
XJR : 6.0 i V12	[DOHC]	01.1989 ▶ 05.1993	<b>246021</b>	C60H	0.7	<b>246565</b>	C60

### XJS

4.0 i 24V	AJ6 [DOHC] Cat	05.1991 ▶ 10.1996	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
5.3 i V12	[OHC]	01.1975 ▶ 12.1981	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### XJSC

3.6 i V6 24V SC Cabriolet	AJ3.6 / AJ6.4 / [DOHC] Cat	10.1983 ▶ 05.1991	<b>246176</b>	RF80H	0.6	<b>246554</b>	F87
---------------------------	----------------------------	-------------------	---------------	-------	-----	---------------	-----

## JEEP

### CHEROKEE

4.0 i		01.1987 ▶ 12.1990	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
4.0 i	XJ [OHV] Cat	09.1987 ▶ 12.1996			1.0	<b>246556</b>	F87-11

### CJ5, CJ8

2.0 CJ-7	J5R- 800	01.1983 ▶ 12.1986	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
----------	----------	-------------------	---------------	------	-----	---------------	-----

### COMANCHE

4.0 i		01.1987 ▶ 12.1990	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
-------	--	-------------------	---------------	-------	-----	---------------	-----

### GRAND CHEROKEE

5.2 i V8		09.1992 ▶ 12.1996			1.0	<b>246556</b>	F87-11
5.9 i V8		09.1996 ▶	<b>246186</b>	RF82H	0.9	<b>246554</b>	F87



3+1



## JEEP (.../...)

### GRAND WAGONEER

5.9 V8		01.1989 ▶ 12.1991	<b>246182</b>	R92H	0.9		
--------	--	-------------------	---------------	------	-----	--	--

### WAGONEER

4.0 i		01.1990 ▶	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
-------	--	-----------	---------------	-------	-----	---------------	-----

## JEEP EAGLE

### 2000 GTX

2.0 i		01.1991 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-----------	---------------	------	-----	---------------	-----

2.2 i		01.1988 ▶ 12.1990	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
-------	--	-------------------	---------------	-------	-----	---------------	-----

### PREMIER

3.0 i		01.1988 ▶ 12.1992	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
-------	--	-------------------	---------------	-------	-----	---------------	-----

### SUMMIT

1.5 i		01.1989 ▶ 12.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-------------------	---------------	------	-----	---------------	-----

1.6 i Turbo		01.1989 ▶ 12.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------------	--	-------------------	---------------	------	-----	---------------	-----

1.8 i		01.1992 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
-------	--	-----------	---------------	-------	-----	---------------	-----

### TALON

1.8 i		01.1993 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-----------	---------------	------	-----	---------------	-----

2.0 i		01.1990 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-----------	---------------	------	-----	---------------	-----

### VISTA

1.5 i		01.1989 ▶ 12.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-------------------	---------------	------	-----	---------------	-----

1.6 i Turbo		01.1989 ▶ 12.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------------	--	-------------------	---------------	------	-----	---------------	-----

2.0 i		01.1989 ▶ 12.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	--	-------------------	---------------	------	-----	---------------	-----

## KIA

### AVELLA

1.3 i 16V	B3 [SOHC] Cat	03.1994 ▶			1.1	<b>246564</b>	H79-11
-----------	---------------	-----------	--	--	-----	---------------	--------

1.5 i 16V	B5 Cat	03.1994 ▶			1.1	<b>246564</b>	H79-11
-----------	--------	-----------	--	--	-----	---------------	--------

### CAPITAL

1.5	B5	01.1990 ▶			1.1	<b>246556</b>	F87-11
-----	----	-----------	--	--	-----	---------------	--------

1.5 i 16V	B5 Cat	01.1990 ▶			1.1	<b>246556</b>	F87-11
-----------	--------	-----------	--	--	-----	---------------	--------

1.8 i	F8	03.1992 ▶	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87
-------	----	-----------	---------------	-------	-----	---------------	-----

### CLARUS

1.8 i 16V GLX, SLX	T8 [DOHC]	02.1996 ▶ 05.1998	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
--------------------	-----------	-------------------	---------------	-------	-----	---------------	-----

2.0 i 16V	FE [DOHC]	02.1996 ▶ 05.1998			1.1	<b>246556</b>	F87-11
-----------	-----------	-------------------	--	--	-----	---------------	--------

### CONCORDE

1.8 i	F8	03.1992 ▶ 06.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-------	----	-------------------	---------------	---------	-----	---------------	--------

2.0 i	FE [OHC]	10.1987 ▶ 06.1995			0.8	<b>246556</b>	F87-11
-------	----------	-------------------	--	--	-----	---------------	--------

### MENTOR

1.5 i	[SOHC]	09.1993 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
-------	--------	-----------	---------------	------	-----	---------------	-----

1.6 i	[DOHC]	06.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-------	--------	-----------	---------------	---------	-----	---------------	--------

1.6 i	[SOHC]	09.1993 ▶			1.0	<b>246564</b>	H79-11
-------	--------	-----------	--	--	-----	---------------	--------

### PRIDE

1.1 i	B1	01.1990 ▶ 04.1994	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
-------	----	-------------------	---------------	------	-----	---------------	-----

1.3	B3 [SOHC]	01.1990 ▶			0.8	<b>246564</b>	H79-11
-----	-----------	-----------	--	--	-----	---------------	--------

1.3 i 16V GLXi	B3 [SOHC] Cat	05.1994 ▶			1.1	<b>246564</b>	H79-11
----------------	---------------	-----------	--	--	-----	---------------	--------

### SEPHIA

1.5 i	B5	01.1992 ▶ 10.1994			1.1	<b>246556</b>	F87-11
-------	----	-------------------	--	--	-----	---------------	--------

1.5 i 16V	B5 Cat	01.1992 ▶ 10.1994			1.1	<b>246556</b>	F87-11
-----------	--------	-------------------	--	--	-----	---------------	--------

1.5 i 16V	B5E MMO	02.1996 ▶ 12.1997			1.1	<b>246564</b>	H79-11
-----------	---------	-------------------	--	--	-----	---------------	--------

1.6 i GTX	B6 [SOHC]	08.1991 ▶ 08.1996			1.1	<b>246564</b>	H79-11
-----------	-----------	-------------------	--	--	-----	---------------	--------

1.8 i 16V	T8 [DOHC]	06.1996 ▶ 12.1997	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
-----------	-----------	-------------------	---------------	-------	-----	---------------	-----

### SHUMA

1.5 i 16V LS, RS	B5D	12.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
------------------	-----	-----------	---------------	---------	-----	---------------	--------

1.8 i 16V	T8D	12.1997 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
-----------	-----	-----------	---------------	-------	-----	---------------	-----

### SPORTAGE

2.0 i	NB7	07.1993 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
-------	-----	-----------	---------------	-------	-----	---------------	-----

2.0 i 16V Karmann	FE/FE-DE	07.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-------------------	----------	-----------	---------------	---------	-----	---------------	--------

## LADA (SHIGULI)

### 110

1.5 i	VAZ 2111	01.1995 ▶			1.1	<b>246564</b>	H79-11
-------	----------	-----------	--	--	-----	---------------	--------

1.5 i 16V	VAZ 2112	01.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	----------	-----------	---------------	---------	-----	---------------	--------

2.0 i 16V GTi, Yellow Shark	C 20 XE [DOHC]	08.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
-----------------------------	----------------	-----------	---------------	----------	-----	---------------	-----

### 111

1.5 i 16V	VAZ 2112	01.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	----------	-----------	---------------	---------	-----	---------------	--------



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## LADA (SHIGULI) (.../...)

<b>112</b>									
1.5 i 16V	VAZ 2112	01.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
<b>1200 (2101)</b>									
1200 : 1.2 (2101, 2102)		01.1970 ▶ 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>1200-1500</b>									
1500 : 1.5 (2102, 2103)		09.1972 ▶ 07.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>1200-1600</b>									
1600 : 1.6 (2103, 2106, 2107)		09.1972 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
<b>1300 (21011)</b>									
1300 : 1.3 (2104, 21011)		08.1974 ▶ 08.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>FORMA (SAMARA)</b>									
1.1	BA3	09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3	Cat	09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5		09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>LAIKA</b>									
1.5		02.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79		
1.6		02.1993 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
<b>NADESCHDA</b>									
1.7 i	BA3 2121.4				1.1	<b>246564</b>	H79-11		
1.7 i	VAZ 2121.3		<b>246180</b>	R84H	0.9	<b>246555</b>	H79		
<b>NATACHA</b>									
1.5		01.1996 ▶			1.1	<b>246564</b>	H79-11		
<b>NIVA, COSSACK</b>									
1600 : 1.6 4x4		09.1987 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79		
1600 : 1.6 4x4	VAZ 2121	12.1976 ▶ 06.1988	<b>246180</b>	R84H	0.7	<b>246555</b>	H79		
1700 : 1.7 i 4x4	VAZ 2112	01.1993 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79		
<b>NOVA, KALINKA</b>									
1.7		01.1996 ▶			1.1	<b>246564</b>	H79-11		
1.7 i	BA3 2121.4	08.1994 ▶			1.1	<b>246564</b>	H79-11		
1200 : 1.2	VAZ 21051	09.1981 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1300 : 1.3	VAZ 2102	05.1981 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1400 : 1.4	VAZ 2105	05.1981 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1500 : 1.5	VAZ 2104, 2105	01.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1600 : 1.6	VAZ 2107 BA3 2106	05.1981 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>OKA</b>									
0.7	VAZ 1111 [SOHC]	09.1989 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.0	A Plus	01.1995 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
<b>RIVA</b>									
1200 : 1.2	21012 [OHC]	11.1985 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1300 : 1.3	21056 [OHC]	11.1985 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1500 : 1.5	21026 [OHC]	11.1985 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1600 : 1.6	21062 [OHC]	01.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>SAGONA</b>									
1.1 i			<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3 i					1.1	<b>246564</b>	H79-11		
1.5					1.1	<b>246564</b>	H79-11		
<b>SAMARA</b>									
1.1	BA3 21081	01.1986 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.1	BA3 21081 Cat	01.1986 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3	VAZ 2108, 2109	01.1986 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3 i	VAZ 2108, 2109 Cat	02.1996 ▶			1.1	<b>246564</b>	H79-11		
1.5	BA3, VAZ 21083	01.1986 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5 i	Cat	07.1988 ▶			1.1	<b>246564</b>	H79-11		
<b>SAMARA FUN</b>									
1.1		09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.3		09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5		09.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
<b>SAMARA SPORT</b>									
1.5		01.1996 ▶			1.1	<b>246564</b>	H79-11		
<b>TOSCANA</b>									
1.3		01.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.4	VAZ 2101	01.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5		01.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		
1.5	BA3 2103	01.1986 ▶ 06.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79		


**3+1**

**LAMBORGHINI**

**COUNTACH**

5.0 V12	L 521	01.1982 ▶ 12.1984	<b>246170</b>	67HP	0.7		
<b>ESPADÀ</b>							
4.0 400 GT		01.1968 ▶ 12.1980	<b>246170</b>	67HP	0.6		
<b>ESPADÀ III</b>							
3.9 V12		05.1982 ▶	<b>246170</b>	67HP	0.6		
<b>ISLERO</b>							
3.9 V12 400 GTS		01.1968 ▶ 12.1980	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
<b>JALPA</b>							
3.5 V8	P 350 Carbu [OHC]	01.1981 ▶	<b>246170</b>	67HP	0.6		
<b>JARAMA</b>							
4.0 400 GT, GTS		01.1968 ▶ 12.1980	<b>246170</b>	67HP	0.6		
<b>MUIRA</b>							
3.9 V12	P 400 S	01.1968 ▶ 12.1980	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
<b>URRACO</b>							
2.0 V8	P 200	06.1972 ▶ 12.1980	<b>246170</b>	67HP	0.6		

**LANCIA**

**A 112**

0.9 Junior, LX	A 112 B...	03.1978 ▶ 12.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 Elegant, Elite	A 112 B1...	01.1971 ▶ 02.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.05 Abarth	A 112 A	08.1977 ▶ 02.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
<b>BETA</b>							
1300 : 1.3		06.1973 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1600 : 1.6		06.1973 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2000 : 2.0		06.1973 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2000 : 2.0 ie	828 CB 1A	05.1980 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>BETA H.P.E.</b>							
1600 : 1.6 HPE		06.1973 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2000 : 2.0 ie	828 CB 1A	05.1980 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>BETA MONTE CARLO</b>							
2000 : 2.0		04.1975 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
<b>DEDRA</b>							
1.6 i, ie SW	182.A4.000 Cat	03.1998 ▶ 01.2000			1.0	<b>246554</b>	F87
1.6 ie	835.A1.000	01.1989 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 ie	835.A1.046 Cat	08.1989 ▶ 09.1994	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
1.6 ie	835.C1.000	04.1993 ▶ 04.1998	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.6 ie LE, LS, SW	159.B9.000	04.1993 ▶ 04.1998	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.8 i, ie LE, LS, LX, SW	182.A2.000, 183.A1.000	01.1996 ▶ 02.1998			1.0	<b>246554</b>	F87
1.8 ie LE, SW, Symbol	835.A2.046, 835.A2.000	01.1989 ▶ 02.1998	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 ie SW	836.A5.000	09.1989 ▶ 12.1995	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 i, ie 16V LX, SW, 4x4 SW Integrale	836.A3.000 Cat	10.1994 ▶ 02.1998	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 ie LS, SW	835.A5.046	01.1989 ▶ 04.1997	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 ie SW	835.A5.000	01.1989 ▶ 10.1994	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 ie Turbo Integrale, Turbo, 4x4 Turbo Integrale	835.A7-A8.000, 835.A7.046 Cat	06.1990 ▶ 10.1994			0.8	<b>246557</b>	H60
2.0 ie Turbo Integrale, Turbo, 4x4 Turbo Integrale	835.A8.046 Cat	04.1990 ▶ 02.1998			0.8	<b>246557</b>	H60
<b>DELTA</b>							
1.1	831.B8.000	01.1986 ▶ 12.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	831.A2.000	09.1979 ▶ 08.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 LX	831.B.000	09.1982 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.4 ie	160.A1.046	01.1993 ▶	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
1.4 ie	836.A4.000	01.1993 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.5	831.A, 831.B1	09.1979 ▶ 06.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 ie	138.C...	12.1985 ▶ 10.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6	831.A4...	11.1982 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 HF Turbo	831.B3, DK	06.1983 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 i, ie HPE	182.A4-A6.000	01.1996 ▶			1.0	<b>246554</b>	F87
1.6 ie	835.C1.000	01.1993 ▶ 11.1997	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59
1.6 ie HF Turbo	831.A7.000	01.1992 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie HF Turbo	831.B7.046 Cat	05.1985 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 i, ie	182.A2.000	01.1996 ▶			1.0	<b>246554</b>	F87
1.8 i, ie GT, HPE	183.A1.000	01.1996 ▶			1.0	<b>246554</b>	F87
1.8 ie	836.A5.000	01.1993 ▶	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
1.8 ie GT	836.A6.000	01.1993 ▶	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
1.8 ie LE	835.C4.000	01.1993 ▶ 11.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 ie 16V	835.C2.000 Cat	01.1993 ▶ 12.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## LANCIA (.../...)

### DELTA (.../...)

1.8 ie 16V Turb S4 Volumex		09.1985 ▶ 12.1990	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
16 : 2.0 ie 16V Turb Evolution	831.E5.000, 831.E5.046	03.1991 ▶ 11.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Turbo Integrale	831.GH8E.000	03.1989 ▶ 12.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i, ie 16V GT, HPE	836.A3.000 Cat	01.1993 ▶ 11.1997	<b>246198</b>	R70H	0.9	<b>246557</b>	H60
2.0 ie 16V Turb HF Integrale, HF Integrale 4x4 Turbo Integrale	831.D5.000, 831.D5.04	01.1989 ▶			0.8	<b>246557</b>	H60
2.0 ie 16V Turb HF Turbo Integrale	831.C5.000	05.1986 ▶ 02.1989			0.8	<b>246557</b>	H60
2.0 ie 16V Turb HPE	175.A4.000	12.1997 ▶			0.9	<b>246567</b>	F59
2.0 ie 16V Turb HPE	836.A2.000 Cat	01.1993 ▶ 11.1997	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 ie Turbo HF 4x4	831.B5.000	05.1986 ▶ 02.1989			0.8	<b>246557</b>	H60
2.0 ie Turbo HF Integrale, HF Turbo	831.C5.046	07.1992 ▶ 11.1997			0.8	<b>246557</b>	H60

### GAMMA

2000 : 2.0 Berlina		09.1976 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2000 : 2.0 Coupé		09.1976 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2500 : 2.5 Berlina		05.1976 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2500 : 2.5 Coupé		05.1976 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2500 : 2.5 ie ie Berlina		06.1980 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2500 : 2.5 ie ie Coupé		06.1980 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

### KAPPA

2.0 ie 16V Turb	838.A4.000	11.1994 ▶ 06.1998			0.8	<b>246557</b>	H60
2.0 ie 20V LE, LS	838.A1.000	10.1994 ▶ 06.1998			1.0	<b>246554</b>	F87
2.0 ie 20V LS	838.A6.000	11.1994 ▶			1.0	<b>246554</b>	F87
2.0 ie 20V Turb	175.A3.000	06.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.4 ie 20V	838.B2.000	06.1998 ▶			1.0	<b>246554</b>	F87
2.4 ie 20V Coupé, LE, LS, LX	838.A2.000	08.1994 ▶			1.0	<b>246554</b>	F87

### LYBRA

1.6 i, ie SW	182.A4.000 Cat	09.1999 ▶			1.0	<b>246554</b>	F87
1.8 i 16V SW	839.A4.000	09.1999 ▶			1.0	<b>246554</b>	F87
2.0 i 20V SW	182.B7.000	09.1999 ▶			1.0	<b>246554</b>	F87

### PHEDRA

2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	06.2002 ▶	<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	06.2002 ▶	<b>246562</b>	RF80LZDC3	0.9		

### PRISMA

1.3 ie	138 C	12.1982 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5	138 C	12.1982 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.5 ie	138 C	12.1982 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 ie	831 ...	12.1982 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 4x4, Integrale	831.B4.046, 831.B4.000	04.1986 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### THEMA

2.0 ie	834.B.000	11.1984 ▶ 05.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	834.B.146	03.1986 ▶ 01.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie	834.B1.000	09.1984 ▶ 05.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 16V	834.B2.246	01.1987 ▶ 08.1992			0.8	<b>246557</b>	H60
2.0 ie 16V	834.F1.000	01.1992 ▶ 01.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 16V Turb	834.B2.000	06.1987 ▶ 05.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie 16V Turb	834.F2.000	10.1991 ▶ 01.1995			0.8	<b>246557</b>	H60
2.0 ie 16V Turbo	834.C1.000, 834.C1.246	01.1987 ▶ 01.1995			0.8	<b>246557</b>	H60
2.0 ie Turbo	834.C.146, 834.C.000	11.1984 ▶ 05.1992			0.8	<b>246557</b>	H60
3.0 ie V6	834.F.000	01.1992 ▶ 01.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### TREVI

1.6	828.B	01.1980 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 ie Integrale	828.B1...	01.1980 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 ie Volumex	828.B1...	01.1980 ▶ 12.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### Y

1.2 ie LE, LS	840.A3.000	01.1996 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.4 ie 12V LS, LX	840.A2-A4.000	01.1996 ▶			1.0	<b>246554</b>	F87

### Y10

1.0 Fire, Fire Appia, Mia, 4x4	156.A2.000	03.1985 ▶ 06.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie Fire	156.A2.100	03.1985 ▶ 06.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie Fire	156.A2.256	03.1985 ▶ 02.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.0 ie Fire 4x4	156.A3.000	09.1986 ▶ 12.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.0 ie Fire, 4x4	156.A2.146	03.1985 ▶ 07.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.05 Touring	156.A.000	03.1985 ▶ 02.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1 i, ie	176.B2.000	02.1995 ▶ 12.1995	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.1 ie Fire 4x4, Appia LX, Avenue, LX, Selectronic	156.C.000	01.1989 ▶ 09.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87





3+1


**LANCIA** (.../...)

**Y10 (.../...)**

1.1 ie Fire, 4x4, Avenue/Clim, Clim, Elite Clim, LX Selectronic	156.C.046 Cat	09.1986 ▶ 12.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.3 ie GT	156.B.000	11.1987 ▶ 12.1995	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.3 ie GT, Elite	146.A5.000, 146.A5.046	11.1987 ▶ 12.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**ZETA**

1.8 i	XU7 JP [LFW]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i	XU7 JP [LFW]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i	XU10 J2C [RFU]	07.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 J2C [RFU]	07.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Turbo	XU10 J2TE [RGX]	09.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

**LAND ROVER**
**DEFENDER**

2.5		08.1990 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 V8		08.1990 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
3.9 i V8		09.1992 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

**DISCOVERY**

2.0 i 16V	T16 [DOHC]	10.1993 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
3.5 i V8	22D		<b>246182</b>	R92H	0.8		
3.5 i V8	24D		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 V8	27G		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 V8 Style		09.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.9 i V8	36D	09.1993 ▶	<b>246181</b>	R90H	0.8		
4.0 i V8		01.1999 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**FREELANDER**

1.8 i 16V	K16 Series 18K4F [DOHC] Cat	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
-----------	-----------------------------	-----------	---------------	----------	-----	---------------	-----

**LAND-ROVER**

109 : 3.5 V8			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
88/109 : 2.3	8:1 CR		<b>246181</b>	R90H	0.8		
90/110 : 2.3	8:1 CR		<b>246181</b>	R90H	0.8		
90/110 : 2.5		09.1983 ▶ 07.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
90/110 : 3.5 V8		09.1983 ▶ 07.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
90/110 : 3.9 i V8		01.1992 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

**RANGE ROVER**

3.5 i V8	(F)	10.1985 ▶ 09.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 i V8	LC		<b>246181</b>	R90H	0.8		
3.5 V8		▶ 12.1996	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
3.5 V8		▶ 12.1996	<b>246189</b>	R88N	0.8		
3.5 V8	V8F	08.1981 ▶ 09.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.9 i V8 Classic	LC	11.1987 ▶ 07.1994	<b>246181</b>	R90H	0.8		
4.0 i V8 SE	42D	09.1994 ▶ 12.1998	<b>246181</b>	R90H	0.8		
4.2 i V8	HC	09.1992 ▶ 09.1994	<b>246181</b>	R90H	0.8		
4.6 i V8 HSE	46D	09.1994 ▶ 12.1998	<b>246181</b>	R90H	0.8		

**LEYLAND-DAF**
**200**

1.7	O Series	04.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	O Series	04.1989 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

**400**

2.0	O Series	04.1989 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.5 V8		04.1989 ▶	<b>246181</b>	R90H	0.8		

**LEYLAND-FREIGHT ROVER**
**SHERPA**

1.7 200	Leyland-Daf	11.1986 ▶			0.7	<b>246565</b>	C60
1.7 230, 250, 255, 280	Leyland-Daf	11.1986 ▶			0.7	<b>246565</b>	C60
2.0 200	Leyland-Daf	11.1986 ▶			0.7	<b>246565</b>	C60
2.0 230, 250, 255, 280	Leyland-Daf	11.1986 ▶			0.7	<b>246565</b>	C60
200 : 1.7		01.1978 ▶ 12.1986			0.8	<b>246566</b>	C79
200 : 1.7		01.1987 ▶ 01.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
200 : 2.0		01.1978 ▶ 12.1986			0.8	<b>246566</b>	C79
200 : 2.0		01.1987 ▶ 01.1989	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.6	Leyland-Daf	11.1986 ▶	<b>246181</b>	R90H	0.8		
300 : 2.0		09.1983 ▶ 05.1986	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
300 : 3.6 V8		11.1985 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## LOTUS

### ECLAT

2.0 16V	Mot. 907	01.1975 ▶ 12.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.2 16V		01.1980 ▶ 12.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.2 16V	Lotus 912	05.1980 ▶ 08.1986	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### ELAN

1.5		01.1963 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6		01.1963 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6 i 16V Turbo	4XE1	09.1989 ▶ 07.1992	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59
S2 : 1.6 i 16V Turbo		01.1994 ▶	<b>246488</b>	RF72HZDC	0.9	<b>246567</b>	F59

### ELISE

1.8 i 16V	K16 Series 18K4F [DOHC] Cat	01.1996 ▶	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59
-----------	-----------------------------	-----------	---------------	----------	-----	---------------	-----

### ELITE

2.0 16V	Mot. 907	01.1973 ▶ 12.1980	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.2 16V	Lotus 912	01.1980 ▶ 12.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### ESPRIT

2.2 Sport 300		01.1993 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.2 Turbo Turbo SE	Mot. 910	02.1980 ▶ 01.1993	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
3.5 i V8 32V Tw	Mot. 618 [2 x DOHC]	03.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
S3 : 2.0 16V	Mot. 907	01.1974 ▶ 12.1980	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
S3 : 2.2 16V	Lotus 912	01.1980 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
S4 : 2.2 Turbo Turbo SE	Mot. 910 S	02.1980 ▶ 01.1993	<b>246178</b>	R64H	0.7	<b>246557</b>	H60

### EUROPA

S2 : 2.0, Special, Twin Cam		01.1968 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-----------------------------	--	-------------------	---------------	------	-----	---------------	-----

### EXCEL

2.2 16V SA, SE	Lotus 912, 912 S	10.1983 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
----------------	------------------	-------------------	---------------	------	-----	---------------	-----

### SEVEN

1.4	[OHV]	01.1962 ▶ 12.1972	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	[OHV]	01.1962 ▶ 12.1972	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5 Twin Cam		01.1965 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6	[OHV]	01.1962 ▶ 12.1972	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 Twin Cam		01.1965 ▶ 12.1975	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

## MASERATI

### 222 / 228

222 : 2.0 V6	Mot. 471..	01.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
222 : 2.8 V6 SE	Mot. 473 Cat	01.1988 ▶ 10.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
228 : 2.8 V6 Bi-Turbo	Mot. 473	12.1984 ▶ 12.1990	<b>246178</b>	R64H	0.6	<b>246557</b>	H60

### 420 / 430

420 : 2.0	Mot. 452	03.1985 ▶ 12.1986	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
420 : 2.0 i	Mot. 470	01.1987 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
422 : 2.0 V6	Mot. 471	01.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60

### 800

0.8 i	F Serie	10.1990 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-------	---------	-----------	---------------	------	-----	---------------	-----

### BITURBO

2.0	Mot. 452	07.1985 ▶ 04.1987	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.5 Si	Mot. 453	09.1987 ▶ 12.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
425 : 2.5 i	Mot. 453	09.1987 ▶ 12.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### BORA

Tous modèles (all models)		01.1971 ▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
---------------------------	--	-------------------	---------------	------	-----	---------------	-----

### GUARA

4.0			<b>246487</b>	RF74HZDC	0.7	<b>246554</b>	F87
-----	--	--	---------------	----------	-----	---------------	-----

### KARIF

2.8 i V6	Mot. 473 Cat	04.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
----------	--------------	-----------	---------------	------	-----	---------------	-----

### KHAMSIN

5.0 V8	115.49	01.1972 ▶ 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
--------	--------	-------------------	---------------	------	-----	---------------	-----

### KYALAMI

4.1	107.21.42	04.1976 ▶ 12.1985	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
4.9	107.22.49	04.1976 ▶ 12.1985	<b>246178</b>	R64H	0.6	<b>246557</b>	H60

### MERAK

2.0 V6 2000	114.62.20	05.1975 ▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
3.0 V6 SS	114.50.30	05.1975 ▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

### QUATTROPORTE

4.1	107.21.42	08.1976 ▶ 12.1989	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
4.9	107.22.49	08.1976 ▶ 12.1989	<b>246178</b>	R64H	0.6	<b>246557</b>	H60

### SEBRING

3.7 V8	Cat	01.1969 ▶ 12.1978	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
--------	-----	-------------------	---------------	------	-----	---------------	-----



3+1


**MASERATI** (.../...)

**SEBRING (.../...)**

4.0 V8	Cat	01.1969 ▶ 12.1978	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
--------	-----	-------------------	---------------	------	-----	---------------	-----

**SPIDER**

2.0 V6	Mot. 471	01.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
--------	----------	-----------	---------------	------	-----	---------------	-----

**MAZDA**
**121 ( CAROL )**

1.1	B1	11.1990 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.1 Revue	B1	10.1987 ▶ 10.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.1 Revue	B116 Cat	04.1989 ▶ 10.1990			1.1	<b>246564</b>	H79-11
1.3 Revue	B3 [SOHC]	10.1987 ▶ 10.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i	J4C Endura-E	▶ 12.1999	<b>246326</b>	RC72H11	1.0		
1.3 i 16V	BJ [DOHC]	11.1990 ▶			1.1	<b>246556</b>	F87-11
1.5 i Revue	B5-MI Cat	01.1991 ▶			1.1	<b>246556</b>	F87-11
1.6 i	B6 Cat	01.1987 ▶ 12.1991			1.1	<b>246564</b>	H79-11
1.8	VC	10.1975 ▶ 12.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	MA	03.1977 ▶ 12.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
Tous modèles (all models)		▶ 12.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**323, 323 C, 323 P, FAMILIA**

1.3 i 16V Hatchback	B3 [SOHC] Cat	06.1994 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V Hatchback	BP [DOHC] Cat	08.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**323, 323 C, FAMILIA**

1.6 16V Hatchback	B6, B62 Cat	06.1989 ▶ 07.1994			1.1	<b>246556</b>	F87-11
1.6 16V Hatchback	B6, BG1	06.1989 ▶ 07.1994	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87
1.6 i Hatchback	B61T Cat	06.1989 ▶ 03.1991			1.1	<b>246564</b>	H79-11
1.8 i 16V 4WD, Hatchback	BP52	11.1989 ▶ 05.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V Coupé, Hatchback, GT	BP [DOHC] Cat	03.1991 ▶ 07.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V GT	BP [DOHC] Cat	06.1989 ▶ 07.1994	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
1.8 i 16V Hatchback	BP [SOHC] Cat	03.1991 ▶ 07.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**323, 323 S, FAMILIA**

1.3 i 16V	B3 [SOHC] Cat	02.1989 ▶ 10.1996			1.1	<b>246556</b>	F87-11
1.3 i 16V	B38 Cat	06.1989 ▶ 03.1991	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.3 i 16V	B3E	09.1989 ▶			1.1	<b>246556</b>	F87-11
1.3 i 16V	B3F Cat	03.1991 ▶ 08.1992			1.1	<b>246556</b>	F87-11
1.3 i 16V	B3-ME [SOHC]	10.1996 ▶ 05.1999			1.1	<b>246556</b>	F87-11
1.5 i 16V	B5 [DOHC]	02.1989 ▶ 06.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.5 i 16V	B5-ZE [DOHC]	06.1994 ▶ 10.1996			1.1	<b>246556</b>	F87-11
1.5 i 16V	Z5 [DOHC]	06.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	Z5-DE [DOHC]	06.1994 ▶ 05.1999			1.1	<b>246556</b>	F87-11
1.6 i 16V	B6 [DOHC] Cat	02.1989 ▶ 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	B6-DE [DOHC]	10.1994 ▶ 06.1998			1.1	<b>246556</b>	F87-11
1.8 i 16V	BP-ZE [DOHC] Cat	06.1996 ▶ 06.1998			1.1	<b>246556</b>	F87-11
1.8 i 16V	FP-DE [DOHC]	06.1998 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V 4WD, Hatchback	BPC Cat	11.1989 ▶ 05.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V Turbo 4WD	BP [DOHC] Cat	11.1989 ▶ 07.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**323, FAMILIA**

1.0	P	01.1976 ▶ 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.1	E1	07.1982 ▶ 08.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	B3 [SOHC]	05.1985 ▶ 05.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	D3	11.1980 ▶ 10.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	E3	11.1980 ▶ 10.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	T	01.1976 ▶ 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 Combi	D3, E3	11.1980 ▶ 10.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 Wagon	E3	01.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i	B3, B383 [SOHC] Cat	04.1987 ▶ 03.1991			1.1	<b>246564</b>	H79-11
1.4	U	03.1978 ▶ 05.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 i LX	B6	09.1987 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5	B5	11.1981 ▶ 05.1989	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5	E5 [OHC]	08.1985 ▶ 04.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 Combi	D5	11.1981 ▶ 10.1985			1.1	<b>246564</b>	H79-11
1.5 Wagon	B50, B53, B56, B564	01.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 i	B5	02.1987 ▶ 02.1989			1.1	<b>246564</b>	H79-11
1.6	B6	06.1986 ▶ 07.1987	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6	B68	01.1986 ▶ 06.1987			1.1	<b>246564</b>	H79-11
1.6 i	B6	07.1985 ▶ 05.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i	B6 Cat	07.1985 ▶ 05.1989			1.1	<b>246564</b>	H79-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MAZDA (…/…)

### 323, FAMILIA (…/…)

1.6 i Wagon	B6	09.1989 ▶ 09.1994	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.6 i Wagon	B6	10.1986 ▶ 08.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i Wagon	B6 Cat	09.1989 ▶ 04.1990			1.1	<b>246556</b>	F87-11
1.6 i Wagon	B6 Cat	10.1986 ▶ 08.1989			1.1	<b>246564</b>	H79-11
1.6 i Wagon Van	B65 Cat	09.1992 ▶			1.1	<b>246564</b>	H79-11
1.6 i Wagon, Wagon 4WD	B65L, B65M Cat	09.1989 ▶			1.1	<b>246564</b>	H79-11
1.6 i 16V	B6 [DOHC] Cat	08.1985 ▶ 04.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i Turbo 4WD, GLX 4WD	B6 [DOHC]	06.1986 ▶ 05.1989	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87

### 323 F, FAMILIA

1.3 i 16V	B3 [SOHC] Cat	10.1996 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	Z5 [DOHC]	05.1994 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	B6E Cat	08.1991 ▶ 08.1994			1.1	<b>246556</b>	F87-11
1.8 i 16V	BP [DOHC] Cat	08.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i V6 24V	KF [DOHC] Cat	05.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### 616

1.6 SNA	NA		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------	----	--	---------------	------	-----	---------------	-----

### 626, CAPELLA

1.3 STC, STCV	TC	01.1971 ▶ 12.1977	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	B6	07.1987 ▶ 10.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6	H6, N	10.1978 ▶ 12.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 3A, AV, SN	NA	01.1973 ▶ 12.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 Coupé	F6, F68	11.1982 ▶ 07.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i	B6 Cat	02.1987 ▶ 04.1997			1.1	<b>246564</b>	H79-11
1.8	F8 [OHC]	07.1987 ▶ 08.1989			1.1	<b>246556</b>	F87-11
1.8	H8-V, F8	10.1978 ▶ 08.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 Wagon	F8 [OHC]	07.1987 ▶ 08.1989			1.1	<b>246556</b>	F87-11
1.8 i	F8	09.1989 ▶ 03.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i Wagon	F8	06.1989 ▶ 11.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	F8-DE [DOHC]	06.1989 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V Hatchback	FP [DOHC]	08.1991 ▶			1.1	<b>246556</b>	F87-11
2.0	FE [OHC]	11.1982 ▶ 06.1987			1.1	<b>246564</b>	H79-11
2.0	FE [OHC]	11.1982 ▶ 06.1987	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0	FE Cat	07.1985 ▶ 06.1987			1.1	<b>246564</b>	H79-11
2.0	FEA [OHC] Cat	07.1987 ▶ 08.1989			1.1	<b>246564</b>	H79-11
2.0	H3, HE3, M	▶ 10.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 Wagon	FE [OHC]	01.1988 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 Wagon	FE [OHC]	09.1989 ▶ 03.1992	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i	FE [OHC]	06.1987 ▶ 09.1989	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i	FE [OHC] Cat	06.1987 ▶ 07.1991			1.1	<b>246564</b>	H79-11
2.0 i GLX, GTI	FE [OHC]	07.1985 ▶ 06.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i GLX, GTI	FE [OHC] Cat	07.1985 ▶ 06.1987	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0 i Wagon	FE [OHC] Cat	06.1987 ▶			1.1	<b>246564</b>	H79-11
2.0 i Wagon	FEKF [OHC] Cat	01.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 12V Wagon	FE [OHC]	01.1988 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 12V Wagon	FE [OHC]	09.1989 ▶ 03.1992	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 16V	FE [DOHC] Cat	07.1987 ▶ 03.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V GLX 4WD, Hatchback	FS [DOHC] Cat	08.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V Wagon	FE [DOHC]	06.1987 ▶ 03.1992	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 16V Wagon	FEKG [DOHC] Cat	01.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### 929

2.0 Coupé, LX	M, FE- HE	10.1977 ▶ 09.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 Station Wagon	HEA, HEE, HE7	12.1981 ▶ 09.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i GLX, Coupé	FE, FA, FEB [OHC]	01.1984 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 V6	JF	01.1986 ▶ 06.1989			1.1	<b>246556</b>	F87-11
2.0 V6 Turbo	JF	01.1986 ▶ 06.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.2 12V	F21	12.1986 ▶ 05.1989			1.1	<b>246556</b>	F87-11
2.2 i 12V	F2E	12.1986 ▶ 06.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
3.0 i V6 18V	JE3	12.1986 ▶ 06.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

### 929 L

1.8	V	01.1974 ▶ 08.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 Combi	M	10.1977 ▶ 12.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### AZ

1.8 i V6 24V	K8 [DOHC] Cat	09.1993 ▶ 01.1998			1.1	<b>246556</b>	F87-11
660 i	F6-A [SOHC]	09.1994 ▶ 10.1998	<b>246180</b>	R84H	0.8	<b>246555</b>	H79


**MAZDA** (.../...)

**BONGO**

1.4	UC [SOHC]	► 07.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	D5	07.1990 ► 09.1995			1.1	<b>246564</b>	H79-11
1.8	F8 [OHC]	06.1983 ► 07.1990			1.1	<b>246556</b>	F87-11
1.8 i	F8	07.1990 ► 06.1999	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0	FE [OHC]	06.1983 ► 08.1990			1.1	<b>246564</b>	H79-11
2.0 i	FE [OHC] Cat	08.1990 ► 06.1999			1.1	<b>246564</b>	H79-11

**BONGO FRIENDEE**

2.0 i 12V	FE-E [SOHC]	06.1995 ►			1.1	<b>246556</b>	F87-11
2.5 i V6 24V	J5-DE [DOHC]	06.1995 ►			1.1	<b>246556</b>	F87-11

**B-SERIE**

B 2000 : 2.0 i V6			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
B 2200 : 2.2	F2 Cat	03.1996 ►			1.1	<b>246564</b>	H79-11
B 2600 : 2.6 i V6	JK 26		<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**CAROL ( 121 )**

660 i	F6-A [SOHC]	01.1991 ► 10.1995	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-------	-------------	-------------------	---------------	------	-----	---------------	-----

**COSMO**

2.0	FE Cat	10.1983 ► 10.1990			1.1	<b>246564</b>	H79-11
-----	--------	-------------------	--	--	-----	---------------	--------

**CRONOS**

1.8 i V6 24V	K8-ZE [DOHC] Cat	10.1991 ► 01.1996			1.1	<b>246556</b>	F87-11
2.0 i 16V	FS-DE [SOHC] Cat	10.1991 ► 01.1996			1.1	<b>246556</b>	F87-11
2.0 i V6 24V	KF-ZE [DOHC] Cat	10.1991 ► 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.5 i V6 24V	KL-ZE [DOHC] Cat	05.1992 ► 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**D**

1.5	UA		<b>246178</b>	R64H	0.8	<b>246557</b>	H60
-----	----	--	---------------	------	-----	---------------	-----

**DEMIO**

1.3 i 16V	B3 [SOHC] Cat	09.1996 ►			1.1	<b>246556</b>	F87-11
1.3 i 16V	B3E	12.1999 ►			1.1	<b>246556</b>	F87-11
1.3 i 16V	B3-ME [SOHC]	08.1996 ► 12.1997			1.1	<b>246556</b>	F87-11
1.5 i 16V	B5-ME [SOHC]	08.1996 ► 12.1997			1.1	<b>246556</b>	F87-11

**E**

1.3	TC	01.1975 ► 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3	TC	09.1980 ► 12.1983	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.4	D417		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	NA	08.1977 ► 09.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	NA	09.1980 ► 12.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	F85		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	FEJL		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2000 : 2.0	FE [OHC]				1.1	<b>246564</b>	H79-11
2000 : 2.0	FE18	11.1984 ► 04.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0	FE58	05.1985 ► 04.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0	FE60, FE61	03.1991 ► 05.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0	FEBM, FEBM, FECL, FEEN, FEET FES3		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0	FEE				1.1	<b>246556</b>	F87-11
2000 : 2.0 4x4	FEBN	10.1988 ► 09.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0 4x4	FEV4	11.1984 ► 02.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**ETUDE**

1.5	B5	02.1988 ► 08.1990			1.1	<b>246556</b>	F87-11
1.6 i 16V	B6 [DOHC] Cat	01.1987 ► 08.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**EUNOS**

1.5 i 16V	B5-ZE [DOHC]	09.1993 ► 01.1998			1.1	<b>246556</b>	F87-11
1.6 i 16V	B6-ZE [DOHC]	09.1989 ► 01.1998			1.1	<b>246556</b>	F87-11
1.8 i 16V	BP-ZE [DOHC] Cat	09.1993 ► 01.1998			1.1	<b>246556</b>	F87-11
1.8 i V6 24V	K8-ZE [DOHC] Cat	06.1991 ► 01.1998			1.1	<b>246556</b>	F87-11

**EUNOS 100**

1.8 i 16V	BP-ZE [DOHC] Cat	11.1989 ► 06.1994			1.1	<b>246556</b>	F87-11
-----------	------------------	-------------------	--	--	-----	---------------	--------

**EUNOS 300**

1.8 i 16V	F8-DE [DOHC]	11.1989 ► 01.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	FE-ZE [DOHC] Cat	11.1989 ► 01.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**EUNOS 500**

1.8 i 16V	BP-ZE [DOHC] Cat	03.1994 ► 12.1995			1.1	<b>246556</b>	F87-11
1.8 i V6 24V	K8-ZE [DOHC] Cat	02.1992 ► 12.1995			1.1	<b>246556</b>	F87-11
2.0 i V6 24V	KF-ZE [DOHC] Cat	02.1992 ► 12.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**EUNOS 800 MILLENIA**

2.0 i V6 24V	KF-ZE [DOHC] Cat	07.1998 ►	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-----------	---------------	---------	-----	---------------	--------





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MAZDA (…/…)

### EUNOS 800 MILLENIA (…/…)

2.5 i V6 24V	KL-ZE [DOHC] Cat	10.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-----------	---------------	---------	-----	---------------	--------

### EUNOS CARGO

1.5	D5	09.1990 ▶			1.1	<b>246564</b>	H79-11
-----	----	-----------	--	--	-----	---------------	--------

2.0	FE Cat	09.1990 ▶			1.1	<b>246564</b>	H79-11
-----	--------	-----------	--	--	-----	---------------	--------

### FESTIVA

1.1 i	B1	02.1985 ▶ 01.1993	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
-------	----	-------------------	---------------	------	-----	---------------	-----

1.3	B3 [SOHC]	02.1985 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	-----------	-----------	---------------	------	-----	---------------	-----

1.3 i	B3 [SOHC] Cat	03.1989 ▶ 05.1994			1.1	<b>246564</b>	H79-11
-------	---------------	-------------------	--	--	-----	---------------	--------

1.3 i	B3-MI [SOHC]	01.1993 ▶			1.1	<b>246556</b>	F87-11
-------	--------------	-----------	--	--	-----	---------------	--------

1.3 i 16V	B3 [SOHC] Cat	01.2000 ▶			1.1	<b>246556</b>	F87-11
-----------	---------------	-----------	--	--	-----	---------------	--------

1.3 i 16V	B3-ME [SOHC]				1.1	<b>246556</b>	F87-11
-----------	--------------	--	--	--	-----	---------------	--------

1.3 i 16V	BJ [DOHC]	10.1986 ▶ 01.1993			1.1	<b>246556</b>	F87-11
-----------	-----------	-------------------	--	--	-----	---------------	--------

1.5 i	B5	01.2000 ▶			1.1	<b>246556</b>	F87-11
-------	----	-----------	--	--	-----	---------------	--------

1.5 i 16V	B5-ME [SOHC]	01.1993 ▶			1.1	<b>246556</b>	F87-11
-----------	--------------	-----------	--	--	-----	---------------	--------

### LANTIS

1.5 i 16V	Z5-DE [DOHC]	09.1993 ▶			1.1	<b>246556</b>	F87-11
-----------	--------------	-----------	--	--	-----	---------------	--------

1.6 i 16V	B6-DE [DOHC]	09.1993 ▶			1.1	<b>246556</b>	F87-11
-----------	--------------	-----------	--	--	-----	---------------	--------

1.8 i 16V	BP-ZE [DOHC] Cat	09.1993 ▶ 09.1997			1.1	<b>246556</b>	F87-11
-----------	------------------	-------------------	--	--	-----	---------------	--------

2.0 i V6 24V	KF-ZE [DOHC] Cat	09.1993 ▶ 09.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-------------------	---------------	---------	-----	---------------	--------

### LUCE

2.0	FE Cat	09.1983 ▶ 05.1990			1.1	<b>246564</b>	H79-11
-----	--------	-------------------	--	--	-----	---------------	--------

2.0 V6	JF	09.1988 ▶ 03.1992			1.1	<b>246556</b>	F87-11
--------	----	-------------------	--	--	-----	---------------	--------

2.0 V6	JF Cat	09.1988 ▶ 03.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------	--------	-------------------	---------------	---------	-----	---------------	--------

2.2	F2 Cat	03.1992 ▶ 01.1996			1.1	<b>246564</b>	H79-11
-----	--------	-------------------	--	--	-----	---------------	--------

3.0 i V6 18V	JE [SOHC] Cat				1.1	<b>246556</b>	F87-11
--------------	---------------	--	--	--	-----	---------------	--------

### M2

1.6 i 16V	B6 [DOHC] Cat	03.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	---------------	-----------	---------------	---------	-----	---------------	--------

### MPV

3.0 i V6 18V	JE [SOHC] Cat	07.1994 ▶ 10.1995			1.1	<b>246556</b>	F87-11
--------------	---------------	-------------------	--	--	-----	---------------	--------

### MS 6

1.8 i V6 24V	K8-ZE [DOHC] Cat	11.1991 ▶ 07.1994			1.1	<b>246556</b>	F87-11
--------------	------------------	-------------------	--	--	-----	---------------	--------

2.0 i 16V	FS-DE [DOHC] Cat	11.1991 ▶ 07.1994			1.1	<b>246556</b>	F87-11
-----------	------------------	-------------------	--	--	-----	---------------	--------

2.0 i V6 24V	KF-ZE [DOHC] Cat	11.1991 ▶ 07.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-------------------	---------------	---------	-----	---------------	--------

### MX-3

1.6 i 16V	B6 [DOHC] Cat	05.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	---------------	-----------	---------------	---------	-----	---------------	--------

1.6 i 16V	B69, B6D Cat	05.1991 ▶			1.1	<b>246556</b>	F87-11
-----------	--------------	-----------	--	--	-----	---------------	--------

1.8 i V6 24V	K8 [DOHC] Cat	05.1991 ▶			1.1	<b>246556</b>	F87-11
--------------	---------------	-----------	--	--	-----	---------------	--------

### MX-5

1.6 i 16V	[DOHC] Cat	12.1994 ▶ 11.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	------------	-------------------	---------------	---------	-----	---------------	--------

1.6 i 16V	B64F [DOHC] Cat	09.1989 ▶ 08.1993			1.1	<b>246556</b>	F87-11
-----------	-----------------	-------------------	--	--	-----	---------------	--------

1.6 i 16V	B6-ZE [DOHC]	01.1990 ▶			1.1	<b>246556</b>	F87-11
-----------	--------------	-----------	--	--	-----	---------------	--------

1.8 i 16V	BP-ZE, BPF1 [DOHC] Cat	09.1993 ▶ 11.1997			1.1	<b>246556</b>	F87-11
-----------	------------------------	-------------------	--	--	-----	---------------	--------

### MX-6

2.0 i 16V	FS [DOHC] Cat	07.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	---------------	-----------	---------------	---------	-----	---------------	--------

2.0 i V6 24V	KF-ZE [DOHC] Cat	07.1991 ▶ 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-------------------	---------------	---------	-----	---------------	--------

2.5 i V6 24V	KL-ZE [DOHC] Cat	07.1991 ▶ 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	------------------	-------------------	---------------	---------	-----	---------------	--------

### PERSONA

1.8	F8 [OHC]	08.1989 ▶ 03.1992			1.1	<b>246556</b>	F87-11
-----	----------	-------------------	--	--	-----	---------------	--------

2.0	FE [OHC]	10.1988 ▶ 03.1992			1.1	<b>246564</b>	H79-11
-----	----------	-------------------	--	--	-----	---------------	--------

### PICK-UP B

1.0	PC	01.1969 ▶ 08.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	----	-------------------	---------------	------	-----	---------------	-----

1.6 Pick-Up B	NA	01.1971 ▶ 10.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------------	----	-------------------	---------------	------	-----	---------------	-----

1.8 Pick-Up B	VC	01.1975 ▶ 10.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------------	----	-------------------	---------------	------	-----	---------------	-----

### PORTER

0.5	G23B	12.1982 ▶ 11.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	------	-------------------	---------------	------	-----	---------------	-----

### RAZOR

1.3	B3 [SOHC]	08.1985 ▶ 06.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	-----------	-------------------	---------------	------	-----	---------------	-----

1.3 i	B3 [SOHC] Cat	04.1987 ▶ 03.1991			1.1	<b>246564</b>	H79-11
-------	---------------	-------------------	--	--	-----	---------------	--------

1.3 i 16V	B3 [SOHC] Cat	02.1989 ▶ 12.1998			1.1	<b>246556</b>	F87-11
-----------	---------------	-------------------	--	--	-----	---------------	--------


1.3 i 16V	B3E	12.1998 ▶			1.1	<b>246556</b>	F87-11
-----------	-----	-----------	--	--	-----	---------------	--------

1.5	E5 [OHC]	10.1989 ▶ 06.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	----------	-------------------	---------------	------	-----	---------------	-----

1.5 i	B5	02.1987 ▶ 02.1989			1.1	<b>246556</b>	F87-11
-------	----	-------------------	--	--	-----	---------------	--------

1.6 i 16V	B6 [DOHC] Cat	08.1985 ▶ 03.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	---------------	-------------------	---------------	---------	-----	---------------	--------

1.8 i 16V	BP-ZE [DOHC] Cat	06.1994 ▶ 12.1998			1.1	<b>246556</b>	F87-11
-----------	------------------	-------------------	--	--	-----	---------------	--------



3+1


**MAZDA** (.../...)

**REVIEW**

1.3 i	B3 [SOHC] Cat	09.1990 ▶			1.1	<b>246564</b>	H79-11
1.5 i	B5	09.1990 ▶			1.1	<b>246556</b>	F87-11

**SENTIA**

2.5 i V6 24V	J5-DE [DOHC]	05.1991 ▶ 10.1995			1.1	<b>246556</b>	F87-11
--------------	--------------	-------------------	--	--	-----	---------------	--------

**SPECTRON / J80 / J100**

1.5	D5	07.1990 ▶ 09.1995			1.1	<b>246564</b>	H79-11
1.8 i	F8	06.1983 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i	FE [OHC]	01.1984 ▶ 09.1995	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i	FE [OHC] Cat	01.1984 ▶ 09.1995			1.1	<b>246564</b>	H79-11

**TELLSTAR**

1.6 i	B6 Cat	05.1987 ▶ 10.1991			1.1	<b>246564</b>	H79-11
1.8	F8 [OHC]	05.1987 ▶ 10.1991			1.1	<b>246556</b>	F87-11
1.8 i	F8	05.1987 ▶ 10.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i	F8	11.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	FP-DE [DOHC]	08.1994 ▶			1.1	<b>246556</b>	F87-11
1.8 i V6 24V	K8-ZE [DOHC] Cat	10.1991 ▶ 09.1994			1.1	<b>246556</b>	F87-11
2.0 i 16V	FE [DOHC] Cat	▶ 10.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	FE/FE-DE	08.1992 ▶ 11.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	FS-DE [DOHC] Cat	02.1992 ▶ 08.1994			1.1	<b>246556</b>	F87-11
2.0 i V6 24V	KF-ZE [DOHC] Cat	10.1991 ▶ 01.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.5 i V6 24V	KL-ZE [DOHC] Cat	08.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**TRANSPORTER**

	SR	01.1983 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--	----	-----------	---------------	------	-----	---------------	-----

**XEDOS 6**

1.6 i 16V	B6 Cat	01.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 24V	KF1 [DOHC] Cat	01.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**XEDOS 9**

2.0 i V6 24V	KF [DOHC] Cat	09.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	---------------	-----------	---------------	---------	-----	---------------	--------

**MCC SMART**
**SMART**

0.6	M 160 E6AL B04	07.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
0.6 Turbo	M 160 E6AL B03	07.1998 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
0.6 Turbo	M 160 E6AL B05	01.2001 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87

**MERCEDES**
**190**

190 : 2.0 i [W201]	M 102.921, M 102.924 Cat	10.1982 ▶ 05.1990	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
190 E : 1.8 i [W201]	M 102.919, M 102.910	04.1990 ▶ 08.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
190 E : 2.0 i [W201]	M 102.961, M 102.962	10.1982 ▶ 08.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
190 E : 2.3 i [W201]	M 102.985	09.1983 ▶ 08.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
190 E : 2.3 i 16V [W201]	M 102.983 Cat	04.1984 ▶ 01.1987	<b>246021</b>	C60H	0.8	<b>246565</b>	C60
190 E : 2.5 i 16V [W201]	M 102.990, M 102.991	09.1988 ▶ 08.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
190 E : 2.6 i V6 [W201]	M 103.942	12.1982 ▶ 08.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79

**CLASSE A**

A 140 : 1.4 i	M 166.940	06.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
A 160 : 1.6 i	M 166.960	06.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
A 190 : 1.9 i	M 166.990	06.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**CLASSE C**

C 180 : 1.8 i 16V	M 111.920, M 111.921	03.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
C 180 : 1.8 i 16V]	M 111.920, M 111.921	03.1993 ▶ 06.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
C 200 : 2.0 i [W202]	M 111.944 kompressor	01.1994 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
C 200 : 2.0 i 16V, T [W202]	M 111.941, M 111.945	01.1994 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
C 200 : 2.0 i 16V, T [W202]	M 111.941, M 111.945	07.1997 ▶ 05.2000	<b>246486</b>	RF74HZ3YE	0.8	<b>246554</b>	F87
C 220 : 2.2 i 16V [W202]	M 111.961	03.1993 ▶ 09.1996	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
C 230 : 2.3 i [W202]	M 111.975 kompressor	08.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
C 230 : 2.3 i 16V, T [W202]	M 111.974	09.1995 ▶ 05.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
C 280 : 2.8 i V6 24V [W202]	M 104.941	05.1993 ▶ 05.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
C 36 : 3.6 AMG, Cabrio, Coupé [W202]	AMG Motor	01.1994 ▶ 05.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

**CLASSE E**

300 : 3.0 E, TE, 4 Matic, T 4 Matic [W124]	M 103.985	07.1993 ▶ 06.1995			0.8	<b>246566</b>	C79
E 200 : 2.0 i, T [W210]	M 111.947	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
E 200 : 2.0 i 16V, Cabrio, Coupé, T, TE [W124]	M 111.940	10.1992 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 200 : 2.0 i 16V, T [W210]	M 111.942	06.1995 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 200 : 2.0 i 16V, T [W210]	M 111.942	07.1997 ▶	<b>246486</b>	RF74HZ3YE	0.8	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MERCEDES (.../...)

### CLASSE E (.../...)

E 220 : 2.2 i, Cabrio, CE, Coupé, T, TE [W124]	M 111.960	10.1992 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 230 : 2.3 i 16V, T [W210]	M 111.970	06.1995 ▶ 06.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
E 230 : 2.3 i 16V, T [W210]	M 111.970, M 111.975	06.1995 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 280 : 2.8 i V6 24V [W210]	M 104.945	01.1996 ▶ 02.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 280 : 2.8 i V6 24V, T, TE [W124]	M 104.942	07.1993 ▶ 04.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 320 : 3.2 i, Cabrio, CE, Coupé, T, TE [W124]	M 104.992	07.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 320 : 3.2 i V6 24V [W210]	M 104.995	06.1995 ▶ 04.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 420 : 4.2 [W124]	M 119.975	07.1993 ▶ 06.1995	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 420 : 4.2 i V8 32V, T [W210]	M 119.985	01.1996 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
E 500 : 5.0 i [W124]	M 119.974	07.1993 ▶ 06.1995	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

### CLASSE G

200 : 2.0 GE [W463]	M 102.965	01.1990 ▶ 07.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
230 : 2.3 G [W460]	M 115.973	03.1979 ▶ 03.1982	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
230 : 2.3 GE [W460]	M 102.981	04.1982 ▶ 08.1985			0.8	<b>246566</b>	C79
230 : 2.3 GE [W460]	M 102.987 Cat	09.1985 ▶ 08.1992			0.8	<b>246566</b>	C79
230 : 2.3 GE [W461]	M 102.979	04.1992 ▶ 06.1996			0.8	<b>246566</b>	C79
230 : 2.3 GE [W463]	M 102.989	09.1989 ▶ 07.1993			0.8	<b>246566</b>	C79
280 : 2.8 GE [W460]	M 110.994	11.1979 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
280 GE : 2.8 [W460]	M 102.964	05.1986 ▶ 03.1992			0.8	<b>246566</b>	C79
300 : 3.0 i G, GE [W463]	M 103.987	09.1989 ▶ 10.1994			0.8	<b>246566</b>	C79
320 : 3.2 G [W463]	M 104.996	08.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
500 : 5.0 V8 GE AMG [W463]	M 117.965	03.1993 ▶ 07.1993	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
G 200 : 2.4 GE [W460]	M 102.964	05.1986 ▶ 03.1992			0.8	<b>246566</b>	C79
G 230 : 2.3 [W463]	M 102.989, M 102.998	08.1993 ▶ 10.1994			0.8	<b>246566</b>	C79
G 300 : 3.0 i [W463]	M 103.987	08.1993 ▶ 10.1994			0.8	<b>246566</b>	C79
G 320 : 3.2 [W463]	M 104.996	08.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
G 500 : 5.0 V8 [W463]	M 117.965	08.1993 ▶ 10.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
G230 : 2.3 [W460]	M 102.989	08.1993 ▶ 10.1994			0.8	<b>246566</b>	C79

### CLASSE S

260 : 2.6 SE [W126]	M 103.941	09.1985 ▶ 06.1991			0.8	<b>246566</b>	C79
280 : 2.8 S [W116]	M 110.922	01.1976 ▶ 07.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
280 : 2.8 S [W126]	M 110.924, M 110.926	12.1979 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
280 : 2.8 SE, SEL [W116]	M 110.985	08.1976 ▶ 07.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
280 : 2.8 SE, SEL [W126]	M 110.987, M 110.989	10.1979 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
300 : 3.0 SE, SEL [W126]	M 103.981	03.1987 ▶ 06.1991			0.8	<b>246566</b>	C79
300 : 3.2 SE, SEL [W140]	M 104.990	03.1991 ▶ 05.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
320 : 3.2 i SE, SEL [W140]	M 104.994	03.1991 ▶ 10.1998	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
350 : 3.5 SE, SEL [W116]	M 116.985	03.1976 ▶ 03.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
380 : 3.8 SE, SEL [W126]	M 116.961, M 116.963	12.1979 ▶ 08.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
380 : 3.8 SEC [C126]	M 116.961, M 116.963	12.1979 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
400 : 4.2 SE, SEL [W140]	M 119.971	02.1991 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
420 : 4.2 SE, SEL [W126]	M 116.965	09.1985 ▶ 06.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
420 : 4.2 SEC [C126]	M 116.965	09.1985 ▶ 06.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
420 SEC : 4.2 i V8 [C140]	M 119.981	03.1994 ▶ 09.1996	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
450 : 4.5 SE, SEL [W116]	M 117.986	12.1975 ▶ 04.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
450 : 6.9 SEL [W116]	M 100.985	07.1975 ▶ 03.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 : 5.0 SE, SEL [W126]	M 116.961, M 116.963	12.1979 ▶ 08.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 : 5.0 SEC [C126]	M 116.961, M 116.963	12.1979 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
500 : 5.0 i V8 32V SE, SEC, SEL [W140]	M 119.970	02.1991 ▶ 05.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
500 : 5.0 V8 SE, SEL [W126]	M 117.965	01.1988 ▶ 06.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 : 5.0 V8 SEC [C126]	M 117.965	09.1985 ▶ 06.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
560 : 5.6 SE, SEL [W126]	M 117.968 Cat	10.1985 ▶ 06.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
560 : 5.6 SEC [C126]	M 117.968 Cat	10.1985 ▶ 06.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
600 : 6.0 i V12 SE, SEL [W140]	M 120.980	04.1991 ▶ 12.1992	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
CL 420 : 4.2 i V8 [C140]	M 119.981	06.1996 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
CL 500 : 5.0 i V8 32V [C140]	M 119.980	06.1996 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
CL 600 : 6.0 i V12 [C140]	M 120.982	06.1996 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 280 : 2.8 i [W140]	M 104.944	06.1993 ▶ 09.1998	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 320 : 3.2 i [W140]	M 104.994	03.1991 ▶ 10.1998	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 420 : 4.2 [C140]	M 119.971	06.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 420 : 4.2 [W140]	M 119.971	06.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 420 : 4.2 i V8 [C140]	M 119.981	06.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 420 : 4.2 i V8 [W140]	M 119.981	06.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 500 : 5.0 i V8 32V [C140]	M 119.970, M 119.980	06.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 500 : 5.0 i V8 32V [W140]	M 119.970, M 119.980	02.1991 ▶ 05.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87


**MERCEDES** (.../...)

**CLASSE S (.../...)**

S 600 : 6.0 i V12 [C140]	M 120.980	06.1993 ▶ 02.1999	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
S 600 : 6.0 i V12, Coupé [W140]	M 120.980	06.1993 ▶ 09.1998	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

**CLASSE V**

V 200 : 2.0 i [638/2]	M 111.948	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
V 230 : 2.3 i Confort, Fashion, Trend [638/2]	M 111.978	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
V 280 : 2.8 i Fashion, Trend [638/2]	M 104.900	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**MODEL 100**

600 : 6.3 SE, SEL	M 100.980, M 100.982	09.1964 ▶ 05.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------------------	----------------------	-------------------	---------------	------	-----	---------------	-----

**MODEL 123**

200 : 2.0 [W123]	M 102.920, M 102.939	06.1980 ▶ 11.1985	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
200 : 2.0 [W123]	M 115.938	02.1976 ▶ 08.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
200 : 2.0 [W123]	M 115.938, M 115.939	02.1976 ▶ 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
200 : 2.0 T [S123]	M 102.920, M 102.939	11.1980 ▶ 11.1985			0.8	<b>246566</b>	C79
200 : 2.0 T [S123]	M 102.939	11.1980 ▶ 11.1985	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
230 : 2.3 C [C123]	M 115.954	02.1976 ▶ 03.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
230 : 2.3 CE [C123]	M 102.980	04.1980 ▶ 12.1985			0.8	<b>246566</b>	C79
230 : 2.3 E, TE [W123]	M 102.980	04.1980 ▶ 12.1985	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
230 : 2.3 T [S123]	M 115.954	02.1976 ▶ 03.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
250 : 2.5 [W123]	M 123.920, M 123.921	02.1976 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
250 : 2.5 T [S123]	M 123.920, M 123.921	02.1976 ▶ 07.1985	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
250 : 2.5 T [S123]	M 123.921	02.1976 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
280 : 2.8 C [C123]	M 110.923	02.1976 ▶ 08.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
280 : 2.8 CE [C123]	M 110.984, M 110.988	02.1976 ▶ 11.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
280 : 2.8 E, TE [W123]	M 110.984, M 110.988	02.1976 ▶ 11.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**MODEL 124**

200 : 2.0 [W124]	M 102.922 Cat	12.1984 ▶ 05.1990			0.8	<b>246566</b>	C79
200 : 2.0 CE Coupé [C124]	M 102.963	09.1988 ▶ 08.1992			0.8	<b>246566</b>	C79
200 : 2.0 E [W124]	M 102.963	09.1989 ▶ 06.1993	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
200 : 2.0 T [S124]	M 102.922 Cat	09.1985 ▶ 05.1990			0.8	<b>246566</b>	C79
200 : 2.0 TE [S124]	M 102.963	09.1988 ▶ 08.1992			0.8	<b>246566</b>	C79
200 : 2.0 i 16V CE Coupé [C124]	M 111.940	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
200 : 2.0 i 16V E [W124]	M 111.940	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
200 : 2.0 i 16V TE [S124]	M 111.940	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
220 : 2.2 i CE Coupé [C124]	M 111.960	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
220 : 2.2 i TE [S124]	M 111.960	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
230 : 2.3 CE Coupé [C124]	M 102.982 Cat	12.1984 ▶ 08.1992			0.8	<b>246566</b>	C79
230 : 2.3 E [W124]	M 102.982 Cat	12.1984 ▶ 08.1992			0.8	<b>246566</b>	C79
230 : 2.3 TE [S124]	M 102.982 Cat	12.1984 ▶ 08.1992	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
260 : 2.6 E [W124]	M 103.940 Cat	09.1985 ▶ 08.1992			0.8	<b>246566</b>	C79
260 : 2.6 E 4Matic [W124]	M 103.943	09.1986 ▶ 08.1992			0.8	<b>246566</b>	C79
280 : 2.8 E [W124]	M 104.942	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
280 : 2.8 TE [S124]	M 104.942	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
300 : 3.0 CE [C124]	M 103.983	09.1985 ▶ 06.1993			0.8	<b>246566</b>	C79
300 : 3.0 E [W124]	M 103.980	01.1985 ▶ 08.1985			0.8	<b>246566</b>	C79
300 : 3.0 E [W124]	M 103.983	09.1985 ▶ 06.1993			0.8	<b>246566</b>	C79
300 : 3.0 E 4Matic [W124]	M 103.985	09.1986 ▶ 06.1993			0.8	<b>246566</b>	C79
300 : 3.0 TE [S124]	M 103.983	09.1985 ▶ 06.1993			0.8	<b>246566</b>	C79
300 : 3.0 TE 4Matic [S124]	M 103.985	09.1986 ▶ 06.1993			0.8	<b>246566</b>	C79
300 : 3.0 24V CE 24 [A124]	M 104.980	09.1989 ▶ 12.1992	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
300 : 3.0 24V CE 24 [C124]	M 104.980	09.1989 ▶ 08.1992	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
300 : 3.0 24V E 24 [W124]	M 104.980	09.1989 ▶ 08.1992	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
300 : 3.0 24V TE 24 [S124]	M 104.980	09.1989 ▶ 08.1992	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
320 : 3.2 i CE [C124]	M 104.992	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
320 : 3.2 i E [W124]	M 104.992	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
320 : 3.2 i TE [S124]	M 104.992	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
400 : 4.2 E [W124]	M 119.975	09.1991 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
500 : 5.0 i E [W124]	M 119.974	01.1991 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

**SÉRIE CLK**

CLK 200 : 2.0 i, Elegance, Sport [C208]	M 111.944 kompressor	06.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
CLK 200 : 2.0 i 16V, Elegance, Sport [C208]	M 111.945	06.1997 ▶	<b>246486</b>	RF74HZ3YE	0.8	<b>246554</b>	F87
CLK 230 : 2.3 i, Elegance, Sport [C208]	M 111.975 kompressor	06.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**SL**

280 SL : 2.8 [R107]	M 110.982, M 110.986, M 110.990	06.1976 ▶ 07.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
280 SLC : 2.8 [C107]	M 110.982, M 110.986, M 110.990	06.1976 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
300 SL : 3.0 [R107]	M 103.982	09.1985 ▶ 08.1989			0.8	<b>246566</b>	C79





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MERCEDES (.../...)

### SL (.../...)

300 SL : 3.0 [R129]	M 103.984	03.1989 ▶ 08.1993			0.8	<b>246566</b>	C79
300 SL : 3.0 24 [R129]	M 104.981	03.1989 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
350 SL : 3.5 [R107]	M 116.982, M 116.984	03.1976 ▶ 02.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
350 SLC : 3.5 [C107]	M 116.982, M 116.984	03.1976 ▶ 02.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
380 SL : 3.8 [R107]	M 116.960, M 116.962	07.1980 ▶ 08.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
380 SLC : 3.8 [C107]	M 116.960, M 116.962	07.1980 ▶ 08.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
420 : 4.2 SL [R107]	M 116.964	01.1986 ▶ 08.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
450 SL : 4.5 [R107]	M 117.982, M 117.985	12.1975 ▶ 10.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
450 SLC : 4.5 [C107]	M 117.982, M 117.985	12.1975 ▶ 10.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
450 SLC : 5.0 [C107]	M 117.960	06.1978 ▶ 02.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 SL : 5.0 [R107]	M 117.960, M 117.962	05.1980 ▶ 12.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 SL : 5.0 [R107]	M 117.962	05.1980 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
500 SL : 5.0 [R107]	M 117.964	01.1986 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
500 SL : 5.0 [R129]	M 119.960	03.1989 ▶ 08.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
500 SL : 5.0 i V8 32V [R129]	M 119.972	09.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
500 SLC : 5.0 [C107]	M 117.962	05.1980 ▶ 12.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
500 SLC : 5.0 [C107]	M 117.964	01.1988 ▶ 08.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
600 : 6.0 SL [R129]	M 120.981	07.1992 ▶ 06.1993	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
SL 280 : 2.8 [R129]	M 104.943	08.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
SL 320 : 3.2 i V6 24V [R129]	M 104.991	07.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
SL 320 : 3.2 i V6 24V [R129]	M 104.991	07.1997 ▶ 05.1998	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
SL 500 : 5.0 i V8 32V [R129]	M 119.972, M 119.982	07.1993 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

### SLK

SLK 200 : 2.0 [R170]	M 111.946	07.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
SLK 200 : 2.0 [R170]	M 111.946	08.1996 ▶ 06.1997	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
SLK 200 : 2.0 Kompressor [R170]	M 111.943 kompressor	08.1996 ▶ 02.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
SLK 230 : 2.3 Kompressor [R170]	M 111.973 kompressor	08.1996 ▶ 02.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

### VANEO

1.6 i	M 166.961 Cat	02.2002 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.9 i	M 166.991	02.2002 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

## MERCEDES

### L, LF, LM

L 207, L 307 : 2.0	Austin A70	03.1973 ▶ 07.1977	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
L 409 : 2.3	M 115.952	01.1975 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
L 410 : 2.3	M 102.943	08.1982 ▶ 12.1988			0.8	<b>246566</b>	C79
LF 409 G : 2.3	M 115.970	01.1975 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
LK 409 : 2.3	M 115.952	01.1975 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
LM 409 : 2.3	M 115...	01.1975 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### SÉRIE O

O 309 : 2.3	M 102.943	08.1982 ▶ 02.1989			0.8	<b>246566</b>	C79
O 309 B : 2.3	M 115.928	08.1972 ▶ 12.1974	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
O 309 B : 2.3	M 115.952	01.1975 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### SPRINTER 2T

214 : 2.3 i	M 111.979	02.1995 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
-------------	-----------	-----------	---------------	-------	-----	---------------	-----

### SPRINTER 3T

314 : 2.3 i	M 111.979	02.1995 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
-------------	-----------	-----------	---------------	-------	-----	---------------	-----

### SPRINTER 4T

414 : 2.3 i	M 111.979	02.1995 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
-------------	-----------	-----------	---------------	-------	-----	---------------	-----

### T1 UTILITAIRE 2T

208 : 2.3	M 102.942, M 102.945				0.8	<b>246566</b>	C79
208 : 2.3	M 115.955, M 115.972	05.1977 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
210 : 2.3	M 102.942, M 102.945	08.1982 ▶ 06.1995			0.8	<b>246566</b>	C79
210 : 2.3	M 115.955, M 115.972		<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### T1 UTILITAIRE 3T

308 : 2.3	M 102.942, M 102.945				0.8	<b>246566</b>	C79
308 : 2.3	M 115.955, M 115.972	05.1977 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
309 : 2.3	M 102...	08.1992 ▶			0.8	<b>246566</b>	C79
310 : 2.3	M 102.942, M 102.945	08.1982 ▶ 06.1995			0.8	<b>246566</b>	C79
310 : 2.3	M 115.972	05.1977 ▶ 08.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### T1 UTILITAIRE 4T

409 : 2.3	M 115...		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
410 : 2.3	M 102...	09.1991 ▶			0.8	<b>246566</b>	C79
410 : 2.3	M 102.902, M 102.942, M 102.945	08.1982 ▶ 08.1991			0.8	<b>246566</b>	C79

### T2/LN1

510 : 2.3	M 102...	09.1991 ▶			0.8	<b>246566</b>	C79
-----------	----------	-----------	--	--	-----	---------------	-----





3+1


**MERCEDES** (.../...)

**T2/LN1 (.../...)**

 510 : 2.3 M 102.946 04.1986 ▶ 08.1991 0.8 **246566** C79

**VITO**

 113 : 2.0 i M 111.948 11.1995 ▶ **246490** RF82HZZY 1.0 **246554** F87

 114 : 2.3 i M 111.978 11.1995 ▶ **246490** RF82HZZY 1.0 **246554** F87

**MERCURY**
**CAPRI**

 1.6 i Turbo 09.1990 ▶ **246186** RF82H 0.8 **246554** F87

**LYNX**

 1.6 i Turbo (8) **246191** RC72H 0.7 **246566** C79

**TRACER**

 1.8 i 16V (8) 09.1990 ▶ **246186** RF82H 0.8 **246554** F87

**VILLAGER**

 3.0 i VG30E 09.1992 ▶ 0.7 **246556** F87-11

**MG-ROVER**
**MAESTRO**

 1.6 R Series TC **246198** R70H 0.8 **246557** H60

 1.6 S Series TC **246173** RF74H 0.8 **246554** F87

 2.0 i O Series **246198** R70H 0.8 **246557** H60

 2.0 Turbo T O Series Turbo **246198** R70H 0.8 **246557** H60

**METRO**

 1.3 A Series **246179** R76H 0.8 **246555** H79

 1.3 Turbo T A Series **246198** R70H 0.8 **246557** H60

**MGB**

 1.8 GT, Sport B Series TC 01.1961 ▶ 12.1981 **246179** R76H 0.8 **246555** H79

 3.5 V8 GT 01.1974 ▶ 12.1976 **246189** R88N 0.8

**MIDGET**

 1.3 i MK II A Series TC **246179** R76H 0.8 **246555** H79

 1500 : 1.5 Triumph TC **246181** R90H 0.8

**MONTEGO**

 2.0 i O Series **246198** R70H 0.8 **246557** H60

 2.0 Turbo O Series Turbo **246198** R70H 0.8 **246557** H60

**MITSUBISHI**
**A81P, A81V, A82V, A82O**
**246179** R76H 0.8 **246555** H79

**AIR TREK**

 2.0 i 16V 4G63 [DOHC] Cat 06.2001 ▶ **246198** R70H 0.8 **246557** H60

**CANTER**

 2.0 i 16V 4G63 [SOHC] Cat 09.1996 ▶ **246179** R76H 0.8 **246555** H79

 2.4 4G53 ▶ 12.1980 **246180** R84H 0.8 **246555** H79

 2.4 FC-35B 4G53 **246179** R76H 0.8 **246555** H79

 2.6 FC-35B 4G54 01.1980 ▶ **246179** R76H 0.8 **246555** H79

 55 : 2.6 4G54 01.1982 ▶ **246179** R76H 0.8 **246555** H79

**CARISMA**

 1.6 i 16V 4G92 [SOHC] Cat 05.1995 ▶ **246332** RF74H11 1.1 **246556** F87-11

 1.8 i 4G93 [SOHC] Cat 05.1995 ▶ **246332** RF74H11 1.1 **246556** F87-11

 1.8 i 16V 4G93 [DOHC] Cat 05.1995 ▶ 1.1 **246556** F87-11

 1.8 i 16V Elegance 4G93 GDI 09.1997 ▶ 1.1 **246556** F87-11

**CELESTE**

 1.4 ▶ 12.1981 **246180** R84H 0.8 **246555** H79

 1.6 GSR, ST 4G32 1 carburator **246180** R84H 1.1 **246555** H79

 1.6 GSR, ST 4G32 2 carburator **246179** R76H 1.1 **246555** H79

 2.0 4G52 ▶ 05.1980 **246179** R76H 0.8 **246555** H79

**CHALLENGER**

 2.4 i 16V 4G64 [SOHC] Cat 07.1996 ▶ 1.1 **246556** F87-11

 3.0 i 24V 6G 72 [DOHC] 07.1996 ▶ 08.1998 1.1 **246556** F87-11

**CHARIOT GRANDIS**

 1.8 i G37B 06.1984 ▶ 05.1991 1.1 **246564** H79-11

 2.0 G63B 06.1984 ▶ 05.1991 1.1 **246564** H79-11

 2.0 i 4G63 [SOHC] Cat 05.1991 ▶ 10.1997 1.1 **246564** H79-11

 2.0 i 16V 4G63 [DOHC] Cat 05.1991 ▶ 10.1997 **246198** R70H 0.8 **246557** H60

 2.4 i 16V 4G64 [SOHC] Cat 05.1993 ▶ 10.1997 1.1 **246556** F87-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MITSUBISHI (.../...)

Model	Engine	Year	Part No.	Thread	Gap	Part No.	Part No.
1.2	4G11	07.1980 ▶ 04.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2	4G16	11.1983 ▶ 04.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.2 GL	G11B	09.1979 ▶ 06.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	4G13	04.1988 ▶ 08.1990			1.1	<b>246564</b>	H79-11
1.3	G13B Cat	06.1986 ▶ 04.1988			1.1	<b>246564</b>	H79-11
1.3 i 12V	4G13 [SOHC] Cat	12.1991 ▶			1.1	<b>246564</b>	H79-11
1.4	4G12	07.1980 ▶ 10.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 GLX, GT	G33B	09.1979 ▶ 06.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 Turbo	4G12 T	06.1980 ▶ 12.1983	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.5	4G15	11.1983 ▶ 04.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5	G15B Cat	01.1984 ▶ 04.1988			1.1	<b>246564</b>	H79-11
1.5	G31B	01.1984 ▶ 04.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5 i	4G15	04.1988 ▶ 05.1992			1.1	<b>246564</b>	H79-11
1.5 i	4G15 Cat	04.1988 ▶ 05.1992			1.1	<b>246564</b>	H79-11
1.5 i 16V	4G15 [DOHC] Cat	03.1996 ▶			1.1	<b>246564</b>	H79-11
1.6 i 16V	4G61 [DOHC] Cat	04.1988 ▶ 05.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 i 16V	4G92 [SOHC] Cat	07.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4x4	4G92 [DOHC] Cat	12.1991 ▶ 05.1996			1.1	<b>246556</b>	F87-11
1.6 i Turbo	4G32 T/C	09.1983 ▶ 06.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 i Turbo	G32B T Cat	07.1986 ▶ 04.1988	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.8 i 16V	4G67 [DOHC] Cat	09.1989 ▶ 05.1992			1.1	<b>246564</b>	H79-11
1.8 i 16V	4G93 [DOHC] Cat	12.1991 ▶ 05.1996			1.1	<b>246556</b>	F87-11
1.8 i 16V Turbo	4G93 T [DOHC] Cat	03.1996 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

## CORDIA

1.6 Turbo	4G32 T	09.1982 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	4G37	09.1986 ▶ 08.1988	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.8 i Turbo	G62B	10.1986 ▶			1.1	<b>246557</b>	H60

## DEBONAIR

2.6	4G54	01.1977 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	------	-------------------	---------------	------	-----	---------------	-----

## DEBONAIR V

2.0 i V6	6G 71	07.1986 ▶ 09.1992			1.1	<b>246564</b>	H79-11
3.0 i 24V	6G 72 [DOHC]	10.1989 ▶ 09.1992			1.1	<b>246556</b>	F87-11
3.0 i V6	6G 72 [SOHC]	09.1988 ▶			1.1	<b>246564</b>	H79-11
3.0 i V6	6G 72 [SOHC]	09.1988 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79

## DELICA

1.4	G33B	10.1982 ▶ 05.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	G32B	10.1980 ▶ 05.1994			1.1	<b>246564</b>	H79-11
1.6 i 16V	4G92 [DOHC] Cat	05.1994 ▶			1.1	<b>246556</b>	F87-11
2.0	FEE	09.1999 ▶			1.1	<b>246556</b>	F87-11
2.0	G63B	12.1983 ▶			1.1	<b>246564</b>	H79-11
2.0 i	4G63 [SOHC] Cat	05.1994 ▶			1.1	<b>246564</b>	H79-11
2.4 i	4G64 [SOHC] Cat	08.1989 ▶ 05.1994			1.1	<b>246564</b>	H79-11
2.4 i 16V	4G64 [SOHC] Cat	05.1994 ▶			1.1	<b>246556</b>	F87-11
3.0 i 24V	6G 72 [DOHC]	05.1994 ▶			1.1	<b>246556</b>	F87-11

## DIAMANTE

2.0 i V6	6G 71	05.1990 ▶ 09.1992			1.1	<b>246564</b>	H79-11
3.0 i 24V	6G 72 [DOHC]	01.1990 ▶			1.1	<b>246556</b>	F87-11
3.0 i V6	6G 72 [SOHC]	01.1990 ▶			1.1	<b>246564</b>	H79-11

## ECLIPSE

2.0 i 16V	4G63 [DOHC] Cat	02.1990 ▶ 06.1995	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 i 16V	4G63 [SOHC] Cat	02.1990 ▶ 06.1995	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 16V 4x4	4G63 [DOHC] Cat	04.1991 ▶ 10.1995			1.1	<b>246564</b>	H79-11
2.0 i 16V 4x4	4G63 [DOHC] Cat	04.1991 ▶ 10.1995	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

## EMERAUDE

1.8 i 16V	4G93 [DOHC] Cat	10.1994 ▶ 08.1996			1.1	<b>246556</b>	F87-11
1.8 i 16V	4G93 [SOHC] Cat	11.1992 ▶ 08.1996			1.1	<b>246556</b>	F87-11

## EXPO

1.8 i	4G93 [SOHC] Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11
2.4 i	4G64 [SOHC] Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11

## FORTE

1.6	G32B	12.1982 ▶			1.1	<b>246564</b>	H79-11
2.0	G63B	12.1982 ▶			1.1	<b>246564</b>	H79-11

## FTO

1.8 i 16V	4G93 [SOHC] Cat	10.1994 ▶			1.1	<b>246556</b>	F87-11
-----------	-----------------	-----------	--	--	-----	---------------	--------


**MITSUBISHI** (.../...)

**GALANT**

1.6	4G32	06.1984 ▶ 10.1987	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.6 MCA	4G32	01.1974 ▶ 04.1980	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.7 GS	4G35	01.1973 ▶ 04.1980	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 5 SL	4G51	05.1976 ▶ 04.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	4G63 [SOHC]	05.1980 ▶ 05.1984	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0	4G63 [SOHC]	05.1980 ▶ 05.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	G63B Cat	06.1986 ▶ 11.1987			1.1	<b>246564</b>	H79-11
2.0 GL, GLS, GLX	4G52	01.1973 ▶ 04.1980			1.1	<b>246564</b>	H79-11
2.4 i	G64B Cat	07.1985 ▶ 02.1988			1.1	<b>246564</b>	H79-11

**GALANT, ASPIRE, ETERNA, CAVA**

1.6	4G32	10.1987 ▶ 10.1992			1.1	<b>246564</b>	H79-11
1.8 Hatchback	4G37	11.1987 ▶ 10.1992			1.1	<b>246564</b>	H79-11
1.8 i	4G37 Cat	10.1989 ▶ 10.1992			1.1	<b>246564</b>	H79-11
1.8 i	4G93 [SOHC] Cat	11.1992 ▶ 05.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i Hatchback	4G37 Cat	11.1987 ▶ 05.1990			1.1	<b>246564</b>	H79-11
1.8 i 16V	4G67 [DOHC] Cat	04.1989 ▶ 05.1992			1.1	<b>246564</b>	H79-11
1.8 i 16V	4G93 [DOHC] Cat	10.1994 ▶ 08.1996			1.1	<b>246556</b>	F87-11
1.8 i 16V	4G93 GDI	08.1998 ▶ 05.2000			1.1	<b>246556</b>	F87-11
2.0 i	4G63 [SOHC]	11.1987 ▶ 10.1992	<b>246198</b>	R70H	1.1	<b>246557</b>	H60
2.0 i 4WD, 4WS, Hatchback	4G63 [SOHC] Cat	06.1990 ▶ 10.1992			1.1	<b>246564</b>	H79-11
2.0 i 16V	4G63 [SOHC] Cat	10.1996 ▶			1.1	<b>246564</b>	H79-11
2.0 i 16V, 4WD, Hatchback	4G63 [DOHC] Cat	11.1987 ▶ 10.1992	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 i 16V 4WD	4G63 [SOHC] Cat	11.1992 ▶ 05.1996	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	4G64 [DOHC] Cat	01.1994 ▶			1.1	<b>246564</b>	H79-11
2.4 i	4G64 [SOHC] Cat	01.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.5 i 24V 4WD	4G73 [DOHC] Cat	11.1992 ▶ 05.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i 24V	6G 72 [SOHC] Cat	▶ 10.1992			1.1	<b>246564</b>	H79-11

**GALANT, ETERNA SIGMA**

1.6 GL, GS, SL	4G32	05.1976 ▶ 04.1980	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.8 5 GL, SL	G51B	08.1977 ▶ 04.1980			1.1	<b>246564</b>	H79-11
1.8 i	G37B	09.1983 ▶ 05.1989			1.1	<b>246564</b>	H79-11
1.8 i	G62B	02.1988 ▶ 05.1990			1.1	<b>246564</b>	H79-11
2.0	G63B	09.1983 ▶ 11.1990			1.1	<b>246564</b>	H79-11
2.0	G63B Cat	09.1983 ▶			1.1	<b>246564</b>	H79-11
2.0 GL, GLX, GSL	G52B	08.1977 ▶ 04.1980			1.1	<b>246564</b>	H79-11
2.0 GLX	4G52	05.1976 ▶ 04.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 GSR	4G52	05.1976 ▶ 04.1980			0.8	<b>246564</b>	H79-11
2.0 i V6	6G 71	10.1986 ▶ 11.1990			1.1	<b>246564</b>	H79-11
3.0 V6	6G 72	10.1986 ▶ 11.1990			1.1	<b>246564</b>	H79-11

**GALLOPER**

3.0 i V6	G6AT	01.1998 ▶			1.1	<b>246564</b>	H79-11
----------	------	-----------	--	--	-----	---------------	--------

**GTO**

3.0 i 24V	6G 72 [DOHC]	10.1990 ▶			1.1	<b>246556</b>	F87-11
3.0 i V6 24V Tu	6G 72 Twin [DOHC]	10.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**JEEP**

2.0	4G52	01.1975 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.6	4G53	01.1982 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**JUPITER**

T33, T41			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
----------	--	--	---------------	------	-----	---------------	-----

**L 200**

1.6	4G32	11.1986 ▶ 03.1995			1.1	<b>246564</b>	H79-11
2.0 4WD	4G63 [SOHC]	11.1986 ▶ 05.1995	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	4G64 [SOHC] Cat	06.1990 ▶ 11.1997			1.1	<b>246564</b>	H79-11
2.6 i 4WD	4G54 B Cat	11.1989 ▶ 05.1995			1.1	<b>246564</b>	H79-11
3.0 i V6 4WD	6G 72 [SOHC] Cat	06.1990 ▶ 05.1991			1.1	<b>246564</b>	H79-11

**L 300**

1.4	4G33	01.1994 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	4G32	05.1980 ▶			1.1	<b>246564</b>	H79-11
1.6 4x4	G32B	06.1986 ▶ 10.1986			1.1	<b>246564</b>	H79-11
1.8 4x4	4G62	04.1983 ▶ 12.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 4x4	4G63 [SOHC]	11.1986 ▶ 06.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 16V	4G63 [SOHC] Cat	06.1994 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	4G63 [SOHC] Cat	06.1994 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i 4x4	4G64 [SOHC] Cat	11.1986 ▶			1.1	<b>246564</b>	H79-11
2.4 i 4x4	G64B Cat	11.1986 ▶ 10.1988			1.1	<b>246564</b>	H79-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания




3+1



## MITSUBISHI (.../...)

<b>L 400</b>									
2.0 i 16V	4G63 [DOHC] Cat					0.8	<b>246556</b>	F87-11	
2.4 i	4G64 [SOHC] Cat	01.1995 ▶				1.1	<b>246556</b>	F87-11	
<b>LANCER</b>									
1.2	4G11	08.1979 ▶ 10.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.2	4G16	09.1984 ▶ 04.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.2	4G16	11.1983 ▶ 08.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.2 E, EL, SL	4G42	01.1973 ▶ 07.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.2 GL	4G36	01.1976 ▶ 07.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.3	4G13	04.1988 ▶ 10.1991			1.1	<b>246564</b>	H79-11		
1.3	4G13 Cat	04.1988 ▶ 07.1995			1.1	<b>246564</b>	H79-11		
1.3	4G13 Cat	04.1988 ▶ 07.1995	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.3, Fiore	G13B	02.1985 ▶ 06.1992			1.1	<b>246564</b>	H79-11		
1.3 i 12V	4G13 [SOHC] Cat	05.1992 ▶			1.1	<b>246564</b>	H79-11		
1.3 i 12V	G13B	01.1983 ▶ 09.1992			1.1	<b>246564</b>	H79-11		
1.3 i 12V GLi	4G13 [SOHC] Cat	09.1992 ▶ 05.1996			1.1	<b>246564</b>	H79-11		
1.3 i 12V GLi, GLX	4G13 [SOHC] Cat	10.1995 ▶			1.1	<b>246564</b>	H79-11		
1.4	4G12	08.1979 ▶ 10.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.4 GL	G12B	01.1979 ▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.4 GL	G12B	01.1979 ▶ 12.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.4 GL, SL, GLX	4G33	01.1973 ▶ 03.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.5	G15B Cat	11.1983 ▶ 08.1990	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.5 12V	4G15	06.1992 ▶			1.1	<b>246564</b>	H79-11		
1.5 12V Station Wagon, Fiore	G15B Cat	06.1985 ▶ 05.1992			1.1	<b>246564</b>	H79-11		
1.5 i	4G15 Cat	04.1988 ▶ 10.1991	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.5 i	G15B	06.1985 ▶ 04.1988			1.1	<b>246564</b>	H79-11		
1.5 i Hatchback	4G15 Cat	05.1989 ▶ 10.1991	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.6	4G32	08.1979 ▶ 08.1984	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.6 GL, GSL, GSR	4G32	11.1976 ▶ 07.1979	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.6 i 16V	4G92 [SOHC] Cat	11.1995 ▶			1.1	<b>246564</b>	H79-11		
1.6 i 16V Hatchback	4G61 [DOHC] Cat	04.1988 ▶ 09.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.6 i 16V Hatchback, 4WD	4G92 [DOHC] Cat	05.1992 ▶			1.1	<b>246556</b>	F87-11		
1.8 i Hatchback 4WD	4G37 Cat	05.1989 ▶ 05.1992			1.1	<b>246564</b>	H79-11		
1.8 i Station Wagon 4WD	4G37 Cat	11.1986 ▶ 05.1992	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.8 i Station Wagon 4WD	G37B	06.1986 ▶ 09.1989			1.1	<b>246564</b>	H79-11		
1.8 i Station Wagon 4WD	G37B	06.1986 ▶ 09.1989	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.8 i 16V	4G67 [DOHC] Cat	11.1989 ▶ 05.1992	<b>246179</b>	R76H	1.1	<b>246555</b>	H79		
1.8 i 16V	4G93 [DOHC] Cat	05.1992 ▶ 11.1995			1.1	<b>246556</b>	F87-11		
1.8 i 16V	4G93 [SOHC] Cat	06.1992 ▶ 10.1996			1.1	<b>246556</b>	F87-11		
1.8 i 16V Hatchback	4G93 [DOHC] Cat	06.1992 ▶ 10.1995			1.1	<b>246556</b>	F87-11		
2.0 i 16V	4G63 [DOHC] Cat	10.1991 ▶ 01.1994	<b>246198</b>	R70H	0.8	<b>246557</b>	H60		
<b>LANCER SEDEIA / CEDIA</b>									
1.8 i 16V	4G93 GDI	05.2000 ▶			1.1	<b>246556</b>	F87-11		
<b>LEGNUM</b>									
1.8 i 16V	4G93 GDI	08.1996 ▶ 05.2000			1.1	<b>246556</b>	F87-11		
<b>LIBERO</b>									
1.3 i 16V	4G13 Cat	05.1992 ▶			1.1	<b>246556</b>	F87-11		
1.6 i 16V	4G92 [DOHC] Cat	10.1996 ▶			1.1	<b>246556</b>	F87-11		
1.8 i 16V	4G93 [DOHC] Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11		
1.8 i 16V	4G93 [SOHC] Cat	05.1992 ▶			1.1	<b>246556</b>	F87-11		
<b>MAGNA</b>									
2.4 i 16V, Wagon	4G64 [SOHC] Cat	01.1996 ▶			1.1	<b>246556</b>	F87-11		
2.6	4G54	08.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
3.0 i 24V, Wagon	6G 72 [SOHC] Cat	01.1996 ▶			1.1	<b>246564</b>	H79-11		
<b>MINICA</b>									
500 : 0.5	G23B	10.1984 ▶ 12.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
550 : 0.55 5	3G 81 [SOHC]	01.1989 ▶ 09.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
660	3G 83 [SOHC]	01.1989 ▶ 09.1993			1.1	<b>246564</b>	H79-11		
<b>MINICAB BRAVO</b>									
0.55	3G 81 [SOHC]	08.1987 ▶ 02.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
<b>MIRAGE</b>									
1.2	G11B		<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.3	G13B Cat	09.1983 ▶ 10.1992			1.1	<b>246564</b>	H79-11		
1.3 i 16V	4G13 Cat	10.1987 ▶ 10.1995			1.1	<b>246556</b>	F87-11		
1.4	G12B		<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
1.4 Turbo	4G12 T				0.8	<b>246564</b>	H79-11		



3+1


**MITSUBISHI** (.../...)

**MIRAGE (.../...)**

1.5	G15B			<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.5	G15B Cat	09.1983 ▶ 05.1992				1.1	<b>246564</b>	H79-11
1.5 i	4G15 Cat	10.1987 ▶ 10.1991				1.1	<b>246564</b>	H79-11
1.6 i 16V	4G61 [DOHC] Cat	10.1987 ▶ 10.1991		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 i 16V	4G92 [DOHC] Cat	10.1991 ▶ 10.1995				1.1	<b>246556</b>	F87-11
1.6 Turbo	G32B T			<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 i	4G93 [SOHC] Cat	10.1995 ▶				1.1	<b>246556</b>	F87-11
1.8 i	G37B	09.1986 ▶ 10.1990				1.1	<b>246564</b>	H79-11

**MIRAGE DINGO**

1.3 i 16V	4G13 Cat	01.2000 ▶				1.1	<b>246556</b>	F87-11
1.8 i 16V	4G93 GDI	02.2000 ▶				1.1	<b>246556</b>	F87-11

**MONTERO**

1.8 i 16V	4G93 GDI	06.1998 ▶				1.1	<b>246556</b>	F87-11
2.0	G63B			<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.4 i	4G64 [SOHC] Cat	12.1990 ▶ 09.1999				1.1	<b>246564</b>	H79-11
2.4 i 16V	4G64 [SOHC] Cat	09.1997 ▶				1.1	<b>246564</b>	H79-11
2.6	4G54	09.1984 ▶ 11.1990		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.6	4G54	12.1982 ▶ 08.1984		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.6	G54B Cat	06.1986 ▶ 11.1990				1.1	<b>246564</b>	H79-11
2.6	G54B Cat	12.1982 ▶ 05.1986		<b>246179</b>	R76H	1.1	<b>246555</b>	H79
3.0 i 24V 12V	6G 72 [SOHC] Cat	09.1997 ▶				1.1	<b>246564</b>	H79-11
3.0 V6	6G 72					1.1	<b>246564</b>	H79-11

**PAJERO**

1.8 i 16V	4G93 GDI	06.1998 ▶				1.1	<b>246556</b>	F87-11
2.0	G63B			<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.4 i	4G64 [SOHC] Cat	12.1990 ▶ 09.1999				1.1	<b>246564</b>	H79-11
2.4 i 16V	4G64 [SOHC] Cat	09.1997 ▶				1.1	<b>246564</b>	H79-11
2.6	4G54	09.1984 ▶ 11.1990		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.6	4G54	12.1982 ▶ 08.1984		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.6	G54B Cat	06.1986 ▶ 11.1990				1.1	<b>246564</b>	H79-11
2.6	G54B Cat	12.1982 ▶ 05.1986		<b>246179</b>	R76H	1.1	<b>246555</b>	H79
3.0 i 24V 12V	6G 72 [SOHC] Cat	09.1997 ▶				1.1	<b>246564</b>	H79-11
3.0 i V6	6G 72 [SOHC]	11.1988 ▶ 11.1990				1.1	<b>246564</b>	H79-11
3.0 i V6	6G 72 [SOHC] Cat	12.1990 ▶ 09.1999				1.1	<b>246564</b>	H79-11

**ROSA**

2.4	4G53			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	------	--	--	---------------	------	-----	---------------	-----

**RVR**

1.8 i 16V	4G93 [DOHC] Cat	07.1991 ▶ 11.1997				1.1	<b>246556</b>	F87-11
1.8 i 16V	4G93 GDI	11.1997 ▶				1.1	<b>246556</b>	F87-11
2.0 i 16V	4G63 [DOHC] Cat	07.1991 ▶ 11.1997		<b>246198</b>	R70H	0.8	<b>246557</b>	H60

**SAPPORO**

1.6	4G32	03.1981 ▶ 11.1984				1.1	<b>246564</b>	H79-11
1.6 GL, SL	4G32	▶ 02.1981		<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0	4G63 [SOHC]	03.1981 ▶ 11.1984		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	4G63 [SOHC]	03.1981 ▶ 11.1984		<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 GL, GLS, GSR	4G52	11.1976 ▶ 05.1980		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 GSR	4G63 GS	03.1981 ▶ 11.1984		<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.4 i	4G64 [SOHC]	06.1987 ▶ 08.1988				1.1	<b>246564</b>	H79-11
2.4 i	4G64 [SOHC] Cat	09.1988 ▶				1.1	<b>246557</b>	H60

**SHOGUN**

2.6	4G54	12.1982 ▶ 08.1990		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	------	-------------------	--	---------------	------	-----	---------------	-----

**SIGMA**

2.0 i V6	6G 71	10.1990 ▶				1.1	<b>246564</b>	H79-11
----------	-------	-----------	--	--	--	-----	---------------	--------

**SPACE GEAR**

2.0 i 16V	4G69	01.1997 ▶				1.1	<b>246556</b>	F87-11
2.0 i 16V Van	4G63 [SOHC] Cat	12.1994 ▶				0.8	<b>246556</b>	F87-11
2.4 i 16V 4WD, Van 4WD	4G64 [SOHC] Cat	12.1994 ▶				1.1	<b>246556</b>	F87-11

**SPACE RUNNER**

1.8 i GLi, GLXi, GLXi 4x4	4G93 [SOHC] Cat	06.1991 ▶		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V GLXi	4G93 [SOHC] Cat	06.1991 ▶ 05.1992		<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
2.0 i 16V	4G63 [SOHC] Cat	01.1999 ▶		<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**SPACE STAR**

1.3 i 16V	4G13 Cat	06.1998 ▶				1.1	<b>246556</b>	F87-11
-----------	----------	-----------	--	--	--	-----	---------------	--------

**SPACE WAGON**

1.6	4G32 B	01.1984 ▶		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	--------	-----------	--	---------------	------	-----	---------------	-----





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## MITSUBISHI (.../...)

### SPACE WAGON (.../...)

1.8	4G37	10.1983 ▶ 04.1991	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.8 i	4G93 [SOHC] Cat	05.1991 ▶ 05.1992	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
1.8 i 16V 4WD	4G93 [SOHC] Cat	05.1991 ▶ 05.1992			1.1	<b>246556</b>	F87-11
1.8 i Turbo	4G62 T ECI	01.1984 ▶ 09.1985	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 4WD	4G63 [SOHC]	06.1988 ▶ 04.1991	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 4WD	G63B	03.1985 ▶ 04.1991			1.1	<b>246564</b>	H79-11
2.0 4WD	G63B Cat	03.1985 ▶ 04.1991			1.1	<b>246564</b>	H79-11
2.0 i 16V 4WD	4G63 [SOHC] Cat	06.1992 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i 16V	4G64 [SOHC] Cat	06.1992 ▶			1.1	<b>246556</b>	F87-11

### STARION

2.6 i Turbo Intercooler	G54B Cat	06.1986 ▶ 05.1990			1.1	<b>246564</b>	H79-11
-------------------------	----------	-------------------	--	--	-----	---------------	--------

### TREDIA

1.4	4G12	12.1982 ▶ 08.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	4G33	09.1982 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.4	G21B	09.1982 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5	4G15	09.1984 ▶ 10.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	4G32	10.1982 ▶ 08.1984			1.1	<b>246564</b>	H79-11
1.6 Turbo	4G32 T	10.1982 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 4WD	4G37	09.1984 ▶ 09.1987			1.1	<b>246564</b>	H79-11
2.0 4WD	G63B	09.1986 ▶			1.1	<b>246564</b>	H79-11

## MORGAN

### 4 4

1.6 1600	[DOHC]		<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 1600	[OHC]		<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.6 1600	[OHV]		<b>246198</b>	R70H	0.8	<b>246557</b>	H60

### PLUS EIGHT

3.5 i V8			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.5 V8		01.1969 ▶ 12.1977	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.9 i V8			<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### PLUS FOUR

2.0	132 C 3000		<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.0 i 16V	M16 i, T16 i [DOHC]		<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

## MOSKVITCH

### 2140

1.5		11.1974 ▶ 12.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-----	--	-------------------	---------------	------	-----	---------------	-----

### 2141, ALEKO

1.5		12.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5		12.1986 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6		12.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6		12.1986 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8		12.1986 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60

### 412, 427, 434

		▶ 12.1976	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--	--	-----------	---------------	------	-----	---------------	-----

### ALEKO

2.0	F3R-...	01.1996 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
-----	---------	-----------	---------------	------	-----	---------------	-----

### ISH, 2126

1.5		09.1987 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

### ZAZ 12 V4

			<b>246189</b>	R88N	0.8		
--	--	--	---------------	------	-----	--	--

## MURAT

### 124

Tous modèles (all models)			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------------------------	--	--	---------------	------	-----	---------------	-----

### 131

Tous modèles (all models)			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
---------------------------	--	--	---------------	------	-----	---------------	-----

## NISSAN

### 100 NX

1.6 16V	GA16DS [DOHC] Cat	10.1990 ▶ 10.1992			1.1	<b>246556</b>	F87-11
1.6 i 16V	GA16DE [DOHC] Cat	10.1992 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
2.0 i 16V	SR20DE [DOHC] Cat	10.1990 ▶			1.1	<b>246556</b>	F87-11

### 180 B

1.6 Coupé	L16		<b>246179</b>	R76H	0.9	<b>246555</b>	H79
-----------	-----	--	---------------	------	-----	---------------	-----



			<b>NISSAN</b> (.../...)				
<b>180 B (.../...)</b>							
1.8 Coupé	L18	► 12.1982	<b>246179</b>	R76H	0.9	<b>246555</b> H79	
1.8 16V		01.1988 ►	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
1.8 Turbo Coupé	L18T	► 12.1982	<b>246179</b>	R76H	0.9	<b>246555</b> H79	
<b>180 SX</b>							
1.8 i 16V Turbo	CA18DET [DOHC]	04.1989 ► 01.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
2.0 i 16V	SR20DE [DOHC] Cat	08.1996 ►			1.1	<b>246556</b> F87-11	
<b>200 SX</b>							
1.8 i 16V Turbo	CA18DET [DOHC]	09.1988 ►	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
1.8 i 16V Turbo	CA18DT [DOHC]	09.1988 ►	<b>246333</b>	RF72H11	1.1		
<b>240 C, K, KGT</b>							
240 KGT : 2.4 Coupé	L24		<b>246179</b>	R76H	0.9	<b>246555</b> H79	
260 Z : 2.6 Coupé	L26	► 12.1982	<b>246179</b>	R76H	0.8	<b>246555</b> H79	
<b>280 ZX,ZXT</b>							
280 ZX : 2.8 i	L28E	10.1978 ► 08.1984			1.1	<b>246564</b> H79-11	
280 ZX : 2.8 i Turbo Turbo	L28ET	09.1982 ► 08.1984			1.1	<b>246564</b> H79-11	
<b>300 ZX</b>							
3.0 i	VG30	01.1984 ►	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
3.0 Turbo Coupé	VG30T	02.1984 ►	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
<b>AD / MAX</b>							
1.3	E13	05.1988 ► 10.1990			1.1	<b>246564</b> H79-11	
1.3	GA13DS	10.1990 ► 05.1999			1.1	<b>246556</b> F87-11	
1.3 i 16V	GA13DE [DOHC] Cat	06.1995 ► 05.1999			1.1	<b>246556</b> F87-11	
1.5	E15	05.1988 ► 10.1990			1.1	<b>246564</b> H79-11	
1.5 i 16V	GA15DE [DOHC] Cat	06.1995 ► 05.1999			1.1	<b>246556</b> F87-11	
1.5 i 16V	QG15DE	05.1999 ►			1.1	<b>246556</b> F87-11	
1.8 i 16V	QG18DE	05.1999 ►			1.1	<b>246556</b> F87-11	
<b>ALMERA</b>							
1.4 i 16V Eco, Eco Pack, GX, LX, Papillon, S, SLX	GA14DE [DOHC] Cat	07.1995 ►	<b>246176</b>	RF80H	0.9	<b>246554</b> F87	
1.5 i 16V	QG15DE	02.2000 ►			1.1	<b>246556</b> F87-11	
1.6 i 16V GX, SLX, SR, SR Deluxe	GA16DE [DOHC] Cat	09.1995 ►	<b>246176</b>	RF80H	0.9	<b>246554</b> F87	
1.8 i 16V	QG18DE	02.2000 ►			1.1	<b>246556</b> F87-11	
2.0 i 16V GTi	SR20DE [DOHC] Cat	03.1996 ►			1.1	<b>246556</b> F87-11	
<b>ALMERA TINO</b>							
1.8 i 16V	QG18DE	12.1998 ►			1.1	<b>246556</b> F87-11	
2.0 i 16V	SR20DE [DOHC] Cat	12.1998 ►			1.1	<b>246556</b> F87-11	
<b>ATLAS</b>							
1.6	Z16	02.1982 ► 01.1992	<b>246179</b>	R76H	0.9	<b>246555</b> H79	
2.0	NA20S	01.1992 ► 06.1999			1.1	<b>246564</b> H79-11	
2.0	Z20	11.1986 ► 06.1990			1.1	<b>246564</b> H79-11	
2.0 i	KA 20 DE	06.1999 ►			1.1	<b>246556</b> F87-11	
<b>AUSTER</b>							
1.6	CA16S	05.1985 ► 02.1990			1.1	<b>246556</b> F87-11	
1.8 i	CA18i	05.1985 ► 02.1990			1.1	<b>246556</b> F87-11	
1.8 i 16V	CA18DE	01.1985 ► 02.1990	<b>246333</b>	RF72H11	1.1		
<b>AVENIR / SALUT</b>							
1.6 16V	GA16DS [DOHC] Cat	05.1990 ► 06.1999			1.1	<b>246556</b> F87-11	
1.8 i 16V	QG18DE	08.1998 ►			1.1	<b>246556</b> F87-11	
1.8 i 16V	SR18DE [DOHC] Cat	01.1993 ► 08.1995			1.1	<b>246556</b> F87-11	
2.0 i 16V	SR20DE [DOHC] Cat	11.1994 ► 08.1998			1.1	<b>246556</b> F87-11	
<b>BLUEBIRD</b>							
1.6	CA16NS	01.1994 ►	<b>246176</b>	RF80H	0.9	<b>246554</b> F87	
1.6	CA16S	11.1983 ► 12.1990	<b>246176</b>	RF80H	1.1	<b>246554</b> F87	
1.6 Station Wagon	L16	01.1980 ► 05.1984	<b>246180</b>	R84H	0.9	<b>246555</b> H79	
1.6 16V	GA16DS [DOHC] Cat	03.1991 ► 01.1996			1.1	<b>246556</b> F87-11	
1.8	CA18S	11.1983 ► 08.1989	<b>246176</b>	RF80H	1.1	<b>246554</b> F87	
1.8	CA18S	11.1983 ► 08.1989	<b>246179</b>	R76H	1.1	<b>246555</b> H79	
1.8 Coupé	L18S	01.1980 ► 05.1984	<b>246180</b>	R84H	0.9	<b>246555</b> H79	
1.8 Station Wagon	L18S	01.1980 ► 05.1984	<b>246180</b>	R84H	0.9	<b>246555</b> H79	
1.8 i	CA18i	05.1988 ► 09.1991			1.1	<b>246556</b> F87-11	
1.8 i 16V	QG18DE	09.1998 ►			1.1	<b>246556</b> F87-11	
1.8 i 16V	SR18DE [DOHC] Cat	09.1991 ► 01.1996			1.1	<b>246556</b> F87-11	
1.8 i 16V Hatchback	CA18D [DOHC] Cat	02.1989 ►	<b>246333</b>	RF72H11	1.1		
1.8 i 16V Hatchback	CA18DE	11.1987 ► 09.1991	<b>246333</b>	RF72H11	1.1		
1.8 i 16V Turbo	CA18DET [DOHC]	09.1987 ► 10.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11	
1.8 i Turbo	CA18ET	11.1983 ► 05.1990	<b>246333</b>	RF72H11	1.1		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## NISSAN (.../...)

### BLUEBIRD (.../...)

1.8 i Turbo	CA18T	12.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 Turbo Coupé	L18T	01.1980 ▶ 05.1984	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.0, Hatchback	CA20S	11.1983 ▶	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
2.0 i, Break	L20B	01.1980 ▶ 05.1984			1.1	<b>246564</b>	H79-11
2.0 i, Hatchback	CA20E Cat	01.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i Coupé	LZ20E	01.1982 ▶ 05.1984			1.1	<b>246564</b>	H79-11
2.0 i 16V	SR20DE [DOHC] Cat	03.1991 ▶ 01.1996			1.1	<b>246556</b>	F87-11
2.0 i 16V OZ	SR20DE [DOHC] Cat	05.1991 ▶ 04.1992			1.1	<b>246556</b>	F87-11

### BLUEBIRD SYLPHY

1.5 i 16V	QG15DE	08.2000 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	QG18DE	08.2000 ▶			1.1	<b>246556</b>	F87-11

### CEDRIC

2.0	CA20	01.1983 ▶			1.1	<b>246564</b>	H79-11
2.0	CA20S	06.1985 ▶ 11.1995			1.1	<b>246564</b>	H79-11
2.0 200C	L20	03.1971 ▶ 06.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	VG20E	07.1987 ▶ 06.1995			1.1	<b>246556</b>	F87-11
2.0 i 200C	L20E	03.1971 ▶ 06.1979	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0 i V6 24V Tu	VG20DET	06.1988 ▶ 06.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.4	L24	07.1979 ▶ 06.1987			0.9	<b>246564</b>	H79-11
2.8 Break, Coupé	L28	07.1979 ▶ 06.1987	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
3.0 i	VG30DE	06.1991 ▶ 06.1995			1.1	<b>246556</b>	F87-11
3.0 i	VG30E	07.1987 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30E Cat	06.1991 ▶ 06.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30S	01.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i Turbo	VG30ET	07.1987 ▶ 06.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### CEFIRO

2.0 i	RB20E	09.1988 ▶ 08.1994			1.1	<b>246556</b>	F87-11
2.0 i 24V Turbo	RB20DET	09.1988 ▶ 08.1994	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### CHERRY

1.0	E10	05.1982 ▶ 05.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	E13	05.1982 ▶ 05.1986	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.4	A14S	10.1979 ▶ 04.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	E15	05.1982 ▶ 05.1986			1.1	<b>246564</b>	H79-11
1.5 i Turbo Turbo Coupé	E15T	07.1983 ▶ 05.1986	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6	E16 Cat	06.1985 ▶ 05.1986			1.1	<b>246564</b>	H79-11
100 A : 1.0, FI	A10	11.1979 ▶ 02.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
120 A : 1.2, Coupé, FI Coupé, GL, GT	A12	10.1978 ▶ 02.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### CIMA

3.0 i	VG30DE	01.1988 ▶ 08.1991			1.1	<b>246556</b>	F87-11
-------	--------	-------------------	--	--	-----	---------------	--------

### CREW

2.0 i	RB20E Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11
-------	-----------	-----------	--	--	-----	---------------	--------

### CUBE

1.3 i 16V	CG13DE [DOHC] Cat	02.1998 ▶ 11.2001			1.1	<b>246556</b>	F87-11
-----------	-------------------	-------------------	--	--	-----	---------------	--------

### ELGRAND

3.3 i V6	VG33E Cat	05.1997 ▶			1.1	<b>246556</b>	F87-11
----------	-----------	-----------	--	--	-----	---------------	--------

### EXPERT

1.8 i 16V	QG18DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
-----------	--------	-----------	--	--	-----	---------------	--------

### FAIRLADY

2.6	L26	08.1973 ▶ 08.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-----	-----	-------------------	---------------	------	-----	---------------	-----

### FAIRLADY Z

2.0 i 24V Turbo	RB20DET	10.1985 ▶ 07.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30DE	10.1986 ▶ 07.1989			1.1	<b>246556</b>	F87-11
3.0 i Turbo	VG30ET	09.1983 ▶ 07.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### FIGARO

1.0 i Turbo	MA10ET	02.1991 ▶ 04.1992			1.1	<b>246564</b>	H79-11
-------------	--------	-------------------	--	--	-----	---------------	--------

### GLORIA

2.0	CA20S	06.1985 ▶ 11.1995			1.1	<b>246564</b>	H79-11
2.0 i	VG20E	01.1996 ▶ 06.1999			1.1	<b>246556</b>	F87-11
2.0 i V6 24V Tu	VG20DET	06.1988 ▶ 06.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30DE	06.1991 ▶ 06.1995			1.1	<b>246556</b>	F87-11
3.0 i	VG30E	06.1983 ▶ 06.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30E Cat	06.1991 ▶ 06.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i Turbo	VG30ET	07.1987 ▶ 06.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### INFINITY

2.0 i 16V	SR20DE [DOHC] Cat	01.1994 ▶	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
-----------	-------------------	-----------	---------------	-------	-----	---------------	-----



3+1


**NISSAN** (.../...)

**LAUREL**

1.8	CA18S	05.1988 ▶ 08.1993			1.1	<b>246556</b>	F87-11
1.8 i	CA18i	01.1989 ▶ 01.1993			1.1	<b>246556</b>	F87-11
2.0	CA20S	01.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0	L20A	01.1981 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	L20B	01.1981 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.0 i	RB20E	01.1981 ▶ 08.1993			1.1	<b>246556</b>	F87-11
2.0 i 24V Turbo	RB20DET	10.1986 ▶ 01.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i Turbo	VG20ET	10.1984 ▶ 01.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.4 Coupé	L24		<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4 Hardtop	L24S	01.1985 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4 i	L24E	01.1981 ▶			1.1	<b>246564</b>	H79-11
2.4 i E	L24E	01.1985 ▶			1.1	<b>246564</b>	H79-11
3.0 Hardtop	VG30S	01.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i E	VG30E Cat	03.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**LEOPARD**

1.8	Z18	08.1984 ▶ 03.1986			1.1	<b>246564</b>	H79-11
2.0 i	L20E	01.1981 ▶ 03.1986			1.1	<b>246564</b>	H79-11
2.0 i	VG20E	08.1988 ▶ 06.1992			1.1	<b>246556</b>	F87-11
2.0 i Turbo	L20ET	01.1981 ▶ 03.1986			1.1	<b>246564</b>	H79-11
2.0 i Turbo	VG20ET	01.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i Ultima	VG30DE	04.1986 ▶			1.1	<b>246556</b>	F87-11
3.0 i Turbo	VG30ET	08.1984 ▶ 03.1986	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**LEOPARDO**

2.0 i	VG20E	01.1997 ▶ 06.1999			1.1	<b>246556</b>	F87-11
2.0 i 24V Turbo	RB20DET	08.1988 ▶ 06.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30DE	02.1986 ▶ 06.1992			1.1	<b>246556</b>	F87-11
3.0 i	VG30E Cat	03.1996 ▶ 12.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**LYBERTA**

1.6	CA16S	07.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i Turbo	CA18ET	07.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0	CA20S	07.1986 ▶			1.1	<b>246564</b>	H79-11
2.0 i	CA20E Cat	07.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**M 10**

2.0 i 4WD	CA20E Cat	03.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	-----------	-----------	---------------	---------	-----	---------------	--------

**MAXIMA**

3.0 i	VG30DE	08.1991 ▶ 08.1994			1.1	<b>246556</b>	F87-11
3.0 i	VG30E	08.1991 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i GL, SLX	VG30E Cat	10.1988 ▶ 08.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**MICRA / MARCH**

1.0 L, LX, SGL	MA10S	12.1982 ▶ 07.1992	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.0 L, LX, SGL	MA10S Cat	12.1982 ▶ 07.1992			1.1	<b>246564</b>	H79-11
1.0 i 16V L, LX, Cypia, Lagoon, Stars Cup	CG10DE [DOHC] Cat	08.1992 ▶			1.1	<b>246556</b>	F87-11
1.0 i Turbo	MA10ET	03.1985 ▶			1.1	<b>246564</b>	H79-11
1.2 GS, GSX, LX, SLX, Super S	MA12S	07.1986 ▶ 11.1988			0.9	<b>246564</b>	H79-11
1.2 GS, GSX, LX, SLX, Super S	MA12S	12.1988 ▶ 07.1992	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.2 GS, GSX, LX, SLX, Super S	MA12S Cat	01.1986 ▶ 07.1992			1.1	<b>246564</b>	H79-11
1.3 i 16V LX, Plaza, SLX, Super S, Stars Cup Tivoli	CG13DE [DOHC] Cat	08.1992 ▶ 11.2001			1.1	<b>246556</b>	F87-11

**PATHFINDER**

2.0	Z20S		<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.4	Z24S		<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4 i	Z24i		<b>246180</b>	R84H	0.9	<b>246555</b>	H79
3.0 i	VG30E Cat	01.1992 ▶			1.1	<b>246554</b>	F87
3.0 i	VG30i				1.1	<b>246556</b>	F87-11
3.3 i V6	VG33	01.1998 ▶			1.1	<b>246556</b>	F87-11

**PATROL**

2.8	L28	07.1980 ▶ 08.1989	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
3.0	RB30S	04.1989 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
4.0	P40	11.1979 ▶ 08.1988	<b>246180</b>	R84H	0.9	<b>246555</b>	H79

**PATROL GR**

4.2 GR	TB42S	08.1987 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
4.2 i GR	RB42S	01.1993 ▶ 12.1994	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
4.2 i GR	TB42E Cat	10.1991 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79

**PICK UP**

1.2	A12	01.1974 ▶ 12.1978	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	-----	-------------------	---------------	------	-----	---------------	-----



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## NISSAN (.../...)

### PICK UP (.../...)

1.3	J13	01.1972 ▶ 12.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5	A15S [OHV]	01.1983 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5	J15	01.1979 ▶ 12.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	J16	08.1979 ▶ 09.1985	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.6	Z16	09.1985 ▶ 09.1989	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.8 4WD	L18	08.1979 ▶ 08.1989	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.0	NA20S	09.1989 ▶			1.1	<b>246564</b>	H79-11
2.0	Z20	09.1985 ▶			1.1	<b>246564</b>	H79-11
2.0	Z20S	09.1985 ▶ 09.1989	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 i	KA 20 DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
2.2 4WD	Z22	04.1983 ▶ 08.1989	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4	Z24	09.1985 ▶ 04.1992	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.4 i 4WD	Z24i Cat	08.1988 ▶ 04.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 i	VG30E Cat	09.1990 ▶			1.1	<b>246554</b>	F87

### PINTARA

2.0 i	CA20E [SOHC] Cat	01.1985 ▶ 04.1992			1.1	<b>246556</b>	F87-11
-------	------------------	-------------------	--	--	-----	---------------	--------

### PRAIRIE

1.5 GL, SGL	E15S	09.1982 ▶ 09.1988			1.1	<b>246564</b>	H79-11
1.8	CA18S	02.1985 ▶ 09.1988	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 4WD	CA20S	▶ 09.1988	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 i 4WD	CA20E Cat	01.1986 ▶ 09.1988	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### PRAIRIE / LIBERTY

2.0 Pro, SLX, 4WD	CA20S	10.1988 ▶ 08.1990	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.0 i 4WD	CA20E Cat	01.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	08.1995 ▶ 11.1998			1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	08.1995 ▶ 11.1998	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87

### PRESEA

1.5 i 16V	GA15DE [DOHC] Cat	01.1995 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	06.1992 ▶ 01.1995			1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	06.1990 ▶ 01.1995			1.1	<b>246556</b>	F87-11

### PRESIDENT

4.4	Y44S	01.1993 ▶	<b>246181</b>	R90H	0.9		
-----	------	-----------	---------------	------	-----	--	--

### PRIMERA

1.6 16V Break, Wagon	GA16DS [DOHC] Cat	07.1990 ▶ 04.1993			1.1	<b>246556</b>	F87-11
1.6 16V L, LS, LSX, LX, SLX	GA16DS [DOHC] Cat	06.1990 ▶			1.1	<b>246556</b>	F87-11
1.6 16V LX, SLX	GA16DS [DOHC] Cat	01.1993 ▶			1.1	<b>246554</b>	F87
1.6 i 16V LX, SLX	GA16DE [DOHC] Cat	04.1993 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.8 i 16V	QG18DE	09.1998 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	09.1992 ▶ 09.1995			1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	02.1997 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE EGI [DOHC] Cat	10.1991 ▶ 11.1996			0.9	<b>246554</b>	F87
2.0 i 16V Break, Traveller, Wagon	SR20Di SPI [DOHC] Cat	06.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
2.0 i 16V GT, Hatchback	SR20DE [DOHC] Cat	06.1996 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V GT, Hatchback	SR20DEH [DOHC] Cat	06.1996 ▶			0.9	<b>246554</b>	F87
2.0 i 16V GT, SGX, ZX, 4WD	SR20DE EGI [DOHC] Cat	06.1990 ▶ 09.1995			0.9	<b>246554</b>	F87
2.0 i 16V Hatchback	SR20DE [DOHC] Cat	09.1994 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V Hatchback	SR20DEL [DOHC] Cat	06.1996 ▶			0.9	<b>246554</b>	F87

### PULSAR

1.0	E10	04.1982 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	E13	01.1980 ▶			1.1	<b>246564</b>	H79-11
1.3	E13S	01.1980 ▶ 08.1990			1.1	<b>246564</b>	H79-11
1.3	GA13DS	08.1990 ▶ 01.1995			1.1	<b>246556</b>	F87-11
1.4	GA14S	10.1988 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.5	E15	04.1982 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5 i 16V	GA15DE [DOHC] Cat	01.1995 ▶			1.1	<b>246556</b>	F87-11
1.5 i Turbo	E15T	04.1982 ▶ 05.1986	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6	E16	04.1982 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6	GA16S	10.1988 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.6 4WD	E16S	06.1986 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6 i 4WD	E16I Cat	06.1986 ▶			1.1	<b>246564</b>	H79-11
1.6 i 16V	CA16D [DOHC] Cat	02.1987 ▶ 10.1988	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	GA16DE [DOHC] Cat	08.1990 ▶ 01.1995			0.9	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	08.1990 ▶ 01.1995			1.1	<b>246556</b>	F87-11
1.8 i 16V 2WD	SR18DE [DOHC] Cat	01.1995 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V 4WD	SR18DE [DOHC] Cat	05.1996 ▶			1.1	<b>246556</b>	F87-11




**NISSAN** (.../...)

**PULSAR (.../...)**

1.8 i 16V Twin Cam	CA18D [DOHC] Cat	10.1988 ▶	<b>246333</b>	RF72H11	1.1		
2.0 i 16V	SR20DE [DOHC] Cat	10.1991 ▶			1.1	<b>246556</b>	F87-11

**RASHEEN**

1.5 i 16V	GA15DE [DOHC] Cat	12.1994 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	01.1997 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	04.1998 ▶			1.1	<b>246556</b>	F87-11

**RNESSA**

2.0 i 16V	SR20DE [DOHC] Cat	10.1997 ▶			1.1	<b>246556</b>	F87-11
-----------	-------------------	-----------	--	--	-----	---------------	--------

**S CARGO**

1.5	E15S	01.1989 ▶ 12.1990			1.1	<b>246564</b>	H79-11
-----	------	-------------------	--	--	-----	---------------	--------

**SAFARI**

4.2	TB42S	09.1988 ▶ 03.1998	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
4.2 i	TB42E Cat	11.1991 ▶ 03.1998	<b>246180</b>	R84H	0.9	<b>246555</b>	H79

**SANTANA ( VW )**

1.8 i	JN [SOHC]	01.1984 ▶	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i		01.1984 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 20V	JZ [DOHC]	02.1987 ▶			0.9	<b>246567</b>	F59

**SILVIA**

1.8 i 16V Coupé	CA18DE	05.1988 ▶ 01.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V Turbo Coupé	CA18DET [DOHC]	02.1986 ▶ 01.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i Turbo	CA18ET	10.1983 ▶ 01.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	SR20DE [DOHC] Cat	01.1991 ▶ 10.1993			1.1	<b>246556</b>	F87-11
2.0 i 16V Coupé	FJ20E	10.1983 ▶			1.1	<b>246564</b>	H79-11
2.0 i Turbo	CA20E	10.1983 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**SKYLINE**

1.8	CA18S	09.1985 ▶ 11.1989	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.8	CA18S	11.1989 ▶ 07.1993			1.1	<b>246556</b>	F87-11
1.8	L18	10.1977 ▶ 08.1985	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.8 i	CA18i	05.1989 ▶ 07.1993			1.1	<b>246556</b>	F87-11
2.0	CA20S	09.1985 ▶ 04.1989	<b>246173</b>	RF74H	1.1	<b>246554</b>	F87
2.0 i	RB20E	09.1985 ▶ 08.1993			1.1	<b>246556</b>	F87-11
2.0 i 24V Turbo	RB20DET	05.1989 ▶ 08.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i Turbo	RB20ET	09.1985 ▶ 08.1987	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.4 Coupé	L24	09.1984 ▶ 08.1985	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4 i Coupé	L24E	10.1977 ▶ 08.1985			1.1	<b>246564</b>	H79-11
2.8 6 cyl.	L28S		<b>246179</b>	R76H	0.9	<b>246555</b>	H79

**STANZA**

1.6	CA16S	01.1986 ▶ 02.1990			1.1	<b>246556</b>	F87-11
1.6	CA16S	08.1981 ▶ 03.1986	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.8 Coupé	CA18S	08.1981 ▶ 03.1986	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.8 i	CA18i	05.1985 ▶ 02.1990			1.1	<b>246556</b>	F87-11
1.8 i 16V	CA18DE	01.1985 ▶ 02.1990	<b>246333</b>	RF72H11	1.1		
2.0 Hatchback	CA20S	12.1985 ▶			1.1	<b>246564</b>	H79-11
2.0 i	CA20E Cat	06.1986 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**SUNNY**

1.0	E10S	01.1982 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.2 120Y, Coupé	A12	01.1970 ▶ 02.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2 Truck	A12S	10.1989 ▶ 03.1994	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.3	A13	01.1970 ▶ 02.1982	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.3	E13S	03.1982 ▶ 01.1990			1.1	<b>246564</b>	H79-11
1.3	GA13DS	01.1990 ▶ 01.1994			1.1	<b>246556</b>	F87-11
1.3 i 16V, Coupé	GA13DE [DOHC] Cat	01.1994 ▶ 10.1998			1.1	<b>246556</b>	F87-11
1.4	GA14S	10.1988 ▶ 08.1991	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.4 140Y Coupé, Traveller	A14	01.1970 ▶ 02.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 16V LX, SLX	GA14DS [DOHC] Cat	10.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.4 i 16V Hatchback	GA14DE [DOHC] Cat	10.1992 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.5	E15S	03.1982 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5 i	A15	01.1970 ▶ 02.1982	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.5 i 16V	GA15DE [DOHC] Cat	06.1995 ▶ 05.1996			1.1	<b>246556</b>	F87-11
1.5 i 16V	QG15DE	10.1998 ▶			1.1	<b>246556</b>	F87-11
1.6 4WD, SLX	E16S	01.1986 ▶ 08.1989	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
1.6 Combi	E16 Cat	03.1985 ▶			1.1	<b>246564</b>	H79-11
1.6 12V Coupe, 4x4	GA16S	10.1988 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.6 16V	GA16DS [DOHC] Cat	01.1991 ▶			1.1	<b>246556</b>	F87-11
1.6 16V Hatchback, 4x4	GA16DS [DOHC] Cat	10.1990 ▶	<b>246184</b>	RF72H	1.1	<b>246567</b>	F59



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## NISSAN (.../...)

### SUNNY (.../...)

1.6 i	SR16DE	01.1994 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.6 i Coupé, 4WD	E16i	01.1986 ▶			1.1	<b>246564</b>	H79-11
1.6 i Coupé, 4WD	E16i Cat	01.1986 ▶			1.1	<b>246564</b>	H79-11
1.6 i 12V 4WD	GA16i [OHC] Cat	10.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	CA16D [DOHC]	02.1987 ▶ 12.1988	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	GA16DE [DOHC] Cat	01.1990 ▶ 01.1994	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.6 i 16V, Coupé	GA16DE [DOHC] Cat	01.1994 ▶ 10.1998	<b>246332</b>	RF74H11	0.9	<b>246556</b>	F87-11
1.6 i 16V 4WD	GA16DE [DOHC] Cat	10.1992 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.6 i 16V 4WD, Hatchback	GA16DE [DOHC] Cat	10.1992 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.8 i	GA18DE	01.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	CA18D [DOHC] Cat	10.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	10.1990 ▶ 12.1995			1.1	<b>246556</b>	F87-11
1.8 i 16V, Coupé	SR18DE [DOHC] Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11
2.0 i	GA20DE	01.1993 ▶			0.9	<b>246554</b>	F87
2.0 i 16V	SR20DE [DOHC] Cat	10.1990 ▶			1.1	<b>246556</b>	F87-11

### TERRANO / REGULUS

2.4 i	Z24i	08.1987 ▶ 07.1992	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
3.0 i	VG30E Cat	11.1989 ▶ 09.1995			1.1	<b>246554</b>	F87
3.0 i	VG30i	08.1986 ▶ 10.1989			1.1	<b>246556</b>	F87-11
3.3 i V6	VG33E Cat	09.1995 ▶			1.1	<b>246556</b>	F87-11

### VIOLET

1.4 140J	A14	05.1977 ▶ 10.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 160J	L16S	01.1971 ▶ 10.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 160J SSS	L16T		<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### WINGROAD

1.5 i 16V	GA15DE [DOHC] Cat	05.1996 ▶ 05.1999			1.1	<b>246556</b>	F87-11
1.5 i 16V	QG15DE	05.1999 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	QG18DE	05.1999 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	SR18DE [DOHC] Cat	05.1996 ▶ 05.1999			1.1	<b>246556</b>	F87-11

## NISSAN

### CABSTAR

1.6	Z16	10.1986 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.0	NA20S	03.1985 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0	Z20	03.1985 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0	Z20S	03.1985 ▶			1.1	<b>246564</b>	H79-11
2.2	Z22	10.1986 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4	Z24	01.1987 ▶	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.8	L28	10.1986 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79

### CARAVAN ( HOMOY )

2.0	NA20S	08.1990 ▶ 06.1999			1.1	<b>246564</b>	H79-11
2.0	Z20	09.1986 ▶ 08.1995			1.1	<b>246564</b>	H79-11
2.0 i	KA 20 DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
3.0 i	VG30E	10.1988 ▶ 09.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i	VG30E Cat	09.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### KING CAB

2.0	Z20	01.1987 ▶	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
2.4	Z24	01.1987 ▶	<b>246179</b>	R76H	1.1	<b>246555</b>	H79

### URVAN

1.8	Z18	04.1982 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0	H20	07.1980 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	NA20S	01.1995 ▶			1.1	<b>246564</b>	H79-11
2.0	Z20	07.1980 ▶			1.1	<b>246564</b>	H79-11
2.0	Z20S	02.1987 ▶ 07.1994	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.4	Z24	09.1989 ▶			1.1	<b>246564</b>	H79-11
2.4	Z24S	11.1986 ▶	<b>246179</b>	R76H	0.9	<b>246555</b>	H79
2.4 i	Z24i Cat	05.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### VANETTE ( LARGO, CARGO, VAN )

1.2	A12	10.1978 ▶ 06.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2 Truck	A12S	11.1988 ▶ 03.1994	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
1.2 Van	A12	10.1986 ▶ 03.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	A14	11.1980 ▶ 05.1981	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5 Truck	A15S [OHV]	11.1988 ▶ 03.1994			1.1	<b>246564</b>	H79-11
1.5 Van	A15S [OHV]	05.1986 ▶ 03.1994			1.1	<b>246564</b>	H79-11
1.5 Van, Coach	A15 [OHV]	09.1985 ▶ 04.1994			1.1	<b>246564</b>	H79-11
1.6 i 16V Cargo	GA16DE [DOHC] Cat	07.1992 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87



3+1



## NISSAN (.../...)

### VANETTE ( LARGO, CARGO, VAN ) (.../...)

1.8 i Turbo Coach	CA18ET	05.1986 ▶ 04.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0	Z20S	09.1986 ▶ 08.1990			1.1	<b>246564</b>	H79-11
2.0 Coach	CA20	09.1985 ▶ 06.1991			1.1	<b>246564</b>	H79-11
2.0 Coach	CA20S	05.1986 ▶ 04.1993			1.1	<b>246564</b>	H79-11
2.0 Truck	NA20S	08.1990 ▶ 03.1994			1.1	<b>246564</b>	H79-11
2.0 i	SR20E	01.1993 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.4	Z203		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4 i	Z24i	08.1986 ▶			0.9	<b>246564</b>	H79-11
2.4 i	Z24i Cat	09.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### VANETTE ( SERENA )

1.6 16V	GA16DS [DOHC] Cat	06.1991 ▶ 05.1194			1.1	<b>246556</b>	F87-11
1.6 i 16V	GA16DE [DOHC] Cat	05.1994 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
2.0 i 16V	SR20DE [DOHC] Cat	06.1991 ▶ 06.1999			1.1	<b>246556</b>	F87-11
2.0 i 16V SLX	SR20DE [DOHC] Cat	06.1999 ▶			1.1	<b>246556</b>	F87-11

## OLCIT

### AXEL

1.1 11, R, RS, 12 TRS					0.6	<b>246565</b>	C60
-----------------------	--	--	--	--	-----	---------------	-----

### SPECIAL

					0.6	<b>246565</b>	C60
--	--	--	--	--	-----	---------------	-----

## OLDSMOBILE

### ACHIEVA

2.3 i		01.1993 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
-------	--	-----------	---------------	-------	-----	---------------	-----

## OPEL

### ADMIRAL

2.8	28 H, S	03.1969 ▶ 01.1978	<b>246189</b>	R88N	0.7		
2.8 i	28 E	07.1971 ▶ 07.1976	<b>246189</b>	R88N	0.7		

### AGILA

1.0 i	Z 10 XE Ecotec [DOHC]		<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.2 i	Z 12 XE Ecotec [DOHC]		<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

### ASCONA

1.2 S	12 N, S	04.1972 ▶ 02.1979	<b>246189</b>	R88N	0.7		
1.3 S	13 N, S [OHC]	03.1979 ▶ 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 N [OHC]	09.1975 ▶ 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 N [OHC]	09.1975 ▶ 08.1981	<b>246189</b>	R88N	0.7		
1.6 S	16 S [OHC]	09.1975 ▶ 08.1981	<b>246189</b>	R88N	0.7		
1.6 S	16 SH, 16 SV [OHC]	09.1981 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	C 16 LZ [OHC I]	09.1986 ▶ 08.1987			1.1	<b>246564</b>	H79-11
1.6 i	C 16 NZ, E 16 NZ [OHC]	09.1987 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	E 18 NV [OHC II]	09.1987 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	18 E, 18 SE [OHC]	09.1982 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i, E	C 18 NE [OHC]	09.1982 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i E	18 E [OHC]	09.1982 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.9 S	19 N, S	03.1971 ▶ 08.1981	<b>246189</b>	R88N	0.7		
2.0 E, S	20 N, S	08.1977 ▶ 08.1981	<b>246189</b>	R88N	0.7		
2.0 i	20 NE [OHC]	09.1986 ▶ 08.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	20 SEH [OHC II]	03.1987 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i E, S	20 E	08.1977 ▶ 08.1981	<b>246189</b>	R88N	0.7		
400 : 2.0 16V E		08.1979 ▶ 08.1981			0.7	<b>246565</b>	C60

### ASTRA

1.2 i 16V	X 12 XE [DOHC]	03.1998 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.2 i 16V	Z 12 XE Ecotec [DOHC]	08.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4	14 NV [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4	X 14 NZ [OHC I]		<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4	X 14 NZ [OHC I]		<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	14, C14 SE [OHC]	03.1992 ▶ 03.1996	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	14, C14 SE [OHC]	03.1992 ▶ 03.1996	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	C 14 NZ [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V	X 14 XE [DOHC]	02.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V	Z 14 XE [DOHC] Cat	08.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	16 LZ2 [OHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## OPEL (.../...)

### ASTRA (.../...)

1.6 i	C 16 NZ [OHC]		<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 NZ [OHC]		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	C 16 SE [OHC]	03.1992 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 SE [OHC]	03.1992 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	C 16 XEV	09.1993 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
1.6 i	E 16 NZ [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	E 16 NZ [OHC]	09.1991 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	X 16 SZ [OHC]		<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	X 16 SZ [OHC]		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	X 16 SZR [OHC]	03.1996 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i 16V	X 16 XEL [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i 16V	Z 16 XE [DOHC]	08.2000 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.8 i 16V	C 18 XE [DOHC]	06.1993 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.8 i 16V	X 18 XE [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V	X 20 XER [DOHC] Cat	11.1999 ▶ 09.2002	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V	X 20 XEV [DOHC]	01.1995 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V GSi	C 20 XE II [DOHC I, DOHC II]	▶ 08.1992	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
2.0 i 16V GSi	C 20 XE-LN I, 20 XE [DOHC I DOHC II]	09.1991 ▶ 08.1992	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
2.2 i 16V	X 22 XE [DOHC]	01.2001 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### BEDFORD, BLITZ

2.0 CF	20 N	08.1984 ▶ 07.1987	<b>246189</b>	R88N	0.7		
--------	------	-------------------	---------------	------	-----	--	--

### CALIBRA

2.0 i 4x4, GT	C 20 NE [OHC]	06.1990 ▶ 04.1997	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i 4x4, GT	C 20 NE [OHC]	06.1990 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V	X 20 XEV [DOHC]	11.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V 4x4	20, C20 XE [DOHC]	06.1990 ▶ 08.1992	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
2.0 i Turbo 4x4	C 20 LET [DOHC]	03.1992 ▶ 08.1995			1.1	<b>246556</b>	F87-11
2.5 i V6	C 25 XE [DOHC]	04.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.5 i V6 24V	X 25 XE [DOHC]	04.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### CAMPO TFO

2.3 i Pick-Up	4ZD1	09.1991 ▶ 08.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
---------------	------	-------------------	---------------	------	-----	---------------	-----

### COMBO

1.2 i	12, X 12 SZ, 12 NZ C12 NZ [OHC]	03.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	07.1994 ▶ 03.1996	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	07.1994 ▶ 03.1996	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.4 i	X 14 SZ [OHC]	04.1996 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.4 i Si	C 14 SE [OHC]	07.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i Si	C 14 SE [OHC]	07.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87


### COMMODORE

2.5 E, S	25 S	▶ 12.1982	<b>246189</b>	R88N	0.7		
2.5 i E, S	25 E	▶ 12.1982	<b>246189</b>	R88N	0.7		
2.8 E	28 EC, 28 HC	▶ 07.1978	<b>246189</b>	R88N	0.7		

### CORSA

1.0 Calypso 2, City, Liberty, S, Steffi, Van, Viva	10 S [OHV]	09.1982 ▶ 03.1993	<b>246189</b>	R88N	0.7		
1.0 i 12V	X 10 XE	03.1997 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.2	12 NC [OHV]	01.1985 ▶ 10.1987	<b>246189</b>	R88N	0.7		
1.2	E 12 GV [OHV]	01.1985 ▶ 03.1993	<b>246189</b>	R88N	0.7		
1.2 GL, Liberty, Van, Viva	12 NV [OHC]	09.1986 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 S	A 12 ST [OHC]	09.1986 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 S	S 12 ST [OHC]	09.1984 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 S, Calypso 2, GL, Steffi, Viva	12 S, 12 ST [OHC]	09.1982 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 i Affaires, City, Joy, Steffi, Viva, Viva Plus	C 12 NZ [OHC]	09.1990 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.2 i City	X 12 SZ, 12 NZ, C12 NZ [OHC]	03.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.2 i City	X 12 SZ, 12 NZ, C12 NZ [OHC]	03.1993 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.2 i 16V	X 12 XE [DOHC]	09.1997 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.2 i 16V	Z 10 XE Ecotec [DOHC]	09.2000 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.2 i 16V	Z 12 XE Ecotec, Z14 XE [DOHC]	09.2000 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.3	13 NB [OHC]	03.1986 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 GL, GT, S, Viva	13 S, 13 SB [OHC]	09.1982 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Sprint R	13 E [OHC]	04.1985 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 i	C 13 N [OHC]	09.1985 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 GL, GT, Sprint, Viva	14 NV [OHC]	01.1990 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 GL, GT, Sprint, Viva	14 NV [OHC]	01.1990 ▶ 03.1993	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87





3+1


**OPEL** (.../...)

**CORSA (.../...)**

1.4 GL, GT, Sprint, Viva	E 14 LV [OHC I]	► 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	01.1990 ► 03.1996	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	01.1990 ► 03.1996	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	C 14 SE [OHC]	01.1991 ► 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 SE [OHC]	01.1991 ► 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	X 14 SZ [OHC]	04.1996 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V	C 14 SEL [DOHC]	09.1994 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V	X 14 XE [DOHC]	09.1994 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	C 16 NZ, E 16 NZ [OHC]	04.1989 ► 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	C 16 SE [OHC]	05.1988 ► 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	C 16 SE [OHC]	09.1989 ► 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 XE [DOHC]	03.1993 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	E 16 SE [OHC I]	05.1988 ► 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i 16V	X 16 XE [DOHC]	09.1994 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
GSi, Sport	Z 18 XE [DOHC]	09.2000 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**DIPLOMAT**

2.8, E	28 H	► 01.1978	<b>246189</b>	R88N	0.7		
2.8 i, E	28 E	► 01.1978	<b>246189</b>	R88N	0.7		

**FRONTERA**

2.0 i	C 20 NE [OHC]	09.1991 ►	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i	C 20 NE [OHC]	09.1991 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i	X 20 SE [OHC]	02.1995 ►	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.2 i 16V	X 22 XE [DOHC]	10.1997 ►	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.4 i	C 24 NE	09.1991 ► 02.1995	<b>246189</b>	R88N	0.7		

**KADETT**

1.0 S	10 N, S [OHV]	08.1973 ► 07.1982	<b>246189</b>	R88N	0.7		
1.2 LS	12 N	08.1979 ► 08.1984	<b>246189</b>	R88N	0.7		
1.2 S	12 S, 12 ST [OHC]	09.1984 ► 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 S	12 SC [OHV]	09.1984 ► 07.1986	<b>246189</b>	R88N	0.7		
1.3	13 N, 13 NB [OHC]	08.1979 ► 08.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	13 S, 13 SC [OHC]	09.1984 ► 08.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 i	C 13 N [OHC]	09.1985 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	► 08.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	► 08.1991	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4	E 14 LV [OHC I]	01.1990 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	► 08.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	► 08.1991	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.5		► 07.1979	<b>246189</b>	R88N	0.7		
1.6 S	16 S [OHC]	► 07.1979	<b>246189</b>	R88N	0.7		
1.6 S	16 SH [OHC]	09.1981 ► 08.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 S, GL, GT, LS, Sprint, Ultima	16 SH, 16 SV [OHC]	09.1981 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	C 16 LZ [OHC I]	09.1986 ► 08.1987			1.1	<b>246564</b>	H79-11
1.6 i	C 16 NZ [OHC]	09.1986 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	E 16 NZ [OHC]	09.1987 ► 08.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	E 16 NZ [OHC]	09.1987 ► 08.1991	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	E 16 SE [OHC I]	04.1989 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	S 18 NV [OHC II]	09.1986 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	E 18 NV [OHC II]	09.1987 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	C 18 NZ [OHC II]	09.1990 ► 08.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i	C 18 NZ [OHC II]	09.1990 ► 08.1991	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i E, GTE	18 E [OHC]	02.1983 ► 08.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i GSi	C 18 NT, C 18 NE, 18 E, 18 SE	09.1984 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 E, Rallye, GT, GTE	20 EH	► 07.1979	<b>246189</b>	R88N	0.7		
2.0 i E, Rallye, GT, GTE	20 E	► 07.1979	<b>246189</b>	R88N	0.7		
2.0 i GSi	20 SEH, 20 SER [OHC II]	09.1986 ► 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i GSi, GSi Fashion	20 NE [OHC]	09.1986 ► 08.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i GSi, GSi Fashion	20 NE [OHC]	09.1986 ► 08.1991	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V GSi	20 XEJ, C 20 XE [DOHC]	03.1988 ► 08.1991	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87

**MANTA**

1.2 S	12 N, S	04.1972 ► 02.1979	<b>246189</b>	R88N	0.7		
1.3 S	13 N, S [OHC]	03.1979 ► 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 S	16 N [OHC]	09.1975 ► 12.1980	<b>246189</b>	R88N	0.7		
1.6 S	16 S [OHC]	09.1975 ► 12.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	18 S [OHC]	07.1982 ► 08.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.9 GT, GTe	19 N, S, E	09.1970 ► 12.1980	<b>246189</b>	R88N	0.7		





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## OPEL (.../...)

### MANTA (.../...)

2.0 S	20 N, S	08.1977 ▶ 08.1988	<b>246189</b>	R88N	0.7		
2.0 i S, E, GTE, GSi	20 E	08.1977 ▶ 08.1988	<b>246189</b>	R88N	0.7		
400 : 2.4 ie ie		05.1982 ▶ 07.1989			0.7	<b>246565</b>	C60

### MERIVA

1.6 i 16V	Z 16 XE, Z 16 SE [DOHC] Cat		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.8 i 16V	Z 18 XE [DOHC]		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### MIDI

2.0 i	Cat	02.1986 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	-----	-----------	---------------	------	-----	---------------	-----

### MONTEREY

3.2 i V6 24V	6 VD 1	04.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	--------	-----------	---------------	---------	-----	---------------	--------

### MONZA

2.0 i	20 E	03.1983 ▶ 10.1984	<b>246189</b>	R88N	0.7		
2.2 i	22 E	11.1984 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.5 i	25 E, S 25 E	05.1981 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.8	28 H	02.1978 ▶ 04.1981	<b>246189</b>	R88N	0.7		
3.0	30 S	04.1978 ▶ 07.1982	<b>246189</b>	R88N	0.7		
3.0 i	30 E	02.1978 ▶ 08.1986	<b>246189</b>	R88N	0.7		
3.0 i	C 30 NE	01.1983 ▶ 08.1986	<b>246189</b>	R88N	0.7		
3.0 i V6	S 30 E	01.1983 ▶ 08.1986	<b>246189</b>	R88N	0.7		

### OMEGA

1.8	S 18 NV, E 18 NVR [OHC II]	09.1986 ▶ 03.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 LS, S	18 SV [OHC, OHC II]	09.1986 ▶ 03.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i GL, LS	18 SEH [OHC II]	09.1986 ▶ 03.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i	X 20 SE [OHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i CD, Century, GL, GLT	C 20 NE, 20 NE [OHC]	09.1986 ▶ 03.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i CD, GL, GLS, Riviera	20 SE [OHC]	09.1986 ▶ 03.1994	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
2.0 i 16V CD, GL	X 20 XEV [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.4 i CD, GL, GLS	C 24 NE	09.1988 ▶ 03.1994	<b>246189</b>	R88N	0.7		
2.5 i V6 24V CD	X 25 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.6 i V6 CD, GLS	C 26 NE	09.1990 ▶ 03.1994	<b>246189</b>	R88N	0.7		
3.0 i V6 24V	X 30 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
3.6 Lotus	C 36 GET [DOHC]	09.1990 ▶ 03.1994	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
3000 : 3.0 24V	C 30 SEJ [DOHC]	09.1989 ▶ 03.1994	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
3000 : 3.0 i Sport, Caravan	C 30 NE	03.1987 ▶ 03.1994	<b>246189</b>	R88N	0.7		
3000 : 3.0 i 24V	C 30 SE [DOHC]	09.1989 ▶ 03.1994	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
3000 : 3.0 i V6 Sport, Caravan	C 30 LE	03.1987 ▶ 03.1994	<b>246189</b>	R88N	0.7		

### REKORD

1.7	17 L, 17 N	01.1972 ▶ 08.1977	<b>246189</b>	R88N	0.7		
1.7	17 S [OHC]	01.1972 ▶ 02.1975	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	18N [OHC]	11.1982 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	S 18 S [OHC]	03.1984 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	C 18 NV [OHC]	05.1985 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.9	19 N, SH	01.1972 ▶ 08.1977	<b>246189</b>	R88N	0.7		
2.0 S	20 N, S	09.1977 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.0 i	20 E	09.1977 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.2 i	22 E	11.1984 ▶ 08.1986	<b>246189</b>	R88N	0.7		

### SENATOR

2.0 i	20 E	03.1983 ▶ 10.1984	<b>246189</b>	R88N	0.7		
2.2 i	22 E	11.1984 ▶ 08.1987	<b>246189</b>	R88N	0.7		
2.5 i	25 E, 25 NE	05.1981 ▶ 12.1989	<b>246189</b>	R88N	0.7		
2.6 i V6	C 26 NE	09.1990 ▶ 09.1993	<b>246189</b>	R88N	0.7		
2.8	28 H	08.1979 ▶ 04.1981	<b>246189</b>	R88N	0.7		
3.0	30 S	08.1979 ▶ 07.1982	<b>246189</b>	R88N	0.7		
3.0 i CD	30 NE, 30 E, C 30 NE	08.1979 ▶ 09.1993	<b>246189</b>	R88N	0.7		
3.0 i 24V CD	C 30 SE [DOHC]	09.1989 ▶ 09.1993	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
3.0 i V6 CD	C 30 LE	08.1979 ▶ 09.1993	<b>246189</b>	R88N	0.7		
3.0 i V6 CD	S 30 E	01.1983 ▶ 08.1987	<b>246189</b>	R88N	0.7		
3.6 i	C 36 NE Irmischer	08.1989 ▶ 09.1993	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
4.0 i	C 40 SE Irmischer	01.1991 ▶ 09.1993	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87

### SINTRA

2.2 i 16V CD, GLS	X 22 XE [DOHC]		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
3.0 i V6 24V CD, GLS	X 30 XE [DOHC]		<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### TIGRA

1.4 i 16V	X 14 XE [DOHC]	09.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i 16V	X 16 XE [DOHC]	09.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87



3+1


**OPEL** (.../...)

**TRANS SPORT**

2.3 i 16V	G 16V	01.1993 ▶	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
3.8 i V6	(L)	01.1993 ▶	<b>246326</b>	RC72H11	1.3		

**VECTRA**

1.4 GL	14 NV [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 GL	14 NV [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 GL, GLS, S	16 SV [OHC]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	16 LZ2, X 16 SZR [OHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	X 16 SZ [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	X 16 SZ [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i Century, GL, GLS	C 16 NZ, E 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i Century, GL, GLS	C 16 NZ, E 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V	Y 16 XE, Z 16 XE [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 4x4, S, S 4x4	18 SV, C 18 SV, E 18 NVR [OHC OHC II]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	E 18 NZ		<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i GLS, Riviera	C 18 NZ [OHC II]	03.1990 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i GLS, Riviera	C 18 NZ [OHC II]	03.1990 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	16 LZ2, X 16 SZR, X 16 XEL Z 16 XE, Y 16 XE [OHC]	11.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	X 18 XE [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	X 18 XE1 [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	Z 18 XE [DOHC]	09.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i	20 NEJ [OHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 4x4, CD, GLS, GT	C 20 NE [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i 4x4, CD, GLS, GT	C 20 NE [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 4x4, GT	20 SEH [OHC II]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 16V	C 20 SEL [DOHC]	▶ 09.2000			1.0	<b>246564</b>	H79-11
2.0 i 16V CDX	C 20 XE-LN [DOHC]	09.1992 ▶ 09.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V CDX	X 20 XEV [DOHC]	09.1992 ▶ 09.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V CDX, 4x4	20 XE [DOHC]	09.1989 ▶ 08.1992	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.0 i 16V CDX, 4x4	C 20 XE [DOHC]	09.1989 ▶ 08.1992	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.0 i Turbo	C 20 LET [DOHC]	09.1992 ▶ 08.1995			1.1	<b>246556</b>	F87-11
2.5 i V6	C 25 XE [DOHC]	02.1993 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 24V	25 XE [DOHC]	02.1993 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 24V	X 25 XE [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**ZAFIRA**

1.6 i 16V	Z 16 XE [DOHC]	07.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V Comfort, Elegance	X 16 XEL [DOHC]	03.1999 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	Z 18 XE [DOHC]	07.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V Elegance	X 18 XE [DOHC]	03.1999 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i Turbo	X 20 XET Cat	01.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

**OTOSAN**
**ANADOL**

1300 : 1.3			<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1600 : 1.6			<b>246180</b>	R84H	0.7	<b>246555</b>	H79

**PANTHER**
**DEVILLE**

4.2			<b>246181</b>	R90H	0.8		
5.3 V12			<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**KALLISTA**

1.6	[OHC]		<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.8 i V6			<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
2.8 V6			<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
2.9 i V6			<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

**RIO SPECIAL**

2.0	[OHC]				0.8	<b>246565</b>	C60
-----	-------	--	--	--	-----	---------------	-----

**SOLO**

1.6	[OHC]		<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
-----	-------	--	---------------	-------	-----	---------------	-----


**PEUGEOT**
**1007**

1.4 i 16V	ET3	04.2005 ▶	● <b>246563</b>	RV90LDC	0.9		
1.4 i 8v	TU3A	04.2005 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## PEUGEOT (.../...)

### 1007 (.../...)

1.6 i 16v	TU5JP4	04.2005 ▶	<b>246520</b>	RF74LZDC	0.9		
<b>104</b>							
1.0 GL, GR, Z, ZA, ZL	XV	09.1983 ▶ 06.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.2 SR	XZ	▶ 06.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4 S	XY6B [150]	▶ 06.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4 S	XY7 [150D]	▶ 05.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4 S	XY7 [150D]	▶ 05.1988	<b>●246560</b>	RF74HZK	0.6	<b>246554</b>	F87
1.4 ZS	XY8	07.1982 ▶ 06.1986			0.6	<b>246565</b>	C60
1.4 ZS2	XYR	▶ 06.1988	<b>246021</b>	C60H	0.6	<b>246565</b>	C60

### 106

1.0	TU9 [C1A] [C1B]	09.1991 ▶ 04.1996	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.0 i	TU9M [CDZ]	07.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.0 i	TU9M [CDZ]	07.1992 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	TU1 [H1A] [H3A]	09.1991 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1 i	TU1JP-L4 [HFZ]	05.2000 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1JP-L4 [HFZ]	05.2000 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1 i	TU1M+ [HDY] [HDZ]	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1M+ [HDY] [HDZ]	04.1996 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.3 i Rallye	TU2J2 [MFZ]	▶ 04.1996	<b>●246322</b>	RF72H3	1.2		
1.4	TU3.2 [K2D-K5A]	09.1991 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3.2 [K2D-K5A]	09.1991 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A]	09.1991 ▶ 04.1996	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3TR [K3A]	09.1991 ▶ 04.1996	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i	TU3J2 [K6B] [KFZ]	09.1991 ▶ 04.1996	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3JP [KFX]	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3JP [KFX]	04.1996 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i	TU3M [KDX] [KDY]	07.1995 ▶ 04.1996	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3M [KDX] [KDY]	07.1995 ▶ 04.1996	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ]	06.1993 ▶ 06.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	TU5JP [NFZ]	06.1993 ▶ 06.1995	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i Rallye, S16, XSi	TU5J2 [NFY-NFW]	07.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i Rallye, S16, XSi	TU5J2 [NFY-NFW]	07.1995 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6 i 16V GTi, S16	TU5 J4 [NFX]	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i 16V GTi, S16	TU5 J4 [NFX]	04.1996 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87

### 107


1.0 i 12v		09.2005 ▶	<b>246520</b>	RF74LZDC	0.9		
-----------	--	-----------	---------------	----------	-----	--	--

### 204

Tous modèles (all models)		10.1965 ▶ 06.1974	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
Tous modèles (all models)		07.1975 ▶ 07.1977	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79

### 205

1.0	TU9 [C1A] [C1B]	10.1987 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.0	XV8 [108C]	02.1983 ▶ 10.1990	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.0 i	TU9M [CDY] [CDZ]	07.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.0 i	TU9M [CDY] [CDZ]	07.1992 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	E1A [M103]	10.1987 ▶ 10.1989	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	TU1 [H1A] [H1B] [H1C]	10.1987 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.1	XW7 [109..]	02.1983 ▶ 10.1990	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.1 i	TU1M [HDY] [HDZ]	07.1989 ▶ 06.1995	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.1 i	TU1M [HDY] [HDZ]	07.1989 ▶ 06.1995	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.3	G1A [M104]	10.1987 ▶ 09.1998	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	F1	10.1987 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	TU3	10.1987 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4	TU3	10.1987 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4	XY6B [150]	02.1983 ▶ 10.1990	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4	XY7 [150D]	02.1983 ▶ 05.1988	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4	XY7 [150D]	02.1983 ▶ 05.1988	<b>●246560</b>	RF74HZK	0.6	<b>246554</b>	F87
1.4	XY7CP [KAZ]	02.1983 ▶ 10.1990			0.6	<b>246566</b>	C79
1.4	XY8	02.1983 ▶ 12.1988			0.6	<b>246565</b>	C60
1.4	Y2	10.1987 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.4 i	TU3 [KDX] [KDY] [KDJ]	07.1988 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.4 i	TU3 [KDX] [KDY] [KDJ]	07.1988 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6	J2	06.1989 ▶	<b>●246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.6	XU51C [B1A]	02.1983 ▶ 06.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.6	XU51C [B1A]	02.1983 ▶ 06.1987	<b>●246560</b>	RF74HZK	0.6	<b>246554</b>	F87
1.6	XU5CP [BAZ]	02.1983 ▶ 06.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79


**PEUGEOT** (.../...)

**205 (.../...)**

1.6	XU5CP [BAZ]	07.1987 ▶ 09.1998	●246560	RF74HZK	0.6	246554	F87
1.6 i CTI, GTI	XU5J1	07.1987 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i CTI, GTI	XU5JA [B6E]	06.1985 ▶ 06.1987			0.6	246565	C60
1.6 i CTI, GTI	XU5JA [B6E]	06.1985 ▶ 06.1987	●246560	RF74HZK	0.6	246554	F87
1.6 i GTi	XU5J [180A]	02.1983 ▶ 06.1987			0.6	246565	C60
1.6 i GTi	XU5J [180A]	02.1983 ▶ 06.1987	●246560	RF74HZK	0.6	246554	F87
1.9 i CTI, Gentry, GTI, Open, Sport, Summer GTI	XU9 JA-Z [DFY] [DKZ]	07.1987 ▶	246487	RF74HZDC	0.9	246554	F87
1.9 i CTI, Gentry, GTI, Open, Sport, Summer GTI	XU9 JA-Z [DFY] [DKZ]	07.1987 ▶	●246560	RF74HZK	0.9	246554	F87
1.9 i Gentry, Griffe, GTI, Rallye	XU9 JA [D6A][D6B]	10.1986 ▶	●246560	RF74HZK	0.9	246554	F87

**206**

1.1 i	TU1JP [HFX] [HFY] [HFZ]	09.1998 ▶	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1JP [HFX] [HFY] [HFZ]	09.1998 ▶	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3JP [K6C] [KFX] [KFW]	09.1998 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3JP [K6C] [KFX] [KFW]	09.1998 ▶	●246560	RF74HZK	0.9	246554	F87
1.4 i 16V	ET3	11.2003 ▶	●246563	RV90LDC	0.9		
1.6 i Roland Garros, XS, XT, XT Premium	TU5JP-L3 [NFZ]	09.1998 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i Roland Garros, XS, XT, XT Premium	TU5JP-L3 [NFZ]	09.1998 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	10.2000 ▶	246520	RF74LZDC	0.9		
2.0 i 16V	EW10 J4-L3 [RFR]	05.1999 ▶	246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L3 [RFR]	05.1999 ▶	●246562	RF80LZDC3	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.1999 ▶	246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.1999 ▶	●246562	RF80LZDC3	0.9		
2.0 i 16V S16	EW10 J4S2 [RFK]	03.2001 ▶	246519	RF80LZDC	0.9		
2.0 i 16V S16	EW10 J4S2 [RFK]	03.2001 ▶	●246562	RF80LZDC3	0.9		

**304**

Tous modèles (all models)		10.1975 ▶	246190	RC68H	0.6	246566	C79
---------------------------	--	-----------	--------	-------	-----	--------	-----

**305**

1.1 GL, SR	XK5	10.1982 ▶ 06.1988	246190	RC68H	0.6	246566	C79
1.3 GL, GR	XL5 [118-118B-118TR]	10.1982 ▶ 07.1990	246190	RC68H	0.6	246566	C79
1.5 EXL, GL, GLS, GR, S, SR	XR5 [117-142-142X]	10.1982 ▶ 07.1990	246190	RC68H	0.6	246566	C79
1.6	XU5CP [BAZ], XU51C [B1A]	08.1987 ▶ 07.1990	●246560	RF74HZK	0.6	246554	F87
1.6	XU5S [171C]	10.1982 ▶ 07.1990			0.6	246565	C60
1.9 GR, GT, GTX, SR	XU9 S [159A]	10.1982 ▶ 07.1990			0.6	246565	C60
1.9 GTX, SR	XU92 C [D2A]	07.1982 ▶ 07.1987	246190	RC68H	0.6	246566	C79
1.9 GTX, SR	XU92 C [D2A]	08.1987 ▶ 07.1990	●246560	RF74HZK	0.6	246554	F87
1.9 i GTX, SR	XU9J1 [DFZ]	07.1982 ▶ 07.1987	246190	RC68H	0.6	246566	C79
1.9 i GTX, SR	XU9J1 [DFZ]	08.1987 ▶ 07.1990	●246560	RF74HZK	0.6	246554	F87

**306**

1.1 i	TU1M [HDY] [HDZ]	05.1993 ▶ 04.1997	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1M [HDY] [HDZ]	05.1993 ▶ 04.1997	●246560	RF74HZK	0.9	246554	F87
1.4 XN, XR	TU3 [K2D-K3A-K5A]	01.1993 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 XN, XR	TU3 [K2D-K3A-K5A]	01.1993 ▶	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3JP [KFX]	09.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3JP [KFX]	09.1996 ▶	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3MC [KDX]	07.1995 ▶ 04.1997	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3MC [KDX]	07.1995 ▶ 04.1997	●246560	RF74HZK	0.9	246554	F87
1.6 i	TU5JP [NFZ]	01.1993 ▶ 06.1995	246487	RF74HZDC	0.9	246554	F87
1.6 i	TU5JP [NFZ]	01.1993 ▶ 06.1995	●246560	RF74HZK	0.9	246554	F87
1.8 i	XU7 JP [LFZ] [L6A]	01.1993 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i	XU7 JP [LFZ] [L6A]	01.1993 ▶	●246560	RF74HZK	0.9	246554	F87
1.8 i 16V	XU7 JP4 [LFY]	04.1997 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i 16V	XU7 JP4 [LFY]	04.1997 ▶	●246560	RF74HZK	0.9	246554	F87
2.0 i	XU10 J2C [RFX] [R6D]	08.1993 ▶ 04.1997	246487	RF74HZDC	0.9	246554	F87
2.0 i	XU10 J2C [RFX] [R6D]	08.1993 ▶ 04.1997	●246560	RF74HZK	0.9	246554	F87
2.0 i 16V	XU10 J4R [R6E] [RFV]	04.1997 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	XU10 J4R [R6E] [RFV]	04.1997 ▶	●246560	RF74HZK	0.9	246554	F87
2.0 i 16V GTi, S16, XSi	XU10 J4RS-L3	06.1996 ▶ 10.2000			0.9	246554	F87
2.0 i 16V S16, Le Mans	XU10 J4-L [RFT] [RFY]	08.1993 ▶ 04.1997	246487	RF74HZDC	0.9	246554	F87

**307**

1.4 i	TU3JP [KFW]		246487	RF74HZDC	0.9	246554	F87
1.4 i 16V	ET3	11.2003 ▶	●246563	RV90LDC	0.9		
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]		246520	RF74LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		246519	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		●246562	RF80LZDC3	0.9		





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## PEUGEOT (.../...)

### 309

1.1	E1A [M103]	10.1985 ▶ 12.1991	●246560	RF74HZK	0.9	246554	F87
1.1	TU1 [H1A] [H1B]	07.1989 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.1 i	TU1M [HDY]	10.1990 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.1 i	TU1M [HDY]	10.1990 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.3	G1 [G1A-G1B], G2 [G2S]	10.1985 ▶ 12.1991	●246560	RF74HZK	0.9	246554	F87
1.4	TU3 S [K2A-K2B]	01.1989 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.4	TU3A [K1D-K1F-K1G-K2D-K3A]	01.1989 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.4	TU3A [K1D-K1F-K1G-K2D-K3A]	01.1989 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.4	Y2	10.1986 ▶ 12.1991	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3 [KDY] [KDZ]	10.1988 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3 [KDY] [KDZ]	10.1988 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.6	J2	10.1986 ▶ 12.1991	●246560	RF74HZK	0.9	246554	F87
1.6	XU51C [B1D-B1E]	07.1987 ▶ 12.1990	●246560	RF74HZK	0.9	246554	F87
1.6	XU51CTR [B3A-B3B]	10.1985 ▶ 06.1987	246190	RC68H	0.6	246566	C79
1.6	XU51CTR [B3A-B3B]	10.1985 ▶ 06.1987	●246560	RF74HZK	0.6	246554	F87
1.6	XU52C [B2A-B2B-B2C-B5A]	07.1988 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.6	XU52C [B2A-B2B-B2C-B5A]	07.1988 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.6	XU5CP [BAZ] [BAY]	10.1985 ▶ 06.1987	246190	RC68H	0.6	246566	C79
1.6	XU5CP [BAZ] [BAY]	10.1985 ▶ 06.1987	●246560	RF74HZK	0.6	246554	F87
1.6 i	XU5J1 [B6A-B6B]	07.1987 ▶ 09.1988	●246560	RF74HZK	0.9	246554	F87
1.6 i	XU5JA [B6D] [B6E]	07.1987 ▶ 12.1993	●246560	RF74HZK	0.6	246554	F87
1.6 i	XU5JA [B6D] [B6E]	11.1985 ▶ 06.1987			0.6	246565	C60
1.9	XU92 C [159A-D2A-D2B]	10.1985 ▶ 06.1987			0.6	246565	C60
1.9	XU92 C [D2A-D2B]	07.1987 ▶ 09.1990	●246560	RF74HZK	0.9	246554	F87
1.9	XU92 C [D2H-D2F]	10.1990 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.9 i	XU9 J1 [DFZ]	03.1986 ▶ 06.1987	246190	RC68H	0.6	246566	C79
1.9 i	XU9 J1 [DFZ]	03.1986 ▶ 06.1987	246487	RF74HZDC	0.6	246554	F87
1.9 i	XU9 JA [D6B]	10.1986 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.9 i	XU9 JA-Z [DFY] [DKZ]	07.1987 ▶ 12.1993	246487	RF74HZDC	0.9	246554	F87
1.9 i	XU9 JA-Z [DFY] [DKZ]	07.1987 ▶ 12.1993	●246560	RF74HZK	0.9	246554	F87
1.9 i 16V GTi 16S	XU9 J4 [D6C]	07.1990 ▶ 12.1993	●246322	RF72H3	1.2		

### 404

Modèles à carburateur (carburetor models)		10.1963 ▶	246180	R84H	0.6	246555	H79
Modèles à injection (injection models)		10.1963 ▶	246178	R64H	0.6	246557	H60

### 405

1.4	TU3 [K1G] [K1A] [K5A]	▶ 06.1992	●246560	RF74HZK	0.9	246554	F87
1.4	TU3.2 [K2D]	▶ 06.1995	246487	RF74HZDC	0.9	246554	F87
1.4	TU3.2 [K2D]	▶ 06.1995	●246560	RF74HZK	0.9	246554	F87
1.4	TU3.2 [K5A]	▶ 06.1992	246487	RF74HZDC	0.9	246554	F87
1.4	TU3A [K1G]	07.1992 ▶ 06.1995	246487	RF74HZDC	0.9	246554	F87
1.4	TU3A [K1G]	07.1992 ▶ 06.1995	●246560	RF74HZK	0.9	246554	F87
1.4	TU3TR [K3A]	07.1987 ▶ 06.1992	246487	RF74HZDC	0.9	246554	F87
1.4	TU3TR [K3A]	07.1987 ▶ 06.1992	●246560	RF74HZK	0.9	246554	F87
1.4 i	TU3 [KDX]	07.1992 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 i	TU3 [KDX]	07.1992 ▶	●246560	RF74HZK	0.9	246554	F87
1.6	XU51C [B1D-B1E]	01.1987 ▶ 06.1992	●246560	RF74HZK	0.9	246554	F87
1.6	XU51CTR [B3A-B3B]	01.1987 ▶ 06.1987	246190	RC68H	0.6	246566	C79
	XU5CP [BAY] [BAZ]						
1.6	XU51CTR [B3A-B3B]	07.1987 ▶ 06.1992	●246560	RF74HZK	0.6	246554	F87
	XU5CP [BAY] [BAZ]						
1.6	XU52C [B2A-B2B-B2C-B5A]	01.1987 ▶ 10.1995	246487	RF74HZDC	0.9	246554	F87
1.6	XU52C [B2A-B2B-B2C-B5A]	01.1987 ▶ 10.1995	●246560	RF74HZK	0.9	246554	F87
1.6 i	XU5JP-Z [BFZ]	09.1994 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i	XU5JP-Z [BFZ]	09.1994 ▶	●246560	RF74HZK	0.9	246554	F87
1.6 i	XU5M [BDY-BDZ]	07.1989 ▶ 10.1995	246487	RF74HZDC	0.9	246554	F87
1.6 i	XU5M [BDY-BDZ]	07.1989 ▶ 10.1995	●246560	RF74HZK	0.9	246554	F87
1.8 i	XU7 JP [L6A] [LFZ]	06.1992 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i	XU7 JP [L6A] [LFZ]	06.1992 ▶	●246560	RF74HZK	0.9	246554	F87
1.9	XU92 [D2C-D2D-D2H-D5A]	11.1987 ▶ 12.1992	246487	RF74HZDC	0.9	246554	F87
1.9	XU92 [D2C-D2D-D2H-D5A]	11.1987 ▶ 12.1992	●246560	RF74HZK	0.9	246554	F87
1.9 i	XU9 JA-J1-J2 [DFZ] [D6A] [D6D] [DFV] [DFY] [DKZ]	▶ 12.1992	246487	RF74HZDC	0.9	246554	F87
1.9 i	XU9 JA-J1-J2 [DFZ] [D6A] [D6D] [DFV] [DFY] [DKZ]	▶ 12.1992	●246560	RF74HZK	0.9	246554	F87
1.9 i	XU9 M [DDZ]	▶ 12.1992	246487	RF74HZDC	0.9	246554	F87
1.9 i	XU9 M [DDZ]	▶ 12.1992	●246560	RF74HZK	0.9	246554	F87
1.9 i 16V Mi16	XU9 J4 [D6C]	01.1987 ▶ 11.1991	●246322	RF72H3	1.2		




**PEUGEOT** (.../...)

**405 (.../...)**

2.0 i GRi, GRi 4x4, SRi, SRX4, STi, Signature	XU10 J2C [RFX] [R6D]	08.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i GRi, GRi 4x4, SRi, SRX4, STi, Signature	XU10 J2C [RFX] [R6D]	08.1992 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V Mi16, Le Mans	XU10 J4-Z [RFY]	08.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V Mi16, Le Mans	XU10 J4-Z [RFY]	08.1992 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87

**406**

1.6 i	XU5JP-Z [BFZ]	11.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.6 i	XU5JP-Z [BFZ]	11.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i	XU7 JP [L6A], XU7 JB [LFX]	01.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i	XU7 JP [L6A], XU7 JB [LFX]	01.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
1.8 i 16V	EW 7 J4 [6FZ]	05.2000 ▶	<b>246519</b>	RF80LZDC	0.9		
1.8 i 16V	EW 7 J4 [6FZ]	05.2000 ▶	● <b>246562</b>	RF80LZDC3	0.9		
1.8 i 16V	XU7 JP4 [LFY]	01.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
1.8 i 16V	XU7 JP4 [LFY]	01.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	EW10 J4 [RFN] [DOHC] [RFR]	05.1999 ▶	<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4 [RFN] [DOHC] [RFR]	05.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9		
2.0 i 16V	XU10 J4R [R6E] [RFV]	01.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [R6E] [RFV]	01.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V Coupé	XU10 J4R [R6E] [RFV]	01.1997 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V Coupé	XU10 J4R [R6E] [RFV]	01.1997 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Turbo SV	XU10 J2TE [RGX]	04.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	10.1999 ▶	<b>246519</b>	RF80LZDC	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	10.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9		
3.0 i V6 24V	ES 9 J4-L3 [XFZ]	10.1996 ▶			0.9	<b>246554</b>	F87

**407**

1.8 i 16V	EW 7 J4 [6FZ]		<b>246519</b>	RF80LZDC	0.9		
1.8 i 16V	EW 7 J4 [6FZ]		● <b>246562</b>	RF80LZDC3	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]		● <b>246562</b>	RF80LZDC3	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat		<b>246519</b>	RF80LZDC	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat		● <b>246562</b>	RF80LZDC3	0.9		

**504**

1.6 GR	XC7	10.1979 ▶ 12.1990	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.8 L, GL, GR, SR	XM	01.1971 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.8 i L, GL, GR, SR	KF5, KF6		<b>246178</b>	R64H	0.6	<b>246557</b>	H60
2.0 L, GL, GR, SR, Ti	XN1/A	01.1971 ▶ 12.1990	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
2.0 i L, GL, GR, SR, Ti	XN2	07.1968 ▶ 10.1977	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
2.0 i L, GL, GR, SR, Ti	XN2	10.1977 ▶ 12.1990	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
2.7 i V6 Cabriolet, Coupé	ZM, ZMJ	08.1977 ▶ 06.1983	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79

**505**

1.6 GL, GR, SR, SX	XC7	05.1979 ▶ 12.1993	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.8 GL, GR, SR, SX	XM7/A	05.1979 ▶ 12.1993	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
2.0 GL, GR, SR, ST, SX	XN1/A, XN6	05.1979 ▶ 12.1993	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
2.0 i GTi, STi, Ti	ZEJ	08.1979 ▶ 12.1989			0.6	<b>246565</b>	C60
2.2 i GTi	ZDJK, ZDJL	05.1981 ▶ 12.1993			0.6	<b>246565</b>	C60
2.2 i Turbo	N9T	10.1982 ▶ 06.1988	<b>246178</b>	R64H	0.6	<b>246557</b>	H60
2.2 i Turbo	N9TE Cat	10.1982 ▶ 06.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

**604**

2.0 i	XN6	▶ 12.1983	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
2.7 i V6 SL, STi, Ti	ZM, ZMJ	08.1975 ▶ 06.1985	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
2.8 i V6 GTi, Ti	ZNJ, ZNJ-K	10.1982 ▶ 06.1986	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79

**605**

2.0 SL, SR	XU10.2C [R2A] [R5A]	10.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i	XU10 J2 [RFX] [R6D] [RFZ] [R6A]	06.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 J2 [RFX] [R6D] [RFZ] [R6A]	06.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i	XU10 M-Z [RDZ]	06.1989 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i	XU10 M-Z [RDZ]	06.1989 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [R6E] [RFV]	07.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	XU10 J4R [R6E] [RFV]	07.1995 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87
2.0 i Turbo	XU10 J2TE [RGX] [RGY]	07.1992 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
3.0 i V6 24V	ES 9 J4-L3 [XFZ]	12.1996 ▶ 05.1999			0.9	<b>246554</b>	F87

**607**

2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	10.1999 ▶	<b>246519</b>	RF80LZDC	0.9		
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	10.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	10.1999 ▶	<b>246519</b>	RF80LZDC	0.9		
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	10.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## PEUGEOT (.../...)

806								
1.8 i	XU7 JP [LFW]	07.1996 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.8 i	XU7 JP [LFW]	07.1996 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
2.0 i	XU10 J2C [RFU]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0 i	XU10 J2C [RFU]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.2000 ▶	<b>246519</b>	RF80LZDC	0.9			
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.2000 ▶	● <b>246562</b>	RF80LZDC3	0.9			
2.0 i 16V	XU10 J4R [RFV] [R6E]	05.1998 ▶ 09.2000	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0 i 16V	XU10 J4R [RFV] [R6E]	05.1998 ▶ 09.2000	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
2.0 i Turbo	XU10 J2TE [RGX]	06.1994 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
807								
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	04.2002 ▶	<b>246519</b>	RF80LZDC	0.9			
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	04.2002 ▶	● <b>246562</b>	RF80LZDC3	0.9			
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	04.2002 ▶	<b>246519</b>	RF80LZDC	0.9			
2.2 i 16V	EW12 J4 [3FZ] [DOHC] Cat	04.2002 ▶	● <b>246562</b>	RF80LZDC3	0.9			
P4								
	XN8		<b>246180</b>	R84H	0.7	<b>246555</b>	H79	

## PEUGEOT

BOXER								
2.0	XU10.2CU		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0	XU10.2CU		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
2.0 i	XU10 J2U [RFW]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0 i	XU10 J2U [RFW]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
EXPERT								
1.6 i	1580 SPI	10.1995 ▶	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59	
1.8 i	XU7 JP [L6B]	10.1995 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.1999 ▶	<b>246519</b>	RF80LZDC	0.9			
2.0 i 16V	EW10 J4-L4 [RFN] [DOHC]	05.1999 ▶	● <b>246562</b>	RF80LZDC3	0.9			
J5								
1.8	XM7 T	▶ 08.1988	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
2.0	XN1	09.1981 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
J7								
1.6	XC7P	01.1974 ▶	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.8	XM7 P		<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
J9								
1.6	XC7P		<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
2.0	XN1P		<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
PARTNER								
1.1 i	TU1JP-L3 [HFY] [HFZ]	05.2000 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.1 i	TU1JP-L3 [HFY] [HFZ]	05.2000 ▶	● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
1.1 i	TU1M+ [HDZ]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.1 i	TU1M+ [HDZ]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
1.4	TU3.2 [K5A]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.4	TU3.2 [K5A]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
1.4 i	TU3JP [KFX]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.4 i	TU3JP [KFX]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	
1.6 i 16V	TU5 JP4-L4 [NFU] [DOHC]	10.2000 ▶	<b>246520</b>	RF74LZDC	0.9			
1.8 i	XU7 JB [LFX]		<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.8 i	XU7 JB [LFX]		● <b>246560</b>	RF74HZK	0.9	<b>246554</b>	F87	

## PIAGGIO

APECAR, VESPACAR								
0.4 Poker Quadriciclo					0.8	<b>246557</b>	H60	
MINIVAN								
1.0 Porter		12.1992 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	

## PLYMOUTH

BREEZE								
2.0 i 16V		08.1995 ▶			0.8	<b>246556</b>	F87-11	
FURY								
5.2 V8		01.1986 ▶ 12.1989	<b>246182</b>	R92H	0.9			
LASER								
1.8	4G37	09.1989 ▶			1.1	<b>246564</b>	H79-11	
2.0 Turbo	4G63	09.1989 ▶			1.1	<b>246564</b>	H79-11	
PROWLER								
3.5 i	(F)	08.1996 ▶			1.1	<b>246556</b>	F87-11	



<b>PLYMOUTH</b> (.../...)										
<b>SUNDANCE</b>										
2.2 i						01.1987 ▶	<b>246182</b>	R92H	0.9	
2.5 i						01.1988 ▶	<b>246182</b>	R92H	0.9	
<b>VOYAGER</b>										
2.2	(C)					01.1986 ▶ 12.1987	<b>246182</b>	R92H	0.9	
2.5 i						01.1987 ▶	<b>246182</b>	R92H	0.9	
2.6	(G)					01.1986 ▶ 12.1987	<b>246182</b>	R92H	0.9	
<b>PONTIAC</b>										
<b>GRAND AM</b>										
2.0 i Turbo	(M)					09.1986 ▶ 08.1989	<b>246179</b>	R76H	0.8	<b>246555</b> H79
2.3						08.1991 ▶	<b>246186</b>	RF82H	0.9	<b>246554</b> F87
2.3 16V	(D) [DOHC]					08.1991 ▶	<b>246186</b>	RF82H	0.9	<b>246554</b> F87
2.3 16V GT	(D) [DOHC]					08.1991 ▶	<b>246186</b>	RF82H	0.9	<b>246554</b> F87
<b>SUNBIRD</b>										
1.8 i Turbo	(J)					01.1984 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b> H79
2.0 i Turbo	(M)					01.1988 ▶ 12.1990	<b>246182</b>	R92H	0.8	
<b>TRANS SPORT</b>										
2.3 i 16V	[DOHC]					08.1991 ▶			1.1	<b>246556</b> F87-11
<b>PORSCHE</b>										
<b>911</b>										
3.2 Carrera	930.21, 930.25					09.1983 ▶ 08.1989	<b>246179</b>	R76H	0.7	<b>246555</b> H79
<b>924</b>										
2.0 i	XG, XJ, XK					01.1976 ▶ 08.1985	<b>246178</b>	R64H	0.7	<b>246557</b> H60
2.5 i S	M44.07, 08, 09, 10					09.1985 ▶ 07.1988	<b>246179</b>	R76H	0.8	<b>246555</b> H79
<b>928</b>										
4.5						05.1977 ▶ 07.1982	<b>246180</b>	R84H	0.7	<b>246555</b> H79
4.7 S	M28.11, 12, 21, 22					08.1983 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b> H79
5.0 CS, GT, S4	M28.41, 42, 47					08.1986 ▶ 07.1991	<b>246179</b>	R76H	0.7	<b>246555</b> H79
5.0 S	M28.43, 44, 45, 46					12.1984 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b> H79
5.4 i V8 32V GTS	M28.49, 50					08.1991 ▶ 11.1995	<b>246179</b>	R76H	0.7	<b>246555</b> H79
<b>944</b>										
2.5	M44.01, 03					07.1981 ▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b> H79
2.5	M44.05, 06, 09, 10					01.1985 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b> H79
2.5 S	M44.40					08.1986 ▶ 07.1988	<b>246198</b>	R70H	0.7	<b>246557</b> H60
2.5 i	M44.07, 08					01.1985 ▶ 07.1987	<b>246179</b>	R76H	0.8	<b>246555</b> H79
2.5 Turbo	M44.50, 51, 52					08.1985 ▶ 07.1991	<b>246179</b>	R76H	0.7	<b>246555</b> H79
2.7	M44.11, 12					11.1988 ▶ 08.1989	<b>246179</b>	R76H	0.7	<b>246555</b> H79
3.0 S2	M44.41					12.1988 ▶ 07.1991	<b>246178</b>	R64H	0.7	<b>246557</b> H60
<b>968</b>										
3.0 i 16V CS	M44.43, 44					08.1991 ▶ 11.1995			0.8	<b>246557</b> H60
3.0 Turbo S						08.1991 ▶ 11.1995	<b>246173</b>	RF74H	0.7	<b>246554</b> F87
<b>BOXSTER</b>										
2.5 i L6 24V	M96.20					09.1996 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b> F87
<b>PREMIER</b>										
<b>PREMIER</b>										
118 : 1.2 NE	A12					10.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b> H79
<b>PROTON</b>										
<b>PERSONA</b>										
1.3 i 12V	4G13 B					01.1993 ▶			1.1	<b>246564</b> H79-11
1.5 i	4G15					01.1993 ▶			1.1	<b>246564</b> H79-11
1.6 i 16V	4G92 [DOHC] Cat					01.1993 ▶			1.1	<b>246556</b> F87-11
1.8 i	4G93 [SOHC] Cat					12.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11
<b>PERSONA 300</b>										
300 : 1.3 i	4G13 B					03.1996 ▶	<b>246179</b>	R76H	1.1	<b>246555</b> H79
300 : 1.5 i	G15B					03.1996 ▶	<b>246179</b>	R76H	1.1	<b>246555</b> H79
<b>PERSONA 400</b>										
400 : 1.3 i GLSi	4G13 B					01.1996 ▶			1.1	<b>246564</b> H79-11
400 : 1.5 i GLi, GLSi	4G15 Cat					11.1994 ▶			1.1	<b>246564</b> H79-11
400 : 1.6 i 16V GLXi	4G92 [DOHC] Cat					11.1994 ▶			1.1	<b>246556</b> F87-11
400 : 1.8 i	4G93 [SOHC] Cat					12.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b> F87-11
<b>SALOON</b>										
1.3 i	G13B					01.1989 ▶	<b>246179</b>	R76H	1.1	<b>246555</b> H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## PROTON (.../...)

### SALOON (.../...)

1.3 i Saloon	G13B Cat	01.1993 ▶			1.1	<b>246564</b>	H79-11
1.5 i	G15B	01.1989 ▶	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.5 i Saloon	G15B	01.1993 ▶			1.1	<b>246564</b>	H79-11

### SATRIA

1.3 i 12V GL	4G13 [SOHC] Cat	02.1995 ▶	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
--------------	-----------------	-----------	---------------	------	-----	---------------	-----

### TIARA

1.1	TU1-K [H1A]	05.1996 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
-----	-------------	-----------	---------------	-------	-----	---------------	-----

## RELIANT

### ANADOL

			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--	--	--	---------------	------	-----	---------------	-----

### KITTEN

0.8		01.1974 ▶ 12.1984	<b>246182</b>	R92H	0.8		
-----	--	-------------------	---------------	------	-----	--	--

### SCIMITAR

1.3 SS1		09.1984 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.4 SS1		09.1984 ▶ 01.1990	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.6 SS1		10.1984 ▶ 01.1990	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.8 i Turbo SS1	CA18ET	03.1986 ▶ 11.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.8 i V6 Break		10.1975 ▶ 09.1990	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.8 i V6 Cabriolet		10.1975 ▶ 09.1990	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
3.0	3012E	01.1985 ▶ 12.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### SCIMITAR SABRE

1.4 i 16V	K 16 series [DOHC]	10.1993 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
1.8 i Turbo	CA18ET	10.1993 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	T16 [DOHC]	01.1994 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

### TW9 PICK-UP

TW9 Pick-up		01.1975 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------------	--	-----------	---------------	------	-----	---------------	-----

## RENAULT

### 10

1.3			<b>246189</b>	R88N	0.6		
-----	--	--	---------------	------	-----	--	--

### 11

1.1	C1E- 715, 720	09.1981 ▶ 03.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2	C1G- 700, 710	10.1984 ▶ 03.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	C1J, C2J	09.1981 ▶ 03.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 i	C3J- 700, 756	06.1987 ▶ 03.1991	<b>246181</b>	R90H	0.8		
1.4 Turbo	C1J- 760, 764, 770, 782	09.1983 ▶ 03.1991	<b>246170</b>	67HP	0.65		
1.7	F2N- 700, 704, 708, 730, 732 796, 798	10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 i	F2N- 712, 742	10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 i	F3N- 708, 722	10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 i	F3N- 718	10.1983 ▶ 03.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### 12

1.3	810- 702, 702A, 702B, 705, 706	▶ 08.1980	<b>246189</b>	R88N	0.6		
1.4	847- 705/706	▶ 08.1980	<b>246189</b>	R88N	0.6		

### 14

1.2	129- 700, 710	05.1976 ▶ 06.1983	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79
1.4	145-700, 150-700	09.1979 ▶ 06.1983	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79

### 15

1.3		▶ 08.1979	<b>246189</b>	R88N	0.6		
1.6		▶ 12.1976	<b>246179</b>	R76H	0.6	<b>246555</b>	H79

### 16

1.6	697, 807	▶ 07.1976	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6	821, 841	▶ 08.1980	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6	843, 701, 843-702	▶ 07.1979	<b>246179</b>	R76H	0.6	<b>246555</b>	H79

### 17

1.6		▶ 08.1979	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

### 18

1.4	847-720 847-721, 847-722	04.1978 ▶ 02.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6	841-717, 718, 727, 728	04.1978 ▶ 02.1986	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
1.6	A2M- 723, 725, 726, 795	04.1978 ▶ 02.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6	A6M-725, A6M-726	10.1981 ▶ 02.1986	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
1.6 Turbo	717, 718, 727, 752	10.1980 ▶ 09.1985	<b>246170</b>	67HP	0.6		
2.2 i TX	J7T- 718, 719	10.1983 ▶ 02.1986	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79
4x4 : 2.0 GTX, TX	J6R- 711, 714, 715, 716	11.1981 ▶ 02.1986	<b>246021</b>	C60H	0.7	<b>246565</b>	C60



3+1


**RENAULT** (.../...)

<b>19</b>								
1.2	C1G- 730	09.1988 ▶	<b>246181</b>	R90H	0.8			
1.2 i	E7F- 730	05.1992 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87	
1.4	C1J- 742	09.1988 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79	
1.4	C2J- 772, 776, 782	09.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.4	E6J- 700, 701, 706	09.1988 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87	
1.4 e	E7J- 700	05.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87	
1.4 i	C3J- 710, 760	09.1988 ▶	<b>246181</b>	R90H	0.8			
1.4 i	E7J- 706, 745, 742	05.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87	
1.4 i	E7J- 707	05.1990 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87	
1.6	C3L		<b>246180</b>	R84H	0.9	<b>246555</b>	H79	
1.7	F2N	09.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F2N- 712	09.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F3N- 718, 740, 741	09.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.7 i	F3N- 742, 743	09.1988 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F3N- 746	09.1988 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60	
1.8 i	F3P	05.1992 ▶	<b>246180</b>	R84H	0.9	<b>246555</b>	H79	
<b>20</b>								
1.6	843- 720, 721	10.1975 ▶ 10.1981	<b>246179</b>	R76H	0.6	<b>246555</b>	H79	
2.0	829- 700, 701, 702, 703	10.1977 ▶ 12.1983	<b>246021</b>	C60H	0.6	<b>246565</b>	C60	
2.0	J6R- 704, 705	10.1977 ▶ 12.1983	<b>246191</b>	RC72H	0.6	<b>246566</b>	C79	
2.2 TX	851- 700, 701	10.1980 ▶ 12.1983	<b>246021</b>	C60H	0.6	<b>246565</b>	C60	
<b>21</b>								
1.4	C2J, C2L	08.1988 ▶ 12.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.7	F2N	03.1986 ▶ 12.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F2N	03.1986 ▶ 12.1994	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F3N	03.1986 ▶ 12.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
2.0	F2R- 702	03.1986 ▶ 03.1992	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
2.0	J6R- 758, 759, 792, 793	03.1986 ▶ 03.1993	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.0 i	J7R- 746, 747	06.1990 ▶ 12.1994			0.9	<b>246566</b>	C79	
2.0 i	J7R- 750, 751	10.1986 ▶ 03.1993	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.0 i 12V	J7R- 740, 754	05.1989 ▶ 12.1994	● <b>246322</b>	RF72H3	1.2			
2.2	J6T- 692, 750, 790, 791, 792	03.1986 ▶ 12.1994	<b>246021</b>	C60H	0.8	<b>246565</b>	C60	
2.2 i	J7T- 754, 755	10.1986 ▶ 12.1995	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.2 i	J7T- 756	10.1986 ▶ 12.1995			0.9	<b>246566</b>	C79	
<b>25</b>								
2.0 i	J6R- 706, 707, 760, 762, 763	01.1984 ▶ 12.1992	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.0 i	J7R- 722, 723	06.1987 ▶ 12.1992	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.0 i 12V	J7R- 720, 721, 726	06.1988 ▶ 07.1991	● <b>246322</b>	RF72H3	1.2			
2.2 i	J7T- 706, 707, 714, 715, 722, 730, 731, 732, 733	01.1984 ▶ 12.1992	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.2 i	J7T- 708	10.1985 ▶ 10.1986	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79	
2.9 i V6	Z7W- 700, 701	10.1986 ▶ 12.1992	<b>246021</b>	C60H	0.8	<b>246565</b>	C60	
2.9 i V6	Z7W- 702, 706, 707, 709	10.1986 ▶ 12.1992			0.8	<b>246565</b>	C60	
<b>30</b>								
2.7		10.1976 ▶ 12.1983	<b>246190</b>	RC68H	0.7	<b>246566</b>	C79	
<b>4</b>								
0.8		10.1976 ▶ 12.1993	<b>246189</b>	R88N	0.6			
0.8 i	680, 800	▶ 12.1993	<b>246189</b>	R88N	0.6			
1.0	C1C- 708	10.1986 ▶ 12.1993	<b>246189</b>	R88N	0.6			
1.1	C1E	10.1976 ▶ 12.1993	<b>246189</b>	R88N	0.6			
<b>5</b>								
0.8	839- 701	10.1972 ▶ 09.1984	<b>246189</b>	R88N	0.6			
0.9	800- 710	10.1972 ▶ 09.1984	<b>246189</b>	R88N	0.6			
1.0	689- 710	10.1972 ▶ 09.1984	<b>246189</b>	R88N	0.6			
1.1	C1E	10.1979 ▶ 03.1985	<b>246189</b>	R88N	0.6			
1.3	810	04.1974 ▶ 09.1984	<b>246189</b>	R88N	0.6			
1.3	810	04.1974 ▶ 12.1981	<b>246189</b>	R88N	0.6			
1.3	810	10.1979 ▶ 09.1984	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.4	847- 712	06.1982 ▶ 07.1984	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.4	847- 725, 729	09.1979 ▶ 09.1984	<b>246181</b>	R90H	0.7			
1.4	C2J- 713	06.1982 ▶ 07.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.4 Alpine, Gordini	840- 725	03.1976 ▶ 09.1981	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79	
<b>6</b>								
0.8	800- 702, 703, 705		<b>246189</b>	R88N	0.6			
1.1	688- 710		<b>246189</b>	R88N	0.6			





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## RENAULT (.../...)

<b>8</b>									
1.1					<b>246189</b>	R88N	0.6		
<b>9</b>									
1.4	C1J, C2J		09.1981 ▶ 03.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.4 i	C3J- 700, 756		06.1987 ▶ 03.1991	<b>246181</b>	R90H	0.8			
1.4 Turbo	C1J- 760, 764, 770, 782		09.1983 ▶ 03.1991	<b>246170</b>	67HP	0.65			
1.7	F2N		10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F2N- 712, 742		10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F3N- 708, 722		10.1983 ▶ 03.1991	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.7 i	F3N- 718		10.1983 ▶ 03.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>A310</b>									
2.7 V6	112- 730/731 (PRV)		09.1976 ▶ 06.1985	<b>246190</b>	RC68H	0.65	<b>246566</b>	C79	
<b>A610</b>									
2.9 V6	Z6W- 700 / 702		03.1985 ▶ 12.1992	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
<b>CLIO 1</b>									
1.0 i	D7D- 760			<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87	
1.1	C1E- 700		06.1990 ▶ 03.1996	<b>246181</b>	R90H	0.75			
1.2	E5F- 710 / 716		06.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
1.2 i	C3G- 700 / 720		09.1995 ▶ 03.1996	<b>246181</b>	R90H	0.75			
1.2 i	D7F- 730		04.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87	
1.2 i	E7F		06.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
1.4	E6J- 712, 713, 718, 760		06.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
1.4 i	E7J		06.1990 ▶ 10.2000	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87	
1.6	C3L			<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.6 i	K7M- 746		▶ 06.2000	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.7	F2N- 770		06.1990 ▶ 03.1996	<b>246178</b>	R64H	0.8	<b>246557</b>	H60	
1.8 i	F3P		06.1990 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>CLIO 2</b>									
1.2 i	D7F- 720, 722, 726, 744, 746 764		09.1998 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87	
1.2 i	D7F- Euro 2000 [OHC] Cat		05.2000 ▶			0.9	<b>246554</b>	F87	
1.2 i 16V	D4F		06.2001 ▶	● <b>246563</b>	RV90LDC	0.9			
1.4 i	E7J		01.1998 ▶ 10.2000	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.4 i	K7J		09.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.4 i 16V	K4J		09.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.6 i	K7M		03.1998 ▶ 06.2000	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.6 i 16V	K4M		09.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
2.0 i 16V	F4R		09.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
<b>CLIO 3</b>									
1.2 i 16V	D4F		09.2005 ▶	● <b>246563</b>	RV90LDC	0.9			
1.4 i 16V	K4J		09.2005 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
1.6 i 16V	K4M		09.2005 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
<b>ESPACE 1</b>									
2.0	J6R- 234-236-734		07.1984 ▶ 12.1990	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.0 i	J7R- 760		06.1987 ▶ 12.1990	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.2 i	J7T- 770		07.1986 ▶ 12.1990	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
<b>ESPACE 2</b>									
2.0 i	J7R- 768		01.1991 ▶ 12.1996	<b>246190</b>	RC68H	0.65	<b>246566</b>	C79	
2.2 i	J7T- 772-773		01.1991 ▶ 12.1996	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
2.2 i	J7T- 776		01.1991 ▶ 12.1996			0.65	<b>246566</b>	C79	
2.9 i V6	Z7W- 712-713-717		04.1994 ▶ 12.1996	<b>246021</b>	C60H	0.9	<b>246565</b>	C60	
<b>ESPACE 3</b>									
2.0 i	F3R- 728, 729, 742, 768, 769		10.1996 ▶ 06.2000	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
2.0 i 16V	F4R- 700, 701, 702		11.1998 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
<b>ESPACE 4</b>									
2.0 i 16V	F4R		09.2002 ▶	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87	
<b>FUEGO</b>									
1.4	847- 720		03.1980 ▶ 10.1985	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.6	A2M, A6M		03.1980 ▶ 10.1985	<b>246179</b>	R76H	0.6	<b>246555</b>	H79	
1.6 Turbo	A5L-750, 723, 752		09.1983 ▶ 10.1985	<b>246170</b>	67HP	0.6			
2.0	J6R- 710, 711, 712, 713, 714 715, 726		10.1980 ▶ 10.1985	<b>246021</b>	C60H	0.7	<b>246565</b>	C60	
2.2 i	J7T- 718, 719		10.1983 ▶ 10.1985	<b>246191</b>	RC72H	0.7	<b>246566</b>	C79	
<b>KANGOO</b>									
1.0 i	D7D			<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87	
1.2 i	D7F- 710, 720, 722, 726, 744 764		10.1997 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87	



3+1

**RENAULT** (.../...)

**KANGOO (.../...)**

1.2 i 16V	D4F	06.2001 ▶	●246563	RV90LDC	0.9		
1.4 i	E7J	10.1997 ▶ 11.2000	246487	RF74HZDC	0.9	246554	F87
1.4 i	K7J	10.2000 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i	K7M- 746		246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	K4M	04.1998 ▶	246487	RF74HZDC	0.9	246554	F87

**LAGUNA 1**

1.6 i 16V	K4M	04.1998 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i	F3P	01.1994 ▶ 03.2001	246180	R84H	0.8	246555	H79
1.8 i 16V	F4P	04.1998 ▶ 11.2000	246487	RF74HZDC	0.9	246554	F87
2.0 i	F3R	01.1994 ▶ 11.2000	246180	R84H	0.8	246555	H79
2.0 i 16V	F4R	01.1999 ▶ 11.2000	246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	N7Q	01.1995 ▶	246321	RF80H3	1.2		
3.0 i V6 24V	L7X- 700	03.1997 ▶ 05.1998	246492	RF74HZ2Y	0.9	246554	F87

**LAGUNA 2**

1.6 i 16V	K4M	03.2001 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	F4R	01.2001 ▶	246487	RF74HZDC	0.9	246554	F87

**MEGANE 1**

1.4 e	E7J	11.1995 ▶ 10.2000	246487	RF74HZDC	0.9	246554	F87
1.4 i	K7J- 700	03.1999 ▶	246487	RF74HZDC	0.9	246554	F87
1.4 i 16V	K4J	03.1999 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 e	K7M	01.1995 ▶ 09.1998	246487	RF74HZDC	0.9	246554	F87
1.6 i	K7M- 704		246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	K4M	01.1996 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i 16V	F4P- 720, 722	01.2001 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i	F3R	11.1995 ▶	246180	R84H	0.8	246555	H79

**MEGANE 2**

1.4 i 16V	K4J		246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	K4M		246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	F4R		246487	RF74HZDC	0.9	246554	F87

**MEGANE SCENIC 1**

1.4 e	E7J	10.1996 ▶	246176	RF80H	0.8	246554	F87
1.4 i 16V	K4J	09.1999 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 e	K7M- 702	05.1999 ▶	246492	RF74HZ2Y	0.9	246554	F87
1.6 e	K7M- 702, 703, 720	▶ 09.1998	246176	RF80H	0.8	246554	F87
1.6 i 16V	K4M	08.1998 ▶	246487	RF74HZDC	0.9	246554	F87
1.8 i 16V	F4P- 720, 722	01.2001 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i	F3R- 750, 751, 791, 796, 797, 798	10.1996 ▶	246180	R84H	0.8	246555	H79
2.0 i 16V	F4R	09.1999 ▶	246487	RF74HZDC	0.9	246554	F87

**MEGANE SCENIC 2**

1.4 i 16V	K4J	05.2003 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	K4M	05.2003 ▶	246487	RF74HZDC	0.9	246554	F87
2.0 i 16V	F4R	05.2003 ▶	246487	RF74HZDC	0.9	246554	F87

**MODUS**

1.2 i 16V	D4F	01.2004 ▶	●246563	RV90LDC	0.9		
1.4 i 16V	K4J	01.2004 ▶	246487	RF74HZDC	0.9	246554	F87
1.6 i 16V	K4M	01.2004 ▶	246487	RF74HZDC	0.9	246554	F87

**SAFRANE**

2.0 i	J7R- 732, 733	04.1992 ▶ 09.1996			0.9	246566	C79
2.0 i 12V	J7R- 734, 735, 738, 739	04.1992 ▶ 09.1996	●246322	RF72H3	1.2		
2.0 i 16V	N7Q- 710, 711	10.1996 ▶ 07.2000	246321	RF80H3	1.2		
2.2 i	J7T- 762, 763	04.1992 ▶ 09.1996			0.9	246566	C79
2.2 i 12V	J7T- 760, 761	04.1992 ▶ 09.1996	●246322	RF72H3	1.2		
2.5 i 20V	N7U- 700, 701	10.1996 ▶ 07.2000	246176	RF80H	0.9	246554	F87

**SG2, SG4**

2.6		▶ 09.1986	246189	R88N	0.6		
-----	--	-----------	--------	------	-----	--	--

**SUPER 5**

1.0	C1C- 700	10.1984 ▶ 05.1987	246180	R84H	0.8	246555	H79
1.1	C1E	10.1984 ▶ 12.1996	246181	R90H	0.8		
1.2	C1G	10.1984 ▶ 12.1996	246181	R90H	0.8		
1.4	C1J, C2J	10.1984 ▶ 12.1996	246180	R84H	0.8	246555	H79
1.4	C2J- 713	10.1980 ▶ 12.1985	246179	R76H	0.8	246555	H79
1.4 i	C3J- 700, 702, 760	10.1984 ▶ 12.1996	246180	R84H	0.8	246555	H79
1.4 Turbo	C1J- 784, 788	10.1984 ▶ 12.1996	246170	67HP	0.65		
1.7	F2N- 710, 740	06.1987 ▶ 12.1996	246178	R64H	0.8	246557	H60



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## RENAULT (.../...)

### SUPER 5 (.../...)

1.7 i	F3N- 702	10.1986 ▶ 12.1996	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.7 i	F3N- 716, 717, 718	10.1986 ▶ 12.1996	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### TWINGO

1.0 i	D7D		<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
1.2 i	C3G- 700, 702	▶ 06.1999	<b>246181</b>	R90H	0.9		
1.2 i	D7F- 700, 701, 702, 703, 706	06.1996 ▶	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
1.2 i 16V	D4F	01.2001 ▶	<b>246563</b>	RV90LDC	0.9		

## RENAULT

### ESTAFETTE

1.3	688- 701, 810	▶ 09.1980	<b>246189</b>	R88N	0.6		
-----	---------------	-----------	---------------	------	-----	--	--

### EXPRESS, RAPID

1.0	C1C- 706	03.1986 ▶ 08.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.1	C1E- 762, 764	08.1990 ▶	<b>246181</b>	R90H	0.8		
1.1	C1E- 792	03.1986 ▶ 08.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2	C1G- 726, 730	09.1991 ▶	<b>246181</b>	R90H	0.8		
1.2 i	C3G- 710, 712	09.1991 ▶	<b>246181</b>	R90H	0.8		
1.4	C1J, C2J	03.1986 ▶ 08.1991	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4	E6J	09.1991 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.4 i	C3J	03.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.4 i	E7J	09.1991 ▶	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
1.6	C3L		<b>246180</b>	R84H	0.9	<b>246555</b>	H79

### MASTER

2.0 Q..2, 2.0 R..2		10.1980 ▶ 08.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.2 i	J7T- 782	09.1980 ▶			0.9	<b>246566</b>	C79

### R4F4 / R4F6

0.8	B1B- 707	10.1982 ▶ 12.1993	<b>246189</b>	R88N	0.6		
1.1	688- 711	10.1976 ▶ 12.1993	<b>246189</b>	R88N	0.6		
1.1	688- 712	10.1976 ▶ 12.1993	<b>246189</b>	R88N	0.6		

### TRAFIC

1.4 P..0	847- 701	09.1980 ▶ 02.1989	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.4 T..0	C1J- 700	09.1980 ▶ 10.1997	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6 4x4 T..1, V..1	A1M- 707, 708	09.1980 ▶ 02.1989	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.6 P..1	841- 705	09.1980 ▶ 02.1989	<b>246180</b>	R84H	0.6	<b>246555</b>	H79
1.7 P..8, T..8	F1N- 720, 722, 724	10.1984 ▶ 10.1997	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
2.0 P..2		09.1980 ▶ 02.1989	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.0 T..2, V..2	J5R- 716	09.1980 ▶ 10.1997	<b>246180</b>	R84H	0.9	<b>246555</b>	H79
2.2 i T..A, V..A	J7T- 780	03.1989 ▶ 10.1997			0.8	<b>246566</b>	C79

## ROLLS-ROYCE

### CAMARGUE

6.8 V8		02.1980 ▶ 06.1985	<b>246181</b>	R90H	0.8		
--------	--	-------------------	---------------	------	-----	--	--

### CORNICHE

6.8 V8		02.1980 ▶ 06.1985	<b>246181</b>	R90H	0.8		
--------	--	-------------------	---------------	------	-----	--	--

### PHANTOM

6.2 V8			<b>246181</b>	R90H	0.8		
6.8 V8		10.1978 ▶	<b>246181</b>	R90H	0.8		

### SILVER CLOUD II, III

6.2 V8			<b>246181</b>	R90H	0.8		
--------	--	--	---------------	------	-----	--	--

### SILVER SHADOW

6.2 V8			<b>246181</b>	R90H	0.8		
6.8 V8			<b>246181</b>	R90H	0.8		

### SILVER SPIRIT

6.8 V8	[OHV]	▶ 08.1988	<b>246181</b>	R90H	0.8		
--------	-------	-----------	---------------	------	-----	--	--

### SILVER SPUR

6.8 V8	[OHV]	▶ 08.1988	<b>246181</b>	R90H	0.8		
6.8 V8 Turbo	[OHV]	10.1997 ▶	<b>246181</b>	R90H	0.8		

### SILVER WRAITH II

6.8 V8			<b>246181</b>	R90H	0.8		
--------	--	--	---------------	------	-----	--	--


### SILVER DAWN

6.8 V8		10.1997 ▶	<b>246181</b>	R90H	0.8		
--------	--	-----------	---------------	------	-----	--	--

## ROVER

### 100

111 : 1.1 Blue Jazz, Caribbean, Red Note, Sunbury Wesley	11K series	05.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
--	------------	-----------	---------------	-------	-----	---------------	-----



3+1


**ROVER** (.../...)

**100 (.../...)**

111 : 1.1 C, L, LS, S, SL	11K series	05.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
114 : 1.4 SL, GS, GTa	14K series 14K2A, 14K2D	05.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
114 : 1.4 i 16V GTi	K 16 series 14 K4C, 14 K4D 14 K4F [DOHC]	05.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

**200**

213 : 1.3 EX, S, SE, SX, Vanden Plas, Sunbury	EV	06.1984 ▶ 09.1990			1.0	<b>246564</b>	H79-11
214 : 1.4 i S	14K series 14K2F [SOHC]	09.1990 ▶ 03.1996	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
214 : 1.4 i 16V GSi, Si, SLi, Cabrio, Sutton	K 16 series 14 K4C, 14 K4D 14 K4F [DOHC]	10.1989 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
216 : 1.6 EX, SX, S, Sprint	S Series	03.1985 ▶ 10.1992	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
216 : 1.6 i SE, Vanden Plas, Vitesse	S Series	03.1985 ▶ 10.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
216 : 1.6 i 16V	16K series 16K4F [DOHC] Cat	11.1995 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
216 : 1.6 i 16V GSi, Cabrio, Coupé	ZC [SOHC]	10.1989 ▶ 11.1995	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
216 : 1.6 i 16V GTi Twin Cam, Cabrio, Saloon Hatchback	ZC [DOHC]	03.1989 ▶ 03.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
218 : 1.8 i 16V	18K4K	01.1996 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
220 : 2.0 i 16V GTi	T16 [DOHC]	06.1991 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
220 : 2.0 i 16V Turbo	T16 [DOHC]	06.1991 ▶	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59

**2000-3500**

2000 : 2.0 SDi		06.1976 ▶ 10.1986	<b>246191</b>	RC72H	1.1	<b>246566</b>	C79
2300 : 2.3		06.1976 ▶ 10.1986	<b>246191</b>	RC72H	1.1	<b>246566</b>	C79
2600 : 2.6		06.1976 ▶ 10.1986	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79
3500 : 3.5 i V8 S, SE, Vanden Plas, Vitesse		06.1976 ▶ 10.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**400**

414 : 1.4 i GSi	14K series [DOHC]	03.1990 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
414 : 1.4 i 16V Si, SLi, GSi	K 16 series 14K4F [DOHC]	01.1993 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
416 : 1.6 i 16V GSi	D6A	03.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
416 : 1.6 i 16V GTi	ZC [DOHC]	03.1990 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
416 : 1.6 i 16V Si, SLi, Tourer	16K series 16K4F [DOHC] Cat	09.1995 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
418 : 1.8 i 16V	18K4K	01.1996 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
420 : 2.0 i 16V Ti GSi, SLi, Sport, GTI	T16, M16i [DOHC]	10.1991 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
420 : 2.0 i 16V Turbo	T16 [DOHC]	11.1991 ▶	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59

**600**

618 : 1.8 i 16V		09.1995 ▶ 02.1999	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
620 : 2.0 i 16V Turbo	T16 [DOHC]	04.1993 ▶ 02.1999	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
623 : 2.3 i 16V	H23 A2 [DOHC]	04.1993 ▶ 02.1999			1.1	<b>246556</b>	F87-11

**800**

820 : 2.0	O Series	03.1988 ▶ 09.1990	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
820 : 2.0 i 16V	T16 [DOHC]	12.1991 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
820 : 2.0 i 16V E, SE	M16E	10.1986 ▶ 12.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
820 : 2.0 i 16V Si, SLi	M16 i [DOHC]	10.1986 ▶ 12.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
820 : 2.0 i 16V Turbo	T16 [DOHC]	01.1992 ▶	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
825 : 2.5 i V6	K Series	01.1996 ▶ 02.1999	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
825 : 2.5 i V6 Si, Sterling	C25A Cat	07.1986 ▶ 12.1991			1.1	<b>246556</b>	F87-11
827 : 2.7 i S, SLi, Sterling, Vitesse	C27A	02.1988 ▶ 12.1991			1.1	<b>246556</b>	F87-11
827 : 2.7 i Si, SLi, Sterling	C27A	01.1992 ▶ 06.1996			1.1	<b>246556</b>	F87-11

**ALLEGRO**

1100, 1300, 1500, 1750		05.1973 ▶ 03.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
------------------------	--	-------------------	---------------	------	-----	---------------	-----

**AMBASSADOR**

1700, 2000		03.1982 ▶ 12.1984	<b>246190</b>	RC68H	0.7	<b>246566</b>	C79
------------	--	-------------------	---------------	-------	-----	---------------	-----

**ITAL**

1.3 Estate	A Plus	07.1980 ▶ 09.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.7	O Series	07.1980 ▶ 09.1984	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79
2.0		10.1980 ▶ 10.1982	<b>246190</b>	RC68H	0.8	<b>246566</b>	C79

**MAESTRO**

1.3 L, HLE, Van	A Series	03.1983 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	R Series		<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 L, HLS, Van	S Series	03.1983 ▶ 08.1988	<b>246173</b>	RF74H	0.9	<b>246554</b>	F87
1.6 MG	S Series TC	05.1984 ▶ 08.1988	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
2.0 i	O Series	10.1984 ▶ 08.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
500/700 : 1.3 City L	12H		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
500/700 : 1.6 City L	16H		<b>246173</b>	RF74H	0.8	<b>246554</b>	F87

**MARINA**

1300, 1800		▶ 12.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1700 : 1.7		▶ 12.1980	<b>246190</b>	RC68H	0.7	<b>246566</b>	C79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## ROVER (.../...)

MAXI								
1500, 1750, 1750 HL			04.1969 ▶ 10.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
METRO								
1.0 Chelsea, HLE, Kensington, Picadilly, Special Van	A Series		10.1986 ▶ 04.1990	<b>246182</b>	R92H	0.8		
1.0 HLE, Van	A Series		10.1980 ▶ 09.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 Advantage, HLE, Jet Black, Red Hot, Sprite	A Series		10.1980 ▶ 04.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 Turbo	A Series		10.1983 ▶ 04.1990	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
310 : 1.0 City L	99H			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
310 : 1.3 City L	12H			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
MG RV8								
3.9 i V8			09.1992 ▶ 12.1995	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
MINI								
0.8 1.0, 1.1				<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.3 Cooper, DeVille			02.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
MINI VAN								
1.0	A Series		▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
MONTEGO								
1.3	A Series		04.1984 ▶ 10.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 Estate, S	S Series		04.1984 ▶ 08.1988	<b>246176</b>	RF80H	0.9	<b>246554</b>	F87
2.0	O Series		04.1984 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i Turbo Estate, MG, Turbo	O Series Turbo		04.1984 ▶ 08.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
PICK-UP								
1.0	A Series		▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
PRINCESS								
1.7 Princess II HL			▶ 12.1981	<b>246190</b>	RC68H	0.7	<b>246566</b>	C79
1100, 1300			▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1800 : 1.8			▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 Princess II			▶ 12.1981	<b>246190</b>	RC68H	1.1	<b>246566</b>	C79
2200 : 2.2			▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
VANDEN PLAS								
1300, 1500, 1750			▶ 12.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

## SAAB

600								
1.5 GLE	Ford V4		▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
16 : 2.0 i, Cabrio	B 202...I Cat		09.1985 ▶ 08.1991	<b>246186</b>	RF82H	1.1	<b>246554</b>	F87
16 : 2.0 Turbo, Turbo Cabrio	B 202...L Cat		02.1984 ▶ 08.1993	<b>246334</b>	RF64H11	1.0		
16 : 2.1 i 16v, Cabrio	B 212...I Cat		09.1990 ▶ 08.1991	<b>246186</b>	RF82H	0.7	<b>246554</b>	F87
2.0 C, GL, GLS	B 20		▶ 08.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i GLS, GLE, GLi, EMS	B 201...I		09.1983 ▶ 08.1991	<b>246179</b>	R76H	0.6	<b>246555</b>	H79
2.0 i Turbo Turbo Coupé	B 204 L Cat		09.1993 ▶	<b>246334</b>	RF64H11	1.1		
2.3 i 16V Coupé	B 234...I Cat		09.1993 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.5 i 24V Coupé	B 258...I Cat		09.1993 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
90								
2.0	B 201...C		08.1984 ▶ 08.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
9000								
16 : 2.3 i 16V, CD, CS	B 234...I Cat		09.1989 ▶ 12.1998	<b>246332</b>	RF74H11	0.8	<b>246556</b>	F87-11
2.0 i CD 16	B 202...I Cat		12.1985 ▶ 08.1993			1.1	<b>246556</b>	F87-11
2.0 i CS	B 204 I Cat		09.1993 ▶ 12.1998	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i Turbo CS Turbo	B 204 L Cat		09.1994 ▶ 12.1998	<b>246334</b>	RF64H11	1.1		
2.0 Turbo CD, CD Turbo	B 202...L Cat		▶ 08.1993	<b>246184</b>	RF72H	1.0	<b>246567</b>	F59
2.0 Turbo CD, CD Turbo, CS Special	B 202...L Cat		05.1988 ▶ 08.1993	<b>246334</b>	RF64H11	1.0		
2.0 Turbo Turbo 16	B 202...L Cat		09.1984 ▶ 08.1993	<b>246334</b>	RF64H11	1.0		
2.3 i Turbo CD Turbo, CD Turbo S, CDE Turbo	B 234...L Cat		09.1990 ▶ 12.1998	<b>246334</b>	RF64H11	1.0		
2.3 i Turbo CS Turbo, CS Aero Turbo, CS Turbo S CSE Turbo	B 234...L Cat		09.1991 ▶ 08.1993	<b>246334</b>	RF64H11	1.0		
2.3 i Turbo Turbo 16	B 234...L Cat		09.1990 ▶ 08.1993	<b>246334</b>	RF64H11	1.0		
2.3 Turbo CD Turbo Ecopower, CDE Turbo Eco. CS Turbo Eco.	B 234 E Cat		09.1993 ▶ 12.1998	<b>246334</b>	RF64H11	1.0		
2.3 Turbo CS Aero Turbo	B 234 R Cat		09.1992 ▶ 12.1998	<b>246334</b>	RF64H11	1.1		
3.0 i V6 24V CD, CS, Griffin	B 308 I Cat		09.1994 ▶ 12.1998	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
9-3								
2.0 i 16V	B 204 E		01.1999 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i 16V	B 204 R		08.1998 ▶	<b>246334</b>	RF64H11	1.1		
2.3 i 16V Turbo	B 235 E		06.1997 ▶	<b>246334</b>	RF64H11	1.1		





			<b>SAAB</b> (.../...)					
<b>95</b>								
1.5	Ford V4	► 12.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>9-5</b>								
2.0 i 16V Turbo	B 205 E	06.1997 ►	<b>246334</b>	RF64H11	1.1			
2.3 i 16V Turbo	B 235 E	06.1997 ►	<b>246334</b>	RF64H11	1.1			
3.0 i V6 24V Turbo	B 308 E	06.1997 ►	<b>246334</b>	RF64H11	1.1			
<b>99</b>								
2.0	F 201 C, BT20, B20	► 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2.0 EMS	BI20	► 12.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2.0 GL	B 20	► 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2.0 Turbo	BSI20	► 12.1980	<b>246178</b>	R64H	0.7	<b>246557</b>	H60	
<b>SANTANA</b>								
<b>2000</b>								
3.4		06.1976 ► 12.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>LAND, ROVER</b>								
109 : 2.3 Normal, Super	4GT	06.1982 ►	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
109 : 3.4 Cazorra, Normal		05.1981 ►	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1300 : 2.3			<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
88 : 2.3 Ligero, Normal, Super	4GT	05.1980 ►	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
<b>SAMURAI</b>								
1.0	F10A	09.1989 ►	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.3	G13	09.1986 ► 12.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 i	G13B [OHC]	10.1991 ►	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>VITARA</b>								
1.6	G16A [OHC] Cat	09.1989 ►	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>SATURN</b>								
<b>SPORTS COUPE</b>								
1.9 i 16V S2	(7) [DOHC]	10.1990 ► 08.1995			1.1	<b>246556</b>	F87-11	
<b>SPORTS SEDAN</b>								
1.9 i 16V SL2 Touring	(7) [DOHC]	10.1990 ► 08.1995			1.1	<b>246556</b>	F87-11	
1.9 i 16V SW1	(7) [DOHC]	08.1994 ► 08.1995			1.1	<b>246556</b>	F87-11	
<b>SEAT</b>								
<b>124 D</b>								
1200 : 1.2, LS		04.1974 ► 10.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1400 : 1.4 Especial		09.1975 ► 10.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1600 : 1.6 Especial		01.1978 ► 10.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1800 : 1.8 Especial		01.1977 ► 05.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2000 : 2.0		05.1979 ► 10.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>127</b>								
0.9 CL, CL 90		09.1977 ► 09.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.0 1010 C, CL		09.1977 ► 09.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>128</b>								
1200 : 1.2		01.1977 ► 06.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1430 : 1.4		01.1977 ► 06.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>131</b>								
1430 : 1.4		03.1975 ► 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1600 : 1.6		06.1975 ► 12.1983	<b>246198</b>	R70H	0.7	<b>246557</b>	H60	
1600 : 1.6 L 90		03.1975 ► 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1800 : 1.8		03.1975 ► 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2000 : 1.9 2000 CLX Supermirafiori		03.1975 ► 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2000 : 2.0		06.1975 ► 12.1983	<b>246198</b>	R70H	0.7	<b>246557</b>	H60	
<b>132</b>								
1600 : 1.6, Nuevo E		03.1973 ► 05.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1800 : 1.8		03.1973 ► 05.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
2.0 Nuevo E 2000		09.1978 ► 10.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>133</b>								
0.8 Especial, L			<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>1430</b>								
1.4			<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1.6			<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
1.8			<b>246179</b>	R76H	0.7	<b>246555</b>	H79	
<b>ALHAMBRA</b>								
1.8 T 20V	AJH	11.1997 ►	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87	



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## SEAT (.../...)

### ALHAMBRA (.../...)

2.0	ATM	06.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	ABF	08.1996 ▶ 06.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i LE, SE, SXE	ADY	04.1996 ▶ 02.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 i	AAA	03.1996 ▶			1.6	<b>246554</b>	F87

### AROSA

1.0 i	AER, ALL	02.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AEX, APQ	02.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AKV	05.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i 16V	AHW	01.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

### CORDOBA

1.0 i	AER	09.1996 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	ANX	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	APQ	12.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AQQ	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i A La Mode, Aventura, GLX, Kenwood, Vario	AEX	12.1995 ▶ 12.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i CLX, Kenwood	ABD	05.1993 ▶ 12.1995			0.9	<b>246555</b>	H79
1.4 i Vario	AKV	09.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i 16V	AFH	07.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	APE	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ABU	05.1993 ▶ 07.1994			0.9	<b>246555</b>	H79
1.6 i	AEH, AKL	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ALM	03.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	APF	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i, Vario	AEE	03.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i CLX, Felina, GLX, Kenwood	1F	11.1993 ▶			0.9	<b>246555</b>	H79
1.6 i CLX, Felina, GLX, Kenwood	AEK	04.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i CLX, Felina, GLX, SXE, Kenwood	AFT	12.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i GLX	ABS, ACC	05.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i GLX, SXE	ADZ	05.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i 16V	ADL	09.1993 ▶			0.9	<b>246567</b>	F59
2.0 i	2E	09.1993 ▶ 04.1996	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	AGG	09.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V	ABF	01.1995 ▶			0.9	<b>246567</b>	F59

### FURA

0.9 GL, L		09.1981 ▶ 12.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.4 Crono	124.B3.000	09.1981 ▶ 12.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### IBIZA

0.9	1000 GL 7000	06.1984 ▶ 09.1993	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 Fresh, Special/-Shop	146.A.000	06.1984 ▶ 08.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.0 i	AER	09.1996 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.0 i CL	AAU	03.1993 ▶			0.9	<b>246555</b>	H79
1.2 CLX, Pack, GLX, Plein Sud, Special, Shop	021.A1.000	06.1984 ▶ 05.1993	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.2 Del Sol, XL, Crono	021.A1.000	06.1984 ▶ 05.1993	<b>246184</b>	RF72H	0.8	<b>246567</b>	F59
1.2 i Plein Sud, Friend, Shop, Sport	021.C1.000	08.1989 ▶ 05.1993			0.8	<b>246567</b>	F59
1.3 i CL, CLX, GLX	AAV	03.1993 ▶ 08.1996			0.9	<b>246555</b>	H79
1.3 i CLX	2G	03.1993 ▶ 08.1994	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.4 i	AKV	01.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	ANX	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	APQ	12.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AQQ	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i CL, CLX, GLX, Kenwood	ABD	05.1993 ▶ 12.1995			0.9	<b>246555</b>	H79
1.4 i CL, CLX, GLX, Kenwood	AEX	12.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i 16V	AFH	07.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	APE	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.5 Business, Del Sol, GLX, Special, Shop, SXi	021.A2.000	06.1984 ▶ 09.1993			0.8	<b>246567</b>	F59
1.5 CLX, Pack, XL, Crono, Crow, Sabatini, Friend	021.A2.000	06.1984 ▶ 09.1993			0.8	<b>246567</b>	F59
1.5 i	021.B2-C2-D2.000 Cat	06.1984 ▶ 09.1993			0.8	<b>246567</b>	F59
1.5 Turbo		07.1988 ▶ 05.1993			0.8	<b>246567</b>	F59
1.6 i	AEE, ALM	03.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AEH, AKL	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	APF	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i CLX, GLX	1F	11.1993 ▶			0.9	<b>246555</b>	H79
1.6 i CLX, GLX	ABU	03.1993 ▶ 07.1994			0.9	<b>246555</b>	H79
1.6 i CLX, GLX	AEK, AFT	12.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.7 i Sport, Plein Sud	021.A3-B3-C3.000 Cat	01.1991 ▶ 09.1993			0.8	<b>246567</b>	F59


**SEAT** (.../...)

**IBIZA (.../...)**

1.8 i GLX	ABS, ACC, ADZ	03.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i 16V GLX	ADL	05.1993 ▶			0.9	<b>246567</b>	F59
1.8 i 20v Turbo Cupra, Sport	AQX	01.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i GTi	2E, AGG	03.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V Cupra	ABF	06.1996 ▶			0.9	<b>246567</b>	F59

**INCA**

1.4 i	AEX, AKV, AQP	11.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	1F	11.1995 ▶ 05.1997			0.9	<b>246555</b>	H79
1.6 i	AEE	06.1997 ▶ 03.1998			0.9	<b>246555</b>	H79

**LEON**

1.4 i 16V	AHW, APE	12.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AEH, AKL, APF, ATN	12.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	AGN [DOHC]	12.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**MALAGA**

1.2 i		06.1984 ▶ 12.1993			0.8	<b>246567</b>	F59
1.5 i		05.1985 ▶ 12.1993			0.8	<b>246567</b>	F59
1.7 i		01.1991 ▶ 12.1993			0.8	<b>246567</b>	F59

**MARBELLA**

0.8 GL, GLX, Le Jouet, LS, Special, Black, Shop Red, Yellow	08 NCA	01.1987 ▶ 12.1993	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 CLX, Dim-Dam-Dom, GLX, XL	09 NCA	01.1987 ▶ 12.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 Fresh, Le Jouet, Special, Shop, Red Black	09 NCA	01.1987 ▶ 12.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 Special	1170A Cat	10.1996 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9 i Del Sol, Shop, Special, Special-Shop Friend Shop, CLX	09 NCB Cat	09.1991 ▶ 12.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**PANDA**

35 : 0.8		▶ 06.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
40, 45 : 0.9, Trans		▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**RITMO**

1.6 100 CLX, Crono		▶ 05.1986	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
65 : 1.2 L, CL, N		▶ 05.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
75 : 1.4 CLX, CL, LN		▶ 05.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**RONDA**

1.2	Sigma 1.2, 021.A1.000	05.1984 ▶ 08.1991			0.7	<b>246567</b>	F59
1.5	021.A2.000, Sigma 1.5	05.1984 ▶ 01.1991			0.8	<b>246567</b>	F59
1.6 100 CLX, Crono	138 AR 6000	▶ 12.1986	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0		▶ 11.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
65 : 1.2 CL	124 B 6000	▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
75 : 1.4 CLX	124 B 7000	▶ 12.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**SPORT**

1.2			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.4			<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**TERRA**

0.9	09 NCA	▶ 08.1991	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
0.9	903 EAC	01.1992 ▶	<b>246181</b>	R90H	0.8		

**TOLEDO**

1.4 i 16V	AHW, APE	11.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 CL, GL, GLX, Sport	ABN	01.1991 ▶ 07.1994			0.9	<b>246555</b>	H79
1.6 i	ABM	11.1993 ▶			0.9	<b>246555</b>	H79
1.6 i	ABU	03.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AEH, AKL	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	APF	09.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ATN	11.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i CL, CL Friend, GLX	1F	05.1991 ▶			0.9	<b>246555</b>	H79
1.6 i CLX, GLX	AEK, AFT, AKS	01.1996 ▶ 10.1998	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i	ABS, ADZ	01.1993 ▶ 04.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	ACC	01.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i GL, GLX	RP	05.1991 ▶ 11.1993	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V	ADL	08.1991 ▶ 08.1993			0.9	<b>246567</b>	F59
1.8 i 16V	KR	05.1991 ▶ 12.1992			0.9	<b>246567</b>	F59
1.8 i 16V	PL	05.1991 ▶ 03.1994			0.9	<b>246567</b>	F59
1.8 i 20V	AGN [DOHC]	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	APG [DOHC]	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	AGG	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i, GLX	2E	05.1991 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## SEAT (.../...)

### TOLEDO (.../...)

2.0 i 16V	9A				0.9	<b>246567</b>	F59
2.0 i 16V	ABF	08.1993 ▶			0.9	<b>246567</b>	F59
2.3 i V5	AGZ	10.1998 ▶			1.6	<b>246554</b>	F87

## SIMCA (CHRYSLER)

<b>1000</b>							
1.1				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1.3 Rallye 1				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1.3 Rallye 2				<b>246178</b>	R64H	0.6	<b>246557</b> H60
<b>1005</b>							
0.9				<b>246179</b>	R76H	0.6	<b>246555</b> H79
<b>1006</b>							
1.1				<b>246179</b>	R76H	0.6	<b>246555</b> H79
<b>1100 / 1300</b>							
0.9 LE				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1.1 LE				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1.3 Ti				<b>246178</b>	R64H	0.6	<b>246557</b> H60
1307 : 1.3				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1308 : 1.4				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1309 : 1.3 GLS				<b>246180</b>	R84H	0.6	<b>246555</b> H79
1309 : 1.6 SX				<b>246180</b>	R84H	0.6	<b>246555</b> H79

## SKODA

<b>100</b>							
1.0 S, L		01.1969 ▶ 12.1979		<b>246189</b>	R88N	0.8	
<b>105,120</b>							
1.0 Estelle, S, L		08.1976 ▶ 12.1990		<b>246189</b>	R88N	0.8	
<b>115</b>							
1.1 Favorit		01.1991 ▶		<b>246184</b>	RF72H	0.8	<b>246567</b> F59
<b>120</b>							
1.2 GL, GLE, L, LE		08.1976 ▶ 12.1990		<b>246189</b>	R88N	0.6	
<b>135</b>							
1.3 L, GL		09.1984 ▶ 12.1990		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
<b>136</b>							
1.3 L, GL		09.1984 ▶ 12.1990		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
<b>FABIA</b>							
1.4 i	AME, ATZ	12.1999 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
1.4 i 16V	AUA, AUB [DOHC]	12.1999 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
<b>FAVORIT</b>							
1.1		10.1990 ▶		<b>246186</b>	RF82H	0.8	<b>246554</b> F87
1.3		10.1990 ▶		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
1.3 ie		08.1992 ▶		<b>246176</b>	RF80H	0.7	<b>246554</b> F87
135 : 1.3		09.1991 ▶		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
135, 136 : 1.3		09.1988 ▶ 09.1994		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
135ie : 1.3 i		07.1993 ▶		<b>246176</b>	RF80H	0.7	<b>246554</b> F87
136ie : 1.3 i		07.1993 ▶		<b>246186</b>	RF82H	0.7	<b>246554</b> F87
136ie : 1.3 i	A02 [OHV] Cat	08.1992 ▶		<b>246176</b>	RF80H	0.7	<b>246554</b> F87
<b>FELICIA</b>							
1.1		10.1994 ▶		<b>246176</b>	RF80H	0.8	<b>246554</b> F87
1.3 i SW	[OHV, OHC]	10.1994 ▶		<b>246176</b>	RF80H	0.8	<b>246554</b> F87
1.6 i GLX, LX	AEE	09.1995 ▶		<b>246511</b>	R74HZ3YE	0.9	<b>246555</b> H79
<b>OCTAVIA</b>							
1.6 i	AEH, AKL	08.1998 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
1.6 i GLX, SLX	AEH, AEK	09.1996 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
1.8 i 20V	AGN [DOHC]	09.1996 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
1.8 T 20V	AEB [DOHC]	01.1998 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
1.8 T 20V	AGU [DOHC]	03.1998 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
2.0 i	AQY	05.1999 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87
<b>RAPID</b>							
135, 136 : 1.3	742...	▶ 12.1990		<b>246186</b>	RF82H	0.9	<b>246554</b> F87
<b>SUPERB</b>							
1.8 T 20V	AWT	02.2002 ▶		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b> F87



3+1


**SSANGYONG**

**KORANDO**

2.3 i	M161 [DOHC]	06.1997 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
3.2 i V6 SEL		06.1997 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

**MUSO**

2.0 i	M161.940	05.1996 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
2.3 i 16V	M161.970	05.1996 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87
3.2 i V6 24V	M162.990	05.1996 ▶	<b>246186</b>	RF82H	0.8	<b>246554</b>	F87

**STEYR (STEYR-DAIMLER-PUCH AG)**

**CITY BUS**

2.3 i	B 230 F Cat	01.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-------	-------------	-----------	---------------	------	-----	---------------	-----

**SUBARU**

**1300**

1.3 i Combi, DL, STD	EA65 [OHV]	09.1980 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
----------------------	------------	-----------	---------------	------	-----	---------------	-----

**1400**

1.4 i DL, GFT, GL	EA63	▶ 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------------------	------	-----------	---------------	------	-----	---------------	-----

**1600**

1.6 4WD, DL, GL, GLF, GF, GFT, SRX, Combi, 4WD	EA71	05.1979 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--	------	-----------	---------------	------	-----	---------------	-----

**1800**

1.8 4WD, Combi, 4WD	EA81	05.1979 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 Combi, 4WD	EA81	05.1979 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 i 4WD, Combi 4WD	EA82 E Cat	01.1988 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 i Turbo 4WD, Combi	EA82 Cat	11.1984 ▶			1.1	<b>246564</b>	H79-11

**1800 XT COUPE**

1.8 i Turbo 4WD	EA82 Cat	11.1984 ▶			1.1	<b>246564</b>	H79-11
-----------------	----------	-----------	--	--	-----	---------------	--------

**ALCYONE**

1.8 i Turbo	EA82 Cat	08.1985 ▶ 09.1991			1.1	<b>246564</b>	H79-11
-------------	----------	-------------------	--	--	-----	---------------	--------

**DOMINGO**

1.0	EF10	06.1983 ▶ 06.1994			1.1	<b>246564</b>	H79-11
1.2 i	EF12	07.1986 ▶ 06.1994			1.1	<b>246564</b>	H79-11

**FORESTER**

2.0 i 16V	EJ20 [DOHC] Cat	02.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [SOHC] Cat	08.1997 ▶ 08.1998			1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 JE [SOHC] Cat	07.1997 ▶ 07.1998			1.1	<b>246556</b>	F87-11
2.5 i 16V	EJ25 [SOHC]	08.1997 ▶			1.1	<b>246556</b>	F87-11

**IMPREZA**

1.5 i 16V	EJ15 [SOHC]	11.1992 ▶ 08.2000	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4WD	EJ16 [SOHC] Cat	08.1992 ▶ 09.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V 4WD	EJ16 E [SOHC] Cat	08.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	EJ18	08.1992 ▶ 12.2000	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V 4WD	EJ18 E [SOHC] Cat	08.1992 ▶ 06.1997	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [DOHC] Cat	08.2000 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [SOHC] Cat	08.1992 ▶ 08.1998			1.1	<b>246556</b>	F87-11
2.0 i 16V 4WD	EJ20 E [SOHC] Cat	08.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.2 i 16V	EJ22 E [OHC] Cat		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.5 i 16V	EJ25 [SOHC]				1.1	<b>246556</b>	F87-11

**JUSTY**

1.0 4WD	EF10	10.1984 ▶			1.1	<b>246564</b>	H79-11
1.2 i 4WD	EF12	05.1987 ▶			1.1	<b>246564</b>	H79-11
1.2 i GLi, 4WD	EF12	05.1991 ▶			1.1	<b>246564</b>	H79-11
1.3 i 4WD	G13B Cat	10.1995 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**LEGACY**

1.6	EA71		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 i 16V	EJ16 [SOHC] Cat	05.1990 ▶ 12.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V	EJ18 E [SOHC] Cat	07.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V 4WD	EJ18	01.1989 ▶ 09.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.8 i 16V 4WD, Station, Super Station	EJ18 SPI Cat	01.1989 ▶ 12.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [DOHC] Cat	02.1989 ▶ 09.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V	EJ20 [SOHC] Cat	10.1993 ▶ 08.1998			1.1	<b>246556</b>	F87-11
2.0 i 16V 4WD	EJ20 [SOHC] Cat	06.1991 ▶ 09.1993	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 16V 4WD	EJ20 E [SOHC] Cat	05.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.2 i 16V 4WD	EJ22 [OHC] Cat	09.1993 ▶ 05.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.2 i 16V 4WD	EJ22 E [OHC] Cat	01.1989 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

**LEONE**

1.5 i 16V	QG15DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
-----------	--------	-----------	--	--	-----	---------------	--------





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## SUBARU (.../...)

### LEONE (.../...)

1.6	EA71	08.1988 ▶ 04.1994	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 i 16V	QG18DE	06.1999 ▶			1.1	<b>246556</b>	F87-11
1.8 i Turbo	EA82 Cat	08.1988 ▶ 01.1989			1.1	<b>246564</b>	H79-11
1300 : 1.3 i	EA65 [OHV]	01.1979 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1600 : 1.6		01.1979 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1800 : 1.8		01.1979 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### LIBERO

1.0 4WD	EF10	10.1983 ▶ 04.1993			1.1	<b>246564</b>	H79-11
1.2 i 4WD	EF12	10.1986 ▶ 04.1993			1.1	<b>246564</b>	H79-11
1.2 i 4WD, 4WD Transporter	EF12 E Cat	05.1993 ▶			1.1	<b>246564</b>	H79-11

### MV

1800 : 1.8	EA81	11.1984 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
------------	------	-----------	---------------	------	-----	---------------	-----

### PLEO

0.66 i	EN07E [SOHC] Cat	10.1998 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------	------------------	-----------	---------------	---------	-----	---------------	--------

### REX

0.55	EK23	11.1986 ▶ 06.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.55	EN05	11.1986 ▶ 02.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.55, SR, SE	EK23	11.1986 ▶ 06.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.55 SG, SL, S, Vicky	EK23	11.1986 ▶ 06.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.66 i	EN07E [SOHC] Cat	03.1990 ▶ 03.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
500 : 0.55 Turbo Compresseur	EK23	06.1988 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
550 : 0.55	EN05	01.1989 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
550 : 0.55 Turbo Compresseur	EN05	01.1989 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
5-500 : 0.5	EK22		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
700 : 0.7	EK42	09.1981 ▶ 12.1988			1.1	<b>246564</b>	H79-11

### SAMBER

0.55	EK23	▶ 03.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
0.66 i	EN07E [SOHC] Cat		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### VANILLE, LIBERO

1.2 i					1.1	<b>246564</b>	H79-11
-------	--	--	--	--	-----	---------------	--------

### VIVIO

660 : 0.66 i, 4WD	EN07E [SOHC] Cat	03.1992 ▶ 10.1998	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-------------------	------------------	-------------------	---------------	---------	-----	---------------	--------

## SUZUKI

### ALTO

0.7	F6A	01.1990 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 i	G10B [OHC]	11.1993 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
600 : 0.6 Turbo	F5A	06.1982 ▶ 12.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
800 : 0.8	Y64, F8A, F8B	10.1981 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### BALENO

1.3 i 16V	G13BB [SOHC] Cat	03.1995 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.5 i 16V 4WD	G15A [SOHC] Cat	04.1995 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.6 4WD	G16A [OHC] Cat	04.1995 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.6 i 16V 4WD	G16B [OHC] Cat	04.1995 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
1.8 i 16V	G18A, J18A [DOHC] Cat	09.1995 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11

### CAPPUCINO

660 : 0.6 12V Turbo	F6A [DOHC] Cat	09.1991 ▶			1.1	<b>246564</b>	H79-11
---------------------	----------------	-----------	--	--	-----	---------------	--------

### CARRY

0.8 ST20K / V550	LJ50		<b>246189</b>	R88N	0.8		
0.8 ST80K / V800	F8A		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
0.8 ST90	F8A	10.1980 ▶ 10.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
0.8 Super	F8A	01.1981 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.0 SK410, SK110	F10A	10.1985 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### CERVO

0.5	F5A	01.1980 ▶			1.1	<b>246564</b>	H79-11
0.7	F6A		<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### JIMNY

1.3 i 16V Pack Luxe, STD	G13B Cat	10.1998 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
--------------------------	----------	-----------	---------------	-------	-----	---------------	-----

### KEI

0.7	F6A	10.1998 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	-----	-----------	---------------	------	-----	---------------	-----

### LJ

80 : 0.8	F8A, F8B	10.1977 ▶ 12.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
----------	----------	-------------------	---------------	------	-----	---------------	-----

### SAMURAI

1.0	F10A	01.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	G13A [OHC]	01.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79


**SUZUKI** (.../...)

<b>SAMURAI (.../...)</b>								
1.3 i	G13BA	01.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
<b>SJ</b>								
410 : 1.0	F10A	09.1981 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
410 : 1.0	F10A Cat	09.1981 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
410 : 1.0 J, V	F10A	09.1986 ▶ 12.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
413 : 1.3	F13A		<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
413 : 1.3	G13A, G13B [OHC] Cat	11.1984 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
413 : 1.3	G13B [OHC]	01.1987 ▶ 12.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
<b>SWIFT</b>								
1.0	G10A [OHC]	10.1984 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.0	G10A [OHC]	10.1984 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.0 i	G10A [OHC] Cat	03.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3	G13B [OHC] Cat	08.1986 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 4WD	G13B [OHC]	03.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 GL, GLX	G13A [OHC]	10.1984 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 i 4WD	G13B Cat	03.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 i 16V	G13B [DOHC] Cat	08.1986 ▶ 03.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.3 i 16V GTi	G13B [DOHC] Cat	03.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79	
1.6 i 4WD	G16A [OHC] Cat	09.1987 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87	
1.6 i 16V 4WD	G16B [OHC] Cat	11.1989 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87	
<b>VITARA ( ESCUDO )</b>								
1.6	G16A [OHC] Cat	09.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79	
1.6 i 16V	G16B [OHC] Cat	02.1991 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87	
2.0 i V6 24V	H20A [DOHC] Cat	11.1994 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87	
<b>WAGON R</b>								
1.3 i	G13BB	05.2000 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11	
<b>X-90</b>								
1.6 i 16V	G16B [OHC] Cat	09.1995 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87	

**TALBOT**

<b>180</b>								
1.8			<b>246198</b>	R70H	0.7	<b>246557</b>	H60	
2.0			<b>246198</b>	R70H	0.7	<b>246557</b>	H60	
<b>AVENGER</b>								
1.6			<b>246179</b>	R76H	0.6	<b>246555</b>	H79	
<b>HORIZON</b>								
1.1 1.3 GL, GL écon., GLS, GLX, LS, S, SX			<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.1 LS		07.1979 ▶ 06.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.3 GL		07.1979 ▶ 06.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.4 EX, GL, GLS		07.1979 ▶ 06.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.4 GL, GL écon., GLS, GLX, LS, S, SX			<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.6 GLS, Prémium		07.1982 ▶ 06.1986	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
<b>MATRA BAGHEERA</b>								
1.3 S	G4	08.1973 ▶ 07.1978	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
1.4 S, X		07.1979 ▶ 08.1980	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
1.4 SX	Y2, Y4	08.1975 ▶ 06.1979	<b>246178</b>	R64H	0.6	<b>246557</b>	H60	
<b>MURENA</b>								
1.6		09.1980 ▶ 06.1983	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.6	J2A		<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
2.2		09.1980 ▶ 07.1984	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
2.2	N2, N4		<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
<b>RANCHO</b>								
1.4	X3Y2	03.1977 ▶ 06.1979	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
1.4 AS, Découverte, Grand Raid, X		07.1979 ▶ 07.1984	<b>246180</b>	R84H	0.6	<b>246555</b>	H79	
<b>SAMBA</b>								
1.0 Bahia, GL, L, LE, LS, Style, Sympa	XV5, XV8	▶ 12.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79	
1.1 AS, Affaire, Bahia, Cabriolet, GL, GLS, LS Roller, Sympa, Trio	XW7 [109..]	▶ 12.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79	
1.2 Rallye	XZ7R	▶ 12.1987			0.6	<b>246565</b>	C60	
1.4 Cabriolet, GL, GLS	XY6B [150]	▶ 12.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79	
1.4 Cabriolet, GL, GLS	XY7 [150D]	▶ 12.1987	<b>246190</b>	RC68H	0.6	<b>246566</b>	C79	
1.4 Cabriolet, GL, GLS	XY7 [150D]	▶ 12.1987	● <b>246560</b>	RF74HZK	0.6	<b>246554</b>	F87	
1.4 Cabriolet, GLS, Rallye, S	XY8	▶ 12.1987			0.6	<b>246565</b>	C60	
<b>SIMCA 1100</b>								
Break L, LS, GL, GLS			<b>246180</b>	R84H	0.6	<b>246555</b>	H79	



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания

**Valeo**



3+1



## TALBOT (.../...)

### SIMCA 1100 (.../...)

ES, GL, GLA, GLE			246180	R84H	0.6	246555	H79
Ti, Spécial (- 01/72)			246178	R64H	0.6	246557	H60
VF1, VF2, VF3, AS			246180	R84H	0.6	246555	H79

### SIMCA 1200 S

1.2 LS, GL, GLE, GLS			246179	R76H	0.6	246555	H79
----------------------	--	--	--------	------	-----	--------	-----

### SIMCA 1500

1.4			246179	R76H	0.6	246555	H79
1.6			246179	R76H	0.6	246555	H79

### SIMCA 1501

1.3 LS			246180	R84H	0.6	246555	H79
1.4			246180	R84H	0.6	246555	H79
1.6 SX			246180	R84H	0.6	246555	H79

### SIMCA SUNBEAM

0.9			246179	R76H	0.6	246555	H79
1.3			246179	R76H	0.6	246555	H79
1.6			246179	R76H	0.6	246555	H79
1.6 100 PS			246198	R70H	0.6	246557	H60

### SOLARA

1.3 LS		► 06.1982	246180	R84H	0.6	246555	H79
1.3 LS, 1.4, 1.6, GL, LS			246180	R84H	0.6	246555	H79
1.4 GL, LS		► 05.1983	246180	R84H	0.6	246555	H79
1.6 GL, GLX, SX		► 07.1986	246180	R84H	0.6	246555	H79

### TAGORA

2.2 GL, GLS		06.1980 ► 12.1983	246180	R84H	0.6	246555	H79
2.7 SX		06.1980 ► 12.1983			0.6	246565	C60

## TATRA

<b>603</b>							
T2-603, T3-603	4 cyl.	01.1970 ►	246198	R70H	0.7	246557	H60

<b>613</b>							
3.5		► 12.1991	246198	R70H	0.9	246557	H60

<b>613-4</b>							
3.5		► 09.1993	246198	R70H	0.9	246557	H60
3.5 i	Cat	10.1993 ►	246173	RF74H	0.9	246554	F87

## TAZ

<b>1500</b>							
1.5		10.1993 ► 03.1994	246198	R70H	0.7	246557	H60

<b>S 1203</b>							
1.2		► 12.1988	246189	R88N	0.7		

<b>S 1203 M</b>							
1.5 M		05.1985 ► 09.1993	246198	R70H	0.7	246557	H60

## TOFAS

<b>124</b>							
1.3 Serce			246179	R76H	0.7	246555	H79

<b>131</b>							
1.3 Murat, Sahin			246179	R76H	0.7	246555	H79
1.6 Dogan SL, SLX, Kartal SL, SLX			246198	R70H	0.7	246557	H60
1.6 Dogan, Kartal			246179	R76H	0.7	246555	H79
1.6 Sahin			246179	R76H	0.7	246555	H79

<b>TEMPRA</b>							
1.6 ie			246198	R70H	0.7	246557	H60
2.0 i ie			246198	R70H	0.7	246557	H60

<b>TIPO</b>							
i Tous modèles / All models Injection		01.1994 ►	246198	R70H	0.7	246557	H60

<b>UNO</b>							
i Tous modèles / All models Injection		01.1995 ►	246198	R70H	0.7	246557	H60

## TOYOTA

<b>1000</b>							
1.0	2K	► 01.1981	246180	R84H	0.8	246555	H79

<b>4 RUNNER</b>							
2.4	22 R	01.1989 ► 11.1995	246180	R84H	0.8	246555	H79
2.4 i	22 RE Cat	01.1989 ► 11.1995	246180	R84H	0.8	246555	H79



## TOYOTA (.../...)

4 RUNNER (.../...)									
3.0 i V6	3VZ-E Cat	08.1989 ▶ 11.1995	246176	RF80H	0.8	246554	F87		
ALTEZZA									
2.0 i 16V	3S-GE, FE [DOHC]	10.1998 ▶			1.1	246556	F87-11		
2.0 i 24V	1G-FE [DOHC]	10.1998 ▶			1.1	246556	F87-11		
ARISTO									
3.0 i 24V	2JZ-GE Cat	10.1991 ▶ 09.1996			1.1	246556	F87-11		
AVENSIS									
1.6 i 16V Hatchback,Combi	4A-FE [DOHC] Cat	10.1997 ▶			1.1	246554	F87		
2.0 i 16V Hatchback,Combi	3S-FE [DOHC] Cat	10.1997 ▶			1.1	246556	F87-11		
AYGO									
1.0 12v		09.2005 ▶	246520	RF74LZDC	0.9				
B B									
1.3 i 16V	2NZ-FE	12.2000 ▶			1.1	246556	F87-11		
1.5 i 16V	1NZ-FE [DOHC]	12.2000 ▶			1.1	246556	F87-11		
CALDINA									
1.5 i 16V	5E-FE [DOHC] Cat	11.1992 ▶			1.1	246556	F87-11		
1.6 i 16V	4A-FE [DOHC] Cat	11.1992 ▶			1.1	246556	F87-11		
1.8 i 16V	4S-FE [DOHC] Cat	11.1992 ▶ 01.1996			1.1	246556	F87-11		
2.0 i 16V	3S-FE [DOHC] Cat	11.1992 ▶ 09.1997			1.1	246556	F87-11		
2.0 i 16V	3S-GE [DOHC]	02.1995 ▶ 09.1997			1.1	246556	F87-11		
CAMI									
1.3 i 16V	HC-EJ	05.1999 ▶ 04.2000			1.0	246554	F87		
1.3 i 16V	K3-VE [DOHC] Cat	05.2000 ▶			1.1	246556	F87-11		
CAMRY									
1.8	1S-E	01.1983 ▶ 02.1990	246180	R84H	0.9	246555	H79		
1.8 Break, Combi	1S	10.1986 ▶ 08.1988	246180	R84H	0.8	246555	H79		
1.8 i	1S-Ci	01.1983 ▶ 02.1990	246180	R84H	0.8	246555	H79		
1.8 i	1S-L	10.1982 ▶ 10.1986	246180	R84H	0.8	246555	H79		
1.8 i	4S-Fi	08.1988 ▶ 07.1990			1.1	246556	F87-11		
1.8 i 16V	4S-FE [DOHC] Cat	07.1990 ▶ 06.1994			1.1	246556	F87-11		
2.0 i	2S	10.1982 ▶ 10.1986	246180	R84H	0.8	246555	H79		
2.0 i	2S-EC	01.1984 ▶ 12.1986	246180	R84H	0.8	246555	H79		
2.0 i	2S-EL	03.1983 ▶ 08.1985	246180	R84H	0.8	246555	H79		
2.0 i	2S-ELC	01.1983 ▶ 08.1986			1.1	246564	H79-11		
2.0 i	2S-ELC	01.1983 ▶ 08.1986	246180	R84H	1.1	246555	H79		
2.0 i 16V	3S-FE [DOHC] Cat	07.1990 ▶ 06.1994			1.1	246556	F87-11		
2.0 i 16V	3S-GE [DOHC]	08.1988 ▶ 07.1990			1.1	246556	F87-11		
2.0 i 16V Break, 4x4	3S-FE [DOHC] Cat	10.1986 ▶ 05.1991			1.1	246556	F87-11		
2.2 i 16V	5S-FE [DOHC] Cat	08.1996 ▶	246332	RF74H11	1.1	246556	F87-11		
2.2 i 16V Combi, GLi	5S-FE [DOHC] Cat	06.1991 ▶ 08.1996	246332	RF74H11	1.1	246556	F87-11		
2.5 i V6 24V, Prominent	4VZ-FE [DOHC] Cat	02.1988 ▶ 06.1994	246332	RF74H11	1.1	246556	F87-11		
CAMRY GRACIA									
2.2 i 16V	5S-FE [DOHC] Cat	12.1996 ▶	246332	RF74H11	1.1	246556	F87-11		
CAMRY WAGON									
2.2 i 16V	5S-FE [DOHC] Cat	03.1992 ▶ 07.1996	246332	RF74H11	1.1	246556	F87-11		
CARINA									
1.6	2T	08.1972 ▶ 07.1981	246179	R76H	0.8	246555	H79		
1.6 GL, ST	2T	08.1981 ▶ 09.1983	246180	R84H	0.8	246555	H79		
1.8	3T	08.1979 ▶ 09.1983	246180	R84H	0.8	246555	H79		
CARINA 2									
1.5	3A	01.1983 ▶	246179	R76H	0.8	246555	H79		
1.5 i	3E [SOHC]	05.1988 ▶ 11.1992			1.1	246564	H79-11		
1.5 i 16V	5A-FE [DOHC]	05.1988 ▶ 11.1992			1.1	246556	F87-11		
1.6 SX, XL	4A-LC Cat	10.1983 ▶ 12.1987			1.1	246564	H79-11		
1.6 XL	4A-L	10.1983 ▶ 11.1987	246180	R84H	0.8	246555	H79		
1.6 i 16V	4A-FE [DOHC] Cat	05.1988 ▶ 05.1990			1.1	246556	F87-11		
1.6 i 16V	4A-FE [DOHC] Cat	08.1996 ▶			1.1	246556	F87-11		
1.6 i 16V	4A-GE [DOHC]	05.1988 ▶ 08.1992			1.1	246556	F87-11		
1.6 i 16V XLi	4A-F [DOHC]	12.1987 ▶ 02.1990	246332	RF74H11	1.1	246556	F87-11		
1.6 i 16V XLi, GLi	4A-FE [DOHC] Cat	06.1991 ▶ 11.1992			1.1	246556	F87-11		
1.6 i 16V XLi, GLi	4A-FE [DOHC] Cat	11.1989 ▶ 06.1991			1.1	246556	F87-11		
1.8	1S	10.1983 ▶ 11.1987	246180	R84H	0.8	246555	H79		
1.8 i	4S-Fi	05.1988 ▶ 05.1990			1.1	246556	F87-11		
1.8 i GLi	1S	10.1983 ▶ 11.1987	246180	R84H	0.8	246555	H79		
1.8 i 16V	4S-FE [DOHC] Cat	05.1988 ▶ 11.1992			1.1	246556	F87-11		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## TOYOTA (../...)

### CARINA 2 (../...)

2.0 i	2S-EL, 2SF	08.1985 ▶ 11.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i 16V GLi	3S-FE [DOHC] Cat	12.1987 ▶ 11.1992			1.1	<b>246556</b>	F87-11

### CARINA 3

1.5 i 16V	5A-FE [DOHC]	08.1996 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE, 4A-GE [DOHC] Cat	08.1996 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE, FE [DOHC]	08.1996 ▶			1.1	<b>246556</b>	F87-11

### CARINA E

1.5 i 16V	5A-FE [DOHC]	08.1992 ▶ 08.1996			1.1	<b>246556</b>	F87-11
1.6 i 16V GLi, XLi	4A-FE [DOHC] Cat	02.1992 ▶ 09.1997			1.1	<b>246556</b>	F87-11
1.8 i 16V	4S-FE [DOHC] Cat	08.1992 ▶ 08.1996			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-FE [DOHC] Cat	02.1992 ▶ 10.1997			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE [DOHC]				1.1	<b>246556</b>	F87-11

### CARINA ED

1.8 i	4S-Fi	05.1988 ▶ 09.1989			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-FE [DOHC] Cat	08.1987 ▶ 09.1989			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE [DOHC]	09.1989 ▶ 10.1993			1.1	<b>246556</b>	F87-11

### CELICA

	3S-GE [DOHC]	11.1993 ▶			1.1	<b>246556</b>	F87-11
1.6	2T, 2TB	08.1977 ▶ 07.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	4A	08.1985 ▶ 09.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 GT, LT, ST	2T-G	08.1977 ▶ 09.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i 16V	4A-GE [DOHC]	08.1983 ▶ 08.1987			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-GEL	08.1983 ▶ 08.1989			1.1	<b>246556</b>	F87-11
1.6 i 16V Coupé, Liftback	4A-FE [DOHC] Cat	10.1989 ▶ 06.1991	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87
1.8 i	4S-Fi	05.1986 ▶ 09.1989			1.1	<b>246556</b>	F87-11
1.8 i 16V	1ZZ-FE [DOHC] Cat	11.1999 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	7A-FE [DOHC] Cat	11.1993 ▶ 08.1999			1.3	<b>246556</b>	F87-11
2.0	21 R, 21 RC	08.1981 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	21 R, 21 RC	09.1984 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	2SC	08.1981 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	3S-GELU	08.1985 ▶ 09.1989			1.1	<b>246556</b>	F87-11
2.0 GT, ST, XT, Liftback	18R	09.1979 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 Liftback	18RG	08.1977 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 16V	3S-FE [DOHC] Cat	09.1989 ▶ 10.1993			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE [DOHC]	10.1989 ▶ 10.1993			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GEL	08.1985 ▶ 09.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.2 i 16V	5S-FE [DOHC] Cat	▶ 12.1990	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.4 i	22 REC	08.1984 ▶ 07.1985	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

### CELICA SUPRA

2.0 i	3Y-E	06.1996 ▶			1.1	<b>246564</b>	H79-11
-------	------	-----------	--	--	-----	---------------	--------

### CHASER / CRESTA

1.8 i	4S-Fi	08.1988 ▶ 09.1990			1.1	<b>246556</b>	F87-11
1.8 i 16V	4S-FE [DOHC] Cat	08.1990 ▶ 09.1996			1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-FE [DOHC]	08.1988 ▶ 09.1996			1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-GE [DOHC]	08.1988 ▶ 11.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
3.0 i 24V	2JZ-GE Cat	11.1992 ▶ 09.1996			1.1	<b>246556</b>	F87-11
3.0 i 24V	7M-GE [DOHC]	08.1989 ▶ 11.1992			1.1	<b>246556</b>	F87-11


### COASTER

	B	01.1974 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.5 i 16V	5E-FE [DOHC] Cat	08.1997 ▶			1.1	<b>246556</b>	F87-11
2.0	5R	01.1974 ▶ 12.1986	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.4	22 R	08.1979 ▶ 01.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.7	3RZ-F [DOHC]	09.1993 ▶ 07.1999			0.8	<b>246554</b>	F87
2.7 i	3RZ-F [DOHC]	07.1999 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

### COROLLA

1.2	3K	05.1970 ▶ 08.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	4K				0.8	<b>246564</b>	H79-11
1.3	4K-C, 2A	09.1979 ▶ 07.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 Coupé	4K	09.1979 ▶ 05.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 Hatchback	2E	10.1984 ▶ 04.1987			0.8	<b>246564</b>	H79-11
1.3 Hatchback	2E-L	10.1984 ▶ 04.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 12V Hatchback, Liftback, Sedan, Wagon	2E	05.1987 ▶ 05.1995	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 12V Hatchback, Liftback, Sedan, Wagon	2E Cat	05.1987 ▶ 05.1995			1.1	<b>246564</b>	H79-11
1.3 i 12V Hatchback	2E-E Cat	08.1989 ▶ 05.1992	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i 16V	2NZ-FE	08.2000 ▶			1.1	<b>246556</b>	F87-11





3+1


**TOYOTA** (.../...)

**COROLLA (.../...)**

1.3 i 16V	4E-FE [DOHC] Cat	05.1992 ▶			1.1	<b>246556</b>	F87-11
1.4 i 16V	4ZZ-FE [DOHC]	10.1999 ▶			1.1	<b>246556</b>	F87-11
1.5 i	3E [SOHC]	08.1987 ▶ 09.1991			1.1	<b>246564</b>	H79-11
1.5 i 16V	1NZ-FE [DOHC]	08.2000 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	5A-FE [DOHC]	07.1987 ▶ 05.1992			1.1	<b>246556</b>	F87-11
1.5 i 16V	5A-FHE [DOHC] Cat	06.1989 ▶ 06.1991	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.5 i 16V	5E-FE [DOHC] Cat	07.1992 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V, Fielder	1NZ-FE [DOHC]	08.2000 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V Spacio	1NZ-FE [DOHC]	05.2001 ▶			1.1	<b>246556</b>	F87-11
1.6	2T	08.1974 ▶ 04.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	2T-G	12.1975 ▶ 05.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	4A	08.1985 ▶ 07.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 Coupé	4A-C Cat	05.1983 ▶ 04.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i Si Compact	4A-GELC	08.1989 ▶ 07.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	05.1992 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	10.1987 ▶ 04.1992	<b>246176</b>	RF80H	0.8	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	10.1987 ▶ 06.1991	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87
1.6 i 16V	4A-FHE [DOHC]	01.1993 ▶ 12.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.6 i 16V	4A-GE [DOHC] Cat	08.1987 ▶ 04.1992			1.1	<b>246556</b>	F87-11
1.6 i 16V Coupé	4A-GE [DOHC]	08.1983 ▶ 07.1987			1.1	<b>246556</b>	F87-11
1.8	3T	09.1979 ▶ 05.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i 16V	7A-FE [DOHC] Cat	05.1992 ▶			1.3	<b>246556</b>	F87-11
1.8 i 16V, Fielder	1ZZ-FE [DOHC] Cat	08.2000 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V Spacio	1ZZ-FE [DOHC] Cat	05.2001 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V Spacio	7A-FE [DOHC] Cat	07.1997 ▶			1.3	<b>246556</b>	F87-11

**CORONA**

1.5 i 16V	5A-FE [DOHC]	12.1987 ▶ 02.1992			1.1	<b>246556</b>	F87-11
1.6	2T	01.1982 ▶ 12.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6 i 16V	4A-FE [DOHC] Cat	01.1996 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	06.1991 ▶ 01.1996			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	08.1988 ▶ 06.1991			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-GELU	01.1985 ▶ 12.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
1.7	6R	01.1974 ▶ 11.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	16R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	2S, 2Y	08.1985 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	3T	01.1982 ▶ 11.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 GL	13TU	09.1978 ▶ 12.1981	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i	1S-EL	08.1985 ▶ 11.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 i	1S-L	10.1983 ▶ 11.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i	4S-Fi	05.1988 ▶ 11.1989			1.1	<b>246556</b>	F87-11
1.8 i	4S-Fi	09.1989 ▶ 10.1993			1.1	<b>246556</b>	F87-11
1.8 i GLi	1S-EL	08.1985 ▶ 11.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	18R	01.1976 ▶ 12.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	21R	01.1976 ▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	3S-GELU	01.1983 ▶			1.1	<b>246556</b>	F87-11
2.0 16V	3SF [DOHC]	12.1987 ▶ 01.1992			1.1	<b>246556</b>	F87-11
2.0 i	1G-E	08.1985 ▶ 11.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i GLi	2S-EL	08.1985 ▶ 11.1987	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i 16V	3S-FE [DOHC] Cat	01.1996 ▶			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-FE [DOHC] Cat	02.1992 ▶ 01.1996			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-FE [DOHC] Cat	12.1987 ▶ 01.1992			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE [DOHC]	12.1985 ▶ 02.1992			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE, FE [DOHC]	09.1989 ▶ 10.1993			1.1	<b>246556</b>	F87-11
2.3	2M		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.4 i	22 REC	08.1984 ▶ 12.1986	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.6	4M	▶ 12.1983	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**CRESSIDA**

1.8	1S-U, 3T	01.1980 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	18R	09.1979 ▶ 07.1981	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	18R	12.1976 ▶ 08.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	21 RC	09.1980 ▶ 08.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	21R	09.1980 ▶ 08.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	21R	09.1984 ▶ 08.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	1G-E	08.1982 ▶ 08.1988	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i 24V	1G-FE [DOHC]	08.1988 ▶			1.1	<b>246556</b>	F87-11



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## TOYOTA (../...)

### CRESSIDA (../...)

2.0 i 24V	1G-GE [DOHC]	08.1984 ▶ 08.1986	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.4	22 R	02.1985 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.6	4M	12.1976 ▶ 07.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i	5M-E	08.1984 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.8 i	5M-GE [DOHC]	08.1984 ▶ 08.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i	5M-GEU	01.1980 ▶ 07.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### CROWN

2.0	3Y	11.1983 ▶ 09.1987	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
2.0	5M	09.1978 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	5R	01.1971 ▶ 08.1978	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 6Cyl	M	10.1974 ▶ 08.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i 24V	1G-FE [DOHC]	09.1988 ▶			1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-GE [DOHC]	09.1988 ▶ 10.1991	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-GEU [DOHC]	01.1985 ▶			1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-GZEU [DOHC]	01.1985 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
2.2	4Y	11.1983 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.3	2M	▶ 12.1983	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.6	4M	09.1979 ▶ 08.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i	5M-E	09.1979 ▶ 09.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i	5M-GE [DOHC]	08.1983 ▶ 08.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 i	6M-GE [DOHC]	10.1984 ▶ 08.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 i 24V	2JZ-GE Cat	10.1991 ▶ 08.1995			1.1	<b>246556</b>	F87-11
3.0 i 24V	7M-GE [DOHC]	10.1987 ▶	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87

### CURREN

1.8 i 16V	4S-FE [DOHC] Cat	10.1995 ▶ 07.1998			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE, FE [DOHC]	01.1994 ▶ 07.1998			1.1	<b>246556</b>	F87-11

### CYNOS

1.3 i 16V	4E-FE [DOHC] Cat	01.1991 ▶ 07.1999			1.1	<b>246556</b>	F87-11
1.5 i 16V	5E-FE [DOHC] Cat	01.1991 ▶ 08.1995			1.1	<b>246556</b>	F87-11
1.5 i 16V	5E-FHE [DOHC] Cat	08.1995 ▶ 07.1999			1.1	<b>246556</b>	F87-11

### DELI BOY

1.5	5K	07.1989 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
-----	----	-----------	---------------	------	-----	---------------	-----

### DUET

1.0 i 12V	EJ-DE Cat	09.1998 ▶			1.0	<b>246554</b>	F87
1.3 i 16V	K3-VE [DOHC] Cat	05.2000 ▶			1.1	<b>246556</b>	F87-11

### DYNA ( TOYO-ACE )

100, 150 : 1.8	1Y, 2Y	01.1985 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
150, 200 : 2.0	3Y	08.1984 ▶ 08.1986			1.1	<b>246564</b>	H79-11
2.0	5R	▶ 12.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0 i	3Y-E				1.1	<b>246564</b>	H79-11
200 : 2.2	4Y	08.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
200 : 2.4	22 R	08.1987 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2000 : 2.0	5R	08.1977 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2500 : 2.5	2J		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3000 : 3.0	B		<b>246179</b>	R76H	0.8	<b>246555</b>	H79

### ESTIMA / LUCIDA / EMINA

2.4 i 16V	2TZ-FE	01.1992 ▶ 01.2000			1.1	<b>246556</b>	F87-11
2.4 i 16V	2TZ-FZE [DOHC]	08.1994 ▶ 01.2000			1.1	<b>246556</b>	F87-11

### GAIA

2.0 i 16V	3S-FE [DOHC] Cat	05.1998 ▶			1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	--	--	-----	---------------	--------

### GRANVIA

3.4 i 24V	5VZ-FE [DOHC]	08.1997 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
-----------	---------------	-----------	---------------	----------	-----	---------------	-----

### HARRIER

2.2 i 16V	5S-FE [DOHC] Cat	04.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	---------------	---------	-----	---------------	--------

### IPSUM

2.0 i 16V	3S-FE [DOHC] Cat	05.1996 ▶			1.1	<b>246556</b>	F87-11
-----------	------------------	-----------	--	--	-----	---------------	--------

### LAND CRUISER / PRADO

2.4	22 R	11.1984 ▶ 05.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.4 i	22 RE Cat	12.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.7 i	3RZ-F [DOHC]	05.1996 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
3.4 i 24V	5VZ-FE [DOHC]	05.1996 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
4.0	3F	08.1987 ▶ 08.1992	<b>246181</b>	R90H	0.8		
4.0 i	3F-E [OHC]	01.1990 ▶ 08.1992			1.1	<b>246564</b>	H79-11
4.2	2F	08.1980 ▶ 08.1987	<b>246181</b>	R90H	0.8		
4.5 i 24V	1FZ-FE [DOHC] Cat	01.1992 ▶ 04.1996			0.8	<b>246554</b>	F87



								<b>TOYOTA</b> (.../...)	
<b>MARK II</b>									
1.8	2Y-J [OHV]	12.1988 ▶ 02.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.8 i	4S-Fi	08.1988 ▶ 02.1990			1.1	<b>246556</b>	F87-11		
1.8 i 16V	4S-FE [DOHC] Cat	08.1990 ▶ 09.1996			1.1	<b>246556</b>	F87-11		
2.0 i	3Y-E	02.1993 ▶ 04.1997			1.1	<b>246564</b>	H79-11		
2.0 i 24V	1G-FE [DOHC]	08.1988 ▶ 04.1997			1.1	<b>246556</b>	F87-11		
2.0 i 24V	1G-GE [DOHC]	08.1988 ▶ 11.1992	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
2.2 i 16V	5S-FE [DOHC] Cat	09.1996 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
3.0 i 24V	2JZ-GE Cat	11.1992 ▶ 09.1996			1.1	<b>246556</b>	F87-11		
3.0 i 24V	7M-GE [DOHC]	08.1989 ▶ 11.1992			1.1	<b>246556</b>	F87-11		
<b>MARK II WAGON, QUALIS</b>									
2.2 i 16V	5S-FE [DOHC] Cat	04.1997 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
<b>MASTER ACE SURF</b>									
1.8	2Y-U [OHV]	11.1982 ▶ 01.1992			1.1	<b>246564</b>	H79-11		
<b>MODELE F</b>									
1.8	2Y Cat		<b>246180</b>	R84H	0.8	<b>246555</b>	H79		
1.8	2Y-C Cat				1.0	<b>246564</b>	H79-11		
2.0	3Y				1.1	<b>246564</b>	H79-11		
2.0	3Y-C Cat		<b>246179</b>	R76H	0.8	<b>246555</b>	H79		
2.2 i 4x4	4EYC Cat Cat				1.1	<b>246564</b>	H79-11		
<b>MR 2</b>									
1.6 i 16V	4A-GE [DOHC] Cat	06.1984 ▶ 10.1989	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
1.6 i 16V GT	4A-GEL	11.1984 ▶ 12.1989			1.1	<b>246556</b>	F87-11		
1.6 i 16V GT	4A-GELU	11.1984 ▶ 12.1989			1.1	<b>246556</b>	F87-11		
2.0 i 16V	3S-FE [DOHC] Cat	12.1989 ▶ 08.1992			1.1	<b>246556</b>	F87-11		
2.0 i 16V	3S-GE [DOHC]	12.1989 ▶ 10.1999			1.1	<b>246556</b>	F87-11		
2.2 i 16V	5S-FE [DOHC] Cat		<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
<b>MR, MR 2</b>									
MR-S : 1.8 i 16V	1ZZ-FE [DOHC] Cat	10.1999 ▶			1.1	<b>246556</b>	F87-11		
<b>NADIA</b>									
2.0 i 16V	3S-FE [DOHC] Cat	08.1998 ▶			1.1	<b>246556</b>	F87-11		
<b>OPA</b>									
1.8 i 16V	1ZZ-FE [DOHC] Cat	01.2001 ▶			1.1	<b>246556</b>	F87-11		
<b>PASEO</b>									
1.5 i 16V	5E-FE [DOHC]	10.1995 ▶			0.8	<b>246556</b>	F87-11		
<b>PICNIC</b>									
2.0 i 16V 4WD	3S-FE [DOHC] Cat	05.1996 ▶			1.1	<b>246556</b>	F87-11		
<b>PLATZ</b>									
1.0 i 16V	1SZ-FE [DOHC]	08.1999 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87		
1.3 i 16V	2NZ-FE	08.1999 ▶			1.1	<b>246556</b>	F87-11		
1.5 i 16V	1NZ-FE [DOHC]	08.1999 ▶			1.1	<b>246556</b>	F87-11		
<b>PREVIA</b>									
2.4 i 16V	2TZ-FE	05.1990 ▶			1.1	<b>246556</b>	F87-11		
<b>PROGRESS</b>									
3.0 i 24V	2JZ-GE Cat	05.1998 ▶			1.1	<b>246556</b>	F87-11		
<b>RAUM</b>									
1.5 i 16V	5E-FE [DOHC] Cat	10.1995 ▶			1.1	<b>246556</b>	F87-11		
<b>RAV 4</b>									
1.8 i 16V	1ZZ-FE [DOHC] Cat	06.2000 ▶			1.1	<b>246556</b>	F87-11		
2.0 i 16V	3S-FE [DOHC] Cat	04.1994 ▶ 05.2000			1.1	<b>246556</b>	F87-11		
2.0 i 16V	3S-GE [DOHC]	08.1996 ▶ 06.2000			1.1	<b>246556</b>	F87-11		
<b>RUNNER</b>									
2.4 i	22 RE Cat				0.8	<b>246556</b>	F87-11		
3.0 i V6	3VZ-E				1.1	<b>246556</b>	F87-11		
<b>SCEPTER</b>									
2.2 i 16V	5S-FE [DOHC] Cat	11.1992 ▶ 07.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11		
<b>SERA</b>									
1.5 i 16V	5E-FHE [DOHC] Cat	03.1990 ▶ 11.1995			1.1	<b>246556</b>	F87-11		
<b>SOARER</b>									
2.0 i 24V	1G-FE [DOHC]	01.1989 ▶ 05.1991			1.1	<b>246556</b>	F87-11		
2.0 i 24V	1G-GEU [DOHC]	01.1988 ▶ 05.1991			1.1	<b>246556</b>	F87-11		
3.0 i 24V	2JZ-GE Cat	01.1994 ▶ 09.1996			1.1	<b>246556</b>	F87-11		
<b>SPARKY</b>									
1.3 i 16V	K3-VE [DOHC] Cat	10.2000 ▶			1.1	<b>246556</b>	F87-11		
<b>SPRINTER</b>									
1.2	3K	05.1970 ▶ 05.1978	<b>246179</b>	R76H	0.8	<b>246555</b>	H79		



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## TOYOTA (../...)

### SPRINTER (../...)

1.3	2E	05.1987 ▶ 06.1991			1.1	<b>246564</b>	H79-11
1.3 i 16V	4E-FE [DOHC]	06.1991 ▶ 05.1995			1.1	<b>246556</b>	F87-11
1.3 i 16V	4E-FE [DOHC] Cat	01.1994 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	5A-FE [DOHC]	06.1991 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	5A-FHE [DOHC] Cat	06.1986 ▶ 05.1992	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.5 i 16V	5E-FE [DOHC] Cat	06.1991 ▶			1.1	<b>246556</b>	F87-11
1.6	2T	05.1970 ▶ 04.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	2T-G	08.1974 ▶ 04.1979	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.6 16V	4A-F [DOHC]	05.1988 ▶ 08.1989	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.6 i 16V	4A-FE [DOHC] Cat	06.1989 ▶ 06.1991			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	06.1991 ▶			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FHE [DOHC]	02.1988 ▶ 08.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.6 i 16V	4A-GE [DOHC] Cat	05.1987 ▶ 05.1992			1.1	<b>246556</b>	F87-11
1.8 i 16V	7A-FE [DOHC] Cat	08.1995 ▶			1.3	<b>246556</b>	F87-11

### STARLET

1.0	1EL	10.1984 ▶ 11.1989	<b>246179</b>	R76H	1.1	<b>246555</b>	H79
1.0	2K	02.1978 ▶ 02.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.2	3K-H	02.1978 ▶ 09.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	1E	12.1989 ▶ 12.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3	1E, 2E	12.1989 ▶ 12.1992	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3	2E	12.1989 ▶ 12.1992			1.1	<b>246564</b>	H79-11
1.3	2E Cat	10.1984 ▶ 08.1987			1.1	<b>246564</b>	H79-11
1.3	2E-LJ	10.1984 ▶ 12.1989	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3	4K	08.1981 ▶ 02.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i	2E-ELU	10.1984 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.3 i	2E-LU	01.1987 ▶ 12.1989			1.1	<b>246564</b>	H79-11
1.3 i 12V	2E-E Cat	12.1989 ▶ 01.1996	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3 i 16V	4E-F [DOHC]	12.1989 ▶ 01.1996			1.1	<b>246556</b>	F87-11
1.3 i 16V	4E-FE [DOHC] Cat	01.1996 ▶ 07.1999			1.1	<b>246556</b>	F87-11

### STOUT

	GG, GR	▶ 12.1980	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
--	--------	-----------	---------------	------	-----	---------------	-----

### SUPRA

2.0 i 24V	1G-FE [DOHC]	01.1986 ▶ 08.1992			1.1	<b>246556</b>	F87-11
2.0 i 24V	1G-GEU [DOHC]	01.1986 ▶ 05.1993			1.1	<b>246556</b>	F87-11
2.8 i GT	5M-GE [DOHC]	12.1981 ▶ 09.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i Supra	5M-E	08.1982 ▶ 12.1985	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.8 i Supra	5M-GE [DOHC]	12.1981 ▶ 09.1987	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 i 24V	2JZ-GE Cat	05.1993 ▶ 09.1996			1.1	<b>246556</b>	F87-11
3.0 i 24V	7M-GE [DOHC]	08.1988 ▶ 04.1993			1.1	<b>246556</b>	F87-11
3.0 i 24V Supra	7M-GE [DOHC]				1.1	<b>246556</b>	F87-11

### TERCEL

1.3	2A	10.1982 ▶ 08.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	2E	05.1986 ▶ 09.1990			1.1	<b>246564</b>	H79-11
1.3 12V	2E	05.1986 ▶ 09.1990	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.3 i 16V	4E-FE [DOHC]	09.1990 ▶ 07.1999			1.1	<b>246556</b>	F87-11
1.5	3A	10.1982 ▶ 01.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	3A-C	10.1982 ▶ 08.1984	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	3A-C Cat	05.1986 ▶ 01.1988			1.1	<b>246564</b>	H79-11
1.5 Break, 4x4	3A-C Cat	09.1987 ▶ 01.1988			1.1	<b>246564</b>	H79-11
1.5 Break, 4x4	3A-C Cat	10.1982 ▶ 08.1987	<b>246180</b>	R84H	1.1	<b>246555</b>	H79
1.5 i	3E [SOHC]	05.1986 ▶ 09.1990			1.1	<b>246564</b>	H79-11
1.5 i	3E-LU				1.1	<b>246564</b>	H79-11
1.5 i 12V	3E-TE	09.1986 ▶ 09.1990			1.1	<b>246564</b>	H79-11
1.5 i 16V	5E-FE [DOHC]	09.1990 ▶ 07.1999			0.8	<b>246556</b>	F87-11
1.5 i 16V	5E-FHE [DOHC] Cat	09.1990 ▶ 09.1994			1.1	<b>246556</b>	F87-11
1.6 i 16V	4A-FE [DOHC] Cat	09.1990 ▶ 06.1991	<b>246176</b>	RF80H	1.1	<b>246554</b>	F87

### TOWN ACE / NOAH

1.5	5K	10.1996 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i 16V, Noah	3S-FE [DOHC] Cat	10.1996 ▶			1.1	<b>246556</b>	F87-11

### TOWN-ACE / NOAH

1.2	3K-J		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	4K-J	08.1985 ▶ 08.1992	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	5K	10.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	12RJ, 2TJ		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	2T		<b>246180</b>	R84H	0.8	<b>246555</b>	H79



3+1

**TOYOTA** (.../...)

**TOWN-ACE / NOAH (.../...)**

1.8	13TU		<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.8	2Y	10.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8, Noah	2Y-U [OHV]	11.1982 ▶ 01.1992			1.1	<b>246564</b>	H79-11
1.8 i	7K	10.1996 ▶ 12.1998	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**TOYO-ACE / DYNA**

1.6	12R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	2Y Cat	08.1987 ▶ 09.1993	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	3Y	05.1995 ▶			1.1	<b>246564</b>	H79-11
2.0	5R		<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**VISTA / ARDEO**

1.8 i	4S-Fi	08.1988 ▶ 07.1990			1.1	<b>246556</b>	F87-11
1.8 i 16V	1ZZ-FE [DOHC] Cat	07.1998 ▶			1.1	<b>246556</b>	F87-11
1.8 i 16V	4S-FE [DOHC] Cat	07.1990 ▶ 06.1994			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-FE [DOHC] Cat	08.1986 ▶ 06.1994			1.1	<b>246556</b>	F87-11
2.0 i 16V	3S-GE [DOHC]	08.1988 ▶ 06.1992			1.1	<b>246556</b>	F87-11

**VITZ**

1.0 i 16V	1SZ-FE [DOHC]	01.1999 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.3 i 16V	2NZ-FE	08.1999 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	1NZ-FE [DOHC]	10.2000 ▶			1.1	<b>246556</b>	F87-11

**WILL VI**

1.3 i 16V	2NZ-FE	01.2000 ▶			1.1	<b>246556</b>	F87-11
-----------	--------	-----------	--	--	-----	---------------	--------

**WILL VS**

1.8 i 16V	1ZZ-FE [DOHC] Cat	04.2001 ▶			1.1	<b>246556</b>	F87-11
-----------	-------------------	-----------	--	--	-----	---------------	--------

**WINDOM**

2.5 i V6 24V	4VZ-FE [DOHC] Cat	08.1993 ▶ 08.1996	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11
--------------	-------------------	-------------------	---------------	---------	-----	---------------	--------

**YARIS**

1.0 i 16V 70 VVTi, Linea Sol / Terra / Luna	1SZ-FE [DOHC]	04.1999 ▶	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
1.3 i 16V 85 VVTi, Linea Sol / Luna	2NZ-FE	11.1999 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V 105 VVTi TS, Sport	1NZ-FE [DOHC]	03.2000 ▶			1.1	<b>246556</b>	F87-11

**YARIS VERSO**

105 VVTi, Linea Sol	1NZ-FE [DOHC]	03.2000 ▶			1.1	<b>246556</b>	F87-11
85 VVTi, Linea Luna	2NZ-FE	11.1999 ▶			1.1	<b>246556</b>	F87-11

**TOYOTA**
**FUN CARGO**

1.3 i 16V	2NZ-FE	08.1999 ▶			1.1	<b>246556</b>	F87-11
1.5 i 16V	1NZ-FE [DOHC]	08.1999 ▶			1.1	<b>246556</b>	F87-11

**HI-ACE**

1.5	2R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	12RJ	01.1972 ▶ 08.1979	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.6	12RJ	09.1979 ▶ 10.1982	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6 Pick-up	12R	01.1982 ▶ 07.1985			0.8	<b>246564</b>	H79-11
1.8	2Y Cat	08.1988 ▶ 05.1995	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	2Y-C Cat		<b>246180</b>	R84H	1.0	<b>246555</b>	H79
1.8	2Y-U [OHV]	12.1982 ▶ 08.1989			1.1	<b>246564</b>	H79-11
1.8 NF	16R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	18R	09.1981 ▶ 10.1982	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	18R	10.1982 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
2.0	3Y	08.1986 ▶ 07.1987			1.1	<b>246564</b>	H79-11
2.0 4x4	1RZ	08.1989 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	3Y-E	09.1989 ▶			1.1	<b>246564</b>	H79-11
2.0 i MPV, Van, Radius	1RZ-E [SOHC]	08.1989 ▶			1.1	<b>246564</b>	H79-11
2.2 4x4	4Y	08.1986 ▶ 07.1987			0.8	<b>246564</b>	H79-11
2.2 4x4	4Y	08.1987 ▶ 08.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.4 i 4x4, MPV	2RZ-E Cat	08.1989 ▶ 07.1995			1.1	<b>246564</b>	H79-11

**HI-LUX / SURF**

1.5	2R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	12R		<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	12RJ	01.1975 ▶ 08.1979	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.6	1Y	01.1975 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8	2Y-J [OHV]	11.1983 ▶ 05.1989	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	2Y-U [OHV]				1.1	<b>246564</b>	H79-11
1.8 Taro	2Y		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	18R, 3Y-C		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	3Y	09.1988 ▶ 09.1997			1.1	<b>246564</b>	H79-11
2.0 i	3Y-E	05.1989 ▶ 09.1997			1.1	<b>246564</b>	H79-11





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## TOYOTA (.../...)

### HI-LUX / SURF (.../...)

2.2	4Y		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.4 i	22 RE Cat		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
3.0 i V6	3VZ-E Cat	08.1990 ▶ 12.1995	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
3.4 i 24V	5VZ-FE [DOHC]	12.1995 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### LITE-ACE / NOAH

1.3	4K		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.3	4K-J	▶ 08.1990	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	5K Cat	01.1992 ▶ 01.1995	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.5	5K Cat	10.1985 ▶ 01.1992	<b>246181</b>	R90H	0.8		
1.6	1Y		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	2Y	10.1986 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8	2Y-C		<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8, Noah	2Y-U [OHV]	10.1982 ▶			1.1	<b>246564</b>	H79-11
1.8 i	7K	10.1996 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0	3Y	01.1993 ▶			1.1	<b>246564</b>	H79-11
2.0 i 16V, Noah	3S-FE [DOHC] Cat	10.1996 ▶			1.1	<b>246556</b>	F87-11

## TRABANT

### 601

1.1	VW		<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	----	--	---------------	------	-----	---------------	-----

## TRIUMPH

### 2500

2500 TC :			<b>246180</b>	R84H	0.7	<b>246555</b>	H79
-----------	--	--	---------------	------	-----	---------------	-----

### ACCLAIM

1.3		▶ 12.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

### DOLOMITE

1300, 1500, 1850			<b>246180</b>	R84H	0.7	<b>246555</b>	H79
------------------	--	--	---------------	------	-----	---------------	-----

### 2.0 Sprint

			<b>246190</b>	RC68H	0.7	<b>246566</b>	C79
--	--	--	---------------	-------	-----	---------------	-----

### SPITFIRE

1500 : 1.5			<b>246180</b>	R84H	0.7	<b>246555</b>	H79
------------	--	--	---------------	------	-----	---------------	-----

### TR 7

2.0			<b>246180</b>	R84H	0.7	<b>246555</b>	H79
-----	--	--	---------------	------	-----	---------------	-----

## TVR

### 280

2.8 i V6		03.1980 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-----------	---------------	------	-----	---------------	-----

### 350

3.5 i V8		03.1980 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
----------	--	-----------	---------------	------	-----	---------------	-----

### 390 SE

3.9 i V8		10.1984 ▶ 12.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-------------------	---------------	------	-----	---------------	-----

### 400 SE

4.0 i V8		09.1988 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-----------	---------------	------	-----	---------------	-----

### 420 SEAC

4.2 i V8		09.1984 ▶ 12.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-------------------	---------------	------	-----	---------------	-----

### 450 SEAC

4.5 i V8		09.1988 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-----------	---------------	------	-----	---------------	-----

### CERBERA

4.2 i V8	APJ8	01.1994 ▶	<b>246321</b>	RF80H3	1.2		
----------	------	-----------	---------------	--------	-----	--	--

### CHIMAERA

4.0		01.1992 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

4.2 V8		01.1992 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
--------	--	-----------	---------------	------	-----	---------------	-----

5.0 V8		01.1992 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
--------	--	-----------	---------------	------	-----	---------------	-----

### CLIPPER

5.9			<b>246181</b>	R90H	0.9		
-----	--	--	---------------	------	-----	--	--

### GRIFFITH

4.2 V8		01.1990 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
--------	--	-----------	---------------	------	-----	---------------	-----

500 : 5.0 V8		01.1993 ▶	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
--------------	--	-----------	---------------	------	-----	---------------	-----

### ROADSTERS

2.8 i V6		10.1986 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
----------	--	-----------	---------------	------	-----	---------------	-----

### S

2.8 V6		01.1987 ▶ 12.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
--------	--	-------------------	---------------	------	-----	---------------	-----

2.9 i V6		01.1989 ▶	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
----------	--	-----------	---------------	-------	-----	---------------	-----

2.9 i V6		01.1989 ▶	<b>246191</b>	RC72H	0.8	<b>246566</b>	C79
----------	--	-----------	---------------	-------	-----	---------------	-----


**TVR** (.../...)

<b>S2</b>							
2.9 i V6		10.1986 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
<b>S2C</b>							
2.9 i V6		10.1986 ▶	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
<b>TAIMAR</b>							
3.0 V6			<b>246179</b>	R76H	0.8	<b>246555</b>	H79
3.0 V6 Turbo			<b>246178</b>	R64H	0.8	<b>246557</b>	H60
<b>TASMIN</b>							
2.8 i V6		01.1980 ▶ 12.1985	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.8 V6		01.1980 ▶ 12.1985	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
<b>TUSCAN</b>							
3.5 i V8		01.1989 ▶	<b>246179</b>	R76H	0.8	<b>246555</b>	H79

**VANDEN PLAS**

<b>1500</b>							
1500 : 1.5			<b>246179</b>	R76H	0.6	<b>246555</b>	H79

**VAUXHALL**

<b>AGILA</b>							
1.0 i	Z 10 XE Ecotec [DOHC]	07.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.2 i	Z 12 XE Ecotec [DOHC]	07.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
<b>ASTRA</b>							
1.2	12 ST [OHC]	01.1989 ▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.2 S	12 S	09.1984 ▶ 12.1988	<b>246189</b>	R88N	0.7		
1.2 i 16V	X 12 XE [DOHC]	03.1998 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.3 S, S Estate	13 S [OHC]	09.1984 ▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	01.1990 ▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	09.1991 ▶ 02.1998	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	09.1991 ▶ 02.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	14 SE [OHC I]	03.1992 ▶ 03.1996	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	14 SE [OHC I]	03.1992 ▶ 03.1996	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	C 14 NZ [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 NZ [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i	C 14 SE [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4 i	C 14 SE [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.4 i 16V	X 14 XE [DOHC]	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 S, S Estate	16 S, 16 SV [OHC]	▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	C 16 LZ2 [OHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	C 16 NZ, E 16 NZ, X 16 SZR [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	C 16 NZ, E 16 NZ [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 SE [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 SE [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	X 16 SZ [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	X 16 SZ [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V	X 16 XEL [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i	C 18 NZ [OHC II]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i	C 18 NZ [OHC II]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i GTE	18 E, 18 SE [OHC]	▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i 16V	C 18 XE [DOHC]	09.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	X 18 XE [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i	C 20 NE [OHC]	09.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i	C 20 NE [OHC]	09.1991 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i GTE	20 SEH [OHC II]	▶ 08.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 16V	20 XE [DOHC]	09.1984 ▶ 08.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	20 XE [DOHC]	09.1992 ▶ 02.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V	C 20 XE [DOHC]	09.1984 ▶ 08.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	C 20 XE [DOHC]	09.1992 ▶ 02.1998	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V	X 20 XEV [DOHC]	01.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i 16V GTE 16V	20 XEH [DOHC]	▶ 08.1991	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
<b>BELMONT</b>							
1.3	13 S [OHC]	09.1985 ▶ 09.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 S, 16 SV [OHC]	09.1985 ▶ 09.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	18 E [OHC]	09.1985 ▶ 09.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
<b>BRAVA</b>							
2.3 i	4ZD1	06.1990 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VAUXHALL (.../...)

### CALIBRA

2.0 i 4x4, GT	C 20 NE [OHC]	06.1990 ▶ 04.1997	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i 4x4, GT	C 20 NE [OHC]	06.1990 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V	C 20 XE [DOHC]	03.1990 ▶ 08.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V	C 20 XE [DOHC]	09.1992 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V	X 20 XEV [DOHC]	11.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i Turbo 4x4	C 20 LET [DOHC]	03.1992 ▶ 04.1997			1.1	<b>246556</b>	F87-11
2.5 i V6	C 25 XE [DOHC]	04.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.5 i V6 24V	X 25 XE [DOHC]	04.1993 ▶ 04.1997	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### CARLTON

1.8	18 NV, 18 SV, S 18 NV, E 18 NVR 18 S [OHC, OHC II]	09.1986 ▶ 10.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	18 S [OHC]	12.1982 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	18 SE [OHC II]	09.1986 ▶ 10.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 S	20 S	10.1978 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.0 i	20 SE [OHC]	09.1986 ▶ 10.1994	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
2.0 i	20 SE [OHC]	09.1986 ▶ 10.1994	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i	X 20 SE [OHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i CD, Century, GL, GLT	C 20 NE [OHC]	09.1986 ▶ 10.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i 16V CD, GL	X 20 XEV [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.2 i	22 E	11.1984 ▶ 08.1986	<b>246189</b>	R88N	0.7		
2.4 i CD, GL, GLS	C 24 NE	09.1986 ▶ 10.1994	<b>246189</b>	R88N	0.7		
2.5 i V6 24V CD	X 25 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.6 i V6	C 26 NE	09.1986 ▶ 10.1994	<b>246189</b>	R88N	0.7		
3.0 24V GSi 3000	C 30 SEJ [DOHC]	01.1990 ▶ 10.1994	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
3.0 i GSi 3000	30 NE	03.1987 ▶ 10.1994	<b>246189</b>	R88N	0.7		
3.0 i 24V GSi 3000	C 30 SE [DOHC]	01.1990 ▶ 10.1994	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87
3.0 i V6 CDX, Estate		08.1989 ▶ 08.1990	<b>246189</b>	R88N	0.7		
3.0 i V6 24V	X 30 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87

### CAVALIER

1.3		08.1977 ▶ 08.1981			1.0	<b>246564</b>	H79-11
1.3 S	13 S [OHC]	09.1981 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.4	14 NV [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.4 i	E 14 NZ [OHC I]	09.1993 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 SH [OHC]	09.1986 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	16 SH [OHC]	09.1986 ▶ 08.1988	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	16 SH [OHC]	09.1986 ▶ 08.1988	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6	16 SV [OHC]	09.1986 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 S	16 S [OHC]	10.1975 ▶ 08.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 S	16 S [OHC]	10.1975 ▶ 08.1981	<b>246189</b>	R88N	0.7		
1.6 i	16 LZ2 [OHC]	09.1994 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	C 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	E 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	E 16 NZ [OHC]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.6 i	X 16 SZ [OHC]	09.1994 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	X 16 SZ [OHC]	09.1994 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.8	18 SV [OHC, OHC II]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 S	E 18 NVR [OHC II]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	18 E, 18 SE [OHC]	09.1981 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	C 18 NZ [OHC II]	09.1988 ▶ 08.1995	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i	C 18 NZ [OHC II]	09.1988 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
1.9 S	19 S	08.1975 ▶ 03.1978	<b>246189</b>	R88N	0.7		
2.0 S	20 S	03.1978 ▶ 08.1981	<b>246189</b>	R88N	0.7		
2.0 i	C 20 NE [OHC]	09.1986 ▶ 08.1988	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i	C 20 NE [OHC]	09.1986 ▶ 08.1988	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 4x4, L, LS, GLS, SRI	20 SE, SEH [OHC]	03.1987 ▶ 08.1995	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
2.0 i 16V	X 20 XEV [DOHC]	09.1993 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V 4x4	C 20 XE [DOHC]	09.1988 ▶ 08.1991	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 16V 4x4	C 20 XE [DOHC]	09.1991 ▶ 08.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V 4x4	C 20 XE [DOHC]	09.1992 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.0 i 16V GSi	20 XE [DOHC]	09.1988 ▶ 08.1991	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 16V GSi	20 XE [DOHC]	09.1991 ▶ 08.1992	<b>246487</b>	RF74HZDC	0.9	<b>246554</b>	F87
2.0 i 16V GSi	20 XE [DOHC]	09.1992 ▶ 08.1995	<b>246490</b>	RF82HZZY	1.0	<b>246554</b>	F87
2.5 i V6	C 25 XE [DOHC]	02.1993 ▶ 08.1993	<b>246492</b>	RF74HZZY	0.9	<b>246554</b>	F87



										<b>VAUXHALL</b> (.../...)	
<b>CAVALIER (.../...)</b>											
2.5 i V6 24V	25 XE [DOHC]	02.1993 ▶ 08.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87				
2.5 i V6 24V	25 XE [DOHC]	09.1993 ▶ 08.1995	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
<b>CHEVANNE</b>											
1.3	13 N [OHV]	10.1980 ▶ 12.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60				
<b>CHEVETTE</b>											
1.3 E, GL, L	13 S [OHV]	10.1980 ▶ 12.1985			1.0	<b>246557</b>	H60				
<b>COMBO</b>											
1.2 i	12 NZ, C 12 NZ, X 12 SZ [OHC]	03.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.2 i	12 NZ, C 12 NZ, X 12 SZ [OHC]	03.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i	C 14 NZ [OHC]	07.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4 i	C 14 NZ [OHC]	07.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i	X 14 SZ [OHC]	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i Si	C 14 SE [OHC]	07.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4 i Si	C 14 SE [OHC]	07.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
<b>CORSA</b>											
	Z 10 XE Ecotec [DOHC]		<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.0 i 12V	X 10 XE	03.1997 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.2 i	12 NZ, C 12 NZ, X 12 SZ [OHC]	08.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.2 i	12 NZ, C 12 NZ, X 12 SZ [OHC]	08.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.2 i 16V	X 12 XE [DOHC]	09.1997 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.2 i 16V	Z 12 XE Ecotec [DOHC]	09.2000 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i	C 14 NZ [OHC]	03.1993 ▶ 10.1996	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4 i	C 14 NZ [OHC]	03.1993 ▶ 10.1996	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i	X 14 SZ [OHC]	04.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i Si	C 14 SE [OHC]	08.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4 i Si	C 14 SE [OHC]	08.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i 16V	X 14 XE [DOHC]	11.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.6 i	C 16 XE [DOHC]	08.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.6 i 16V	X 16 XE [DOHC]	09.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
<b>FRONTERA</b>											
2.0 i	C 20 NE [OHC]	01.1992 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
2.0 i	C 20 NE [OHC]	01.1992 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
2.0 i	X 20 SE [OHC]	02.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
2.2 i 16V	X 22 XE [DOHC]	02.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
2.4 i	C 24 NE	01.1992 ▶	<b>246189</b>	R88N	0.7						
<b>HA</b>											
1.3 Van	[OHV]	10.1980 ▶ 12.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60				
<b>MONTEREY</b>											
3.2 i 24V	6 VD 1	06.1992 ▶	<b>246332</b>	RF74H11	1.1	<b>246556</b>	F87-11				
<b>NOVA</b>											
1.0	10 S [OHV]	05.1983 ▶ 03.1993	<b>246189</b>	R88N	0.7						
1.2	12 NC, 12 NV [OHV]	05.1983 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79				
1.2	12 S	05.1983 ▶ 10.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79				
1.2	12 ST [OHC]	01.1990 ▶ 03.1993	<b>246189</b>	R88N	0.7						
1.2 i	C 12 NZ [OHC]	09.1990 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.2 i	C 12 NZ [OHC]	09.1990 ▶ 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.3	13 S, 13 SB [OHC]	05.1983 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79				
1.4	14 NV [OHC]	01.1990 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4	14 NV [OHC]	01.1990 ▶ 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i	C 14 NZ [OHC]	01.1990 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.4 i	C 14 NZ [OHC]	01.1990 ▶ 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.4 i Si	C 14 SE [OHC]	09.1991 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79				
1.6 i	C 16 SE [OHC]	05.1988 ▶ 03.1993	<b>246180</b>	R84H	0.7	<b>246555</b>	H79				
1.6 i	C 16 SE [OHC]	05.1988 ▶ 03.1993	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
1.6 i GSi, GTE	E 16 SE [OHC I]	05.1988 ▶ 03.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79				
<b>OMEGA</b>											
2.0 i	20 SE, X 20 SE [OHC]	01.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
2.0 i 16V	X 20 XEV [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
2.5 i V6 24V	X 25 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
3.0 i V6 24V	X 30 XE [DOHC]	01.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87				
<b>ROYALE</b>											
2.8 S	28 S	▶ 12.1982	<b>246189</b>	R88N	0.7						
3.0 i E	30 E	▶ 12.1982	<b>246189</b>	R88N	0.7						
<b>SENATOR</b>											
2.5 i	25 E	09.1984 ▶ 12.1989	<b>246189</b>	R88N	0.7						





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VAUXHALL (.../...)

### SENATOR (.../...)

2.6 i V6	C 26 NE	09.1990 ▶ 08.1993	<b>246189</b>	R88N	0.7		
3.0 i	30 E	01.1983 ▶ 08.1987	<b>246189</b>	R88N	0.7		
3.0 i	C 30 NE	09.1987 ▶ 08.1993	<b>246189</b>	R88N	0.7		
3.0 i 24V	C 30 SE [DOHC]	09.1989 ▶ 08.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
3.0 i V6	C 30 LE	09.1987 ▶ 08.1993	<b>246189</b>	R88N	0.7		

### SINTRA

2.2 i 16V CD, GLS	X 22 XE [DOHC]	03.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
3.0 i V6 24V CD, GLS	X 30 XE [DOHC]	03.1996 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

### TIGRA

1.4 i 16V	X 14 XE [DOHC]	11.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V	X 16 XE [DOHC]	11.1994 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

### VECTRA

1.4 [86_, 87_]	14 NV [OHC]	09.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 [86_, 87_]	16 SV [OHC]	09.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 i	16 LZ2, X 16 SZR [OHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i	C 16 NZ, E 16 NZ [OHC]	09.1988 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	C 16 NZ, E 16 NZ [OHC]	09.1988 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i [86_, 87_]	X 16 SZ [OHC]	09.1988 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i [86_, 87_]	X 16 SZ [OHC]	09.1988 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.6 i 16V	X 16 XEL [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8	18 SV, C 18 SV, E 18 NVR [OHC OHC II]	09.1988 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i [86_, 87_]	C 18 NZ [OHC II]	03.1990 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i [86_, 87_]	C 18 NZ [OHC II]	03.1990 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V	X 18 XE [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i	20 NE, C 20 NE [OHC]	09.1988 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.0 i	20 NE, C 20 NE [OHC]	09.1988 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i	20 NEJ [OHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i [86_, 87_]	20 SEH [OHC II]	09.1988 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 16V	C 20 XE, 20 XE [DOHC]	▶ 08.1992	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.0 i 16V CDX	C 20 XE -20 XE, X 20 XEV [DOHC]	09.1995 ▶ 03.2002	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.0 i Turbo [86_, 87_]	C 20 LET [DOHC]	09.1992 ▶ 08.1995			1.1	<b>246556</b>	F87-11
2.5 i V6	C 25 XE [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 [86_, 87_]	C 25 XE [DOHC]	▶ 08.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.5 i V6 24V	25 XE [DOHC]	09.1993 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 24V	X 25 XE [DOHC]	09.1995 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
2.5 i V6 24V [86_, 87_]	25 XE [DOHC]	▶ 08.1993	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87

### VICEROY

2500 : 2.5	25 S	10.1980 ▶ 12.1982	<b>246189</b>	R88N	0.7		
------------	------	-------------------	---------------	------	-----	--	--

### VIVA

1300 : 1.3		01.1972 ▶ 12.1979	<b>246179</b>	R76H	1.0	<b>246555</b>	H79
------------	--	-------------------	---------------	------	-----	---------------	-----

### ZAFIRA

1.6 i 16V Comfort, Elegance	X 16 XEL [DOHC]	03.1999 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87
1.8 i 16V Elegance	X 18 XE1 [DOHC]	03.1999 ▶	<b>246490</b>	RF82HZ2Y	1.0	<b>246554</b>	F87

## VOLKSWAGEN


### BORA

1.4 i 16V	AHW, AKQ	09.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	APE	01.1999 ▶ 04.1999	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ATN	11.1999 ▶ 05.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Comfort	AHL	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Comfort, Variant	AEH, AKL, APF [OHC]	09.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i 16V	AJV	02.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V 4 Motion, 4 Motion Variant	AGN [DOHC]	09.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AGU [DOHC]	05.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i Comfort, Sport, Variant	APK, AQY	09.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.3 i V5	AGZ	10.1998 ▶			1.6	<b>246554</b>	F87

### CORRADO

1.8 G60	PG	09.1988 ▶ 09.1993			0.8	<b>246557</b>	H60
1.8 i 16V	KR	09.1988 ▶ 07.1992			0.9	<b>246567</b>	F59
2.0 i	2E	04.1993 ▶ 09.1994			0.9	<b>246555</b>	H79
2.0 i	ADY	07.1994 ▶ 10.1995	<b>246511</b>	RF74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V	9A	08.1991 ▶ 12.1995			0.9	<b>246567</b>	F59
2.9 VR6	ABV	08.1995 ▶ 12.1995			1.6	<b>246554</b>	F87




**3+1**

**VOLKSWAGEN** (.../...)

**DERBY**

0.9	HA	04.1975 ▶ 01.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0	GL	10.1981 ▶ 10.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1	HB, HD	04.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	GK	07.1982 ▶ 12.1984			0.8	<b>246557</b>	H60
1.3	GK	07.1982 ▶ 12.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.3	HH	01.1977 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	HJ	01.1977 ▶ 07.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	HK	08.1983 ▶ 07.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	MH	08.1985 ▶ 08.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	MH	08.1985 ▶ 08.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

**GOLF**

,	EX	08.1983 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.1	FA, FJ	04.1974 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.1	GG	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	GF, GS	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	HK	08.1983 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	EH	08.1977 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	GH	08.1979 ▶ 12.1981	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.5	JB	08.1977 ▶ 07.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	EJ	08.1979 ▶ 07.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	EM	08.1981 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FN, FP	08.1975 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FR	08.1975 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FT	08.1975 ▶ 07.1977	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FV	02.1976 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 Rivage, Young Line	EW	08.1983 ▶ 12.1992			0.9	<b>246555</b>	H79
1.6 Rivage, Young Line	EW	08.1983 ▶ 12.1992	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 Rivage, Young Line	RE	08.1983 ▶ 12.1992	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 Rivage, Young Line	RE, HN	08.1983 ▶ 12.1992			0.9	<b>246555</b>	H79
1.6 i	EG	01.1979 ▶ 07.1982	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 i GLi, GTi	EG	06.1976 ▶ 07.1982	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.7	EN	08.1980 ▶ 07.1984	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
1.8 Bel Air, Classic Line, Match, Quartett Sport Line, Young Line	2H, KT	08.1982 ▶ 08.1993	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 Bel Air, Classic Line, Match, Quartett Sport Line, Young Line	EX	08.1983 ▶ 07.1984	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 Bel Air, Classic Line, Match, Quartett Sport Line, Young Line	JH	08.1983 ▶ 08.1993	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Bel Air, Classic Line, Match, Quartett Sport Line, Young Line	DX	08.1982 ▶ 08.1993	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

**GOLF 2**

1.0	GN	08.1983 ▶ 07.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0	HZ	08.1985 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0	HZ	08.1985 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3	HW	08.1983 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	NU	08.1985 ▶ 08.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3	NZ	02.1987 ▶ 07.1988	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.3	NZ	02.1987 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 i	2C	08.1985 ▶ 08.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 i	2C	08.1985 ▶ 08.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 i	2G	01.1989 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 i	2G	01.1989 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.6	ABN	08.1986 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6	HM, HN	08.1983 ▶ 07.1988			0.9	<b>246555</b>	H79
1.6	PN	08.1986 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	EZ	08.1983 ▶ 12.1992			0.9	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	EZ	08.1983 ▶ 12.1992	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	RE, RF	02.1986 ▶ 10.1991			0.9	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	RE, RF	02.1986 ▶ 10.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 Boston, Carat, GL, GLX, Memphis, Syncro	GX	01.1984 ▶ 07.1988	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 Boston, Carat, GL, GLX, Memphis, Syncro	RG	08.1985 ▶ 07.1987	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 Country	1P	02.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 Country	JJ	08.1982 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 Country	MZ	08.1984 ▶ 02.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 Rallye	1H	04.1989 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLKSWAGEN (.../...)

### GOLF 2 (.../...)

1.8 G60 Edition One, GTI, Syncro, Rallye	PG	01.1990 ▶ 07.1991	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 i Boston, Carat, GL, GLX, Memphis, Syncro	RD	08.1985 ▶ 07.1988	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Boston, Carat, GL, GLX, Memphis, Syncro	RP	08.1982 ▶ 10.1991	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	PB, PF	01.1987 ▶ 10.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	PB, PF	01.1987 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i Country, GTI, GTI Cup, Syncro	RH	08.1986 ▶ 07.1987	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	RH	08.1986 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i Country, GTI, GTI Cup, Syncro	RV	08.1987 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	RV	08.1987 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	DX	08.1982 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	EV	08.1982 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	GZ	08.1983 ▶ 07.1989	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	HT	01.1985 ▶ 07.1985	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	HV	04.1984 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V GTi, GTi Edition One, GTi Match, GTX	KR	08.1985 ▶ 07.1992			0.9	<b>246567</b>	F59
1.8 i 16V GTi, GTi Edition One, GTX	PL	02.1986 ▶ 10.1991			0.9	<b>246567</b>	F59
2.0 i 16V	9A	07.1989 ▶ 12.1992			0.9	<b>246567</b>	F59

### GOLF 3


1.3 i	ADX	10.1994 ▶ 09.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AEX	10.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i CL, S, Variant	ABD	08.1991 ▶ 07.1995			0.9	<b>246555</b>	H79
1.6 i	AEA	07.1994 ▶ 07.1995	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AEE	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AEK	07.1994 ▶ 12.1995	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AFT	08.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AKS	04.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Luxus, Sport	AEK	07.1994 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Pink Floyd	ABU	07.1992 ▶ 09.1994			0.9	<b>246555</b>	H79
1.8 i	ABS, ADZ, ACC	09.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	ANN	01.1998 ▶			0.9	<b>246555</b>	H79
1.8 i	ANP	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Bel Air, Classic Line, Luxus, Match, Quartett Sport Line	AAM	09.1993 ▶			0.9	<b>246555</b>	H79
1.8 i CL	AAM	08.1991 ▶			0.9	<b>246555</b>	H79
1.8 i CL, GL, GT/Special, Pink Floyd, S, Syncro Variant	ABS	08.1991 ▶ 08.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Variant	ANP	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Young Line	AAM	09.1993 ▶			0.9	<b>246555</b>	H79
2.0 i	2E	09.1993 ▶ 09.1994			0.9	<b>246555</b>	H79
2.0 i	AEP, ADY, AGG, AKR	10.1994 ▶ 08.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i GTi	2E	09.1991 ▶ 09.1994			0.9	<b>246555</b>	H79
2.0 i 16V GTi	ABF	09.1991 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i Cabriolet	ADY, AGG, AKR	10.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.8 VR6	AAA	08.1991 ▶ 08.1997			1.6	<b>246554</b>	F87
2.9 VR6, Syncro	ABV	08.1995 ▶ 08.1997			1.6	<b>246554</b>	F87

### GOLF 4

1.4 i	APQ	12.1997 ▶ 05.1998	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i 16V	AHW, AKQ	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	APE	08.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ATN	11.1999 ▶ 05.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Variant	AEH, AKL, APF [OHC]	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i	ADD	09.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i 20V 4 Motion, 4 Motion Variant	AGN [DOHC]	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AGU [DOHC]	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0	AQY	08.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i Variant	AEG, APK, AQY	08.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.3 i V5, 4 Motion	AGZ	08.1997 ▶			1.6	<b>246554</b>	F87

### JETTA

1.1	GG	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	GF	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	GT	08.1983 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	HK	08.1983 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	NZ	08.1985 ▶ 07.1992	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.3	NZ	08.1985 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 Beach, Boston, CL, Classic, Jubilé, Junior Memphis, Travelling	MH	08.1985 ▶ 12.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79



3+1


**VOLKSWAGEN** (.../...)

**JETTA (.../...)**

1.3 Beach, Boston, CL, Classic, Jubilé, Junior Memphis, Travelling	MH	08.1985 ▶ 12.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 i	2G	01.1989 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 i	2G	01.1989 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.5	JB	08.1977 ▶ 07.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	FR	08.1975 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	HM, HN	08.1983 ▶ 07.1988			0.9	<b>246555</b>	H79
1.6	PN	08.1986 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	EZ	08.1983 ▶ 12.1992			0.9	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	EZ	08.1983 ▶ 12.1992	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 Beach, Boston, CL, Flight, Memphis, Travelling	RF	02.1986 ▶ 10.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i GLi, GTi	EG	06.1976 ▶ 07.1982	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 Boston, Carat, Champ, GL, GLX, Memphis Syncro/CL/GT	GU	08.1982 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 Boston, Carat, GL, GLX, Memphis, Syncro	GX	01.1984 ▶ 07.1988	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 Country	1P	02.1986 ▶ 08.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i Boston, Carat, GL, GLX, Memphis, Syncro	RD	08.1985 ▶ 07.1988	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Boston, Carat, GL, GLX, Memphis, Syncro	RP	08.1982 ▶ 10.1991	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	PB, PF	01.1987 ▶ 10.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	PB, PF	01.1987 ▶ 10.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i Country, GTI, GTI Cup, Syncro	RH	08.1986 ▶ 07.1987	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.8 i Country, GTI, GTI Cup, Syncro	RH	08.1986 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	DX	08.1982 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	EV	08.1982 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	GZ	08.1983 ▶ 07.1989	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GTi	HV	04.1984 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V GTi, GTi Edition One, GTi Match, GTX	KR	08.1985 ▶ 07.1992			0.9	<b>246567</b>	F59
1.8 i 16V GTi, GTi Edition One, GTX	PL	02.1986 ▶ 10.1991			0.9	<b>246567</b>	F59

**K 70**

1.6	DA, DB	▶ 10.1974	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	DC	▶ 10.1974	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**KAEFER / BEETLE / COCCINELLE**

1.6	ACD	01.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
-----	-----	-----------	---------------	------	-----	---------------	-----

**LUPO**

1.0 i Comfort, Pack	AER, ALL	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AFK	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	ANM, AQQ	05.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AUA [DOHC]	04.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AUB	08.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	BBY [DOHC] Cat	04.2002 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V Comfort, Pack, Sport	AHW, AKQ, APE	10.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i 16V	AJV	08.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**NEW BEETLE**

2.0 i	AEG, AQY	01.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	APK	06.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87

**PASSAT**

1.3	EP	08.1981 ▶ 04.1988			0.9	<b>246555</b>	H79
1.3	EP	08.1981 ▶ 04.1988	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.3	FY, FZ, ZA, ZF	05.1972 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	ABN	08.1989 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6	ANA	08.1996 ▶ 11.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6	DT, DTA	08.1983 ▶ 04.1988			0.9	<b>246555</b>	H79
1.6	PP	03.1987 ▶ 04.1988			0.9	<b>246555</b>	H79
1.6	RL, JU	08.1983 ▶ 04.1988			0.9	<b>246555</b>	H79
1.6	WP	08.1979 ▶ 01.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WV	09.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WVA, YN, WY, WZ, YP	09.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YG, YH	09.1975 ▶ 07.1980	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YS	01.1976 ▶ 07.1980	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6	YT	09.1975 ▶ 08.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YU	09.1975 ▶ 08.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	YY	09.1979 ▶ 07.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 CL	EZ	04.1988 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6 CL	EZ	04.1988 ▶ 07.1992	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6 i	AEK	07.1994 ▶ 12.1995	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLKSWAGEN (.../...)


### PASSAT (.../...)

1.6 i	AFT	08.1995 ▶ 03.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AHL	09.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ALZ [OHK]		<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ARM	11.1998 ▶ 05.1999	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Confort	ADP	10.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8	RM	02.1986 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8	RM	02.1986 ▶ 04.1988	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
1.8 CL, GL	JV	01.1983 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 CL, GL, Syncro	DS	09.1982 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 CL, GL, Syncro	JN	01.1983 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i	AAM	08.1990 ▶ 03.1997			0.9	<b>246555</b>	H79
1.8 i	ABS	08.1991 ▶ 09.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	ADZ	07.1994 ▶ 03.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	DZ	01.1983 ▶ 07.1991	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i CL, GL	RP	01.1983 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i CL, GL, GT	PB	04.1988 ▶ 07.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i CL, GL, GT	PB	04.1988 ▶ 07.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i CL, GL, GT	PF	04.1988 ▶ 07.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i CL, GL, GT	PF	04.1988 ▶ 07.1990	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V GL	KR	04.1988 ▶ 07.1992			0.9	<b>246567</b>	F59
1.8 i 20V	AFY	08.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V	APT, ARG	01.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i 20V Confort, Syncro	ADR	09.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	ANB	08.1996 ▶ 11.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V	AWT	11.2000 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 T 20V GLS Turbo	AEB [DOHC]	09.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.9 5S	WN	10.1980 ▶ 08.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 CL, GL, Syncro, TX	AAW	01.1991 ▶			0.9	<b>246555</b>	H79
2.0 Syncro	HP	08.1983 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i Syncro	2E	03.1990 ▶ 09.1994			0.9	<b>246555</b>	H79
2.0 i Syncro	ACX	06.1993 ▶ 12.1995	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Syncro	ADY	06.1993 ▶ 09.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Syncro	AEP	06.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Syncro	AGG	06.1993 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i Syncro	JS	08.1983 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i 16V	9A	08.1988 ▶ 09.1993			0.9	<b>246567</b>	F59
2.0 i 16V	ABF	08.1993 ▶ 03.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i 16V	ALT	11.2001 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.1 L5	WE	01.1981 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.2 i L5	KV	08.1984 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5	KX	08.1985 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.2 i L5 Syncro	HY	08.1984 ▶ 04.1988			0.8	<b>246557</b>	H60
2.2 i L5 Syncro	JT	08.1985 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.3 i V5	AGZ	08.1996 ▶ 11.2000			1.6	<b>246554</b>	F87
2.8 VR6	AAA	01.1985 ▶ 08.1996			1.6	<b>246554</b>	F87
2.9 VR6 Syncro	ABV	08.1995 ▶ 08.1996			1.6	<b>246554</b>	F87

### POLO

	AEH [OHK]	11.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
0.8	HE	04.1975 ▶ 09.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
0.9	HA	04.1975 ▶ 09.1981	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 Bel Air, College, Fancy, Fox, Movie, Peppermint	HZ	08.1985 ▶ 12.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 Bel Air, College, Fancy, Fox, Movie, Peppermint	HZ	08.1985 ▶ 12.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.0 Coupé	AAK	08.1989 ▶ 12.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.0 Coupé	GL	10.1981 ▶ 10.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.0 i	ACM	08.1989 ▶ 07.1994	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.0 i	AER	03.1996 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.0 i	ALL	05.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.0 i Coupé, Fox, Houston	AAU	08.1990 ▶ 09.1994			0.9	<b>246555</b>	H79
1.05 i	AEV	10.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.1	HB, HD, HC	04.1975 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Coupé	GT	08.1982 ▶ 12.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Coupé	HH	01.1977 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Coupé	HJ	01.1977 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Coupé	HK	08.1983 ▶ 07.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3 Coupé	HW	08.1983 ▶ 07.1985	<b>246179</b>	R76H	0.7	<b>246555</b>	H79





3+1


**VOLKSWAGEN** (.../...)

**POLO (.../...)**

1.3 Coupé	NU	08.1985 ▶ 12.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 Coupé	NZ	08.1985 ▶ 07.1988	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.3 Coupé	NZ	08.1985 ▶ 07.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3 Coupé GT, G40	PY	01.1987 ▶ 09.1990			0.8	<b>246557</b>	H60
1.3 Coupé, GT	GK	07.1982 ▶ 12.1992			0.8	<b>246557</b>	H60
1.3 Coupé, GT	GK	07.1982 ▶ 12.1992	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.3 GT40	MM	01.1989 ▶			0.8	<b>246557</b>	H60
1.3 i CL, GL	ADX	10.1994 ▶ 04.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.3 i CLi, Coupé, GT	3F	10.1989 ▶ 09.1994			0.8	<b>246557</b>	H60
1.4 i	ANM	07.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i	ANW, APQ, AUD	11.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	ANX	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i Classic, Coupé, Flight, GL, Variant	AEX	10.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i Classic, Coupé, Variant	AKV	09.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i Variant	APQ	12.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i 16V	AFH	04.1996 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AFK	07.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AHW	01.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	APE, AUA [DOHC]	10.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.4 i 16V	AUB	10.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	AEH, AKL, AUR [OHC]	10.1999 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i	ALM	07.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	ARC	10.1999 ▶ 04.2000	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Classic, Flight, GL, GT	1F	11.1995 ▶			0.9	<b>246555</b>	H79
1.6 i Classic, Variant	AFT	11.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i Coupé, Flight, GL, GT, Variant	AEE	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i Flight, GL, GT, Variant	AEA	10.1994 ▶ 07.1995	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i 16V GTi	AJV	04.1998 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i	ADD	03.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	ADZ	05.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79

**SANTANA**

1.3	EP	08.1981 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.3	FY	09.1975 ▶ 07.1983	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.3	FZ	09.1975 ▶ 07.1983	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6	DT, JU	08.1983 ▶ 07.1987	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
1.6	WP	08.1979 ▶ 01.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WV, WVA	08.1981 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	WY	09.1979 ▶ 07.1983	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	YP	09.1975 ▶ 12.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	DS, JN, JV	09.1982 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8	JV	09.1982 ▶ 04.1988	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
1.8 i	DZ	09.1982 ▶ 04.1988	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9 5S	WN	10.1980 ▶ 08.1983	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0	HP	08.1983 ▶ 12.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	JS	08.1983 ▶ 07.1985	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.1 L5	KM	09.1982 ▶ 07.1984	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.1 L5	WE	03.1977 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**SCIROCCO**

1.1	FA, FJ	04.1974 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.3	HK, GT, GF	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	FB	02.1974 ▶ 07.1977	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	FH	02.1974 ▶ 07.1977	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.5	GH	08.1977 ▶ 07.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.5	JB	08.1977 ▶ 07.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	EM	08.1975 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FN	01.1976 ▶ 07.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FP	08.1975 ▶ 08.1977	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.6	FR	08.1975 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	FV	02.1976 ▶ 07.1979	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6 GT	EW	01.1983 ▶ 07.1992			0.9	<b>246555</b>	H79
1.6 GT	EWA	01.1983 ▶ 07.1987			0.9	<b>246555</b>	H79
1.6 GT	HN	08.1983 ▶ 07.1986			0.9	<b>246555</b>	H79
1.6 GT	RE	04.1986 ▶ 07.1990			0.9	<b>246555</b>	H79
1.6 i GTi	EG	06.1976 ▶ 07.1982	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8	JH	08.1982 ▶ 07.1992	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLKSWAGEN (.../...)

### SCIROCCO (.../...)

1.8 GT	EX	08.1983 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 GT	JJ, KT	08.1982 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i GT, GTX	DX	08.1982 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V GT, GTX	KR	10.1985 ▶ 07.1989			0.9	<b>246567</b>	F59
1.8 i 16V GT, GTX	PL	01.1986 ▶ 07.1992			0.9	<b>246567</b>	F59

### SHARAN

1.8 T 20V	AJH	09.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0	ATM	05.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	ADY	07.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i	AKT	01.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.0 i 16V	ABF	05.1995 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 VR6	AAA	05.1995 ▶			1.6	<b>246554</b>	F87

### VENTO

1.3 i	ADX	10.1994 ▶ 10.1998	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	ABD	08.1991 ▶ 07.1995			0.9	<b>246555</b>	H79
1.4 i	AEX	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	ABU	07.1992 ▶ 09.1994			0.9	<b>246555</b>	H79
1.6 i	AEA	07.1994 ▶ 07.1995	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AEE	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	AKS	05.1997 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i CL, GL	AEK	07.1994 ▶ 12.1995	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.6 i CL, GL	AFT	07.1994 ▶	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
1.8 i CL	AAM	09.1991 ▶			0.9	<b>246555</b>	H79
1.8 i CL, GL, TX	ABS	09.1991 ▶ 08.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i CL, GL, TX	ACC, ADZ	07.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	ADY	07.1994 ▶ 09.1998	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	AEP	07.1994 ▶ 07.1997	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	AGG	07.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i	AKR	05.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i GTi	2E	09.1991 ▶ 09.1994	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
2.0 i 16V	ABF	09.1991 ▶ 07.1997	<b>246486</b>	RF74HZ3YE	0.9	<b>246554</b>	F87
2.8 VR6	AAA	11.1991 ▶ 09.1998			1.6	<b>246554</b>	F87

## VOLKSWAGEN

### BUS

1.9 Syncro	DF, DG	08.1982 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.9 Syncro	DF, DG	08.1982 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.1 Syncro	DJ	08.1985 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.1 Syncro	DJ	08.1985 ▶ 07.1992	<b>246198</b>	R70H	0.8	<b>246557</b>	H60
2.1 Syncro	SR	08.1989 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.5 TDi	ACV	08.1995 ▶ 04.1998			0.9	<b>246555</b>	H79

### CADDY

1.4 i	AEX	10.1994 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	AKV, APQ	12.1997 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.4 i	ANX	01.1998 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.5	JB	08.1982 ▶ 07.1983	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	EM	08.1982 ▶ 07.1983	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.6	EW	08.1983 ▶ 07.1984	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.6	HN	08.1983 ▶ 07.1989			0.9	<b>246555</b>	H79
1.6 i	1F	11.1995 ▶ 04.1996			0.9	<b>246555</b>	H79
1.6 i	AEE	11.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8	JH	08.1985 ▶ 12.1995	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79

### CALIFORNIA

1.8	PD	12.1990 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	AAC	09.1990 ▶			0.9	<b>246555</b>	H79
2.5 i Syncro	AAF	11.1990 ▶ 12.1993			0.9	<b>246555</b>	H79
2.5 TDi	ACV	08.1995 ▶ 03.1998			0.9	<b>246555</b>	H79
2.8 VR6, T4	AES	11.1995 ▶ 04.2000			1.6	<b>246554</b>	F87

### CARAVELLE

2.5 i Syncro	ACU	07.1994 ▶			0.9	<b>246555</b>	H79
2.5 TDi	ACV	07.1995 ▶			0.9	<b>246555</b>	H79
2.8 VR6, T4	AES	11.1995 ▶ 04.2000			1.6	<b>246554</b>	F87

### EUROVAN

2.5 i	AAF	09.1991 ▶ 12.1993			0.9	<b>246555</b>	H79
2.5 i	ACU	01.1994 ▶ 05.1996			0.9	<b>246555</b>	H79
2.5 TDi	ACV	01.1995 ▶			0.9	<b>246555</b>	H79


**VOLKSWAGEN** (.../...)

**ILTIS**

1.7	WL, YX	08.1978 ▶ 12.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
-----	--------	-------------------	---------------	------	-----	---------------	-----

**LT**

2.0	CL, CH	04.1975 ▶ 09.1983	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i	AGL	05.1996 ▶	<b>246492</b>	RF74HZ2Y	0.9	<b>246554</b>	F87
2.4	HS, DL	12.1982 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.4 28, 31, 35, 40	1E	01.1991 ▶ 07.1995			0.9	<b>246555</b>	H79
2.4 28, 31, 35, 40	1E	08.1995 ▶			0.9	<b>246555</b>	H79
2.4 28, 31, 35, 40	1E	10.1988 ▶ 12.1990	<b>246179</b>	R76H	0.65	<b>246555</b>	H79
2.4 40 4x4, 45 4x4	DL	09.1985 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**LT 40-55**

2.4 D	1E	12.1978 ▶ 02.1991			0.9	<b>246555</b>	H79
-------	----	-------------------	--	--	-----	---------------	-----

**MULTIVAN**

1.8	PD	12.1990 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i, T4	AAC	09.1990 ▶			0.9	<b>246555</b>	H79
2.5 i, Synchron	AAF, ACU	11.1990 ▶ 08.1996			0.9	<b>246555</b>	H79
2.5 i, T4	AAF, ACU, AEN	11.1990 ▶ 08.1996			0.9	<b>246555</b>	H79
2.5 i, T4	AET, AEU	08.1996 ▶			0.9	<b>246555</b>	H79
2.5 TDi	ACV	08.1995 ▶ 04.1998			0.9	<b>246555</b>	H79
2.5 TDi T4	ACV	05.1997 ▶			0.9	<b>246555</b>	H79
2.8 VR6, T4	AES	11.1995 ▶ 04.2000			1.6	<b>246554</b>	F87

**TARO**

1.8	2Y	02.1989 ▶ 09.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.2	4Y	06.1989 ▶ 07.1994	<b>246180</b>	R84H	0.8	<b>246555</b>	H79
2.4	22R	06.1989 ▶	<b>246180</b>	R84H	0.8	<b>246555</b>	H79

**TRANSPORTER**

1.8	PD	12.1990 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9 Syncro	DF	08.1982 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9 Syncro	DG	08.1982 ▶ 07.1984	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.9 Syncro	SP	08.1982 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	AAC	09.1990 ▶			0.9	<b>246555</b>	H79
2.1 Syncro	DJ	07.1985 ▶ 07.1987	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.1 Syncro	SR	08.1989 ▶ 07.1992	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.5 i	AEN	03.1995 ▶ 08.1996			0.9	<b>246555</b>	H79
2.5 i	AET, AEU	01.1996 ▶			0.9	<b>246555</b>	H79
2.5 i Syncro	AAF	09.1990 ▶ 12.1993			0.9	<b>246555</b>	H79
2.5 i Syncro	ACU	01.1994 ▶ 08.1996			0.9	<b>246555</b>	H79
2.5 TDi	ACV	01.1995 ▶			0.9	<b>246555</b>	H79
2.8 VR6, T4	AES	11.1995 ▶ 04.2000			1.6	<b>246554</b>	F87

**VOLKSWAGEN (BR)**
**APOLLO**

1.8 GLS	AP 1800	12.1994 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GLS	AP 1800	12.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79

**FUSCA**

1.6	1600	08.1993 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6	1600	08.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79

**GOL**

1.0 i	AE 1000	01.1995 ▶	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87
1.6	AE 1600 Alcool	07.1990 ▶	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
1.6 Mi	AP 1600	10.1996 ▶	<b>246178</b>	R64H	0.8	<b>246557</b>	H60
1.6 i	AP 1600	01.1995 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GT	AP 1800	03.1984 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GT	AP 1800	03.1984 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 GTS	AP 1800	03.1984 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GTS	AP 1800	03.1984 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i	AP 1800	10.1994 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 i Mi	AP 1800	10.1996 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i GTi	AP 2000	01.1995 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i GTi	AP 2000	01.1995 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Mi	AP 2000	10.1996 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i 16V Mi 16	AP 2000	10.1996 ▶	<b>246173</b>	RF74H	0.7	<b>246554</b>	F87

**LOGUS**

1.6 CL, GL	AE 1600 Alcool	02.1993 ▶	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
1.6 i	AP 1600	01.1995 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.6 i	AP 1600	01.1995 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLKSWAGEN (BR) (.../...)

### LOGUS (.../...)

1.8 i CL, GL, GLS	AP 1800	02.1993 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 i CL, GL, GLS	AP 1800	02.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i	AP 2000	07.1994 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i	AP 2000	07.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79

### PARITI

1.6	AE 1600 Alcool	07.1990 ▶	<b>246184</b>	RF72H	0.7	<b>246567</b>	F59
1.6 Mi	AP 1600	10.1996 ▶			0.9	<b>246555</b>	H79
1.8	UD 1800	01.1988 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8	UE 1800	01.1988 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 i	AP 1800	10.1994 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 i	AP 1800	10.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i Mi	AP 1800	10.1996 ▶			0.9	<b>246555</b>	H79
2.0 i	AP 2000	10.1994 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i	AP 2000	10.1996 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i Mi	AP 2000	10.1996 ▶			0.9	<b>246555</b>	H79

### SANTANA

1.8	UE 1800	05.1985 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GL	AP 1800	04.1991 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 GL	UD 1800	04.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 Quantum	AP 1800	05.1985 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 Quantum	UD 1800	11.1984 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i	AP 1800	03.1993 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
1.8 i	AP 1800	03.1993 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.8 i Mi	AP 1800	10.1996 ▶			0.9	<b>246555</b>	H79
1.8 i Quantum	AP 1800	12.1994 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 Executive	AP 2000	08.1989 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 GLS	AP 2000	04.1991 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 GLS	AP 2000	04.1991 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 Quantum	AP 2000	04.1988 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 Quantum	AP 2000	04.1988 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0 i GLS	AP 2000	06.1991 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i i Quantum	AP 2000	01.1994 ▶	<b>246178</b>	R64H	0.7	<b>246557</b>	H60
2.0 i i Quantum	AP 2000	01.1994 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Mi	AP 2000	10.1996 ▶			0.9	<b>246555</b>	H79

### VOYAGE

1.8		08.1989 ▶	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
-----	--	-----------	---------------	------	-----	---------------	-----

## VOLKSWAGEN (ESP)

### SANTANA

1.8	DS	06.1985 ▶	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
2.0 i	JS	06.1985 ▶	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60

## VOLKSWAGEN (ESP)

### CADDY

1.4 i	AEX	11.1995 ▶	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.6 i	1F	11.1995 ▶			0.9	<b>246555</b>	H79

## VOLKSWAGEN (MEX)

### GOLF

1.8 i	PF	12.1988 ▶ 12.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	PF	12.1988 ▶ 12.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i	RV	12.1988 ▶ 12.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8 i	RV	12.1988 ▶ 12.1991	<b>246195</b>	76H3E	0.8	<b>246557</b>	H60
1.8 i 16V	PL	12.1988 ▶ 07.1989			0.9	<b>246567</b>	F59
2.0 i 16V	9A	01.1990 ▶ 12.1991			0.9	<b>246567</b>	F59

### KAEFER / BEETLE / COCCINELLE

1.6	ACD	10.1992 ▶	<b>246181</b>	R90H	0.7		
-----	-----	-----------	---------------	------	-----	--	--

## VOLKSWAGEN (US)

### GOLF

1.8	HT, GX	08.1984 ▶ 07.1987	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79
1.8 i	RD	08.1984 ▶ 07.1987	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79

### RABBIT

1.7	JF	12.1981 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.8	JH	08.1982 ▶ 07.1984	<b>246511</b>	R74HZ3YE	0.9	<b>246555</b>	H79



3+1


**VOLVO**

**140**

142, 144, 145 : 1.8	B 18 A		<b>246189</b>	R88N	0.7		
<b>240</b>							
1.8 DL, GL	B 17 A	11.1978 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 DL, GL	B 19 A/K	09.1976 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 DL, GL	B 200 K	08.1984 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i DL, GL, GLE, GLT	B 19 E	09.1976 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i DL, GL, GLE, GLT	B 200 E	08.1984 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i DL, GL, GLE, GLT	B 200 F Cat	04.1991 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Turbo GLT	B 19 ET	08.1981 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo GLT	B 200 ET	08.1984 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Turbo GLT	B 200 FT	08.1984 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.1 DL, GL	B 21 A	08.1974 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.1 i DL, GL, GLE, GLT	B 21 E	08.1974 ▶ 07.1982	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.1 i Turbo GLE, GLT	B 21 ET	08.1980 ▶ 07.1986	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 DL, GL, GLE, GLT	B 23 A	08.1984 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 GL	B 230 K	08.1984 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i DL, GL, GLE, GLT	B 230 A	08.1984 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i DL, GL, GLE, GLT, SE	B 23 E	03.1979 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i DL, GL, GLE, GLT, SE	B 230 E	03.1979 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i DL, GL, GLE, GLT, SE	B 230 F Cat	08.1984 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i DL, GL, GLE, GLT, SE	B 230 FD Cat	08.1992 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i GL	B 230 K	08.1986 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo GLT	B 230 ET	08.1984 ▶ 08.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.8 i V6	B 28 E	08.1980 ▶ 07.1984			0.7	<b>246565</b>	C60

**260**

2.3	B 23 A	08.1981 ▶ 07.1982	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.7 i V6 Coupé	B 27 E	08.1974 ▶ 07.1980			0.7	<b>246565</b>	C60
2.7 V6	B 27 A	08.1974 ▶ 07.1982			0.7	<b>246565</b>	C60
2.8 i V6 Coupé	B 28 E	08.1980 ▶ 07.1984			0.7	<b>246565</b>	C60
2.8 V6 Coupé	B 28 A	08.1979 ▶ 07.1982			0.7	<b>246565</b>	C60

**340-360**

1.1 DL, GL	B 110 E	▶ 12.1980	<b>246189</b>	R88N	0.7		
1.3 DL, GL	B 130 E	▶ 12.1980	<b>246189</b>	R88N	0.7		
1.4 DL, GL	B 14 Renault	02.1976 ▶ 09.1978	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.4 DL, GL	B 14 Renault	02.1976 ▶ 09.1978	<b>246189</b>	R88N	0.7		
1.7 DL, GL	B 17 2K	07.1985 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 DL, GL	B 17 2K	09.1986 ▶ 07.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
1.7 DL, GL	B 172 KD	09.1986 ▶ 07.1991	<b>246180</b>	R84H	0.7	<b>246555</b>	H79
2.0	B 200 K	08.1984 ▶ 07.1988	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 Sport	B 19 A	08.1979 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i	B 200 E	08.1984 ▶ 07.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i	B 200 F		<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**360**

1.3 DL, GL, GLE	B 13 E	01.1989 ▶	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 DL, GL, GLE	B 19 A	08.1982 ▶ 07.1984	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i DL, GL, GLE	B 200 K	08.1984 ▶ 07.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i DL, GL, GLE, GLT	B 19 E	08.1982 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i DL, GL, GLE, GLT	B 200 EE, ES, E, F	08.1984 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**440**

1.6 i DL, GL, GLE, GLT, SE	B 16F Cat	09.1988 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, ES, GL, GLE, GLT, SE	B 18 E	09.1988 ▶ 09.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, ES, GL, GLE, GLT, SE	B 18 ED	09.1988 ▶ 12.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, ES, GL, GLE, GLT, SE	B 18 EP	09.1988 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, ES, GL, GLE, GLT, SE	B 18 ES	09.1988 ▶ 09.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, ES, GL, GLE, GLT, SE	B 18 FP	08.1989 ▶ 12.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, GL, GLE, GLT, SE	B 18 F	09.1988 ▶ 03.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, GL, GLE, GLT, SE	B 18 K	09.1988 ▶ 08.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, GL, GLE, GLT, SE	B 18 KD	09.1989 ▶ 12.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, GL, GLE, GLT, SE	B 18 KP	09.1988 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i DL, GL, GLE, GLT, SE	B 18 KPD	09.1988 ▶ 02.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i Turbo	B 18 FT, FTM	09.1988 ▶ 08.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.8 i DL, GL, GLE, GLT, SE	B 18 U Cat	09.1991 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i	B 20 F Cat	09.1992 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

**480**

1.7 i	B 18 ED	10.1987 ▶ 08.1988	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
-------	---------	-------------------	---------------	------	-----	---------------	-----





Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Swiece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLVO (.../...)

### 480 (.../...)

1.7 i ES	B 18 E, ES	04.1986 ▶ 07.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
1.7 i ES	B 18 F	05.1987 ▶ 12.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
1.7 i Turbo	B 18 FT, FTM	03.1988 ▶ 08.1995	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i	B 20 F Cat	09.1992 ▶ 12.1996	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### 66

1.1	BB110E	08.1975 ▶ 08.1978	<b>246189</b>	R88N	0.7		
1.3	B 130	08.1975 ▶ 08.1978	<b>246189</b>	R88N	0.7		

### 740

2.0 DL, DLE, GL	B 200 K	08.1984 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i GL, GLE, SE	B 200 E, G, GE	08.1989 ▶ 08.1994	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i GLE	B 19 E, B 200 E	08.1983 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i 16V GLT	B 204 E	08.1988 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i 16V Turbo	B 204 GT	08.1989 ▶ 08.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 19 ET	04.1984 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 200 ET	08.1984 ▶ 08.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Turbo	B 200 ET	09.1986 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i Turbo	B 200 FT	08.1990 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 204 FT Cat	08.1989 ▶ 07.1990	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 DL, GL, GLE	B 230 K	08.1984 ▶ 07.1986	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i DL, GL, GLE	B 230 K	08.1986 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i DL, GL, GLT, SE	B 230 A	08.1984 ▶ 07.1987	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i DL, GL, GLT, SE	B 230 F Cat	08.1984 ▶ 07.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i GLE	B 230 E	08.1983 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i GLE, GLT	B 23 E	04.1983 ▶ 07.1985	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i GLT, SE	B 230 G	08.1991 ▶ 07.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i 16V	B 234 G	08.1990 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i 16V GLT	B 234 F Cat	04.1988 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 ET	08.1984 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i Turbo	B 230 FT Cat	08.1984 ▶ 07.1989	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i Turbo	B 230 FT Cat	08.1989 ▶ 07.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 GT	08.1989 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60

### 760

2.0 i 16V Turbo	B 204 GT	01.1990 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 200 ET	08.1984 ▶ 07.1987	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 200 ET	08.1987 ▶ 07.1989	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 204 FT Cat	01.1990 ▶ 07.1992	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i Turbo	B 23 ET	04.1982 ▶ 07.1984	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 ET	08.1984 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 FT Cat	08.1984 ▶ 07.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 GT	08.1989 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.8 i V6 GLE	B 28 E	02.1982 ▶ 04.1986			0.7	<b>246565</b>	C60
2.8 i V6 GLE	B 28 F, B 280 F	08.1982 ▶ 08.1991			0.7	<b>246565</b>	C60
2.8 i V6 GLE	B 280 E	05.1986 ▶ 07.1991			0.7	<b>246565</b>	C60
2.8 V6 GLE	B 28 A	08.1982 ▶ 07.1986			0.7	<b>246565</b>	C60

### 780

2.0 i 16V Turbo	B 204 GT	08.1987 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo GLE	B 200 ET	01.1986 ▶ 07.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo GLE	B 204 FT Cat	01.1989 ▶ 12.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 FT Cat	01.1989 ▶ 12.1990	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.8 i V6 GLE	B 280 E, F	05.1986 ▶ 07.1991			0.7	<b>246565</b>	C60

### 850

2.0 i S, SE, GLT	B 5202 F, S Cat	09.1994 ▶ 12.1996	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 20V S, SE, GLT	B 5204	09.1991 ▶ 12.1996	<b>246173</b>	RF74H	0.8	<b>246554</b>	F87
2.0 i 20V Turbo	B 5204 FT Cat	01.1994 ▶ 12.1997	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.3 i 20V Turbo	B 5234 FT Cat	09.1993 ▶ 12.1997	<b>246487</b>	RF74HZDC	0.7	<b>246554</b>	F87
2.5 i S, SE, GL	B 5252 F, S Cat	09.1992 ▶ 12.1997	<b>246176</b>	RF80H	0.7	<b>246554</b>	F87
2.5 i 20V S, SE, GLT	B 5254 F, S Cat	09.1991 ▶ 12.1997	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.5 i 20V Turbo	B 5254 FT	09.1996 ▶ 12.1997	<b>246488</b>	RF72HZDC	0.8	<b>246567</b>	F59

### 940

2.0 i	B 200 E	09.1990 ▶ 08.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i GL, GLT, SE	B 200 F, G	09.1991 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.0 i 16V GL, GLE, GLT, SE	B 204 E	09.1990 ▶ 08.1991	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i 16V Turbo	B 204 GT	09.1992 ▶ 08.1994	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 200 FT	01.1991 ▶ 08.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 204 FT Cat	09.1992 ▶ 08.1994	<b>246198</b>	R70H	0.7	<b>246557</b>	H60





3+1


**VOLVO** (.../...)

**940 (.../...)**

2.3 i GL, GLE, GLT, SE	B 230 F, B 230 FD Cat	09.1990 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i GL, GLE, GLT, SE	B 230 FB Cat	09.1992 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i GL, GLT, SE	B 230 G	09.1991 ▶ 08.1995	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i S, SE	B 230 FK Cat	09.1994 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i 16V GL, GLT, SE	B 234 F Cat	09.1990 ▶ 09.1994	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i 16V GL, GLT, SE	B 234 G	09.1990 ▶ 08.1992	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 FT Cat	09.1990 ▶ 08.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 GT	09.1991 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

**960**

2.0 i Turbo	B 200 FT	09.1992 ▶ 08.1997	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.0 i Turbo	B 204 FT Cat	09.1990 ▶ 08.1994	<b>246198</b>	R70H	0.7	<b>246557</b>	H60
2.3 i Turbo	B 230 FT Cat	09.1990 ▶ 08.1996	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.3 i Turbo	B 230 GK, GT	09.1991 ▶ 08.1997	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
2.5 i 24V	B 6254 F, G Cat	08.1994 ▶ 08.1997	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87
2.8 i V6	B 280 E, F	09.1990 ▶ 08.1991			0.7	<b>246565</b>	C60
2.9 i V6 24V	B 6304 FS, GS Cat	09.1990 ▶ 07.1998	<b>246176</b>	RF80H	0.8	<b>246554</b>	F87

**C**

202 : 2.0	B 20 A	03.1975 ▶ 12.1991	<b>246189</b>	R88N	0.7		
-----------	--------	-------------------	---------------	------	-----	--	--

**C70**

2.0 i	B 5202 S, F Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V	B 5204 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V Turbo	B 5204 T	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.3 i 20V	B 5234 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.4 i 20V	B 5244 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.5 i	B 5252 S Cat	01.1997 ▶ 03.2000	<b>246321</b>	RF80H3	1.2		
2.5 i 20V	B 5254 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		

**S40**

1.6 i 16V	B 4164 F	06.1996 ▶	<b>246321</b>	RF80H3	1.2		
1.6 i 16V	B 4164 S	06.1996 ▶ 08.1999	<b>246321</b>	RF80H3	1.2		
1.6 i 16V	B 4164 S2	03.1999 ▶	<b>246321</b>	RF80H3	1.2		
1.8 i 16V	B 4184 S	09.1995 ▶	<b>246321</b>	RF80H3	1.2		
1.8 i 16V Optimum	B 4184 SM	09.1995 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 16V	B 4204S	09.1995 ▶	<b>246321</b>	RF80H3	1.2		

**S70**

2.0 i	B 5202 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V	B 5204 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V Turbo	B 5204 T	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.3 i 20V	B 5234 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.4 i 20V	B 5244 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.5 i	B 5252 S Cat	01.1997 ▶ 03.2000	<b>246321</b>	RF80H3	1.2		
2.5 i 20V	B 5254 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		

**S80**

2.4 i	B 6244 F	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.4 i 20V	B 5244 S		<b>246321</b>	RF80H3	1.2		
2.9 i V6 24V	B 6304 S	06.1998 ▶	<b>246321</b>	RF80H3	1.2		

**S90**

2.5 i 24V	B 6254 F, G Cat	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.9 i V6 24V	B 6304 S, F, G	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87

**SAMFENG**

2.3 i	B 230 GS	08.1994 ▶ 07.1997	<b>246179</b>	R76H	0.8	<b>246555</b>	H79
-------	----------	-------------------	---------------	------	-----	---------------	-----

**V40**

1.6 i 16V	B 4164 F, S	06.1996 ▶	<b>246321</b>	RF80H3	1.2		
1.6 i 16V	B 4164 S2	03.1999 ▶	<b>246321</b>	RF80H3	1.2		
1.8 i 16V	B 4184 S	09.1995 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 16V	B 4204S	09.1995 ▶	<b>246321</b>	RF80H3	1.2		

**V70**

2.0 i	B 5202 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V	B 5204 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		
2.0 i 20V Turbo	B 5204 T	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
2.3 i 20V	B 5234 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.4 i 20V	B 5244 S	01.1999 ▶	<b>246321</b>	RF80H3	1.2		
2.5 i	B 5252 S Cat	01.1997 ▶ 03.2000	<b>246321</b>	RF80H3	1.2		
2.5 i 20V	B 5254 F, S Cat	01.1997 ▶	<b>246321</b>	RF80H3	1.2		

**V90**

2.5 i 24V	B 6254 F, G Cat	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
-----------	-----------------	-----------	---------------	----------	-----	---------------	-----



Spark plugs  
Bougies d'allumage  
Bujías de encendido  
Velas de ignição  
Candele di accensione

Ontstekingsbougies  
Zündkerzen  
Świece zapłonowe  
Buji  
Свечи зажигания



3+1



## VOLVO (.../...)

### V90 (.../...)

2.9 i V6 24V	B 6304 S, F, G	01.1997 ▶	<b>246487</b>	RF74HZDC	0.8	<b>246554</b>	F87
--------------	----------------	-----------	---------------	----------	-----	---------------	-----

## WARTBURG

### 353

1.0		07.1971 ▶ 09.1989	<b>246189</b>	R88N	0.6		
1.0 W		01.1978 ▶ 12.1990	<b>246189</b>	R88N	0.6		
1.3	Mot. VW	09.1988 ▶ 05.1991	<b>246179</b>	R76H	0.7	<b>246555</b>	H79

## YULON (YUE LOONG)


### 101 FEELING

1.6	CA16S	01.1988 ▶			1.1	<b>246556</b>	F87-11
1.8	CA18S	01.1988 ▶			1.1	<b>246556</b>	F87-11

## ZASTAVA (YUGO)

### YUGO

101 : 1.1		06.1972 ▶ 12.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79
101 : 1.3 1300		06.1972 ▶ 12.1993	<b>246179</b>	R76H	0.7	<b>246555</b>	H79



1.3

Spark plugs

Bougies d'allumage

Bujías de encendido

Vela de ignição

Candele di accensione

Ontstekingsbougies

Zündkerzen

Świece zapłonowe

Буји

Свечи зажигания



**Valeo**

**Valeo**



<b>AC-DELCO</b>	
2501	F 64 H
2503	64 H3E
3500	70 H3E
4500	76 H3E
4503	F 72 H3E
4504	F 72 H
5500	F 74 H
6500	84 H3E
6501	C 72 H
6503	F 80 HDC
7500	F 82 H
41 XLS	6 H
41-2 XLS	7 H
42 XL	5 H
42-5 LTS	C 64 H
43 XL	5 H
45 NS	90 H
C 41 CLTS	C 60 H
C 41 CXLS	6 H
C 42 CFS	88 N
C 42 CLTS	C 68 H
C 42 CXLS	76 H
C 42 LTS	C 68 H
C 42 N	5 H
C 42 XLS	84 H
C 43 CXLS	90 H
CFR 1 CLS	RF 72 H
CFR 2 CLS	RF 74 H
CFR 3 CLS	RF 80 H
CR 41 CXLS	R 64 H
CR 42 CFS	R 88 N
CR 42 CLTS	RC 72 H
CR 42 CXLS	R 76 H
CR 42 CXLSX	R 76 H11
CR 42 LTS	RC 72 H
CR 42 XLS	R 76 H
CR 42 XLSX	R 76 H11
CR 425 CFS	R 88 N
CR 425 XLS	R 84 H
CR 43 XLS	R 90 H
CR 44 NS	R 70 H
CR42CLTS	RC 68 H
FR 1 LS	RF 74 H
FR 2 CLS	RF 80 H
FR 2 LS	RF 80 H
FR 2 LS	RF 82 H
FR 3 CLS	RF 82 H
FR 3 LS	RF 82 H
LM 46	T 9
N 705	67 HP
N 802	C 64 HP
R 3602	RC 64 H
R 41 CXLS	R 64 H
R 42 CFS	R 76 N
R 42 CLTS	RC 72 H
R 42 CXLS	R 76 H
R 42 FS	R 76 N
R 42 LTS	RC 64 H
R 42 XLS	R 76 H
R 43 CFS	R 88 N
R 43 CXLS	R 90 H
R 43 N	R 84 H
R 44 CXLS	R 90 H
R 45 NS	R 90 H
R 45 NSX	R 90 H11
R 83 CTS	GC 68 N
R2601	RF 64 H
R2602	R 64 H11
R3601	R 70 H11
R4601	RF 72 H11
R4603	RF 72 H3
R4604	RF 72 H3E
R4606	RF 72 HZDC
R4607	RF 72 HZ3YE
R4900	RC 68LPP
R5601	RF 74 H3
R5602	RF 74 HZ2Y
R5603	RF 74 HZ2
R5604	RF 74 H11
R5605	RF 74 HZDC
R5606	RF 74 HZ3YE
R5607	R 74 HZ3YE
R5608	RF 74 HZ
R5610	RF 74 HZY11
R6600	R 84 HZY
R6601	RF 80 HZY
R6603	RC 72 H11

<b>AC-DELCO (.../...)</b>	
R6604	RF 80 H3
R6605	RF 80 H11
R6606	R 84 H11
R7601	RF 82 H11
R7602	RF 82 HZ2Y
R7603	RF 82 HZDCS11
R9600	R 92 H
S 42 F	4 N
S 42 XLR	R 64 H
S 43 XL	5 H
<b>AUTOLITE</b>	
43	GC 68 N
62	R 70 H
63	R 76 H
64	R 84 H
102	C 60 H
103	RC 72 H
283	R 76 N
3921	RF 64 H
3922	RF 72 H
3922	RF 72 H11
3923	RF 80 H
3923	RF 80 H11
3924	RF 82 H
3924	RF 82 H11
9061	64 H3E
9062	70 H3E
9063	76 H3E
9064	84 H3E
9921	F 72 H3E
9921	RF 72 H3E
<b>BERU</b>	
14-3 DPO	67 HP
14-4 A2	4 N
14-4 AU	4 N
14-4 C2	5 H
14-4 CU	5 H
14-5 CU	5 H
14-5 DTU	64 H3E
14-5 DU	6 H
14-5 DUO	6 H
14-6 B	88 N
14-6 DTU	70 H3E
14-6 DU	7 H
14-6 DUO	7 H
14-7 BU	88 N
14-7 DTU	76 H3E
14-7 DU	76 H
14-7 DUO	76 H
14-8 DTU	84 H3E
14-8 DU	84 H
14-8 DUO	84 H
14-8 LUR	R 84 HZY
14-9 DU	90 H
14-9 DUO	90 H
14-9 EUO	T 9
14F-5 DU	F 64 H
14F-6 DTU	F 72 H3E
14F-6 DU	F 72 H
14F-6 DUO	F 72 H
14F-6 DUOR	F 72 H
14F-7 DU	F 74 H
14F-7 DU	F 80 H
14F-7 DUO	F 74 H
14F-7 DUO	F 80 H
14F-7 DUOR	F 74 H
14F-7 DUOR	F 80 H
14F-7 LDU	RF 74 HZ2Y
14F-7 LDUR	RF 74 HZ2Y
14F-8 DU	F 82 H
14F-8 DU4	F 82 H
14F-8 DUO	F 82 H
14F-8 LUR	RF 80 HZY
14FGH-6 DTUR	RF 72 HZ3YE
14FGH-7 DTUR	RF 74 HZ3YE
14FGH-7 DTURX	RF 74 HZ3YE
14FGR-7 CTU	RF 74 H3
14FR-5 DU	RF 64 H
14FR-6 DU	RF 72 H
14FR-6 DUX	RF 72 H11
14FR-7 DU	RF 74 H
14FR-7 DU	RF 80 H
14FR-7 DUX	RF 74 H11
14FR-7 KDU	RF 74 HZ2
14FR-7 LDU	RF 74 HZ2Y
14FR-7 LUX	RF 74 HZY11
14FR-8 DU	RF 82 H

<b>BERU (.../...)</b>	
14FR-8 DUX	RF 82 H11
14FR-8 LDU	RF 82 HZ2Y
14FR-8 LDU4	RF 82 HZ2Y
14GH-7 DTUR	R 74 HZ3YE
14K-5 DU	C 60 H
14K-5 DUO	C 60 H
14K-6 DU	C 64 H
14K-6 DUO	C 64 H
14K-7 DU	C 72 H
14K-7 DUO	C 72 H
14KR-6 DU	RC 64 H
14KR-6 ZPPV	RC 68LPP
14KR-7 DU	RC 72 H
14KR-7 DUO	RC 72 H
14KR-7 DUX	RC 72 H11
14R-5 DU	R 64 H
14R-6 BU	R 76 N
14R-6 DU	R 70 H
14R-6 DUX	R 70 H11
14R-7 BU	R 88 N
14R-7 DU	R 76 H
14R-7 DUX	R 76 H11
14R-8 DU	R 84 H
14R-8 DU4	R 84 H
14R-8 DUX	R 84 H11
14R-9 DU	R 90 H
18KR-6 BU	GC 68 N
18KR-7 BU	GC 68 N
<b>BOSCH</b>	
DR 6 BC	GC 68 N
DR 7 BC	GC 68 N
F 5 DC	F 64 H
F 6 DC	F 72 H
F 6 DCOR	RF 72 H
F 6 DCX	RF 72 H11
F 6 DTC	F 72 H3E
F 6 LTRC	RF 72 HZ3YE
F 7 DC	F 74 H
F 7 DC	F 80 H
F 7 DCO	F 74 H
F 7 DCO	F 80 H
F 7 DCOR	RF 74 H
F 7 DCOR	RF 80 H
F 7 DCR4	RF 74 H
F 7 DCR4	RF 80 H
F 7 DPP 222 T	RF 74 HZ3YE
F 7 DTC	F 72 H3E
F 7 KTCR	RF 74 HZ3YE
F 7 LCR	R 76 H
F 7 LCR	RF 74 HZ2Y
F 7 LDOR	RF 74 HZ2Y
F 7 LTRC	RF 74 HZ3YE
F 8 DC	F 82 H
F 8 DCO	F 82 H
F 8 DCOR	RF 82 H
F 8 DC4	F 82 H
F 8 DCX	RF 82 H11
F 8 LCR	RF 80 HZY
F 8 LDCR	RF 82 HZ2Y
FGR 7 DQC	RF 74 H3
FR 5 DC	RF 64 H
FR 5 DCX	RF 64 H11
FR 6 DC	RF 72 H
FR 6 DC2	RF 72 HZDC
FR 6 DCX	RF 72 H11
FR 6 DTC	RF 72 H3E
FR 6 DTCW	RF 72 H3E
FR 6 KTC	RF 74 HZ3YE
FR 7 DC	RF 74 H
FR 7 DC	RF 80 H
FR 7 DCO	RF 74 H
FR 7 DCO	RF 80 H
FR 7 DCO	RF 74 HZDC
FR 7 DC2	RF 80 H
FR 7 DCR4	RF 80 H
FR 7 DCCU	RF 74 H11
FR 7 DCU	RF 80 H11
FR 7 DCX	RF 74 H11
FR 7 DCX	RF 80 H11
FR 7 DE	RF 74 HZDC
FR 7 DTC	RF 80 H3
FR 7 KC	RF 74 HZ
FR 7 KCW	RF 74 HZ
FR 7 KDC	RF 74 HZ11
FR 7 KDC	RF 74 HZ2
FR 7 LC2	RF 74 HZY11
FR 7 LCX	RF 74 HZY11
FR 7 LDC	RF 74 HZ2Y

<b>BOSCH (.../...)</b>	
FR 7 LDC4	RF 74 HZ2Y
FR 7 LTC	RF 74 HZ3YE
FR 8 DC	RF 82 H
FR 8 DCO	RF 82 H
FR 8 DCU	RF 82 H11
FR 8 DCX	RF 82 H11
FR 8 LCX	RF 82 HZDCS11
FR 8 LDC	RF 82 HZ2Y
FR 9 LCX	RF 90 HZ11
H 5 DC	C 60 H
H 5 DCO	C 60 H
H 6 D	H 6 D
H 6 DC	C 64 H
H 6 DCO	C 64 H
H 7 DC	C 72 H
H 7 DCO	C 72 H
H 7 DTC	RC 64 H3
HR 6 DC	RC 64 H
HR 7 DC	RC 72 H
HR 7 DCO	RC 72 H
HR 7 DCX	RC 72 H11
HR 7 MPP	RC 68LPP
W 4 A	4 N
W 4 AC	4 N
W 4 CP	67 HP
W 5 BC	R 64 H
W 5 CC	5 H
W 5 DC	6 H
W 5 DCO	6 H
W 5 DTC	64 H3E
W 6 D1	7 H
W 6 DC	7 H
W 6 DCO	7 H
W 6 DTC	70 H3E
W 7 BC	88 N
W 7 DC	76 H
W 7 DCO	76 H
W 7 DCR	R 76 H
W 7 DTC	76 H3E
W 7 LTRC	R 74 HZ3YE
W 8 DC	84 H
W 8 DCO	84 H
W 8 DTC	84 H3E
W 8 LCR	R 84 HZY
W 9 DC	90 H
W 9 DCO	90 H
W 9 ECO	T 9
WR 11 EO	T 10
WR 5 DC	R 64 H
WR 6 BC	R 76 N
WR 6 DC	R 70 H
WR 7 BC	R 88 N
WR 7 DC	R 76 H
WR 7 DCX	R 76 H11
WR 7 LTC	R 74 HZ3YE
WR 8 DC	R 84 H
WR 8 DC4	R 84 H
WR 8 DCX	R 84 H11
WR 9 DC	R 90 H
WR 9 DCX	R 90 H11
<b>CHAMPION</b>	
BN 7 Y	C 64 H
C 10 YCC	F 82 H
C 11 YCC	F 82 H
C 12 YCC	F 82 H
C 279 YC	F 72 H
C 281 YC	F 80 H
C 6 BMC	F 68 H3
C 6 YC	F 64 H
C 6 YCC	F 64 H
C 6 YCX	F 64 H
C 7 BMC	F 72 H3
C 7 BMC	RF 74 H3
C 7 YC	F 74 H
C 7 YCC	F 74 H
C 7 YCX	F 74 H
C 9 YC	F 80 H
C 9 YCC	F 80 H
C 9 YCX	F 80 H
J 17 LM	T 9
J 19 LM	T 10
L 87 YC	88 N
L 87 YCC	88 N
N 11 YC	90 H
N 11 YCC	90 H
N 279 YC	6 H
N 281 YC	84 H



<b>CHAMPION</b> (.../...)	
N 3 G	67 HP
N 4	5 H
N 4 C	5 H
N 6 BYC	64 H3E
N 6 YC	6 H
N 6 YCC	6 H
N 6 YCX	6 H
N 7 BYC	70 H3E
N 7 BYC4	70 H3E
N 7 Y	7 H
N 7 YC	7 H
N 7 YCC	7 H
N 7 YCX	7 H
N 9 BYC	76 H3E
N 9 BYC4	76 H3E
N 9 YC	76 H
N 9 YC4	R 76 H11
N 9 YCC	76 H
N 9 YCX	76 H
OE032	RF 74 HZ3YE
RC 10 DMC	RF 82 HZ2Y
RC 10 YC	R 84 H
RC 10 YC4	RF 80 H11
RC 10 YCC	RF 82 H
RC 11 LCC4	RF 82 HZDCS11
RC 12 MC4	RF 90 HZ11
RC 12 YC	RF 82 H
RC 12 YCC	RF 82 H
RC 6 YC	RF 64 H
RC 6 YCC	RF 64 H
RC 7 BMC	RF 72 H3
RC 7 BMC	RF 74 H3
RC 7 BYC	RF 72 H3E
RC 7 BYC4	RF 72 H3E
RC 7 YC	RF 74 H
RC 7 YC4	RF 74 H11
RC 7 YCC	RF 74 H
RC 7 YCC	RF 74 HZDC
RC 7 YCC4	RF 74 H11
RC 8 BYC	RF 74 H2
RC 8 YC	RF 74 HZ2Y
RC 8 YCC	RF 74 HZ2Y
RC 8 YCC4	RF 72 HZ3YE
RC 8 YC	RF 74 H
RC 8 YC4	RF 72 H11
RC 8 YCC	RF 72 HZDC
RC 87 YCL	RF 74 HZDC
RC 89 TMC	RF 80 H3
RC 9 BMC	RF 80 H3
RC 9 MCC	RF 80 HZY
RC 9 YC	RF 80 H
RC 9 YC4	RF 80 H11
RC 9 YCC	RF 80 H
RC 9 YCC4	RF 80 H11
RE 7 PYC5	RC 68LPP
RES 9 PYP4	RC 68LPP
RES 9 YCC4	RC 68LPP
RF 7 YC	GC 68 N
RF 7 YCC	GC 68 N
RF 9 YC	GC 68 N
RL 82 YC	R 76 N
RL 82 YCC	R 76 N
RL 87 YC	R 88 N
RN 11 YC	R 90 H
RN 11 YC4	R 90 H11
RN 11 YCC	R 90 H
RN 11 YCC4	R 90 H11
RN 12 YC	R 92 H
RN 6 YC	R 64 H
RN 6 YCC	R 64 H
RN 7 YC	R 70 H
RN 7 YC4	R 70 H11
RN 7 YCC	R 70 H
RN 7 YCC4	R 70 H11
RN 8 VTYC4	R 74 HZ3YE
RN 9 YC	R 76 H
RN 9 YC 4	R 76 H11
RN 9 YCC	R 76 H
RN 9 YCC4	R 76 H11
RS 7 YC	RC 64 H
RS 7 YCC	RC 64 H
RS 9 YC	RC 72 H
RS 9 YCC	RC 72 H
S 279 YC	C 64 H
S 281 YC	C 68 H
S 379 YC	C 60 H
S 6 YC	C 60 H

<b>CHAMPION</b> (.../...)	
S 6 YCC	C 60 H
S 7 YC	C 64 H
S 7 YCC	C 64 H
S 9 YC	C 72 H
S 9 YCC	C 72 H
<b>DENSO</b>	
J 14 CR-U	R 92 H
J 16 CR-U	R 84 HZY
K 16 PR-L 11	RF 80 H11
K 16 PR-L11	RF 80 H11
K 16 PR-U	RF 80 H
K 16 PR-U 11	RF 80 H11
K 16 P-U	F 80 H
K 16 R-U	RF 74 HZ
K 16 R-U11	RF 74 HZ11
K 20 PBR	RF 72 H3E
K 20 PR-L11	RF 72 H11
K 20 PR-U11	RF 74 H11
K 20 R-U	RF 74 HZ
K 20 R-U11	RF 74 HZ11
K 20 TR-11	RF 74 HZ11
K 22 PB	F 68 H3
K 22 PR-U11	RF 72 H11
KJ 16 CR11	RF 80 HZY
KJ 20 CRL-11	RF 74 HZY11
MA 14 P-U	GC 68 N
MA 16 PR-U	GC 68 N
MA 17 P-U	GC 68 N
MA 20 PR-U	GC 68 N
PT 16 VR13	RC 68LPP
Q 14 R-U11	RF 82 H11
Q 16 PR-U	RF 80 H
Q 16 PR-U11	RF 80 H11
Q 16 P-U11	RF 80 H11
Q 16 R-U	RF 82 H
Q 16 R-U11	RF 80 H11
Q 16 U	F 82 H
Q 20 PR-U	RF 74 H
Q 20 PR-U11	RF 74 H11
Q 20 P-U	F 74 H
Q 20 R-U	RF 74 H
Q 20 R-U11	RF 74 H11
Q 20 U	F 74 H
Q 22 PR-U	RF 64 H
Q 22 PR-U11	RF 64 H11
Q 22 P-U	F 64 H
QJ 16 AR-U	RF 82 HZDCS11
QJ 16 CR-11	RF 80 HZY
QJ 16 CR-U11	RF 80 HZY
QJ 20 CR-11	RF 74 HZY11
QJ 20 CR-U11	RF 74 HZY11
T 16 EPR-U	RC 72 H
T 20 EPR-U	RC 68 H
T 20 EP-U	C 68 H
T 20 EX-U	C 68 H
T 22 EP-U	C 60 H
W 14 EP	90 H
W 14 EPR-U	R 90 H
W 14 EPR-U11	R 90 H11
W 14 EX-U	90 H
W 14 EX-U11	R 90 H
W 14 LM-U	T 9
W 14 LM-US	T 9
W 16 EP	84 H
W 16 EPB-10	84 H3E
W 16 EPR	R 84 H
W 16 EPR-U	R 84 H
W 16 EPR-U10	R 84 H11
W 16 EPR-U11	R 84 H11
W 16 EP-U	84 H
W 16 EX	84 H
W 16 EXR-U	R 84 H
W 16 EXR-U11	R 84 H11
W 16 EX-U	84 H
W 16 EX-U11	R 84 H11
W 20 EP	76 H
W 20 EPB	76 H3E
W 20 EPBR-S	R 74 HZ3YE
W 20 EPR	R 76 H
W 20 EPR-U	R 76 H
W 20 EPR-U10	R 76 H11
W 20 EPR-U11	R 76 H11
W 20 EP-U	76 H
W 20 ES	5 H

<b>DENSO</b> (.../...)	
W 20 ES-U	5 H
W 20 EX	76 H
W 20 EXR-U	R 76 H
W 20 EXR-U11	R 76 H11
W 20 EX-U	76 H
W 20 EX-U11	R 76 H11
W 20 FP	88 N
W 20 FPR	R 88 N
W 20 FPR-U	R 88 N
W 20 FP-U	88 N
W 22 EP	6 H
W 22 EP11	R 64 H11
W 22 EPB	64 H3E
W 22 EPR-U	R 64 H
W 22 EPR-U11	R 64 H11
W 22 ES	5 H
W 22 ES-U	5 H
W 22 EXR-U	R 64 H
W 22 EXR-U11	R 64 H11
W 22 EX-U	6 H
W 22 FPR	R 76 N
W 22 FPR-U	R 76 N
W 22 FS	4 N
W 22 FS-U	4 N
W 24 ES-ZU	67 HP
W 9 LMR-US	T 10
W16 EPB-10	84 H3E
<b>EYQUEM</b>	
202 CT	T 10
502 CT	T 9
805 LJS	C 64 HP
805 LP	67 HP
883 LJP	C 55 HP
C 32 LS	90 H
C 42 S	88 N
C 52 LJS	C 72 H
C 52 LS	84 H
C 52 LS 3X	84 H3E
C 62 LJS	C 68 H
C 62 LJS	C 68 H
C 62 LS	76 H
C 62 LS 3X	76 H3E
C 72	4 N
C 72 L	5 H
C 72 LJS	C 64 H
C 72 LJS	C 64 H
C 72 LS	7 H
C 72 LS	7 H
C 72 LS 3X	70 H3E
C 82 LJS	C 60 H
C 82 LS	6 H
C 82 LS	6 H
C 82 LS 3X	64 H3E
FC 42 LS	F 82 H
FC 52 LS	F 80 H
FC 58 LS	F 74 H
FC 62 LS	F 72 H
FC 62 LS 3	F 72 H3
FC 62 LS 3X	F 72 H3E
FC 82 LS	F 64 H
FC 82 LS 3	F 68 H3
FN 52 LS	F 80 HDC
RC 30 LS	R 92 H
RC 32 LS	R 90 H
RC 32 LS 5	R 90 H11
RC 42 S	R 88 N
RC 52 LJS	RC 72 H
RC 52 LJS 5	RC 72 H11
RC 52 LS	R 84 H
RC 52 LS 5	R 84 H11
RC 52 LZE	R 84 HZY
RC 58 LZ 3EX	R 74 HZ3YE
RC 62 HJSDP	RC 68LPP
RC 62 LJS	RC 68 H
RC 62 LS	R 76 H
RC 62 LS 5	R 76 H11
RC 62 S	R 76 N
RC 72 LJS	RC 64 H
RC 72 LJS 3	RC 64 H3
RC 72 LS	R 70 H
RC 72 LS 5	R 70 H11
RC 82 LS	R 64 H
RC 82 LS 5	R 64 H11
RFC 32 LZ 5	RF 90 HZ11
RFC 42 LS	RF 82 H

<b>EYQUEM</b> (.../...)	
RFC 42 LS 5	RF 82 H11
RFC 42 LZ 2E	RF 82 HZ2Y
RFC 52 LS	RF 80 H
RFC 52 LS 3	RF 80 H3
RFC 52 LS 5	RF 80 H11
RFC 52 LZE	RF 80 HZY
RFC 58 LS	RF 74 H
RFC 58 LS 3	RF 74 H3
RFC 58 LS 5	RF 74 H11
RFC 58 LZ	RF 74 HZ
RFC 58 LZ 2	RF 74 HZ2
RFC 58 LZ 2E	RF 74 HZ2Y
RFC 58 LZ 3EX	RF 74 HZ3YE
RFC 58 LZ 5	RF 74 HZ11
RFC 58 LZE 5	RF 74 HZ11
RFC 62 LS	RF 72 H
RFC 62 LS 3	RF 72 H3
RFC 62 LS 3X	RF 72 H3E
RFC 62 LS 5	RF 72 H11
RFC 62 LZ 3EX	RF 72 HZ3YE
RFC 82 LS	RF 64 H
RFC 82 LS 5	RF 64 H11
RFN 42 LZG 5	RF 82 HZDCS11
RFN 58 LZ	RF 74 HZDC
RFN 62 LZ	RF 72 HZDC
RKC 62 JS	GC 68 N
RKC 62 JS	GC 68 N
RKC 62 JS	GC 68 N
RKC 62 JS	GC 68 N
<b>MAGNETI MARELLI</b>	
6 LC	F 82 H
7 LC	F 80 H
7 LCR	RF 80 H
8 LC	F 72 H
8 LCR	RF 72 H
9 LC	RF 64 H
CW 6 LP	84 H
CW 6 LPR	R 84 H
CW 6 N	88 N
CW 6 NP	76 H
CW 7 LP	R 76 H
CW 7 N	R 76 N
CW 7 NP	7 H
CW 7 NPR	7 H
CW 75 LP	R 70 H
CW 78 LP	6 H
CW 78 LPR	6 H
DW 4 CJ	T 9
F 6 NC	88 N
F 6 NCR	R 88 N
F 7 LC	76 H
F 7 NCR	R 76 N
F 8 LC	7 H
T 7 LC	C 72 H
T 7 LCR	RC 72 H
T 8 LC	C 64 H
T 8 LCR	RC 64 H
TW 7 LP	C 72 H
TW 78 LP	C 64 H
<b>MOTORCRAFT</b>	
A 7 LM	T 9
AE 1 C	4 N
AE 1 X	4 N
AE 2	4 N
AE 22	4 N
AE 22 C	4 N
AE 3 X	88 N
AER 22 C	R 76 N
AER 32	R 88 N
AER 32 C	R 88 N
AG 1 C	6 H
AG 1 X	6 H
AG 12	6 H
AG 2	5 H
AG 2 CU	76 H
AG 2 X	76 H3E
AG 22	76 H
AG 22 CT	76 H
AG 22 CU	5 H
AG 252	5 H
AG 252 C	5 H
AG 32 C	76 H
AG 32 CT1	84 H
AG 32 CU	84 H3E
AG 32A	76 H
AG 42 C	84 H
AG 42 CU	84 H





	Valeo
<b>MOTORCRAFT (.../...)</b>	
AG 52 C	<b>84 H</b>
AG 82	<b>90 H</b>
AGF 12	<b>C 64 H</b>
AGF 12 C	<b>C 64 H</b>
AGF 22	<b>C 72 H</b>
AGF 22 C	<b>C 72 H</b>
AGF 32 CU	<b>C 72 H</b>
AGP 12 C	<b>F 64 H</b>
AGP 22 C	<b>F 72 H</b>
AGP 22 CD	<b>F 72 H</b>
AGP 32 C	<b>F 80 H</b>
AGPR 12 C	<b>RF 64 H</b>
AGPR 12 CD	<b>RF 64 H</b>
AGPR 22 C	<b>RF 72 H</b>
AGPR 22 C1	<b>RF 74 H11</b>
AGPR 22 CD	<b>RF 74 H</b>
AGPR 22 CD1	<b>RF 74 H11</b>
AGPR 32 C	<b>RF 80 H</b>
AGPR 32 C1	<b>RF 80 H11</b>
AGPR 32 CD	<b>RF 80 H11</b>
AGR 1 X	<b>R 70 H</b>
AGR 12	<b>R 70 H</b>
AGR 2 C	<b>R 76 H</b>
AGR 22	<b>R 76 H</b>
AGR 22 C	<b>R 76 H</b>
AGR 22 CU	<b>R 76 H</b>
AGR 252	<b>R 76 H</b>
AGR 32	<b>R 84 H</b>
AGR 32 C	<b>R 84 H</b>
AGR 32 CU	<b>R 84 H</b>
AGR 34 CU	<b>R 84 H</b>
AGR 42	<b>R 90 H</b>
AGR 42 C	<b>R 90 H</b>
AGR 42 CU	<b>R 90 H</b>
AGR 44 CU	<b>R 90 H</b>
AGR 52	<b>R 84 H</b>
AGRF 22	<b>RC 72 H</b>
AGRF 22 C	<b>RC 72 H</b>
AGRF 22 C1	<b>RC 72 H11</b>
AGRF 22 CD	<b>RC 72 H</b>
AGRF 22 CD1	<b>RC 72 H11</b>
AGRF 32	<b>RC 72 H</b>
AGS 12 C	<b>R 64 H</b>
AGS 22 C	<b>R 76 H</b>
AGS 32 C	<b>R 84 H</b>
AGS 32 C1	<b>R 84 H11</b>
AGS 42 C	<b>R 90 H</b>
AGSF 12 C	<b>RC 64 H</b>
AGSF 22 C	<b>RC 72 H</b>
AGSF 32 C	<b>RC 72 H</b>
AGSF 32 C1	<b>RF 82 H</b>
AGSP 52	<b>88 N</b>
AV 2 CU	<b>4 N</b>
AV 22 CU	<b>4 N</b>
AWRF 32	<b>RC 68 H</b>
AWRF 42	<b>RC 72 H</b>
AWSF 22 C	<b>RC 68 H</b>
AWSF 32	<b>RC 68 H</b>
AWSF 32 C	<b>RC 68 H</b>
AWSF 42	<b>RC 72 H</b>
AWSF 42 C	<b>RC 72 H</b>
AYRF 22 PP	<b>RC 68LPP</b>
BRF 22 C	<b>GC 68 N</b>
BRF 22 C X	<b>GC 68 N</b>
BRF 32 C	<b>GC 68 N</b>
BRF 32 X C	<b>GC 68 N</b>
<b>NGK</b>	
APR 5 FS	<b>GC 68 N</b>
APR 6 FS	<b>GC 68 N</b>
B 2 LM	<b>T 10</b>
B 4 LM	<b>T 9</b>
B 7 ES	<b>5 H</b>
B 7 HS	<b>4 N</b>
B 8 EV	<b>67 HP</b>
BCP 4 ES	<b>F 82 H</b>
BCP 4 ES-11	<b>RF 82 H11</b>
BCP 5 E	<b>F 80 H</b>
BCP 5 E-11	<b>RF 80 H11</b>
BCP 5 ES	<b>F 80 H</b>
BCP 6 E	<b>F 74 H</b>
BCP 6 E-11	<b>RF 74 H11</b>
BCP 6 ES	<b>F 74 H</b>
BCP 6 ES-11	<b>RF 74 H11</b>
BCP 6 ET	<b>F 72 H3E</b>
BCP 6 EY	<b>RF 74 HZ</b>
BCP 7 E	<b>F 64 H</b>

	Valeo
<b>NGK (.../...)</b>	
BCP 7 ES	<b>F 64 H</b>
BCPR 4 ES	<b>RF 82 H</b>
BCPR 4 ES-11	<b>RF 82 H11</b>
BCPR 4 EY-11	<b>RF 82 H11</b>
BCPR 5 E	<b>RF 80 H</b>
BCPR 5 E-11	<b>RF 80 H11</b>
BCPR 5 ES	<b>RF 80 H</b>
BCPR 5 ES-11	<b>RF 80 H11</b>
BCPR 5 EY	<b>RF 80 H</b>
BCPR 5 EY-11	<b>RF 80 H11</b>
BCPR 6 E	<b>RF 74 H</b>
BCPR 6 E-11	<b>RF 74 H11</b>
BCPR 6 ES	<b>RF 74 H</b>
BCPR 6 ES-11	<b>RF 74 H11</b>
BCPR 6 ET	<b>RF 72 H3E</b>
BCPR 6 EY	<b>RF 74 HZ</b>
BCPR 6 EY-11	<b>RF 74 HZ11</b>
BCPR 7 E	<b>RF 64 H</b>
BCPR 7 E-11	<b>RF 64 H11</b>
BCPR 7 ES	<b>RF 64 H</b>
BCPR 7 ES-11	<b>RF 64 H11</b>
BCPR 7 EY	<b>RF 64 H</b>
BCPR 7 EY-11	<b>RF 64 H11</b>
BK 5 E	<b>F 80 H</b>
BK 5 E-11	<b>RF 80 H11</b>
BK 6 E	<b>F 74 H</b>
BK 6 E-11	<b>RF 74 H11</b>
BK 7 E-11	<b>RF 64 H11</b>
BKR 4 E	<b>RF 82 H</b>
BKR 4 E-11	<b>RF 82 H11</b>
BKR 4 ES	<b>RF 82 H</b>
BKR 4 ES-11	<b>RF 82 H11</b>
BKR 4 EY	<b>RF 82 H</b>
BKR 4 EY-11	<b>RF 82 H11</b>
BKR 5 E	<b>RF 80 H</b>
BKR 5 E-11	<b>RF 80 H11</b>
BKR 5 EK	<b>RF 82 HZ2Y</b>
BKR 5 EKU	<b>RF 80 H3</b>
BKR 5 ES	<b>RF 80 H</b>
BKR 5 ES-11	<b>RF 80 H11</b>
BKR 5 ESZ	<b>F 80 HDC</b>
BKR 5 EY	<b>RF 80 H</b>
BKR 5 EY-11	<b>RF 80 H11</b>
BKR 5 EYA	<b>RF 74 HZ</b>
BKR 5 EYA-11	<b>RF 74 HZ11</b>
BKR 5 N-11	<b>RF 80 H11</b>
BKR 6 E	<b>RF 74 H</b>
BKR 6 E-11	<b>RF 74 H11</b>
BKR 6 EK	<b>RF 74 HZ2Y</b>
BKR 6 EKC	<b>RF 74 HZ2</b>
BKR 6 EKUB	<b>RF 74 H3</b>
BKR 6 E-N-11	<b>RF 74 H11</b>
BKR 6 ES	<b>RF 74 H</b>
BKR 6 ES-11	<b>RF 74 H11</b>
BKR 6 EY	<b>RF 74 HZ</b>
BKR 6 EY-11	<b>RF 74 HZ11</b>
BKR 6 EYA	<b>RF 74 HZ</b>
BKR 6 EYA-11	<b>RF 74 HZ11</b>
BKR 6 EZ	<b>RF 74 HZDC</b>
BKR 6 N-11	<b>RF 74 H11</b>
BKR 7 E	<b>RF 64 H</b>
BKR 7 E-11	<b>RF 64 H11</b>
BKR 7 ES-11	<b>RF 64 H11</b>
BKR 7 EY	<b>RF 64 H</b>
BKUR 6 EK	<b>RF 74 HZ2</b>
BKUR 6 ET	<b>RF 74 HZ3YE</b>
BKUR 6 ET-10	<b>RF 74 HZ3YE</b>
BKUR 7 ET	<b>RF 72 HZ3YE</b>
BP 4 ES	<b>90 H</b>
BP 5 E	<b>84 H</b>
BP 5 EA	<b>84 H</b>
BP 5 EFS	<b>C 72 H</b>
BP 5 ES	<b>84 H</b>
BP 5 ESZ	<b>90 H</b>
BP 5 ET	<b>76 H3E</b>
BP 5 ET-10	<b>76 H3E</b>
BP 5 EY	<b>84 H</b>
BP 5 EZ	<b>84 H</b>
BP 6 E	<b>76 H</b>
BP 6 EF	<b>C 68 H</b>
BP 6 EFS	<b>C 68 H</b>
BP 6 ES	<b>76 H</b>
BP 6 ET	<b>70 H3E</b>
BP 6 EY	<b>76 H</b>
BP 6 EZ	<b>76 H</b>
BP 6 H	<b>88 N</b>
BP 6 HS	<b>88 N</b>

	Valeo
<b>NGK (.../...)</b>	
BP 6 HSA	<b>88 N</b>
BP 7 E	<b>6 H</b>
BP 7 EFS	<b>C 60 H</b>
BP 7 ES	<b>6 H</b>
BP 7 ET	<b>64 H3E</b>
BP 7 EY	<b>6 H</b>
BPC 5 E	<b>F 80 H</b>
BPR 4 E	<b>R 90 H</b>
BPR 4 E-11	<b>R 90 H11</b>
BPR 4 ES	<b>R 90 H</b>
BPR 4 ES-11	<b>R 90 H11</b>
BPR 4 EY	<b>R 92 H</b>
BPR 4 EY-11	<b>R 90 H11</b>
BPR 5 E	<b>R 84 H</b>
BPR 5 E-11	<b>R 84 H11</b>
BPR 5 EA	<b>R 84 H</b>
BPR 5 EA-11	<b>R 84 H11</b>
BPR 5 ES	<b>R 84 H</b>
BPR 5 ES-11	<b>R 84 H11</b>
BPR 5 EY	<b>R 84 H</b>
BPR 5 EY-11	<b>R 84 H11</b>
BPR 5 EZ	<b>R 84 H</b>
BPR 6 E	<b>R 76 H</b>
BPR 6 E-11	<b>R 76 H11</b>
BPR 6 EF	<b>R 76 H11</b>
BPR 6 EFS	<b>RC 68 H</b>
BPR 6 ES	<b>R 76 H</b>
BPR 6 ES-11	<b>R 76 H11</b>
BPR 6 EY	<b>R 76 H</b>
BPR 6 EY-11	<b>R 76 H11</b>
BPR 6 HS	<b>R 88 N</b>
BPR 7 E	<b>R 64 H</b>
BPR 7 ES	<b>R 64 H</b>
BPR 7 ES-11	<b>R 64 H11</b>
BPR 7 EY	<b>R 64 H</b>
BPR 7 EY-11	<b>R 64 H11</b>
BPR 7 HS	<b>R 76 N</b>
BUR 6 ET	<b>R 74 HZ3YE</b>
PTR 5 A-13	<b>RC 68LPP</b>
TR 5 A-13	<b>RC 68LPP</b>
ZFR 5 F	<b>RF 80 HZY</b>
ZFR 6 A-11	<b>RF 74 HZY11</b>
ZFR 6 F-11	<b>RF 74 HZY11</b>
ZFR 6 J-11	<b>RF 74 HZY11</b>
ZGR 5 A	<b>R 84 HZY</b>
<b>UNIPART</b>	
GSP2010	<b>76 H3E</b>
GSP2011	<b>RC 68LPP</b>
GSP2012	<b>RC 72 H11</b>
GSP2013	<b>R 84 HZY</b>
GSP2014	<b>RF 74 HZ</b>
GSP2015	<b>RF 74 HZY11</b>
GSP2017	<b>RF 82 HZ2Y</b>
GSP2018	<b>RF 82 HZ2Y</b>
GSP2020	<b>R 90 H</b>
GSP2021	<b>GC 68 N</b>
GSP2022	<b>RF 80 H</b>
GSP2023	<b>RF 64 H</b>
GSP2025	<b>RF 80 HZY</b>
GSP2026	<b>GC 68 N</b>
GSP2028	<b>RF 74 HZ2Y</b>
GSP2029	<b>R 88 N</b>
GSP2030	<b>R 74 HZ3YE</b>
GSP2031	<b>84 H3E</b>
GSP2033	<b>GC 68 N</b>
GSP2034	<b>R 84 H</b>
GSP2035	<b>F 82 H</b>
GSP2036	<b>R 64 H</b>
GSP2037	<b>RF 72 H11</b>
GSP2039	<b>R 84 H11</b>
GSP2042	<b>RF 74 HZ11</b>
GSP2045	<b>RF 80 H11</b>
GSP2048	<b>RF 72 HZ3YE</b>
GSP2053	<b>RF 74 HZDC</b>
GSP2054	<b>RC 72 H11</b>
GSP2060	<b>RF 72 H3E</b>
GSP2061	<b>R 76 H11</b>
GSP2064	<b>RF 72 H3E</b>
GSP2066	<b>RF 74 HZDC</b>
GSP2073	<b>RF 74 HZ3YE</b>
GSP2075	<b>88 N</b>
GSP2077	<b>C 60 H</b>
GSP2078	<b>RF 74 H3</b>
GSP2081	<b>R 70 H11</b>
GSP2082	<b>67 HP</b>
GSP2085	<b>RF 64 H11</b>
GSP2086	<b>C 64 HP</b>

	Valeo
<b>UNIPART (.../...)</b>	
GSP2087	<b>RF 74 HZ3YE</b>
GSP2088	<b>RF 72 H3E</b>
GSP2089	<b>RF 74 H3</b>
GSP2091	<b>R 90 H11</b>
GSP2096	<b>RF 74 HZ3YE</b>
GSP2097	<b>RF 74 HZ3YE</b>
GSP2098	<b>76 H</b>
GSP2099	<b>84 H</b>
GSP2100	<b>RF 74 H</b>
GSP2101	<b>C 64 H</b>
GSP2102	<b>C 68 H</b>
GSP2107	<b>RC 68LPP</b>
GSP2109	<b>C 68 H</b>
GSP2111	<b>R 76 H</b>
GSP2112	<b>RF 74 H</b>
GSP2113	<b>RF 74 HZY11</b>
GSP2114	<b>RF 74 H11</b>
GSP2115	<b>RC 68 H</b>
GSP2116	<b>RF 72 H</b>
GSP2117	<b>R 84 H</b>
GSP2118	<b>R 70 H</b>
GSP2119	<b>R 76 H11</b>
GSP2120	<b>RC 64 H</b>
GSP2121	<b>C 72 H</b>
GSP2125	<b>RF 74 HZ3YE</b>
GSP2136	<b>RF 80 H3</b>



# 2

Glow plugs

Bougies de préchauffage

Bujías de precalentamiento

2.1

**Valeo**



**145**

Velas de pré-aquecimento

2.2



**Valeo**

**147**

Candele di preriscaldamento

2.3



**Valeo**

**179**

Voorgloeibougies

2.4



**Valeo**

**183**

Glühkerzen

Świece żarowe

Isitma bujisi

Свечи накаливания

**Valeo**



2.1

Glow plugs

Bougies de préchauffage

Bujías de precalentamiento

Velas de pré-aquecimento

Candele di preriscaldamento

Voorgloeibougies

Glühkerzen

Świece żarowe

Isitma bujisi





Свечи накаливания

**Valeo**



**Valeo**



<b>Valeo</b>		<b>Valeo</b>		<b>Valeo</b>		<b>Valeo</b>	
<b>245005</b>	C255S	<b>345002</b>	C252S				
<b>344012</b>	C257S	<b>345011</b>	C256S				
<b>344875</b>	C100S	<b>345013</b>	C258S				
<b>344876</b>	C200S	<b>345014</b>	C259S				
<b>344877</b>	C101S	<b>345015</b>	C260S				
<b>344878</b>	C102S	<b>345016</b>	C261S				
<b>344879</b>	C103S	<b>345017</b>	C262S				
<b>344880</b>	C104S	<b>345018</b>	C263S				
<b>344881</b>	C201S	<b>345019</b>	C264S				
<b>344882</b>	C105S						
<b>344883</b>	C106S						
<b>344884</b>	C107S						
<b>344885</b>	C108S						
<b>344886</b>	C109S						
<b>344887</b>	C110S						
<b>344888</b>	C111R						
<b>344889</b>	C202R						
<b>344891</b>	C203R						
<b>344892</b>	C204R						
<b>344893</b>	C205R						
<b>344894</b>	C206R						
<b>344895</b>	C207R						
<b>344896</b>	C208R						
<b>344915</b>	C114R						
<b>344916</b>	C115R						
<b>344917</b>	C116S						
<b>344918</b>	C117S						
<b>344919</b>	C209S						
<b>344920</b>	C118S						
<b>344921</b>	C210S						
<b>344952</b>	C214S						
<b>344953</b>	C215S						
<b>344954</b>	C216S						
<b>344955</b>	C217S						
<b>344956</b>	C218S						
<b>344957</b>	C219S						
<b>344958</b>	C220S						
<b>344959</b>	C221S						
<b>344960</b>	C222S						
<b>344961</b>	C223S						
<b>344962</b>	C224S						
<b>344963</b>	C225S						
<b>344964</b>	C226S						
<b>344965</b>	C212S						
<b>344966</b>	C211S						
<b>344967</b>	C213S						
<b>344972</b>	C227S						
<b>344973</b>	C228S						
<b>344974</b>	C229S						
<b>344986</b>	C236S						
<b>344988</b>	C238S						
<b>344991</b>	C241S						
<b>344993</b>	C243S						
<b>344995</b>	C245S						
<b>344997</b>	C247S						



2.2

Glow plugs

Bougies de préchauffage

Bujías de precalentamiento

Velas de pré-aquecimento

Candele di preriscaldamento


Gloeibougies

Glühkerzen


Świece żarowe

Isitma bujisi

Свечи накаливания







Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento


Gloeibougies  
Gluhkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания

**Valeo**

	CC	KW					
<b>ALFA ROMEO</b>							
<b>145</b>							
1.9 JTD	1,9	<b>77</b>	AR 32302	02.1999 ▶ 10.1999	4	C227S	<b>344972</b>
1.9 JTD	1,9	<b>77</b>	AR 32302	11.1999 ▶ 01.2001	4	C247S	<b>344997</b>
1.9 TD	1,9	<b>66</b>	AR 33601, AR 67501	10.1994 ▶ 02.1999	4	C206R	<b>344894</b>
<b>146</b>							
1.9 JTD	1,9	<b>77</b>	AR 32302	02.1999 ▶ 10.1999	4	C227S	<b>344972</b>
1.9 JTD	1,9	<b>77</b>	AR 32302	11.1999 ▶ 01.2001	4	C247S	<b>344997</b>
1.9 TD	1,9	<b>66</b>	AR 33601, AR 67501	12.1994 ▶ 02.1999	4	C206R	<b>344894</b>
<b>147</b>							
1.9 JTD	1,9	<b>74</b>		06.2003 ▶	4	C247S	<b>344997</b>
1.9 JTD	1,9	<b>85</b>	937 A2.000	04.2001 ▶	4	C247S	<b>344997</b>
<b>155</b>							
1.9 TD	1,9	<b>66</b>	AR 67501	04.1993 ▶ 12.1997	4	C206R	<b>344894</b>
2.5 TD	2,5	<b>92</b>	VM 07 B, VM 31 B	04.1993 ▶ 04.1995	4	C206R	<b>344894</b>
2.5 TD	2,5	<b>92</b>	VM 07 B, VM 31 B	05.1995 ▶ 12.1997	4	C214S	<b>344952</b>
<b>156</b>							
1.9 JTD	1,9	<b>77</b>	AR 32302	09.1997 ▶ 10.2000	4	C227S	<b>344972</b>
1.9 JTD	1,9	<b>81</b>	AR 37101	10.2000 ▶ 05.2001	4	C247S	<b>344997</b>
1.9 JTD	1,9	<b>85</b>	937 A2.000	05.2001 ▶	4	C247S	<b>344997</b>
2.4 JTD	2,4	<b>100</b>	AR 32501	09.1997 ▶ 10.2000	5	C227S	<b>344972</b>
2.4 JTD	2,4	<b>103</b>	839 A6.000	10.2000 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>110</b>	841 C000	03.2002 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>129</b>		10.2003 ▶	5	C247S	<b>344997</b>
<b>156 SPORTWAGON</b>							
1.9 JTD	1,9	<b>77</b>	AR 32302	05.2000 ▶ 10.2000	4	C227S	<b>344972</b>
1.9 JTD	1,9	<b>81</b>	AR 37101	10.2000 ▶ 05.2001	4	C247S	<b>344997</b>
1.9 JTD	1,9	<b>85</b>	937 A2.000	05.2001 ▶	4	C247S	<b>344997</b>
2.4 JTD	2,4	<b>100</b>	AR 32501	05.2000 ▶ 10.2000	5	C227S	<b>344972</b>
2.4 JTD	2,4	<b>103</b>	839 A6.000	10.2000 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>110</b>	841 C000	03.2002 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>129</b>		10.2003 ▶	5	C247S	<b>344997</b>
<b>164</b>							
2.5 TD	2,5	<b>84</b>	VM 84 A	06.1987 ▶ 09.1992	4	C103S	<b>344879</b>
2.5 TD	2,5	<b>92</b>	VM 08 B, VM 32 B	05.1995 ▶ 09.1998	4	C214S	<b>344952</b>
2.5 TD	2,5	<b>92</b>	VM 08 B, VM 32 B	09.1992 ▶ 04.1995	4	C206R	<b>344894</b>
<b>166</b>							
2.4 JTD	2,4	<b>100</b>	AR 34202	09.1998 ▶ 10.2000	5	C227S	<b>344972</b>
2.4 JTD	2,4	<b>103</b>	AR 36202	10.2000 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>110</b>	841 C000	04.2002 ▶	5	C247S	<b>344997</b>
<b>33</b>							
1.8 TD	1,8	<b>54</b>	VM 82 A	02.1990 ▶ 06.1990	3	C103S	<b>344879</b>
1.8 TD	1,8	<b>62</b>	VM 96 A	07.1990 ▶ 03.1994	3	C103S	<b>344879</b>
<b>33 SPORTWAGON</b>							
1.8 TD	1,8	<b>62</b>		01.1986 ▶ 12.1989	4	C103S	<b>344879</b>
<b>6</b>							
2.5 TD	2,5	<b>77</b>	VM-HR 588 HT	06.1983 ▶ 05.1986	5	C103S	<b>344879</b>
<b>75</b>							
2.0 TD	2,0	<b>70</b>	VM 80 A	05.1985 ▶ 09.1992	4	C103S	<b>344879</b>
2.4 TD	2,4	<b>82</b>	VM 81 A	01.1989 ▶ 02.1992	4	C103S	<b>344879</b>
<b>90</b>							
2.4 TD	2,4	<b>81</b>	VM 81 A	10.1984 ▶ 01.1987	4	C103S	<b>344879</b>
<b>ALFA ROMEO</b>							
<b>AR 6</b>							
1.9 D	1,9	<b>51</b>	160D100	04.1985 ▶ 12.1989	4	C206R	<b>344894</b>
2.4 D	2,4	<b>53</b>	8144.61.200	04.1985 ▶ 02.1986	4	C111R	<b>344888</b>
<b>AR 8</b>							
2.4 D	2,4	<b>53</b>	8140.61.200	04.1978 ▶ 08.1986	4	C111R	<b>344888</b>
2.5 D	2,5	<b>55</b>	8144.67.220	09.1986 ▶ 12.1989	4	C102S	<b>344878</b>
<b>ALPINA</b>							
<b>D10 (E39)</b>							
3.0 D Biturbo	3,0	<b>180</b>		09.1999 ▶	6	C241S	<b>344991</b>



			CC	KW					Valeo
<b>ARO</b>									
<b>240-244</b>									
2.5 D			2,5	52	Peugeot XD3P	01.1983 ▶	4	C100S	344875
2.5 TD			2,5	70	Peugeot XD3TP	01.1992 ▶	4	C100S	344875
2.7 D			2,7	50		09.1989 ▶	4	C100S	344875
2.7 D			2,7	52		04.1985 ▶	4	C100S	344875
<b>AUDI</b>									
<b>100, AVANT</b>									
2.0 D			2,0	51	CN	08.1982 ▶ 07.1988	5	C200S	344876
2.0 TD			2,0	64	DE	08.1982 ▶ 02.1988	5	C200S	344876
2.0 TD			2,0	74	NC	03.1988 ▶ 11.1990	5	C200S	344876
2.4 D			2,4	60	3D	08.1989 ▶ 12.1990	5	C200S	344876
2.4 D			2,4	60	AAS	12.1990 ▶ 06.1994	5	C200S	344876
2.5 TDI			2,5	85	AAT, ABP	12.1990 ▶ 06.1994	5	C205R	344893
2.5 TDI			2,5	88	1T	01.1990 ▶ 11.1990	5	C205R	344893
<b>80 CABRIOLET</b>									
1.9 TDI			1,9	66	1Z, AHU	06.1995 ▶ 08.2000	4	C205R	344893
<b>80, AVANT</b>									
1.6 D			1,6	40	CR, JK	08.1980 ▶ 08.1986	4	C200S	344876
1.6 D			1,6	40	JK	09.1986 ▶ 08.1991	4	C200S	344876
1.6 TD			1,6	51	CY	08.1981 ▶ 05.1986	4	C200S	344876
1.6 TD			1,6	59	RA, SB	09.1986 ▶ 08.1991	4	C200S	344876
1.9 D			1,9	50	1Y	08.1989 ▶ 08.1991	4	C200S	344876
1.9 TD			1,9	55	AAZ	09.1991 ▶ 12.1994	4	C200S	344876
1.9 TDI			1,9	66	1Z	09.1991 ▶ 12.1994	4	C205R	344893
<b>90</b>									
1.6 TD			1,6	51	CY	10.1985 ▶ 01.1987	4	C200S	344876
1.6 TD			1,6	59	RA, SB	04.1987 ▶ 09.1991	4	C200S	344876
<b>A2</b>									
1.4 TDI			1,4	55	AMF	09.2003 ▶ 09.2004	3	C263S	●345018
1.4 TDI			1,4	66	ATL	11.2003 ▶ 09.2004	3	C263S	●345018
<b>A3</b>									
1.9 TDI			1,9	66	AGR, ALH	09.1996 ▶ 07.2001	4	C205R	344893
1.9 TDI			1,9	74	ATD, AXR	10.2000 ▶	4	C205R	344893
<b>A3</b>									
1.9 TDI			1,9	77	BKC	05.2003 ▶ 09.2004	4	C263S	●345018
<b>A3</b>									
1.9 TDI			1,9	81	AHF, ASV	08.1997 ▶ 07.2001	4	C205R	344893
1.9 TDI. quattro			1,9	96	ASZ	08.2000 ▶ 05.2003	4	C205R	344893
<b>A3 SPORTBACK</b>									
1.9 TDI			1,9	77	BKC	09.2004 ▶ 09.2004	4	C263S	●345018
<b>A4, AVANT</b>									
1.9 TDI			1,9	55	AFF	12.1995 ▶ 11.2000	4	C205R	344893
1.9 TDI			1,9	66	1Z, AHH, AHU	01.1995 ▶ 11.2000	4	C205R	344893
1.9 TDI			1,9	74	AVB	05.2001 ▶	4	C205R	344893
1.9 TDI			1,9	85	AJM	03.2000 ▶ 11.2000	4	C205R	344893
1.9 TDI			1,9	85	BKE	11.2004 ▶	4	C263S	●345018
1.9 TDI			1,9	96	AVF, AWX	11.2000 ▶	4	C205R	344893
1.9 TDI quattro			1,9	85	AJM, ATJ	03.2000 ▶ 11.2000	4	C205R	344893
1.9 TDI quattro			1,9	96	AVF	11.2001 ▶	4	C205R	344893
1.9 TDI. quattro			1,9	81	AFN, AVG	09.1996 ▶ 11.2000	4	C205R	344893
<b>A6, AVANT</b>									
1.9 TDI			1,9	66	1Z, AHU	06.1994 ▶ 02.1997	4	C205R	344893
1.9 TDI			1,9	81	AFN	02.1997 ▶	4	C205R	344893
1.9 TDI			1,9	85	AJM	07.2000 ▶	4	C205R	344893
1.9 TDI			1,9	96	AVF, AWX	08.2001 ▶	4	C205R	344893
2.5 TDI			2,5	84	AAT	01.1995 ▶ 02.1997	5	C205R	344893
2.5 TDI			2,5	85	AAT	06.1994 ▶ 02.1997	5	C205R	344893
2.5 TDI. quattro			2,5	103	AEL	10.1995 ▶ 02.1997	5	C205R	344893
<b>BMW</b>									
<b>1 (E87)</b>									
118 d			2,0	90	M47N204D4	09.2004 ▶	4	C259S	●345014
120 d			2,0	120	M47N204D4	09.2004 ▶	4	C259S	●345014
<b>3 (E30)</b>									
324 d			2,4	63	M21 D 24	09.1985 ▶ 08.1991	6	C100S	344875




Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preriscaldamento

Gloeibougies  
Gloßkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания



			CC	KW					Valeo
<b>BMW (../...)</b>									
<b>3 (E30) (../...)</b>									
324 td			2,4	85	M 21 D 24, M 21 D 24 (Kat.)	09.1987 ▶ 08.1991	6	C106S	344883
<b>3 (E36)</b>									
318 tds			1,8	66	M 41 D 18 (Inter.)	01.1995 ▶ 02.1998	4	C106S	344883
325 td			2,5	85	M 51 D 25	09.1991 ▶ 02.1998	6	C106S	344883
325 tds			2,5	105	M 51 D 25 (Inter.)	05.1993 ▶ 02.1998	6	C106S	344883
<b>3 (E46)</b>									
318 d			2,0	85		09.2001 ▶	4	C259S	●345014
320 d			2,0	100	M 47 D 20	04.1998 ▶ 09.2001	4	C241S	344991
320 d			2,0	110	M47N204D4	09.2001 ▶	4	C259S	●345014
330 d			3,0	135	M 57 D 30	10.1999 ▶	6	C241S	344991
330 d			3,0	150	M57N306D2	03.2003 ▶	6	C259S	●345014
330 xd			3,0	135	M 57 D 30	06.2000 ▶	6	C241S	344991
330 xd			3,0	150	M57N306D2	03.2003 ▶	6	C259S	●345014
<b>3 (E90)</b>									
320 d			2,0	120	M47N204D4	01.2005 ▶	4	C259S	●345014
<b>3 COMPACT (E36)</b>									
318 tds			1,8	66	M 41 D 18 (Inter.)	01.1995 ▶ 08.2000	4	C106S	344883
<b>3 COMPACT (E46)</b>									
318 td			2,0	85		03.2003 ▶	4	C259S	●345014
320 td			2,0	110	M47N204D4	09.2001 ▶	4	C241S	344991
<b>3 COUPE (E46)</b>									
320 Cd			2,0	110	M47N204D4	11.2003 ▶	4	C259S	●345014
330 Cd			3,0	150	M57N306D2	03.2003 ▶	6	C259S	●345014
<b>3 TOURING (E30)</b>									
324 td			2,4	85	M 21 D 24, M 21 D 24 (Kat.)	01.1988 ▶ 06.1993	6	C106S	344883
<b>3 TOURING (E36)</b>									
318 tds			1,8	66	M 41 D 18 (Inter.)	01.1995 ▶ 10.1999	4	C106S	344883
325 tds			2,5	105	M 51 D 25 (Inter.)	09.1995 ▶ 10.1999	6	C106S	344883
<b>3 TOURING (E46)</b>									
318 d			2,0	85		03.2002 ▶	4	C259S	●345014
320 d			2,0	100	M 47 D 20	03.2000 ▶ 09.2001	4	C241S	344991
320 d			2,0	110	M47N204D4	09.2001 ▶	4	C259S	●345014
330 d			3,0	135	M 57 D 30	10.1999 ▶	6	C241S	344991
330 d			3,0	150	M57N306D2	03.2003 ▶	6	C259S	●345014
330 xd			3,0	135	M 57 D 30	06.2000 ▶	6	C241S	344991
330 xd			3,0	150	M57N306D2	03.2003 ▶	6	C259S	●345014
<b>5 (E28)</b>									
524 d			2,4	63	M 21 D 24	09.1986 ▶ 12.1987	6	C100S	344875
524 td			2,4	85	M 21 D 24	09.1983 ▶ 12.1987	6	C100S	344875
<b>5 (E34)</b>									
524 td			2,4	85	M 21 D 24, M 21 D 24 (Kat.)	03.1988 ▶ 08.1991	6	C106S	344883
525 td			2,5	85	M 51 D 25	04.1993 ▶ 09.1995	6	C106S	344883
525 tds			2,5	105	M 51 D 25 (Inter.)	09.1991 ▶ 09.1995	6	C106S	344883
<b>5 (E39)</b>									
520 d			2,0	100	M 47 D 20	02.2000 ▶ 06.2002	4	C241S	344991
520 d			2,0	110		06.2002 ▶	4	C241S	344991
525 d			2,5	120		02.2000 ▶	6	C241S	344991
525 td			2,5	85	M 51 D 25	01.1997 ▶	6	C106S	344883
525 tds			2,5	105	M 51 D 25 (Inter.)	01.1996 ▶	6	C106S	344883
530 d			3,0	135	M 57 D 30	08.1998 ▶ 09.2000	6	C241S	344991
530 d			3,0	142	M 57 D 30	09.2000 ▶	6	C241S	344991
<b>5 (E60)</b>									
525d			2,5	130	M57N256D4	06.2004 ▶	6	C259S	●345014
530d			3,0	160	-	07.2003 ▶	6	C259S	●345014
535d			3,0	200	-	09.2004 ▶	6	C259S	●345014
<b>5 TOURING (E34)</b>									
525 td			2,5	85	M 51 D 25	03.1993 ▶ 01.1997	6	C106S	344883
525 tds			2,5	105	M 51 D 25 (Inter.)	12.1991 ▶ 01.1997	6	C106S	344883
<b>5 TOURING (E39)</b>									
520 d			2,0	100	M 47 D 20	02.2000 ▶ 06.2002	4	C241S	344991
520 d			2,0	110		06.2002 ▶	4	C241S	344991
525 d			2,5	120		02.2000 ▶	6	C241S	344991
525 tds			2,5	105	M 51 D 25 (Inter.)	03.1997 ▶	6	C106S	344883
530 d			3,0	135	M 57 D 30	08.1998 ▶ 09.2000	6	C241S	344991
530 d			3,0	142	M 57 D 30	09.2000 ▶	6	C241S	344991

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW					
<b>BMW</b> (.../...)									
<b>5 TOURING (E61)</b>									
525d			2,5	130	M57N256D4	06.2004 ▶	6	C259S	●345014
530d			3,0	160	-	06.2004 ▶	6	C259S	●345014
535d			3,0	200	-	09.2004 ▶	6	C259S	●345014
<b>7 (E38)</b>									
725 tds			2,5	105	M 51 D 25 (Inter.)	04.1996 ▶ 11.2001	6	C106S	344883
730 d			3,0	135	M 57 D 30	08.1998 ▶ 04.2000	6	C241S	344991
730 d			3,0	142		04.2000 ▶ 11.2001	6	C241S	344991
<b>7 (E65, E66)</b>									
730 d			3,0	160		10.2002 ▶	6	C259S	●345014
<b>X3</b>									
2.0 d			2,0	110	M47N204D4	10.2004 ▶	4	C259S	●345014
3.0 d			3,0	150		01.2004 ▶	6	C259S	●345014
<b>X5</b>									
3.0 d			3,0	135		05.2001 ▶	6	C241S	344991
3.0 d			3,0	160		12.2003 ▶	6	C259S	●345014
<b>CHRYSLER</b>									
<b>PT CRUISER</b>									
2.2 CRD			2,2	89		03.2002 ▶	4	C236S	344986
<b>VOYAGER I</b>									
2.5 TD			2,5	87	09B, M00	01.1992 ▶ 09.1995	4	C208R	344896
<b>VOYAGER II</b>									
2.5 TD			2,5	85	425 CLIRS, X	01.1995 ▶ 03.2001	4	C214S	344952
<b>VOYAGER III</b>									
2.5 CRD			2,5	105		02.2000 ▶	4	C214S	344952
<b>CITROEN</b>									
<b>AX</b>									
1.4 D			1,4	37	K9Y (TUD3Y)	08.1991 ▶ 12.1997	4	C108S	344885
1.4 D			1,4	38	K9A (TUD3)	09.1988 ▶ 06.1992	4	C108S	344885
1.5 D			1,5	40	VJY (TUD5)	08.1994 ▶ 12.1997	4	C207R	344895
1.5 D			1,5	43	VJZ (TUD5)	08.1994 ▶ 12.1997	4	C207R	344895
<b>BERLINGO</b>									
1.8 D			1,8	43	A9A (XUD7)	07.1998 ▶	4	C215S	344953
1.9 D			1,9	50	D9B (XUD9A, L), DJY (XUD9A)	07.1996 ▶ 08.1998	4	C208R	344896
1.9 D			1,9	50	D9B (XUD9A, L), DJY (XUD9A)	09.1998 ▶	4	C215S	344953
1.9 D			1,9	51	WJY (DW8B), WJZ (DW8)	07.1998 ▶	4	C216S	344954
2.0 HDI 90			2,0	66	RHY (DW10TD)	12.1999 ▶	4	C218S	344956
<b>BX, BREAK</b>									
1.8 D			1,8	44	161 (XUD7)	10.1985 ▶ 01.1993	4	C100S	344875
1.8 TRD			1,8	66	A8A (XUD7TE), AJZ (XUD7TE)	03.1988 ▶ 02.1993	4	C100S	344875
1.9 D			1,9	47	162 (XUD9), D9A (XUD9)	09.1983 ▶ 12.1987	4	C100S	344875
1.9 D			1,9	51	D9B (XUD9A, U)	03.1987 ▶ 02.1993	4	C100S	344875
<b>C1</b>									
1.4 HDi			1,4	40	8HX (DV4TD)	06.2005 ▶	4	C258S	●345013
<b>C2</b>									
1.4 HDi			1,4	50	8HX (DV4TD)	09.2003 ▶	4	C258S	●345013
<b>C3</b>									
1.4 16V HDi			1,4	66	8HY (DV4TED4)	02.2002 ▶	4	C258S	●345013
1.4 HDi			1,4	50	8HX (DV4TD)	02.2002 ▶	4	C258S	●345013
<b>C3 PLURIEL</b>									
1.4 HDi			1,4	50	8HX (DV4TD)	04.2004 ▶	4	C258S	●345013
<b>C4, COUPE</b>									
1.6 HDI 110 FAP			1,6	80	-	11.2004 ▶	4	C258S	●345013
1.6 HDI 90			1,6	66	-	11.2004 ▶	4	C218S	344956
2.0 HDI 135 FFAP			2,0	100	-	11.2004 ▶	4	C218S	344956
<b>C5, BREAK</b>									
1.6 HDI 110 FAP			1,6	80	-	11.2004 ▶	4	C258S	●345013
2.0 HDi			2,0	79	RHS (DW10ATED4, FAP)	06.2001 ▶	4	C218S	344956
2.0 HDi			2,0	80	RHZ (DW10ATED)	03.2001 ▶	4	C218S	344956
2.0 HDi 90			2,0	66	RHY (DW10TD)	03.2001 ▶	4	C218S	344956
2.2 HDi			2,2	98	4HX (DW12TED4, FAP)	03.2001 ▶	4	C218S	344956
<b>C8</b>									
2.0 HDi			2,0	79	RHS (DW10ATED4, FAP)	07.2002 ▶	4	C218S	344956
2.2 HDi			2,2	94	4HX (DW12TED4, FAP)	07.2002 ▶	4	C218S	344956



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания




	CC	KW					Valeo
<b>CITROEN  (.../...)</b>							
<b>CX II, BREAK</b>							
2.5 D	2,5	54	M25-660	08.1985 ▶ 12.1992	4	C111R	<b>344888</b>
2.5 D Turbo	2,5	70	M25-648	08.1985 ▶ 12.1986	4	C111R	<b>344888</b>
2.5 D Turbo	2,5	88	M25-669	01.1987 ▶ 12.1992	4	C111R	<b>344888</b>
2.5 D Turbo 2	2,5	88	M25-669	01.1987 ▶ 12.1992	4	C111R	<b>344888</b>
<b>EVASION</b>							
1.9 TD	1,9	66	D8B (XUD9TF), DHX (XUD9TF, BTF)	09.1998 ▶ 07.2002	4	C215S	<b>344953</b>
1.9 TD	1,9	66	D8B (XUD9TF), DHX (XUD9TF, BTF)	11.1994 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	68		10.1995 ▶ 12.1998	4	C208R	<b>344896</b>
2.0 HDI	2,0	80	RHZ (DW10ATED)	08.1999 ▶ 07.2002	4	C218S	<b>344956</b>
2.0 TD	2,0	68		05.1997 ▶ 07.2002	4	C208R	<b>344896</b>
2.1 TD	2,1	80	P8C (XUD11BTE)	05.1996 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 TD	2,1	80	P8C (XUD11BTE)	09.1998 ▶ 07.2002	4	C215S	<b>344953</b>
<b>SAXO</b>							
1.5 D	1,5	40	VJY (TUD5)	09.1996 ▶	4	C207R	<b>344895</b>
1.5 D	1,5	42	VJZ (TUD5)	09.1996 ▶	4	C207R	<b>344895</b>
<b>VISA</b>							
1.7 D	1,8	44	161A (XUD7)	04.1984 ▶ 03.1991	4	C100S	<b>344875</b>
<b>XANTIA, BREAK</b>							
1.9 D	1,9	50	DJZ (XUD9Y)	06.1994 ▶ 01.1998	4	C100S	<b>344875</b>
1.9 D	1,9	51	D9B (XUD9A, L)	06.1994 ▶ 05.1995	4	C100S	<b>344875</b>
1.9 SD	1,9	55	DHW (XUD9SD)	01.1998 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 SD	1,9	55	DHW (XUD9SD)	02.1996 ▶ 01.1998	4	C208R	<b>344896</b>
1.9 SD	1,9	55	DHW (XUD9SD)	09.1998 ▶	4	C215S	<b>344953</b>
1.9 TD	1,9	66	DHX (XUD9TF, BTF), DHY (XUD9TE, Y)	01.1998 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	66	DHX (XUD9TF, BTF), DHY (XUD9TE, Y)	09.1998 ▶	4	C215S	<b>344953</b>
1.9 TD	1,9	66	DHX (XUD9TF, BTF), DHY (XUD9TE, Y)	10.1994 ▶ 01.1998	4	C208R	<b>344896</b>
2.0 HDI 109	2,0	80	RHZ (DW10ATED)	02.1999 ▶	4	C218S	<b>344956</b>
2.0 HDI 90	2,0	66		03.1999 ▶	4	C218S	<b>344956</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	01.1998 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	06.1995 ▶ 01.1998	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	09.1998 ▶ 02.1999	4	C215S	<b>344953</b>
<b>XM, BREAK</b>							
2.1 D 12V	2,1	60	P9A (XUD11A)	05.1989 ▶ 06.1994	4	C100S	<b>344875</b>
2.1 TD 12V	2,1	80	P8A (XUD11ATE), P8C (XUD11BTE) PHZ (XUD11ATE), PJZ (XUD11ATE)	05.1994 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8A (XUD11ATE), P8C (XUD11BTE) PHZ (XUD11ATE), PJZ (XUD11ATE)	09.1998 ▶ 10.2000	4	C215S	<b>344953</b>
2.1 TD 12V	2,1	80	P8A (XUD11ATE), PHZ (XUD11ATE) PJZ (XUD11ATE)	05.1989 ▶ 06.1994	4	C208R	<b>344896</b>
2.5 TD	2,5	95	THY (DK5ATE)	05.1994 ▶ 10.2000	4	C208R	<b>344896</b>
<b>XSARA COUPE</b>							
1.4 HDi	1,4	50	8HX (DV4TD)	01.2003 ▶	4	C258S	<b>●345013</b>
1.9 D	1,9	50	DJY (XUD9A)	02.1998 ▶ 09.2000	4	C215S	<b>344953</b>
1.9 D	1,9	51	WJY (DW8B), WJZ (DW8)	02.1999 ▶	4	C216S	<b>344954</b>
1.9 TD	1,9	66	DHY (XUD9TE, Y)	02.1998 ▶ 09.2000	4	C215S	<b>344953</b>
2.0 HDi 109	2,0	80		05.2001 ▶	4	C218S	<b>344956</b>
2.0 HDi 90	2,0	66	RHY (DW10TD)	02.1999 ▶	4	C218S	<b>344956</b>
<b>XSARA PICASSO</b>							
1.6 HDi	1,6	80		05.2004 ▶	4	C258S	<b>●345013</b>
2.0 HDi	2,0	66	RHY (DW10TD)	06.2000 ▶	4	C218S	<b>344956</b>
<b>XSARA, BREAK</b>							
1.4 HDi	1,4	50	8HX (DV4TD)	01.2003 ▶	4	C258S	<b>●345013</b>
1.5 D	1,5	42	VJZ (TUD5)	04.1997 ▶ 09.2000	4	C215S	<b>344953</b>
1.8 D	1,8	43	161A (XUD7), A9A (XUD7)	04.1997 ▶ 09.2000	4	C215S	<b>344953</b>
1.8 TD	1,8	66		10.1997 ▶ 09.2000	4	C215S	<b>344953</b>
1.9 D	1,9	50	DJY (XUD9A)	04.1997 ▶ 09.2000	4	C215S	<b>344953</b>
1.9 D	1,9	51	WJY (DW8B), WJZ (DW8)	07.1998 ▶	4	C216S	<b>344954</b>
1.9 SD	1,9	55	DHV (XUD9BSD)	01.1998 ▶ 09.2000	4	C215S	<b>344953</b>
1.9 TD	1,9	66	DHY (XUD9TE, Y)	04.1997 ▶ 09.2000	4	C215S	<b>344953</b>
2.0 HDi 109	2,0	80	RHZ (DW10ATED)	05.2001 ▶	4	C218S	<b>344956</b>
2.0 HDi 90	2,0	66	RHY (DW10TD)	02.1999 ▶	4	C218S	<b>344956</b>
<b>ZX, BREAK</b>							
1.8 D	1,8	44	161A (XUD7)	06.1993 ▶ 06.1997	4	C100S	<b>344875</b>
1.9 D	1,9	47	DJZ (XUD9Y)	03.1991 ▶ 04.1994	4	C100S	<b>344875</b>
1.9 D	1,9	50	D9B (XUD9A, U)	06.1994 ▶ 05.1995	4	C100S	<b>344875</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый





			CC	KW					Valeo
<b>CITROEN</b> (.../...)									
<b>ZX, BREAK (.../...)</b>									
1.9 TD			1,9	66	DHY (XUD9TE, Y)	07.1992 ▶ 06.1997	4	C208R	344896
<b>CITROEN</b>									
<b>C15</b>									
1.8 D			1,8	44	161A (XUD7)	07.1986 ▶ 12.2000	4	C100S	344875
1.9 D			1,9	44		12.2000 ▶	4	C215S	344953
<b>C25</b>									
1.9 D			1,9	51	D9B (XUD9A, U)	07.1987 ▶ 02.1994	4	C100S	344875
1.9 TD			1,9	60	M705	04.1992 ▶ 02.1994	4	C208R	344896
2.5 D			2,5	54	CRD93L (U25-661)	10.1985 ▶ 02.1994	4	C111R	344888
2.5 TD			2,5	70	CRD93LS (U25-673)	08.1987 ▶ 02.1994	4	C111R	344888
<b>C35</b>									
2.5 D			2,5	51	B25637	02.1980 ▶ 01.1994	4	C111R	344888
<b>JUMPER</b>									
1.9 D			1,9	50	XUD9AU	01.1999 ▶ 04.2002	4	C215S	344953
1.9 D			1,9	51	D9B (XUD9A, U)	01.1999 ▶ 04.2002	4	C215S	344953
1.9 TD			1,9	66	D8C (XUD9UTF)	08.1994 ▶ 08.1998	4	C208R	344896
1.9 TD			1,9	66	D8C (XUD9UTF)	09.1998 ▶ 04.2002	4	C215S	344953
1.9 TD			1,9	68	D8C (XUD9UTF)	02.1994 ▶ 08.1998	4	C208R	344896
1.9 TD			1,9	68	D8C (XUD9UTF)	09.1998 ▶ 04.2002	4	C215S	344953
2.0 HDi			2,0	62	DW10UTD	04.2002 ▶	4	C218S	344956
2.2 HDi			2,2	74	DW12TED	04.2002 ▶	4	C218S	344956
2.5 D			2,5	63	T9A (DJ5)	08.1994 ▶ 04.2002	4	C208R	344896
2.5 TD			2,5	76	T8A (DJ5T)	08.1994 ▶ 04.2002	4	C208R	344896
2.5 TDi			2,5	79	THX (DJ5TED)	12.1996 ▶ 11.2000	4	C224S	344962
<b>JUMPY</b>									
1.9 D			1,9	51	D9B (XUD9A, U)	10.1995 ▶ 04.1998	4	C215S	344953
1.9 D			1,9	51	VJZ (DW8)	04.1998 ▶	4	C216S	344954
1.9 TD			1,9	66	DHX (XUD9TF, BTF)	09.1998 ▶	4	C215S	344953
1.9 TD			1,9	66	DHX (XUD9TF, BTF)	10.1995 ▶ 08.1998	4	C208R	344896
1.9 TD			1,9	68	D8B (XUD9TF)	04.1996 ▶ 08.1998	4	C208R	344896
1.9 TD			1,9	68	D8B (XUD9TF)	09.1998 ▶	4	C215S	344953
2.0 HDi			2,0	69		10.1999 ▶	4	C218S	344956
2.0 HDi			2,0	80	RHZ (DW10ATED)	03.2000 ▶	4	C218S	344956
<b>DAEWOO</b>									
<b>KORANDO, CABRIO</b>									
2.9 D			2,9	72	MB-OM 662	02.1999 ▶	5	C201S	344881
2.9 TD			2,9	88	MB-OM 601 29TD	02.1999 ▶	5	C201S	344881
<b>MUSSO</b>									
2.2 TD			2,2	74	MB OM 601	09.1999 ▶	4	C201S	344881
2.9 D			2,9	73	MB-OM 662	01.1999 ▶ 09.1999	5	C201S	344881
2.9 TD			2,9	88	MB-OM 601 29TD	01.1999 ▶	5	C201S	344881
<b>REXTON</b>									
2.9 TD			2,9	88		04.2002 ▶	5	C201S	344881
<b>FIAT</b>									
<b>127</b>									
1.3 D			1,3	33		04.1981 ▶ 12.1986	4	C101S	344877
<b>147</b>									
1.3 D			1,3	36		10.1980 ▶ 10.1995	4	C102S	344878
<b>BRAVA / BRAVO</b>									
1.9 D			1,9	48	160 A7.000	10.1995 ▶ 10.1996	4	C101S	344877
1.9 JTD 105			1,9	77	182 B4.000 → Mot.-Nr. 1716458	12.1998 ▶ 10.1999	4	C227S	344972
1.9 JTD 105			1,9	77	182 B4.000 Mot.-Nr. 1716459 →	11.1999 ▶ 10.2001	4	C247S	344997
1.9 TD 100 S			1,9	74	182 A7.000	03.1996 ▶ 10.2001	4	C225S	344963
1.9 TD 75 S			1,9	55	182 A8.000	03.1996 ▶ 10.2001	4	C225S	344963
<b>CAMPAGNOLA</b>									
2.4 D			2,4	53	Sofim-8144.61.200	06.1974 ▶ 10.1986	4	C111R	344888
<b>CROMA</b>									
1.9 TD i.d.			1,9	66	154 C6.000	05.1989 ▶ 10.1992	4	C109S	344886
1.9 TD i.d.			1,9	69	154 D1.000	11.1992 ▶ 12.1996	4	C109S	344886
2.5 D			2,5	55	8144.67	12.1985 ▶ 12.1989	4	C101S	344877
2.5 TD			2,5	74	8144.91.2000	12.1985 ▶ 08.1989	4	C102S	344878
2.5 TD			2,5	85	8144.97, 8144.97 Y	01.1993 ▶ 12.1993	4	C204R	344892
2.5 TD			2,5	85	8144.97, 8144.97 Y	05.1989 ▶ 12.1992	4	C110S	344887



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Gloühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания



  	CC	KW					
<b>FIAT</b>  (.../...)							
<b>CROMA</b> (.../...)							
2.5 TDE	2,5	77	8144.97 S	12.1991 ▶ 08.1996	4	C102S	<b>344878</b>
<b>DOBLO</b>							
1.9 JTD	1,9	74	182 B9.000	10.2001 ▶	4	C247S	<b>344997</b>
1.9 JTD	1,9	77		07.2003 ▶	4	C247S	<b>344997</b>
<b>DUNA</b>							
1.7 DS	1,7	44	149 B3.000	01.1987 ▶ 12.1991	4	C101S	<b>344877</b>
<b>ELBA</b>							
1.3 D	1,3	33		04.1986 ▶ 10.1992	4	C100S	<b>344875</b>
1.7 D	1,7	43		04.1989 ▶ 12.1996	4	C100S	<b>344875</b>
<b>IDEA</b>							
1.9 JTD	1,9	74		01.2004 ▶	4	C247S	<b>344997</b>
<b>MAREA, WEEKEND</b>							
1.9 JTD 105	1,9	77	Mot.-Nr. → 1713818	04.1999 ▶ 10.1999	4	C227S	<b>344972</b>
1.9 JTD 105	1,9	77	Mot.-Nr. 1713819 →	11.1999 ▶ 01.2001	4	C247S	<b>344997</b>
1.9 JTD 110	1,9	81	186 A6.000	01.2001 ▶	4	C247S	<b>344997</b>
1.9 TD 100	1,9	74	182 A7.000	09.1996 ▶	4	C225S	<b>344963</b>
1.9 TD 75	1,9	55	182 A8.000	09.1996 ▶	4	C225S	<b>344963</b>
2.4 JTD 130	2,4	96	839 A5.000 Mot.-Nr. → 1713818	04.1999 ▶ 10.1999	5	C227S	<b>344972</b>
2.4 JTD 130	2,4	96	839 A5.000 Mot.-Nr. 1713819 →	11.1999 ▶ 01.2001	5	C247S	<b>344997</b>
2.4 TD 125	2,4	91	185 A2.000	11.1999 ▶ 01.2001	5	C225S	<b>344963</b>
<b>MULTIPLA</b>							
1.9 JTD 105	1,9	77	182 B4.000 Mot.-Nr. → 1692990	04.1999 ▶ 10.1999	4	C227S	<b>344972</b>
1.9 JTD 105	1,9	77	182 B4.000 Mot.-Nr. 1692991 →	11.1999 ▶	4	C247S	<b>344997</b>
1.9 JTD 110	1,9	81	186 A6.000	03.2001 ▶ 07.2002	4	C247S	<b>344997</b>
1.9 JTD 115	1,9	85		07.2002 ▶	4	C247S	<b>344997</b>
<b>PALIO, WEEKEND</b>							
1.7 TD	1,7	51	176 A3.000	04.1996 ▶ 03.2001	4	C206R	<b>344894</b>
<b>PANDA</b>							
1.3 D	1,3	27	156 A5.000	04.1986 ▶ 08.1992	4	C208R	<b>344896</b>
<b>PUNTO</b>							
1.7 D	1,7	42	176 B3.000	04.1994 ▶ 09.1997	4	C206R	<b>344894</b>
1.7 TD	1,7	51	176 A3.000	01.1994 ▶ 09.1999	4	C206R	<b>344894</b>
1.7 TD	1,7	52	176 A5.000	01.1994 ▶ 09.1999	4	C206R	<b>344894</b>
1.7 TD 60	1,7	46	176 B7.000	09.1996 ▶ 09.1999	4	C206R	<b>344894</b>
<b>PUNTO II</b>							
1.9 JTD	1,9	63	188 A7.000	10.2001 ▶	4	C247S	<b>344997</b>
1.9 JTD	1,9	74		06.2003 ▶	4	C247S	<b>344997</b>
1.9 JTD 80	1,9	59	188 A2.000	09.1999 ▶	4	C247S	<b>344997</b>
<b>REGATA , WEEKEND</b>							
1.7 D 60	1,7	43	138 B6.000	09.1983 ▶ 12.1986	4	C101S	<b>344877</b>
1.7 D 60	1,7	44	149 B3.000	05.1985 ▶ 03.1989	4	C101S	<b>344877</b>
1.9 D 65	1,9	48	149 A1.000	04.1984 ▶ 07.1989	4	C101S	<b>344877</b>
1.9 TD 80	1,9	59	831 D1.000	05.1986 ▶ 07.1989	4	C101S	<b>344877</b>
<b>RITMO II</b>							
1.7 D 60	1,7	44	138 C.000, 149 B3.000	05.1985 ▶ 12.1987	4	C101S	<b>344877</b>
1.9 TD 80	1,9	59	831 D1.000	12.1985 ▶ 12.1987	4	C101S	<b>344877</b>
<b>STILO</b>							
1.9 JTD	1,9	59	192 A3.000	02.2002 ▶	4	C247S	<b>344997</b>
1.9 JTD	1,9	85	192 A1.000	10.2001 ▶	4	C247S	<b>344997</b>
<b>STRADA</b>							
1.7 TD	1,7	51	176 A3.000	06.1999 ▶	4	C209S	<b>344919</b>
1.9 JTD	1,9	59		04.2003 ▶	4	C247S	<b>344997</b>
<b>TEMPRA</b>							
1.9 D	1,9	48	160 A7.000	07.1991 ▶ 08.1996	4	C206R	<b>344894</b>
1.9 TD	1,9	59	160 B6.046	07.1992 ▶ 08.1996	4	C206R	<b>344894</b>
1.9 TD	1,9	66	160 A6.000, 160 D1.000	05.1990 ▶ 08.1996	4	C206R	<b>344894</b>
<b>TIPO</b>							
1.7 D	1,7	43	149 B4.000	01.1988 ▶ 10.1994	4	C101S	<b>344877</b>
1.7 D	1,7	45		01.1988 ▶ 10.1995	4	C101S	<b>344877</b>
1.9 D	1,9	48	160 A7.000	07.1991 ▶ 08.1996	4	C101S	<b>344877</b>
1.9 TD	1,9	59	160 B6.046	03.1992 ▶ 06.1993	4	C101S	<b>344877</b>
1.9 TD	1,9	66	160 A6.000, 160 A6.046	09.1990 ▶ 03.1993	4	C101S	<b>344877</b>
1.9 TD	1,9	66	160 A6.000, 160 D1.000	04.1993 ▶ 04.1995	4	C206R	<b>344894</b>
<b>ULYSSE</b>							
1.9 TD	1,9	66	DHX (XUD9TF, L)	02.1995 ▶ 08.2002	4	C215S	<b>344953</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW				
<b>FIAT</b> (.../...)								
<b>ULYSSE (.../...)</b>								
2.0 JTD			2,0	79		05.2003 ▶	4	C218S <b>344956</b>
2.0 JTD			2,0	80	RHW(DW10ATED4)	08.2002 ▶	4	C218S <b>344956</b>
2.0 JTD			2,0	80	RHZ	10.1999 ▶ 08.2002	4	C218S <b>344956</b>
2.1 TD			2,1	80	P8C	03.1996 ▶ 10.1999	4	C215S <b>344953</b>
2.2 JTD			2,2	94	4HW(DW12ATED4)	08.2002 ▶	4	C218S <b>344956</b>
<b>UNO</b>								
1.3 D			1,3	33	127 A5.000, 146 B1.000	06.1983 ▶ 03.1992	4	C101S <b>344877</b>
1.4 TD 70			1,4	52	146 B.000, 146 B3.000	10.1986 ▶ 10.1990	4	C101S <b>344877</b>
1.7 D 60			1,7	42	146 B2.000	09.1989 ▶ 12.1993	4	C101S <b>344877</b>
1.7 D 60			1,7	44	149 B3.000	07.1986 ▶ 08.1989	4	C101S <b>344877</b>
1.9 D			1,9	44	149 B5.046	09.1989 ▶ 03.1994	4	C101S <b>344877</b>
<b>FIAT</b>								
<b>DUCATO</b>								
1.9 D			1,9	50	D9B, DJY	04.1998 ▶ 04.2002	4	C215S <b>344953</b>
1.9 D			1,9	51	230 A2.000	06.1995 ▶ 04.2002	4	C204R <b>344892</b>
1.9 D			1,9	52	149 B1.000	02.1987 ▶ 08.1990	4	C101S <b>344877</b>
1.9 D			1,9	52	149 B1.000	09.1990 ▶ 03.1994	4	C101S <b>344877</b>
1.9 TD			1,9	59	230 A4.000	08.1994 ▶ 04.2002	4	C206R <b>344894</b>
1.9 TD			1,9	60	230 A3.000	04.1994 ▶ 03.1998	4	C204R <b>344892</b>
1.9 TD			1,9	60	230 A3.000	04.1998 ▶ 04.2002	4	C204R <b>344892</b>
1.9 TD			1,9	60	280 A1.000	01.1990 ▶ 08.1990	4	C204R <b>344892</b>
1.9 TD			1,9	60	280 A1.000	09.1990 ▶ 03.1994	4	C110S <b>344887</b>
1.9 TD			1,9	66	DHX (XUD9TF, L)	04.1998 ▶ 04.2002	4	C204R <b>344892</b>
2.0 JTD			2,0	62	RHV (DW10)	04.2002 ▶	4	C218S <b>344956</b>
2.0 JTD			2,0	62	RHV (DW10)	10.2001 ▶ 04.2002	4	C218S <b>344956</b>
2.5 D			2,5	55	8144.67	07.1990 ▶ 03.1994	4	C102S <b>344878</b>
2.5 D			2,5	55	8144.67, CRD93L (U25-661)	01.1986 ▶ 08.1990	4	C102S <b>344878</b>
2.5 D			2,5	62	8140.67	08.1994 ▶ 04.2002	4	C203R <b>344891</b>
2.5 TD			2,5	68	8144.21	01.1987 ▶ 08.1990	4	C102S <b>344878</b>
2.5 TD			2,5	70	8140.27	08.1990 ▶ 03.1994	4	C102S <b>344878</b>
<b>FIORINO</b>								
1.3 D			1,3	33		03.1982 ▶ 10.1982	4	C111R <b>344888</b>
1.3 D			1,3	33		11.1982 ▶ 12.1987	4	C101S <b>344877</b>
1.7 D			1,7	42	149 B2.000	01.1988 ▶	4	C101S <b>344877</b>
1.7 D			1,7	44	149 B3.000	12.1987 ▶ 12.1990	4	C101S <b>344877</b>
1.7 D 60			1,7	42	146 B2.000	05.1988 ▶	4	C101S <b>344877</b>
1.7 D 60			1,7	44	149 B3.000	05.1988 ▶	4	C101S <b>344877</b>
1.7 TD 65			1,7	46	146 D7.000	01.1997 ▶	4	C206R <b>344894</b>
<b>SCUDO</b>								
1.9 D			1,9	51	D9B	02.1996 ▶ 04.1998	4	C208R <b>344896</b>
1.9 D			1,9	51	VJZ (DW8)	04.1998 ▶	4	C208R <b>344896</b>
1.9 TD			1,9	66	DHX (XUD9TF, L)	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	66	DHX (XUD9TF, L)	09.1998 ▶	4	C215S <b>344953</b>
1.9 TD			1,9	68	D8B	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	68	D8B	09.1998 ▶	4	C215S <b>344953</b>
1.9 TD Eco			1,9	66	DHX (XUD9TF, L)	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD Eco			1,9	66	DHX (XUD9TF, L)	09.1998 ▶	4	C215S <b>344953</b>
2.0 JTD			2,0	69	RHX	12.1999 ▶	4	C218S <b>344956</b>
2.0 JTD			2,0	80	RHZ	12.1999 ▶	4	C218S <b>344956</b>
<b>TALENTO</b>								
1.9 D			1,9	52	149 B1.000	03.1989 ▶ 03.1994	4	C101S <b>344877</b>
<b>FORD</b>								
<b>ESCORT '81 EXPRESS</b>								
1.6 D			1,6	40	LTA	02.1984 ▶ 02.1986	4	C104S <b>344880</b>
<b>ESCORT '86 EXPRESS</b>								
1.6 D			1,6	40	LTA	02.1986 ▶ 07.1990	4	C104S <b>344880</b>
1.8 D			1,8	44	RTA, RTB	07.1988 ▶ 07.1990	4	C105S <b>344882</b>
<b>ESCORT '91 EXPRESS</b>								
1.8 D			1,8	44	RTH	07.1990 ▶ 12.1994	4	C105S <b>344882</b>
<b>ESCORT '95 EXPRESS</b>								
1.8 D			1,8	44	RTE, RTH	01.1995 ▶	4	C105S <b>344882</b>
1.8 TD			1,8	51	RVA	12.1995 ▶ 06.2001	4	C217S <b>344955</b>
<b>ESCORT CLASSIC</b>								
1.8 TD			1,8	66	RFD, RFK	10.1998 ▶ 07.2000	4	C105S <b>344882</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Gloühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания



	CC	KW					Valeo
<b>FORD (../...)</b>							
<b>ESCORT IV, COMBI</b>							
1.6 D	1,6	40	LTC	01.1986 ▶ 01.1989	4	C104S	344880
1.8 D	1,8	44	RTA, RTB	01.1989 ▶ 07.1990	4	C105S	344882
<b>ESCORT V, COMBI</b>							
1.8 D	1,8	44	RTE, RTE, RTH	07.1990 ▶ 12.1992	4	C105S	344882
<b>ESCORT VI, COMBI</b>							
1.8 D	1,8	44	RTE, RTE, RTH	09.1992 ▶ 01.1995	4	C105S	344882
1.8 TD	1,8	66	RFD, RFK	02.1993 ▶ 01.1995	4	C105S	344882
1.8 TD	1,8	66	RFS	02.1993 ▶ 01.1995	4	C217S	344955
<b>ESCORT VII CABRIOLET</b>							
1.8 TD	1,8	51	RVA	10.1996 ▶ 08.1999	4	C217S	344955
<b>ESCORT VII CABRIOLET</b>							
1.8 TD	1,8	66	RFD, RFK	09.1995 ▶ 08.1998	4	C105S	344882
<b>ESCORT VII, COMBI</b>							
1.8 D	1,8	44	RTE, RTE, RTH	01.1995 ▶ 12.1996	4	C105S	344882
1.8 TD	1,8	51	RVA	12.1995 ▶ 10.1998	4	C217S	344955
1.8 TD	1,8	66	RFD, RFK	01.1995 ▶ 10.1998	4	C105S	344882
<b>FIESTA COURIER</b>							
1.8 D	1,8	44	RTC, RTD, RTG	09.1991 ▶ 02.1996	4	C105S	344882
1.8 D	1,8	44	RTK	02.1996 ▶	4	C217S	344955
1.8 DI	1,8	55		09.2000 ▶	4	C217S	344955
<b>FIESTA II</b>							
1.6 D	1,6	40	LTB	04.1984 ▶ 02.1989	4	C104S	344880
<b>FIESTA III</b>							
1.8 D	1,8	44	RTC, RTD, RTG	03.1989 ▶ 12.1995	4	C105S	344882
1.8 TD	1,8	57		03.1993 ▶ 12.1995	4	C105S	344882
<b>FIESTA IV</b>							
1.8 D	1,8	44	RTJ, RTK	08.1995 ▶ 04.2000	4	C217S	344955
1.8 DI	1,8	55	RTN, RTP, RTQ	04.2000 ▶ 01.2002	4	C255S	345005
<b>FIESTA V</b>							
1.4 TDCi	1,4	50	F6JA, F6JB	11.2001 ▶	4	C258S	●345013
1.6 TDCi	1,6	66	HHJA, HHJB	11.2004 ▶	4	C258S	●345013
<b>FOCUS C-MAX</b>							
1.6 TDCi	1,6	66	HHJA, HHJB	02.2005 ▶	4	C258S	●345013
1.6 TDCi	1,6	80		10.2003 ▶	4	C258S	●345013
2.0 TDCi	2,0	100	G6DA, G6DB	10.2003 ▶	4	C261S	●345016
2.0 TDCi	2,0	98	G6DC	06.2003 ▶	4	C261S	●345016
<b>FOCUS II</b>							
1.6 TDCi	1,6	66	HHJA, HHJB	11.2004 ▶	4	C258S	●345013
2.0 TDCi	2,0	100	G6DA, G6DB	10.2003 ▶	4	C261S	●345016
2.0 TDCi	2,0	98	G6DC	06.2003 ▶	4	C261S	●345016
<b>FOCUS, COMBI</b>							
1.8 DI / TDDi	1,8	55	BHDA, BHDB	08.1999 ▶	4	C255S	345005
1.8 T DI / TDDi	1,8	66	C9DA, C9DB, C9DC	10.1998 ▶	4	C255S	345005
1.8 TDCi	1,8	74	FFDA	09.2002 ▶	4	C255S	345005
1.8 TDCi	1,8	85	F9DA, F9DB	03.2001 ▶	4	C255S	345005
<b>FUSION</b>							
1.4 TDCi	1,4	50	F6JA	08.2002 ▶	4	C258S	●345013
<b>GALAXY</b>							
1.9 TDI	1,9	66	1Z, AHU, ANU	03.1995 ▶ 09.2001	4	C205R	344893
1.9 TDI	1,9	81	AFN, AVG	08.1997 ▶ 04.2000	4	C205R	344893
1.9 TDI	1,9	85	AUY	04.2000 ▶ 09.2001	4	C205R	344893
<b>MONDEO I, TURNIER</b>							
1.8 TD	1,8	65	RFM, RFN	06.1993 ▶ 08.1996	4	C105S	344882
1.8 TD	1,8	66	RFM, RFN	10.1995 ▶ 08.1996	4	C105S	344882
<b>MONDEO II, TURNIER</b>							
1.8 TD	1,8	66	RFN	09.1996 ▶ 11.2000	4	C217S	344955
<b>MONDEO III, TURNIER</b>							
1.8 SCi	1,8	96		06.2003 ▶	4	C252S	345002
2.0 16V DI / TDDi	2,0	66	D5BA	11.2000 ▶	4	C252S	345002
2.0 16V DI / TDDi	2,0	85	D6BA, HJBA, HJBB, HJBC	11.2000 ▶	4	C252S	345002
2.0 TDCi	2,0	96		10.2001 ▶	4	C252S	345002
2.2 TDCi	2,2	114		09.2004 ▶	4	C252S	345002
<b>ORION I</b>							
1.6 D	1,6	40	LTA	02.1984 ▶ 03.1986	4	C104S	344880

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW					Valeo
<b>FORD</b> (.../...)									
<b>ORION II</b>									
			1,6	40	LTC	12.1985 ▶ 01.1989	4	C104S	344880
			1,8	44	RTA, RTB	01.1989 ▶ 07.1990	4	C105S	344882
<b>ORION III</b>									
			1,8	44	RTE, RTF, RTH	11.1990 ▶ 12.1993	4	C105S	344882
			1,8	66	RFD, RFK	03.1992 ▶ 12.1993	4	C105S	344882
<b>SCORPIO I, COMBI</b>									
			2,5	51	STR	12.1985 ▶ 02.1992	4	C208R	344896
			2,5	68	SFA, SFB	06.1988 ▶ 07.1993	4	C208R	344896
			2,5	85	SCB	08.1993 ▶ 09.1994	4	C208R	344896
<b>SCORPIO II, COMBI</b>									
			2,5	85	SCC	10.1994 ▶ 08.1998	4	C214S	344952
			2,5	92	VM	09.1996 ▶ 08.1998	4	C214S	344952
<b>SIERRA, COMBI</b>									
			1,8	55	RFA, RFB, RFL	08.1988 ▶ 02.1993	4	C105S	344882
			2,3	49	YTR, YTT	01.1987 ▶ 09.1989	4	C208R	344896
<b>FORD</b>									
<b>P 100 II</b>									
			1,8	55	RFA	10.1987 ▶ 12.1992	4	C105S	344882
<b>TOURNEO CONNECT</b>									
			1,8	55		09.2002 ▶	4	C255S	345005
			1,8	66		09.2002 ▶	4	C255S	345005
<b>TRANSIT</b>									
			1,8	55		09.2002 ▶	4	C255S	345005
			2,0	55	D3FA	08.2000 ▶	4	C252S	345002
			2,0	63		08.2000 ▶	4	C252S	345002
			2,0	74	ABFA	08.2000 ▶	4	C252S	345002
			2,0	92		08.2000 ▶	4	C252S	345002
			2,4	55	F4FA	01.2000 ▶	4	C252S	345002
			2,4	66	D2FA, D2FE	01.2000 ▶	4	C252S	345002
			2,4	88	D4FA	01.2000 ▶	4	C252S	345002
			2,4	101		03.2004 ▶	4	C252S	345002
			2,4	85		03.2004 ▶	4	C252S	345002
			2,4	92		07.2001 ▶	4	C252S	345002
<b>FSO</b>									
<b>POLONEZ II</b>									
			1,9	51		08.1988 ▶ 08.1992	4	C102S	344878
<b>POLONEZ III</b>									
			1,9	51		09.1992 ▶	4	C100S	344875
<b>HONDA</b>									
<b>ACCORD VI</b>									
			2,0	77	20T2N	04.1996 ▶ 10.1998	4	C213S	344967
<b>ACCORD VII</b>									
			2,0	77		02.1999 ▶	4	C210S	344921
<b>CIVIC V AERODECK</b>									
			2,0	77		04.1998 ▶ 02.2001	4	C213S	344967
<b>CIVIC V FASTBACK</b>									
			2,0	63	20T2R	01.1997 ▶ 02.2001	4	C213S	344967
<b>INNOCENTI</b>									
<b>ELBA</b>									
			1,7	42	146 B2.000	08.1991 ▶ 12.1996	4	C100S	344875
<b>ISUZU</b>									
<b>CAMPO</b>									
			2,2	39	C223	08.1987 ▶ 10.1988	4	C116S	344917
<b>GEMINI</b>									
			1,5	37	4EC1	02.1988 ▶ 12.1990	4	C114R	344915
			1,5	37	4EC1	02.1988 ▶ 12.1990	4	C116S	344917
			1,5	49	4EC1T	02.1988 ▶ 11.1988	4	C115R	344916
			1,5	49	4EC1T	12.1988 ▶ 12.1990	4	C117S	344918
<b>MIDI</b>									
			2,0	51	4FC1T	01.1989 ▶	4	C115R	344916
			2,0	51	4FC1T	01.1989 ▶	4	C115R	344916


















Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания


**Valeo**

  	CC	KW					
<b>ISUZU</b>  (.../...)							
<b>MIDI</b> (.../...)							
2.0 TD	2,0	<b>51</b>	4FC1T	01.1989 ▶	4	C117S	<b>344918</b>
2.0 TD	2,0	<b>51</b>	4FC1T	01.1989 ▶	4	C117S	<b>344918</b>
2.2 D	2,2	<b>45</b>	4FD1	01.1989 ▶	4	C115R	<b>344916</b>
2.2 D	2,2	<b>45</b>	4FD1	01.1989 ▶	4	C115R	<b>344916</b>
2.2 D	2,2	<b>45</b>	4FD1	01.1989 ▶	4	C117S	<b>344918</b>
2.2 D	2,2	<b>45</b>	4FD1	01.1989 ▶	4	C117S	<b>344918</b>
2.4 TD	2,4	<b>56</b>	4FG1T	01.1994 ▶	4	C115R	<b>344916</b>
2.4 TD	2,4	<b>56</b>	4FG1T	01.1994 ▶	4	C117S	<b>344918</b>
<b>TROOPER SOFT TOP</b>							
2.2 TD	2,2	<b>53</b>	C223T	03.1984 ▶ 07.1987	4	C114R	<b>344915</b>
2.2 TD	2,2	<b>53</b>	C223T	08.1987 ▶ 10.1988	4	C116S	<b>344917</b>
<b>JAGUAR</b> 							
<b>S-TYPE</b>							
2.7 L	2,7	<b>152</b>		06.2004 ▶	6	C262S	<b>345017</b>
<b>X-TYPE</b>							
2.0 D	2,0	<b>96</b>		07.2003 ▶	4	C252S	<b>345002</b>
<b>JEEP</b> 							
<b>CHEROKEE</b>							
2.1 TD	2,1	<b>59</b>	J8S	06.1989 ▶ 03.1992	4	C202R	<b>344889</b>
2.1 TD	2,1	<b>64</b>	J8S	10.1984 ▶ 08.1994	4	C202R	<b>344889</b>
2.5 TD	2,5	<b>85</b>	VM HR 425 CLJRX	01.1988 ▶ 04.1995	4	C208R	<b>344896</b>
2.5 TD	2,5	<b>85</b>	VM HR 425 CLJRX	05.1995 ▶	4	C214S	<b>344952</b>
2.5 TD	2,5	<b>89</b>	VM-HR 425	10.1995 ▶	4	C214S	<b>344952</b>
<b>GRAND CHEROKEE I</b>							
2.5 TD	2,5	<b>85</b>	M51, M52	10.1995 ▶ 04.1999	4	C214S	<b>344952</b>
<b>GRAND CHEROKEE II</b>							
2.7 CRD	2,7	<b>120</b>		10.2001 ▶	5	C214S	<b>344952</b>
3.1 TD	3,1	<b>103</b>		04.1999 ▶	5	C214S	<b>344952</b>
<b>LADA</b> 							
<b>NIVA</b>							
1.9 D	1,9	<b>47</b>	XUD9A	01.1993 ▶	4	C100S	<b>344875</b>
1.9 D	1,9	<b>55</b>	XUD9SD	01.1999 ▶	4	C215S	<b>344953</b>
<b>LANCIA</b> 							
<b>DEDRA</b>							
1.9 TDS	1,9	<b>66</b>	160 D1.000, 835 A4.000, 835 A4.046	04.1989 ▶ 09.1994	4	C101S	<b>344877</b>
1.9 TDS	1,9	<b>66</b>	160 D1.000, 835 A4.000, 835 A4.046	10.1994 ▶ 07.1999	4	C206R	<b>344894</b>
<b>DELTA I</b>							
1.9 TDS	1,9	<b>59</b>	831 D1.000	10.1986 ▶ 12.1989	4	C101S	<b>344877</b>
<b>DELTA II</b>							
1.9 TD	1,9	<b>66</b>	160 D1.000, 835 A4.000	10.1994 ▶ 08.1999	4	C206R	<b>344894</b>
<b>KAPPA</b>							
2.4 JTD	2,4	<b>100</b>	838 A8.000	06.1998 ▶ 10.2001	5	C247S	<b>344997</b>
2.4 T.DS	2,4	<b>91</b>	838 A3.000, 838 A7.000	08.1994 ▶ 10.2001	5	C225S	<b>344963</b>
<b>LYBRA</b>							
1.9 JTD	1,9	<b>77</b>	AR 32302	07.1999 ▶ 09.2000	4	C247S	<b>344997</b>
1.9 JTD	1,9	<b>81</b>	AR 37101	09.2000 ▶ 05.2001	4	C247S	<b>344997</b>
1.9 JTD	1,9	<b>85</b>		05.2001 ▶	4	C247S	<b>344997</b>
2.4 JTD	2,4	<b>103</b>	839 A6.000	09.2000 ▶ 05.2002	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>110</b>	841C.000	05.2002 ▶	5	C247S	<b>344997</b>
2.4 JTD	2,4	<b>99</b>	839 A5.000, AR 32501	07.1999 ▶ 09.2000	5	C247S	<b>344997</b>
<b>PHEDRA</b>							
2.0 JTD	2,0	<b>79</b>		07.2003 ▶	4	C218S	<b>344956</b>
2.0 JTD	2,0	<b>80</b>	RHW(DW10ATED4)	09.2002 ▶	4	C218S	<b>344956</b>
2.2 JTD	2,2	<b>94</b>	4HW(DW12ATED4)	09.2002 ▶	4	C218S	<b>344956</b>
<b>PRISMA</b>							
1.9 D	1,9	<b>48</b>	831 D.000	01.1983 ▶ 12.1989	4	C101S	<b>344877</b>
1.9 TD	1,9	<b>59</b>	831 D1.000	05.1985 ▶ 12.1989	4	C101S	<b>344877</b>
<b>THEMA</b>							
2.5 TD	2,5	<b>74</b>	8144.91	11.1984 ▶ 09.1988	4	C110S	<b>344887</b>
2.5 TDS	2,5	<b>77</b>	8144.97S	05.1988 ▶ 07.1992	4	C208R	<b>344896</b>
2.5 TDS	2,5	<b>85</b>	8144.97	06.1988 ▶ 05.1992	4	C204R	<b>344892</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый












			CC	KW					Valeo
<b>LANCIA</b> (.../...)									
<b>THESIS</b>									
2.4 JTD			2,4	110	841C.000	07.2002 ▶	5	C247S	344997
<b>ZETA</b>									
2.0 JTD			2,0	80	RHW, RHZ	09.1999 ▶ 09.2002	4	C218S	344956
2.1 TD			2,1	80	P 8 C	05.1996 ▶ 09.1999	4	C208R	344896
<b>LAND ROVER</b>									
<b>88/109</b>									
2.3 D			2,3	46		01.1983 ▶ 12.1986	4	C111R	344888
<b>90/110</b>									
2.5 TD			2,5	63		09.1986 ▶ 07.1990	4	C111R	344888
<b>DEFENDER</b>									
2.5 90 TDI			2,5	83	23 L	09.1990 ▶	4	C257S	●344012
2.5 Td5 4WD			2,5	90		06.1998 ▶	5	C257S	●344012
<b>DISCOVERY I</b>									
2.5 TDI			2,5	83	12 L, 21 L	09.1989 ▶ 06.1994	4	C257S	●344012
<b>DISCOVERY II</b>									
2.5 TDI			2,5	83	12 L, 21 L	08.1996 ▶	4	C257S	●344012
2.5 TDI			2,5	90	19 L	10.1995 ▶	4	C257S	●344012
<b>FREELANDER</b>									
2.0 DI			2,0	72		02.1998 ▶ 11.2000	4	C210S	344921
2.0 Td4			2,0	82		11.2000 ▶	4	C241S	344991
<b>RANGE ROVER I</b>									
2.4 D			2,4	78	11 A	04.1986 ▶ 12.1990	4	C103S	344879
<b>RANGE ROVER II</b>									
2.5 D			2,5	100	25 6T (BMW)	07.1994 ▶ 03.2002	6	C106S	344883
2.5 D			2,5	83	14 L	08.1994 ▶ 03.2002	4	C106S	344883
<b>RANGE ROVER III</b>									
3.0 Td 6			3,0	130		03.2002 ▶	6	C241S	344991
<b>LDV INTERNATIONAL</b>									
<b>400</b>									
2.5 TD			2,5	71		11.1995 ▶	4	C107S	344884
<b>MAHINDRA</b>									
<b>CJ 3</b>									
2.1 D			2,1	46	Peugeot	10.1988 ▶ 09.1992	4	C100S	344875
2.3 D			2,3	28	Peugeot	10.1988 ▶ 09.1992	4	C100S	344875
2.5 D			2,5	29	Peugeot	10.1988 ▶ 09.1992	4	C100S	344875
<b>MAZDA</b>									
<b>121 III</b>									
1.8 D			1,8	44	RTJ	03.1996 ▶	4	C217S	344955
<b>2</b>									
1.4 D			1,4	50		04.2003 ▶	4	C258S	●345013
<b>MERCEDES</b>									
<b>190 (W201)</b>									
2.0 D			2,0	53	OM 601.911	02.1989 ▶ 08.1989	4	C201S	344881
2.0 D			2,0	53	OM 601.911	08.1983 ▶ 01.1989	4	C107S	344884
2.0 D			2,0	55	OM 601.911	08.1989 ▶ 08.1993	4	C201S	344881
2.5 D			2,5	66	OM 602.911	02.1989 ▶ 08.1993	5	C201S	344881
2.5 D			2,5	66	OM 602.911	04.1985 ▶ 01.1989	5	C107S	344884
2.5 D			2,5	69	OM 602.911	08.1989 ▶ 08.1993	5	C201S	344881
2.5 TD			2,5	90	OM 602.961	02.1988 ▶ 01.1989	5	C107S	344884
2.5 TD			2,5	90	OM 602.961	02.1989 ▶ 08.1993	5	C201S	344881
2.5 TD			2,5	93	OM 602.961	02.1988 ▶ 01.1989	5	C107S	344884
2.5 TD			2,5	93	OM 602.961	02.1989 ▶ 08.1993	5	C201S	344881
<b>200 D, COMBI (W124)</b>									
2.0 D			2,0	53	OM 601.912	02.1989 ▶ 08.1989	4	C201S	344881
2.0 D			2,0	53	OM 601.912	12.1984 ▶ 01.1989	4	C107S	344884
2.0 D			2,0	55	OM 601.912	08.1989 ▶ 06.1993	4	C201S	344881
<b>250 D, COMBI (W124)</b>									
2.5 D			2,5	66	OM 602.912	02.1989 ▶ 06.1993	5	C201S	344881
2.5 D			2,5	66	OM 602.912	04.1985 ▶ 01.1989	5	C107S	344884
2.5 D			2,5	69	OM 602.912	02.1989 ▶ 06.1993	5	C201S	344881



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preriscaldamento

Gloeibougies  
Glühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания




  	CC	KW					
<b>MERCEDES  (.../...)</b>							
<b>250 D, COMBI (W124) (.../...)</b>							
2.5 D	2,5	<b>69</b>	OM 602.912	04.1985 ▶ 01.1989	5	C107S	<b>344884</b>
<b>250 TD, COMBI (W124)</b>							
2.5 TD	2,5	<b>93</b>	OM 602.962	02.1989 ▶ 06.1993	5	C201S	<b>344881</b>
2.5 TD	2,5	<b>93</b>	OM 602.962	09.1988 ▶ 01.1989	5	C107S	<b>344884</b>
<b>300 D, COMBI (W124)</b>							
3.0 D	3,0	<b>80</b>	OM 603.912	02.1989 ▶ 08.1989	6	C201S	<b>344881</b>
3.0 D	3,0	<b>80</b>	OM 603.912	12.1984 ▶ 01.1989	6	C107S	<b>344884</b>
3.0 D	3,0	<b>81</b>	OM 603.912	06.1990 ▶ 06.1993	6	C201S	<b>344881</b>
3.0 D	3,0	<b>83</b>	OM 603.912	08.1989 ▶ 06.1993	6	C201S	<b>344881</b>
<b>300 D, COMBI 4-MATIC (W124)</b>							
3.0 D	3,0	<b>80</b>	OM 603.913	02.1989 ▶ 08.1992	6	C201S	<b>344881</b>
3.0 D	3,0	<b>80</b>	OM 603.913	09.1986 ▶ 01.1989	6	C107S	<b>344884</b>
3.0 D	3,0	<b>83</b>	OM 603.913	08.1989 ▶ 06.1993	6	C201S	<b>344881</b>
<b>300 TD, COMBI (W124)</b>							
3.0 TD	3,0	<b>105</b>	OM 603.960, OM 603.963	09.1986 ▶ 09.1988	6	C107S	<b>344884</b>
3.0 TD	3,0	<b>108</b>	OM 603.960	02.1989 ▶ 06.1993	6	C201S	<b>344881</b>
3.0 TD	3,0	<b>108</b>	OM 603.960	09.1988 ▶ 01.1989	6	C107S	<b>344884</b>
<b>300 TD, COMBI 4-MATIC (W124)</b>							
3.0 TD	3,0	<b>105</b>	OM 603.960, OM 603.963	09.1986 ▶ 09.1988	6	C107S	<b>344884</b>
3.0 TD	3,0	<b>108</b>	OM 603.963	01.1988 ▶ 01.1989	6	C107S	<b>344884</b>
3.0 TD	3,0	<b>108</b>	OM 603.963	02.1989 ▶ 06.1993	6	C201S	<b>344881</b>
<b>A-CLASS (W168)</b>							
A 160 CDI	1,7	<b>44</b>	OM 668.941	07.1998 ▶ 02.2001	4	C238S	<b>344988</b>
A 160 CDI	1,7	<b>55</b>		02.2001 ▶	4	C238S	<b>344988</b>
A 170 CDI	1,7	<b>66</b>	OM 668.940	07.1998 ▶ 02.2001	4	C238S	<b>344988</b>
A 170 CDI	1,7	<b>70</b>	OM 668.942	02.2001 ▶	4	C238S	<b>344988</b>
<b>A-CLASS (W169)</b>							
A 160 CDI	2,0	<b>60</b>		09.2004 ▶	4	C260S	<b>●345015</b>
A 180 CDI	2,0	<b>80</b>		09.2004 ▶	4	C260S	<b>●345015</b>
A 200 CDI	2,0	<b>103</b>		09.2004 ▶	4	C260S	<b>●345015</b>
<b>B-CLASS (W245)</b>							
B 180 CDI	2,0	<b>80</b>		03.2005 ▶	4	C260S	<b>●345015</b>
B 200 CDI	2,0	<b>103</b>		03.2005 ▶	4	C260S	<b>●345015</b>
<b>C-CLASS SPORTCOUPE (CL203)</b>							
C 200 CDI	2,0	<b>90</b>	OM 646.962	07.2003 ▶	4	C236S	<b>344986</b>
C 220 CDI	2,2	<b>105</b>	OM 611.962	03.2001 ▶	4	C236S	<b>344986</b>
C 220 CDI	2,2	<b>110</b>	OM 646.963	02.2004 ▶	4	C236S	<b>344986</b>
<b>C-CLASS, COMBI (W202)</b>							
C 200 CDI	2,0	<b>75</b>	OM 611.960	03.1998 ▶ 05.2000	4	C236S	<b>344986</b>
C 200 D	2,0	<b>55</b>	OM 601.913	03.1993 ▶ 05.2000	4	C201S	<b>344881</b>
C 200 D	2,0	<b>65</b>	OM 604.915	10.1996 ▶ 05.2000	4	C221S	<b>344959</b>
C 220 CDI	2,2	<b>92</b>	OM 611.960	09.1997 ▶ 05.2000	4	C236S	<b>344986</b>
C 220 D	2,2	<b>55</b>	OM 604.910	07.1996 ▶ 05.2000	4	C219S	<b>344957</b>
C 220 D	2,2	<b>55</b>	OM 604.910	07.1996 ▶ 05.2000	4	C221S	<b>344959</b>
C 220 D	2,2	<b>70</b>	OM 604.910	02.1995 ▶ 05.2000	4	C221S	<b>344959</b>
C 220 D	2,2	<b>70</b>	OM 604.910	08.1993 ▶ 01.1995	4	C219S	<b>344957</b>
C 250 D	2,5	<b>83</b>	OM 605.910	05.1993 ▶ 05.2000	5	C219S	<b>344957</b>
C 250 D	2,5	<b>83</b>	OM 605.910	05.1993 ▶ 05.2000	5	C221S	<b>344959</b>
C 250 TD	2,5	<b>110</b>	OM 605.960	10.1995 ▶ 05.2000	5	C221S	<b>344959</b>
<b>C-CLASS, COMBI (W203)</b>							
C 200 CDI	2,0	<b>75</b>		02.2001 ▶	4	C236S	<b>344986</b>
C 200 CDI	2,0	<b>85</b>	OM 611.962	09.2000 ▶	4	C236S	<b>344986</b>
C 200 CDI	2,0	<b>90</b>	OM 646.962	04.2003 ▶	4	C236S	<b>344986</b>
C 220 CDI	2,2	<b>105</b>	OM 611.962	05.2000 ▶	4	C236S	<b>344986</b>
C 220 CDI	2,2	<b>110</b>	OM 646.963	02.2004 ▶	4	C236S	<b>344986</b>
C 270 CDI	2,7	<b>125</b>	OM 612.962	12.2000 ▶	5	C236S	<b>344986</b>
<b>CLK (C209)</b>							
270 CDI	2,7	<b>125</b>	OM 612.962, OM 612.967	10.2002 ▶	5	C236S	<b>344986</b>
<b>E-CLASS, COMBI (W124)</b>							
E 200 D	2,0	<b>55</b>	OM 601.912	06.1993 ▶ 06.1995	4	C201S	<b>344881</b>
E 250 D	2,5	<b>83</b>	OM 605.911	07.1993 ▶ 06.1995	5	C219S	<b>344957</b>
E 250 D	2,5	<b>83</b>	OM 605.911	07.1993 ▶ 06.1995	5	C221S	<b>344959</b>
E 250 TD	2,5	<b>93</b>	OM 602.962	06.1993 ▶ 06.1995	5	C201S	<b>344881</b>
E 300 D	3,0	<b>100</b>	OM 606.910	07.1993 ▶ 06.1995	6	C219S	<b>344957</b>
E 300 D	3,0	<b>100</b>	OM 606.910	07.1993 ▶ 06.1995	6	C221S	<b>344959</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW				
<b>MERCEDES</b> (.../...)								
<b>E-CLASS, COMBI (W124) (.../...)</b>								
E 300 TD			3,0	108	OM 603.960	06.1993 ▶ 06.1995	6	C201S <b>344881</b>
E 300 TD 4-matic			3,0	108	OM 603.963	06.1993 ▶ 06.1995	6	C201S <b>344881</b>
<b>E-CLASS, COMBI (W210)</b>								
E 200 CDI			2,0	75		06.1998 ▶ 07.1999	4	C236S <b>344986</b>
E 200 CDI			2,0	85	OM 611.961	07.1999 ▶ 03.2002	4	C236S <b>344986</b>
E 200 D			2,0	65	OM 604.917	01.1996 ▶ 03.2002	4	C221S <b>344959</b>
E 220 CDI			2,2	105	OM 611.961	07.1999 ▶ 03.2002	4	C236S <b>344986</b>
E 220 CDI			2,2	92		06.1998 ▶ 07.1999	4	C236S <b>344986</b>
E 220 D			2,2	55	OM 604.912	05.1996 ▶ 03.2002	4	C221S <b>344959</b>
E 220 D			2,2	70	OM 604.912	06.1995 ▶ 07.1999	4	C221S <b>344959</b>
E 250 D			2,5	83	OM 605.912	06.1995 ▶ 07.1999	5	C221S <b>344959</b>
E 250 TD			2,5	110	OM 605.962	06.1997 ▶ 07.1999	5	C221S <b>344959</b>
E 270 CDI			2,7	125	OM 612.961	07.1999 ▶ 03.2002	5	C236S <b>344986</b>
E 290 TD			2,9	95	OM 602.982	03.1996 ▶ 07.1999	5	C222S <b>344960</b>
E 300 D			3,0	100	OM 606.912	06.1995 ▶ 06.1997	6	C221S <b>344959</b>
E 300 TD			3,0	130	OM 606.962	12.1996 ▶ 07.1999	6	C221S <b>344959</b>
E 320 CDI			3,2	145	OM 613.961	07.1999 ▶ 03.2002	6	C236S <b>344986</b>
<b>E-CLASS, COMBI (W211)</b>								
E 200 CDI			2,0	75		07.2002 ▶	4	C236S <b>344986</b>
E 200 CDI			2,0	90		07.2002 ▶	4	C236S <b>344986</b>
E 220 CDI			2,2	110	OM 646.961	03.2002 ▶	4	C236S <b>344986</b>
E 270 CDI			2,7	130	OM 647.961	03.2002 ▶	5	C236S <b>344986</b>
E 280 CDI			3,2	130		05.2004 ▶	6	C236S <b>344986</b>
E 320 CDI			3,2	150	OM 648.961	11.2002 ▶	6	C236S <b>344986</b>
E 400 CDI			4,0	191	OM 628.961	02.2003 ▶	8	C236S <b>344986</b>
<b>G-CLASS (W460)</b>								
240 GD			2,4	53	OM 616.936	08.1980 ▶ 08.1987	4	C107S <b>344884</b>
250 GD			2,5	62	OM 602.930	02.1989 ▶ 12.1992	5	C201S <b>344881</b>
250 GD			2,5	62	OM 602.930	10.1987 ▶ 01.1989	5	C107S <b>344884</b>
250 GD			2,5	68	OM 602.930	02.1989 ▶ 08.1992	5	C201S <b>344881</b>
250 GD			2,5	68	OM 602.930	12.1988 ▶ 01.1989	5	C107S <b>344884</b>
300 GD			3,0	65	OM 617.931	02.1989 ▶ 12.1991	5	C201S <b>344881</b>
300 GD			3,0	65	OM 617.931	08.1980 ▶ 01.1989	5	C107S <b>344884</b>
300 GD			3,0	83	OM 603.912	02.1989 ▶ 07.1993	6	C201S <b>344881</b>
300 GD			3,0	83	OM 603.912	03.1979 ▶ 01.1989	6	C107S <b>344884</b>
<b>G-CLASS (W461)</b>								
250 GD			2,5	68	OM 602.939	02.1990 ▶	5	C201S <b>344881</b>
290 GD/G 290 D			2,9	70	OM 602.942	04.1992 ▶	5	C201S <b>344881</b>
G 290 TD			2,9	88	OM 602.983	07.1997 ▶	5	C201S <b>344881</b>
<b>G-CLASS (W463)</b>								
250 GD			2,5	69	OM 602.931	06.1990 ▶	5	C201S <b>344881</b>
300 GD			3,0	83	OM 603.931	09.1989 ▶ 09.1997	6	C201S <b>344881</b>
350 G TD			3,5	100	OM 603.972	09.1991 ▶ 09.1997	6	C201S <b>344881</b>
G 270 CDI			2,7	115	OM 612.966	10.2001 ▶	5	C236S <b>344986</b>
G 300 TD			3,0	130	OM 606.964	08.1996 ▶	6	C221S <b>344959</b>
G 400 CDI			4,0	184	OM 628.962	12.2000 ▶	8	C236S <b>344986</b>
<b>M-CLASS (W163)</b>								
ML 270 CDI			2,7	120	OM 612.963	12.1999 ▶	5	C236S <b>344986</b>
ML 400 CDI			4,0	184	OM 628.963	09.2001 ▶	8	C236S <b>344986</b>
<b>S-CLASS (W140)</b>								
S 300 TD			3,0	130	OM 606.961	05.1996 ▶ 10.1998	6	C221S <b>344959</b>
S 350 TD			3,5	110	OM 603.971	01.1993 ▶ 10.1998	6	C201S <b>344881</b>
<b>S-CLASS (W220)</b>								
S 320 CDI			3,2	145	OM 613.960	08.1999 ▶ 09.2002	6	C236S <b>344986</b>
S 320 CDI			3,2	150	OM 648.960	09.2002 ▶	6	C236S <b>344986</b>
S 400 CDI			4,0	184	OM 628.960	06.2000 ▶	8	C236S <b>344986</b>
S 400 CDI			4,0	191		06.2003 ▶	8	C236S <b>344986</b>
<b>VANEO (414)</b>								
1.7 CDI			1,7	55		02.2002 ▶	4	C236S <b>344986</b>
1.7 CDI			1,7	67		02.2002 ▶	4	C236S <b>344986</b>
<b>V-CLASS</b>								
V 200 CDI			2,0	75		03.1999 ▶	4	C236S <b>344986</b>
V 220 CDI			2,2	90	OM 611.980	03.1999 ▶	4	C236S <b>344986</b>
V 230 TD			2,3	72	OM 601.970	09.1996 ▶	4	C201S <b>344881</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания



	CC	KW					Valeo
<b>MERCEDES</b> (.../...)							
<b>100 (631)</b>							
100 D	2,4	41	OM 616	12.1990 ▶ 12.1994	4	C201S	<b>344881</b>
100 D	2,4	53	OM 616.963	02.1988 ▶ 01.1989	4	C107S	<b>344884</b>
100 D	2,4	53	OM 616.963	02.1989 ▶ 05.1992	4	C201S	<b>344881</b>
100 D	2,4	55	OM 616, OM 616.963	12.1990 ▶ 02.1996	4	C201S	<b>344881</b>
<b>207 D</b>							
2.4 D	2,4	53	OM 616.937, OM 616.939	09.1982 ▶ 01.1990	4	C107S	<b>344884</b>
<b>SPRINTER 2-T</b>							
208 CDI	2,2	60	OM 611.987	04.2000 ▶	4	C236S	<b>344986</b>
208 D	2,2	60	-	10.1996 ▶ 04.2000	4	C201S	<b>344881</b>
208 D	2,3	58	OM 601.943	02.1995 ▶ 04.2000	4	C201S	<b>344881</b>
210 D	2,9	75	OM 602.980	03.1997 ▶ 04.2000	5	C222S	<b>344960</b>
211 CDI	2,2	80	OM 611.981	04.2000 ▶	4	C236S	<b>344986</b>
212 D	2,9	90	OM 602.980 Mot.-Nr. → 9849	02.1995 ▶ 04.2000	5	C208R	<b>344896</b>
212 D	2,9	90	OM 602.980 Mot.-Nr. 9850 →	02.1995 ▶ 04.2000	5	C222S	<b>344960</b>
212 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. → 136	02.1995 ▶ 04.2000	5	C208R	<b>344896</b>
212 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. 137 →	02.1995 ▶ 04.2000	5	C222S	<b>344960</b>
213 CDI	2,2	95		04.2000 ▶	4	C236S	<b>344986</b>
216 CDI	2,7	115	OM 612.981	04.2000 ▶	5	C236S	<b>344986</b>
<b>SPRINTER 3-T</b>							
308 CDI	2,2	60	OM 611.987	04.2000 ▶	4	C236S	<b>344986</b>
308 D	2,3	58	OM 601.943	02.1995 ▶ 04.2000	4	C201S	<b>344881</b>
308 D	2,3	60	-	02.1995 ▶ 04.2000	4	C201S	<b>344881</b>
310 D	2,9	75	OM 602.980	05.1997 ▶ 03.2000	5	C222S	<b>344960</b>
311 CDI	2,2	80	OM 611.981	08.2002 ▶	4	C236S	<b>344986</b>
312 D	2,9	90	OM 602.980 Mot.-Nr. → 9849	02.1995 ▶ 08.2002	5	C208R	<b>344896</b>
312 D	2,9	90	OM 602.980 Mot.-Nr. 9850 →	02.1995 ▶ 08.2002	5	C222S	<b>344960</b>
312 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. → 136	02.1995 ▶ 08.2002	5	C208R	<b>344896</b>
312 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. 137 →	02.1995 ▶ 04.2000	5	C222S	<b>344960</b>
313 CDI	2,2	95		08.2002 ▶	4	C236S	<b>344986</b>
316 CDI	2,7	115	OM 612.981	08.2002 ▶	5	C236S	<b>344986</b>
<b>SPRINTER 4-T</b>							
408 CDI	2,2	60	OM 611.987	04.2000 ▶	4	C236S	<b>344986</b>
408 D	2,3	58	OM 601.943	02.1996 ▶	4	C201S	<b>344881</b>
410 D	2,9	75	OM 602.980	05.1997 ▶	5	C201S	<b>344881</b>
411 CDI	2,2	80	OM 611.981	04.2000 ▶	4	C236S	<b>344986</b>
412 D	2,9	85	OM 602.980 Mot.-Nr. → 9849	02.1996 ▶ 03.2000	5	C208R	<b>344896</b>
412 D	2,9	85	OM 602.980 Mot.-Nr. 9850 →	02.1996 ▶ 03.2000	5	C222S	<b>344960</b>
412 D	2,9	90	OM 602.980 Mot.-Nr. → 9849	02.1996 ▶ 03.2000	5	C208R	<b>344896</b>
412 D	2,9	90	OM 602.980 Mot.-Nr. 9850 →	02.1996 ▶ 03.2000	5	C222S	<b>344960</b>
412 D AUTOMATIC	2,9	85	OM 602.980 Mot.-Nr. → 136	02.1996 ▶ 03.2000	5	C208R	<b>344896</b>
412 D AUTOMATIC	2,9	85	OM 602.980 Mot.-Nr. 137 →	02.1996 ▶ 03.2000	5	C222S	<b>344960</b>
412 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. → 136	02.1996 ▶ 03.2000	5	C208R	<b>344896</b>
412 D AUTOMATIC	2,9	90	OM 602.980 Mot.-Nr. 137 →	02.1996 ▶ 03.2000	5	C222S	<b>344960</b>
413 CDI	2,2	95		04.2000 ▶	4	C236S	<b>344986</b>
416 CDI	2,7	115	OM 612.981	04.2000 ▶	5	C236S	<b>344986</b>
<b>T1 (601)</b>							
208 D 2.3	2,3	58	OM 601.940	02.1989 ▶ 02.1996	4	C201S	<b>344881</b>
208 D 2.3	2,3	58	OM 601.940	10.1988 ▶ 01.1989	4	C201S	<b>344881</b>
208 D 2.3	2,3	60	OM 601.940	02.1989 ▶ 02.1996	4	C201S	<b>344881</b>
208 D 2.3	2,3	60	OM 601.940	10.1988 ▶ 01.1989	4	C201S	<b>344881</b>
209 D	3,0	65	OM 617.913	12.1982 ▶ 09.1988	5	C107S	<b>344884</b>
210 D	2,9	70	OM 602.940	11.1988 ▶ 02.1996	5	C201S	<b>344881</b>
210 D	2,9	72	OM 602.940	11.1988 ▶ 02.1996	5	C201S	<b>344881</b>
<b>T1 (602)</b>							
308 D 2.3	2,3	58	OM 601.940	05.1990 ▶ 02.1996	4	C201S	<b>344881</b>
308 D 2.3	2,3	60	OM 601.940	06.1989 ▶ 02.1996	4	C201S	<b>344881</b>
310 D	2,9	70	OM 602.940	06.1989 ▶ 02.1996	5	C201S	<b>344881</b>
310 D	2,9	72	OM 602.940	06.1990 ▶ 02.1996	5	C201S	<b>344881</b>
<b>VIANO (W639)</b>							
220 CDI	2,2	110		09.2003 ▶	4	C236S	<b>344986</b>
220 CDI	2,2	80		09.2003 ▶	4	C236S	<b>344986</b>
<b>VITO</b>							
108 CDI 2.2	2,2	60	OM 611A	03.1999 ▶	4	C236S	<b>344986</b>
108 D 2.3	2,3	58	OM 601.942	02.1996 ▶	4	C201S	<b>344881</b>
109 CDI 2.2	2,2	65		09.2003 ▶	4	C236S	<b>344986</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый





			CC	KW					Valeo
<b>MERCEDES</b> (.../...)									
<b>VITO (.../...)</b>									
			2,2	<b>75</b>	OM 611LA (75 KW CDI)	03.1999 ▶	4	C236S	<b>344986</b>
			2,3	<b>72</b>	OM 601.970	03.1997 ▶	4	C201S	<b>344881</b>
			2,3	<b>72</b>	OM 601.970	02.1996 ▶	4	C201S	<b>344881</b>
			2,2	<b>80</b>		09.2003 ▶	4	C236S	<b>344986</b>
			2,2	<b>90</b>	OM 611.980	03.1999 ▶	4	C236S	<b>344986</b>
			2,2	<b>110</b>		09.2003 ▶	4	C236S	<b>344986</b>
<b>MITSUBISHI</b>									
<b>CARISMA</b>									
			1,9	<b>66</b>	F8QT	10.1996 ▶ 09.2000	4	C212S	<b>344965</b>
<b>COLT II</b>									
			1,8	<b>43</b>	4 D 65	02.1984 ▶ 09.1986	4	C264S	<b>●345019</b>
			1,8	<b>44</b>	4 D 65	09.1986 ▶ 04.1988	4	C264S	<b>●345019</b>
<b>COLT III</b>									
			1,8	<b>44</b>	4 D 65	04.1988 ▶ 05.1992	4	C264S	<b>●345019</b>
<b>LANCER III</b>									
			1,8	<b>44</b>	4 D 65	09.1986 ▶ 04.1988	4	C264S	<b>●345019</b>
<b>PAJERO I</b>									
			2,5	<b>64</b>	4 D 56 T	01.1990 ▶ 11.1990	4	C264S	<b>●345019</b>
<b>PAJERO I</b>									
			2,5	<b>70</b>	4 D 56 T	11.1989 ▶ 11.1990	4	C264S	<b>●345019</b>
<b>PAJERO I CANVAS TOP</b>									
			2,5	<b>62</b>	4 D 56 T	05.1986 ▶ 10.1989	4	C264S	<b>●345019</b>
			2,5	<b>70</b>	4 D 56 T	11.1989 ▶ 11.1990	4	C264S	<b>●345019</b>
<b>PAJERO II, CANVAS TOP</b>									
			2,5	<b>73</b>	4 D 56 TD	12.1990 ▶ 06.1993	4	C264S	<b>●345019</b>
<b>PAJERO SPORT</b>									
			2,5	<b>70</b>	4 D 56 T	08.1998 ▶	4	C264S	<b>●345019</b>
<b>L 200</b>									
			2,5	<b>51</b>	4 D 56	11.1986 ▶ 08.1996	4	C264S	<b>●345019</b>
<b>L 200</b>									
			2,5	<b>64</b>	4 D 56 T	11.1992 ▶ 10.1993	4	C264S	<b>●345019</b>
<b>L 300</b>									
			2,3	<b>50</b>	4 D 55	04.1983 ▶ 10.1986	4	C264S	<b>●345019</b>
			2,5	<b>51</b>	4 D 56	11.1986 ▶ 12.1992	4	C264S	<b>●345019</b>
			2,5	<b>64</b>	4 D 56 T	11.1988 ▶ 12.1992	4	C264S	<b>●345019</b>
<b>NISSAN</b>									
<b>ALMERA II</b>									
			1,5	<b>60</b>		01.2003 ▶	4	C228S	<b>344973</b>
<b>MICRA</b>									
			1,5	<b>42</b>	TD15	02.1998 ▶ 02.2003	4	C207R	<b>344895</b>
			1,5	<b>48</b>		01.2003 ▶	4	C228S	<b>344973</b>
			1,5	<b>60</b>		09.2003 ▶	4	C228S	<b>344973</b>
<b>TERRANO II</b>									
			2,7	<b>92</b>	TD27TI	10.1997 ▶	4	C256S	<b>●345011</b>
<b>NISSAN</b>									
<b>INTERSTAR</b>									
			1,9	<b>60</b>	F9Q 772	07.2002 ▶	4	C228S	<b>344973</b>
			2,2	<b>66</b>	G9T 722	07.2002 ▶	4	C243S	<b>344993</b>
<b>PRIMASTAR</b>									
			1,9	<b>74</b>		03.2001 ▶	4	C228S	<b>344973</b>
			1,9	<b>60</b>		03.2001 ▶	4	C228S	<b>344973</b>
<b>OPEL</b>									
<b>ARENA</b>									
			1,9	<b>44</b>	F8Q 600, F8Q 606	03.1998 ▶ 08.2001	4	C223S	<b>344961</b>
			2,5	<b>55</b>	S8U 758, S8U 780, S8U 782	03.1998 ▶ 08.2001	4	C203R	<b>344891</b>
<b>ASCONA C</b>									
			1,6	<b>40</b>	16 D, 16 DA	03.1982 ▶ 08.1988	4	C209S	<b>344919</b>
<b>ASTRA F, CARAVAN</b>									
			1,7	<b>42</b>	17 D	03.1992 ▶ 09.1992	4	C209S	<b>344919</b>
			1,7	<b>44</b>	17 DR	07.1992 ▶ 09.1998	4	C209S	<b>344919</b>
			1,7	<b>50</b>	X 17 DTL	11.1994 ▶ 09.1998	4	C209S	<b>344919</b>
			1,7	<b>60</b>	17 DT (TC4EE1) X 17 DT (TC4EE1) Mot.-Nr. → 956632	03.1992 ▶ 09.1998	4	C117S	<b>344918</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glohnkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания




			CC	KW					Valeo
<b>OPEL (.../...)</b>									
<b>ASTRA G CABRIOLET</b>									
2.2 DTI			2,2	92		09.2002 ▶	4	C245S	344995
<b>ASTRA G COUPE</b>									
2.2 DTI			2,2	92		09.2002 ▶	4	C245S	344995
<b>ASTRA G, CARAVAN</b>									
1.7 TD			1,7	50	X 17 DTL	09.1998 ▶ 08.2000	4	C209S	344919
2.0 DI			2,0	60	X 20 DTL, Y 20 DTL	09.1998 ▶	4	C226S	344964
2.0 DTI 16V			2,0	74	X 20 DTH, Y 20 DTH	08.1999 ▶	4	C226S	344964
2.2 DTI			2,2	92		09.2002 ▶	4	C245S	344995
<b>CAMPO</b>									
2.2 D			2,2	39	C223	08.1991 ▶ 09.1996	4	C116S	344917
3.1 TD			3,1	80	4 JG2T	03.1995 ▶ 12.1996	4	C117S	344918
<b>CORSA A</b>									
1.5 D			1,5	37	15 D (4EC1) Mot.-Nr. → 804794	09.1987 ▶ 03.1993	4	C114R	344915
1.5 D			1,5	37	15 D (4EC1) Mot.-Nr. 804795 →	09.1987 ▶ 03.1993	4	C116S	344917
1.5 TD			1,5	49	15 DT (T4EC1) Mot.-Nr. → 804794	03.1988 ▶ 03.1993	4	C117S	344918
1.5 TD			1,5	49	15 DT (T4EC1) Mot.-Nr. 804795 →	03.1988 ▶ 03.1993	4	C115R	344916
<b>FRONTERA A</b>									
2.3 TD			2,3	74	23 DTR	03.1992 ▶ 02.1995	4	C209S	344919
2.5 TDS			2,5	85	25TDS (MM41B)	09.1996 ▶ 10.1998	4	C214S	344952
<b>FRONTERA B</b>									
2.2 DTI			2,2	85	X 22 DTH, Y 22 DTH	09.2000 ▶ 09.2002	4	C245S	344995
2.2 DTI			2,2	85	X 22 DTH, Y 22 DTH	10.1998 ▶ 08.2000	4	C226S	344964
<b>KADETT E, CARAVAN, COMBO</b>									
1.6 D			1,6	40	16 DA	01.1986 ▶ 12.1989	4	C209S	344919
1.7 D			1,7	42	17 D	01.1989 ▶ 07.1994	4	C209S	344919
1.7 D			1,7	44	17 DR	07.1992 ▶ 07.1994	4	C209S	344919
<b>MONTEREY A</b>									
3.1 TD			3,1	84	4 JG2TC	09.1991 ▶ 12.1997	4	C117S	344918
<b>OMEGA A, CARAVAN</b>									
2.3 D			2,3	54	23 YD	10.1986 ▶ 03.1994	4	C209S	344919
2.3 TD			2,3	66	23 YDT	10.1986 ▶ 08.1988	4	C209S	344919
2.3 TD Interc.			2,3	74	23 DTR	08.1988 ▶ 03.1994	4	C209S	344919
<b>OMEGA B, CARAVAN</b>									
2.0 DTI 16V			2,0	74	X 20 DTH	09.1997 ▶ 09.2000	4	C226S	344964
2.2 DTI 16V			2,2	88	Y 22 DTH	09.2000 ▶ 07.2003	4	C245S	344995
2.5 TD			2,5	96	25 DT, X 25 DT	04.1994 ▶ 07.2003	6	C106S	344883
<b>REKORD E, CARAVAN</b>									
2.2 D			2,2	52	23 D	11.1982 ▶ 08.1986	4	C111R	344888
2.2 TD			2,2	63	23 TD	06.1984 ▶ 08.1986	4	C209S	344919
<b>SENATOR A</b>									
2.2 TD			2,2	63	23 TD Mot.-Nr. 40019 →	11.1984 ▶ 08.1987	4	C209S	344919
<b>SIGNUM</b>									
2.0 DTI			2,0	74		05.2003 ▶	4	C245S	344995
2.2 DTI			2,2	92		05.2003 ▶	4	C245S	344995
<b>SINTRA</b>									
2.2 DTI			2,2	85	X 22 DTH	07.1997 ▶ 04.1999	4	C226S	344964
<b>VECTRA A</b>									
1.7 D			1,7	42	17 D	10.1988 ▶ 09.1992	4	C209S	344919
1.7 D			1,7	44	17 DR	07.1992 ▶ 11.1995	4	C209S	344919
1.7 TD			1,7	60	17 DT (TC4EE1) X 17 DT (TC4EE1) Mot.-Nr. → 731417	03.1990 ▶ 11.1995	4	C114R	344915
1.7 TD			1,7	60	17 DT (TC4EE1) X 17 DT (TC4EE1) Mot.-Nr. → 731417	03.1990 ▶ 11.1995	4	C116S	344917
<b>VECTRA B, CARAVAN</b>									
2.0 DI 16V			2,0	60	X 20 DTL	08.1999 ▶ 04.2002	4	C226S	344964
2.0 DI 16V			2,0	60	X 20 DTL	11.1996 ▶ 07.1999	4	C220S	344958
2.0 DTI 16V			2,0	74	X 20 DTH, Y 20 DTH	06.1997 ▶ 08.2000	4	C226S	344964
2.0 DTI 16V			2,0	74	X 20 DTH, Y 20 DTH	09.2000 ▶ 04.2002	4	C245S	344995
2.2 DTI 16V			2,2	92	Y 22 DTR	09.2000 ▶ 04.2002	4	C245S	344995
<b>VECTRA C GTS</b>									
2.0 DTI 16V			2,0	74		08.2002 ▶	4	C245S	344995
2.2 DTI 16V			2,2	92		08.2002 ▶	4	C245S	344995
<b>VECTRA C, CARAVAN</b>									
2.0 DTI 16V			2,0	74		04.2002 ▶	4	C245S	344995
2.2 DTI 16V			2,2	92		04.2002 ▶	4	C245S	344995

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW				
<b>OPEL</b> (.../...)								
<b>ZAFIRA</b>								
			2,0	<b>60</b>	X 20 DTL	10.1999 ▶	4	C226S <b>344964</b>
			2,0	<b>74</b>	Y 20 DTH	09.2000 ▶	4	C226S <b>344964</b>
			2,2	<b>92</b>	Y 22 DTR	01.2002 ▶	4	C245S <b>344995</b>
<b>OPEL</b>								
<b>MOVANO</b>								
			1,9	<b>59</b>	F9Q 770	09.2000 ▶ 10.2001	4	C228S <b>344973</b>
			1,9	<b>60</b>		10.2001 ▶	4	C228S <b>344973</b>
			2,2	<b>66</b>	G9T 720	09.2000 ▶	4	C243S <b>344993</b>
			2,5	<b>59</b>	S8U 770	07.1998 ▶ 09.2000	4	C203R <b>344891</b>
			2,5	<b>84</b>	G9U 720	10.2001 ▶	4	C243S <b>344993</b>
<b>VIVARO</b>								
			1,9	<b>60</b>		08.2001 ▶	4	C228S <b>344973</b>
			1,9	<b>74</b>	F9Q 760	08.2001 ▶	4	C228S <b>344973</b>
			2,5	<b>99</b>		05.2003 ▶	4	C243S <b>344993</b>
<b>PEUGEOT</b>								
<b>1007</b>								
			1,4	<b>50</b>		04.2005 ▶	4	C258S <b>345013</b>
<b>106 I</b>								
			1,4	<b>37</b>	K9Y (TUD3Y)	09.1992 ▶ 04.1996	4	C108S <b>344885</b>
			1,5	<b>40</b>	VJY (TUD5)	06.1994 ▶ 04.1996	4	C207R <b>344895</b>
			1,5	<b>43</b>		06.1994 ▶ 04.1996	4	C207R <b>344895</b>
<b>106 II</b>								
			1,5	<b>40</b>	VJY (TUD5)	05.1996 ▶	4	C207R <b>344895</b>
			1,5	<b>42</b>	VJX (TUD5)	10.2000 ▶	4	C207R <b>344895</b>
<b>205 I</b>								
			1,7	<b>44</b>	161A (XUD7)	08.1983 ▶ 10.1987	4	C100S <b>344875</b>
<b>205 II</b>								
			1,7	<b>44</b>	161A (XUD7)	07.1987 ▶ 12.1989	4	C100S <b>344875</b>
			1,7	<b>57</b>	A8B (XUD7TE)	01.1990 ▶ 09.1998	4	C100S <b>344875</b>
			1,9	<b>47</b>	DJZ (XUD9Y)	10.1987 ▶ 09.1998	4	C100S <b>344875</b>
<b>206 CC</b>								
			1,6	<b>80</b>		05.2004 ▶	4	C258S <b>345013</b>
<b>206, SW</b>								
			1,4	<b>50</b>	8HX (DV4TD)	07.2002 ▶	4	C258S <b>345013</b>
			1,4	<b>50</b>	8HX (DV4TD)	09.2001 ▶	4	C258S <b>345013</b>
			1,6	<b>80</b>		05.2004 ▶	4	C258S <b>345013</b>
			1,9	<b>51</b>	WJZ (DW8)	09.1998 ▶ 11.2001	4	C216S <b>344954</b>
			2,0	<b>66</b>	RHY (DW10TD)	12.1999 ▶	4	C218S <b>344956</b>
<b>305 II, BREAK</b>								
			1,9	<b>47</b>	162 (XUD9), D9A (XUD9)	10.1982 ▶ 07.1988	4	C100S <b>344875</b>
			1,9	<b>48</b>	162 (XUD9)	10.1982 ▶ 07.1988	4	C100S <b>344875</b>
<b>306, BREAK</b>								
			1,8	<b>43</b>	A9A (XUD7)	05.1993 ▶	4	C215S <b>344953</b>
			1,9	<b>50</b>	DJY (XUD9A)	03.1997 ▶ 08.1998	4	C215S <b>344953</b>
			1,9	<b>51</b>	WJY (DW8B), WJZ (DW8)	09.1998 ▶	4	C216S <b>344954</b>
			1,9	<b>55</b>	DHV (XUD9BSD)	03.1998 ▶	4	C215S <b>344953</b>
			1,9	<b>47</b>	DJZ (XUD9Y)	06.1994 ▶ 08.1998	4	C100S <b>344875</b>
			1,9	<b>47</b>	DJZ (XUD9Y)	09.1998 ▶	4	C215S <b>344953</b>
			1,9	<b>50</b>	DJY (XUD9A)	06.1994 ▶ 08.1998	4	C100S <b>344875</b>
			1,9	<b>50</b>	DJY (XUD9A)	09.1998 ▶	4	C215S <b>344953</b>
			1,9	<b>66</b>	DHY (XUD9TE)	06.1994 ▶ 08.1998	4	C208R <b>344896</b>
			1,9	<b>66</b>	DHY (XUD9TE)	09.1998 ▶	4	C215S <b>344953</b>
			2,0	<b>66</b>	RHY (DW10TD)	06.1999 ▶	4	C218S <b>344956</b>
<b>307 CC</b>								
			2,0	<b>100</b>	RHR (DW10BTED4)	10.2003 ▶	4	C218S <b>344956</b>
<b>307, SW</b>								
			1,4	<b>50</b>	8HX (DV4TD), 8HZ (DV4TD)	10.2001 ▶	4	C258S <b>345013</b>
			1,6	<b>80</b>	9HY (DV6TED4)	02.2004 ▶	4	C258S <b>345013</b>
			2,0	<b>79</b>	RHS (DW10ATED4)	08.2000 ▶	4	C218S <b>344956</b>
			2,0	<b>100</b>	RHR (DW10BTED4)	10.2003 ▶	4	C218S <b>344956</b>
			2,0	<b>66</b>	RHY (DW10TD)	08.2000 ▶	4	C218S <b>344956</b>
<b>309 I</b>								
			1,9	<b>47</b>	162 (XUD9), D9A (XUD9)	06.1986 ▶ 07.1989	4	C100S <b>344875</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glühkerzen  
Swiece zarowce  
Isitma bujisi  
Свечи накаливания




  	CC	KW					
<b>PEUGEOT</b>  (.../...)							
<b>309 II</b>							
1.8 D	1,8	44	161A (XUD7)	07.1989 ▶ 12.1993	4	C100S	<b>344875</b>
1.8 TD	1,8	57	A8B (XUD7TE)	08.1989 ▶ 12.1993	4	C100S	<b>344875</b>
1.9 D	1,9	47	16Z (XUD9), D9A (XUD9), DJZ (XUD9Y)	07.1989 ▶ 12.1993	4	C100S	<b>344875</b>
<b>405 I, BREAK</b>							
1.8 TD	1,8	66	A8A (XUD7TE), AJZ (XUD7TEY)	03.1988 ▶ 12.1992	4	C100S	<b>344875</b>
1.9 D	1,9	47	DJZ (XUD9Y)	07.1988 ▶ 09.1992	4	C100S	<b>344875</b>
1.9 D	1,9	51	D9B (XUD9A)	03.1988 ▶ 12.1992	4	C100S	<b>344875</b>
<b>405 II, BREAK</b>							
1.9 D	1,9	47	DJZ (XUD9Y)	08.1992 ▶ 10.1996	4	C208R	<b>344896</b>
1.9 D	1,9	50	DJY (XUD9A)	06.1994 ▶ 10.1996	4	C100S	<b>344875</b>
1.9 TD	1,9	66	DHY (XUD9TE)	08.1992 ▶ 10.1995	4	C208R	<b>344896</b>
<b>406 COUPE</b>							
2.2 HDI FAP	2,2	98	4HX (DW12TED4, FAP)	03.2000 ▶	4	C218S	<b>344956</b>
<b>406, BREAK</b>							
1.9 D	1,9	55	DHW (XUD9SD)	10.1996 ▶ 05.2004	4	C215S	<b>344953</b>
1.9 TD	1,9	66	DHX (XUD9TE)	01.1996 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	66	DHX (XUD9TE)	09.1998 ▶ 05.2004	4	C215S	<b>344953</b>
1.9 TD	1,9	68	DHY (XUD9TE)	01.1996 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	68	DHY (XUD9TE)	09.1998 ▶ 05.2004	4	C215S	<b>344953</b>
2.0 HDi 110	2,0	80	RHZ (DW10ATED)	02.1999 ▶ 08.2001	4	C218S	<b>344956</b>
2.0 HDi 110 FAP	2,0	79	RHS (DW10ATED4)	08.2001 ▶ 05.2004	4	C218S	<b>344956</b>
2.0 HDi 90	2,0	66	RHY (DW10TD)	02.1999 ▶ 05.2004	4	C218S	<b>344956</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	01.1996 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	09.1998 ▶ 05.2004	4	C215S	<b>344953</b>
2.2 HDi FAP	2,2	98	4HX (DW12TED4, FAP)	03.2000 ▶ 05.2004	4	C218S	<b>344956</b>
<b>407 COUPE</b>							
2.7 V6 HDi FAP 205	2,7	150	-	01.2006 ▶	6	C262S	<b>●345017</b>
<b>407, SW</b>							
1.6 HDi 110 FAP	1,6	80	9HY (DV6TED4)	05.2004 ▶	4	C258S	<b>●345013</b>
2.0 HDi 135 FAP	2,0	100	RHR (DW10BTE4)	05.2004 ▶	4	C261S	<b>●345016</b>
<b>504, BREAK</b>							
1.9 D	1,9	40	XD4x88	01.1980 ▶ 12.1989	4	C111R	<b>344888</b>
2.3 D	2,3	51	134 (XD2)	05.1981 ▶ 12.1989	4	C100S	<b>344875</b>
<b>505, BREAK</b>							
2.3 TD	2,3	59	147 (XD2S)	09.1981 ▶ 06.1986	4	C100S	<b>344875</b>
2.5 D	2,5	51	155 (XD3)	10.1981 ▶ 11.1990	4	C100S	<b>344875</b>
2.5 D	2,5	55	155 (XD3)	06.1981 ▶ 12.1993	4	C100S	<b>344875</b>
2.5 TD	2,5	66	152A (XD3T)	10.1983 ▶ 12.1993	4	C100S	<b>344875</b>
2.5 TD	2,5	70	152A (XD3T)	10.1983 ▶ 12.1990	4	C100S	<b>344875</b>
2.5 TD	2,5	77	152B (XD3TE)	10.1986 ▶ 12.1993	4	C100S	<b>344875</b>
<b>604</b>							
2.5 TD	2,5	66	152A (XD3T)	08.1983 ▶ 12.1986	4	C100S	<b>344875</b>
<b>605</b>							
2.1 D	2,1	60	P9A (XUD11A)	06.1989 ▶ 07.1995	4	C100S	<b>344875</b>
2.1 TD	2,1	80	PHZ (XUD11ATE)	06.1989 ▶ 09.1999	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	08.1994 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 TD 12V	2,1	80	P8C (XUD11BTE)	09.1998 ▶ 09.1999	4	C215S	<b>344953</b>
2.5 TD	2,5	95	THY (DK5ATE)	07.1994 ▶ 09.1999	4	C208R	<b>344896</b>
<b>607</b>							
2.7 V6 HDi FAP 205	2,7	150	-	01.2005 ▶	6	C262S	<b>●345017</b>
2.0 HDi	2,0	80	RHZ (DW10ATED)	05.2000 ▶	4	C218S	<b>344956</b>
2.2 HDi	2,2	98	4HX (DW12TED4, FAP)	02.2000 ▶	4	C218S	<b>344956</b>
<b>806</b>							
1.9 TD	1,9	66	DHX (XUD9TE)	07.1995 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	66	DHX (XUD9TE)	09.1998 ▶ 08.2002	4	C215S	<b>344953</b>
1.9 TD	1,9	68	DHY (XUD9TE)	05.1997 ▶ 08.1998	4	C208R	<b>344896</b>
1.9 TD	1,9	68	DHY (XUD9TE)	09.1998 ▶ 08.2002	4	C215S	<b>344953</b>
2.0 HDi	2,0	80	RHZ (DW10ATED)	08.1999 ▶ 08.2002	4	C218S	<b>344956</b>
2.0 HDi 16V	2,0	80	RHW (DW10ATED4)	08.1999 ▶ 08.2002	4	C218S	<b>344956</b>
2.1 td 12V	2,1	80	P8C (XUD11BTE)	06.1996 ▶ 08.1998	4	C208R	<b>344896</b>
2.1 td 12V	2,1	80	P8C (XUD11BTE)	09.1998 ▶ 08.1999	4	C215S	<b>344953</b>
<b>807</b>							
2.0 HDi FAP	2,0	79	RHS (DW10ATED4)	06.2002 ▶	4	C218S	<b>344956</b>
2.2 HDi FAP	2,2	94	4HX (DW12TED4, FAP)	06.2002 ▶	4	C218S	<b>344956</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW				
<b>PEUGEOT</b> (.../...)								
<b>PARTNER</b>								
1.8 D			1,8	43	A9A (XUD7)	06.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.8 D			1,8	43	A9A (XUD7)	09.1998 ▶	4	C215S <b>344953</b>
1.9 D			1,9	50	DJY (XUD9A)	06.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 D			1,9	50	DJY (XUD9A)	09.1998 ▶	4	C215S <b>344953</b>
1.9 D			1,9	51	DJY (XUD9A)	06.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 D			1,9	51	DJY (XUD9A)	09.1998 ▶	4	C215S <b>344953</b>
1.9 D			1,9	51	WJY (DW8B), WJZ (DW8)	12.1998 ▶	4	C216S <b>344954</b>
2.0 HDI			2,0	66	RHY (DW10TD)	02.2000 ▶	4	C218S <b>344956</b>
<b>PEUGEOT</b>								
<b>BOXER</b>								
1.9 D			1,9	51	D8C (XUD9AU)	03.1994 ▶ 08.1998	4	C208R <b>344896</b>
1.9 D			1,9	51	D8C (XUD9AU)	09.1998 ▶ 04.2002	4	C215S <b>344953</b>
1.9 TD			1,9	66	DHY (XUD9TE)	08.1994 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	66	DHY (XUD9TE)	09.1998 ▶ 04.2002	4	C215S <b>344953</b>
1.9 TD			1,9	68	D8C (XUD9UTF)	03.1994 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	68	D8C (XUD9UTF)	09.1998 ▶ 04.2002	4	C215S <b>344953</b>
2.0 HDi			2,0	62	RHV (DW10UTD)	08.2001 ▶	4	C218S <b>344956</b>
2.2 HDi			2,2	74	4HY (DW12UTED)	04.2002 ▶	4	C218S <b>344956</b>
2.5 D			2,5	63	T9A (DJ5)	08.1994 ▶ 04.2002	4	C208R <b>344896</b>
2.5 TD			2,5	76	T8A (DJ5T)	07.1994 ▶ 04.2002	4	C208R <b>344896</b>
2.5 TDI			2,5	79	THX (DJ5TED)	01.1997 ▶ 04.2002	4	C224S <b>344962</b>
<b>EXPERT</b>								
1.9 D			1,9	51	D9B (XUD9AU)	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 D			1,9	51	D9B (XUD9AU)	09.1998 ▶	4	C215S <b>344953</b>
1.9 D 70			1,9	51	WJZ (DW8)	12.1998 ▶	4	C216S <b>344954</b>
1.9 TD			1,9	66	DHX (XUD9TE)	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	66	DHX (XUD9TE)	09.1998 ▶	4	C215S <b>344953</b>
1.9 TD			1,9	68	D8B (XUD9TE)	02.1996 ▶ 08.1998	4	C208R <b>344896</b>
1.9 TD			1,9	68	D8B (XUD9TE)	09.1998 ▶	4	C215S <b>344953</b>
2.0 HDI			2,0	69	-	07.2000 ▶	4	C218S <b>344956</b>
2.0 HDI			2,0	80	RHW (DW10ATED4)	07.2000 ▶	4	C218S <b>344956</b>
2.0 HDI			2,0	80	RHZ (DW10ATED)	07.2000 ▶	4	C218S <b>344956</b>
<b>J5</b>								
1.9 D			1,9	51	D9B (XUD9A)	10.1990 ▶ 01.1994	4	C100S <b>344875</b>
2.5 D			2,5	54	CRD93 (U25, 661)	07.1991 ▶	4	C100S <b>344875</b>
2.5 D			2,5	54	CRD93 (U25, 661)	09.1991 ▶ 09.1990	4	C111R <b>344888</b>
2.5 D			2,5	54	CRD93 (U25, 661)	10.1990 ▶ 06.1991	4	C111R <b>344888</b>
2.5 TD			2,5	70	CRD93LS (U25, 673)	07.1991 ▶	4	C100S <b>344875</b>
2.5 TD			2,5	70	CRD93LS (U25, 673)	10.1990 ▶ 06.1991	4	C111R <b>344888</b>
<b>J9</b>								
2.1 D			2,1	41	XDPX90	03.1980 ▶ 06.1987	4	C100S <b>344875</b>
2.5 D			2,5	53	XD3P	08.1982 ▶ 06.1987	4	C100S <b>344875</b>
<b>PUCH</b>								
<b>G-MODELL (W 460)</b>								
240 GD			2,4	53	OM 616.936	08.1980 ▶ 08.1987	4	C107S <b>344884</b>
250 GD			2,5	62	OM 602.930	02.1989 ▶ 12.1992	5	C201S <b>344881</b>
250 GD			2,5	62	OM 602.930	10.1987 ▶ 01.1989	5	C107S <b>344884</b>
300 GD			3,0	65	OM 617.931	08.1980 ▶ 12.1991	5	C107S <b>344884</b>
<b>G-MODELL (W 461)</b>								
290 GD/G 290 D			2,9	70	OM 602.942	04.1992 ▶	5	C201S <b>344881</b>
G 290 TD			2,9	88		07.1997 ▶	4	C201S <b>344881</b>
<b>G-MODELL (W 463)</b>								
300 GD			3,0	83	OM 603.931	09.1989 ▶	6	C201S <b>344881</b>
350 G TD			3,5	100	OM 603.972	09.1991 ▶	6	C201S <b>344881</b>
G 300 TD			3,0	130	OM 606.964	08.1996 ▶	6	C221S <b>344959</b>
<b>RENAULT</b>								
<b>AVANTIME</b>								
2.2 dCi			2,2	110		05.2002 ▶	4	C243S <b>344993</b>
<b>CLIO I</b>								
1.9 D			1,9	40		01.1997 ▶ 09.1998	4	C102S <b>344878</b>
1.9 D			1,9	47	F8Q 672, 676, 678, 692, 696	10.1994 ▶ 02.1998	4	C211S <b>344966</b>
1.9 D			1,9	47	F8Q 714, 730, 732	06.1990 ▶ 09.1998	4	C202R <b>344889</b>
1.9 D			1,9	48	F8Q 714, 730, 732	06.1990 ▶ 09.1998	4	C202R <b>344889</b>





Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Gloühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания




	CC	KW					Valeo
<b>RENAULT  (.../...)</b>							
<b>CLIO II</b>							
1.5 dCi	1,5	48	K9K 700, K9K 704	06.2001 ▶	4	C228S	<b>344973</b>
1.5 dCi	1,5	60	K9K 702	06.2001 ▶	4	C228S	<b>344973</b>
1.5 dCi	1,5	74	-	01.2004 ▶	4	C228S	<b>344973</b>
1.9 D	1,9	47	F8Q 630, 662	09.1998 ▶	4	C223S	<b>344961</b>
1.9 D	1,9	47	F8Q 632	03.1998 ▶	4	C229S	<b>344974</b>
1.9 dTi	1,9	59	F9Q 780	02.2000 ▶	4	C228S	<b>344973</b>
<b>ESPACE I</b>							
2.1 TD	2,1	65	J8S 240, J8S 774	10.1984 ▶ 12.1990	4	C102S	<b>344878</b>
<b>ESPACE II</b>							
2.1 TD	2,1	65	J8S 610, J8S 772, J8S 776, J8S 778	01.1991 ▶ 10.1996	4	C102S	<b>344878</b>
2.1 TD	2,1	66	J8S 612	11.1994 ▶ 10.1996	4	C102S	<b>344878</b>
<b>ESPACE III</b>							
1.9 dTi	1,9	72	F9Q 722	02.1999 ▶	4	C228S	<b>344973</b>
2.2 12V TD	2,2	83	G8T 714, G8T 716	11.1996 ▶ 10.2000	4	C210S	<b>344921</b>
2.2 dCi	2,2	95	G9T 710	10.2000 ▶	4	C243S	<b>344993</b>
<b>ESPACE IV</b>							
1.9 dCi	1,9	88		11.2002 ▶	4	C228S	<b>344973</b>
2.2 dCi	2,2	110	G9T 742, G9T 743	11.2002 ▶	4	C243S	<b>344993</b>
<b>KANGOO, RAPID</b>							
1.5 dCi	1,5	42	-	12.2002 ▶	4	C228S	<b>344973</b>
1.5 dCi	1,5	48	K9K 700, K9K 704	12.2001 ▶	4	C228S	<b>344973</b>
1.5 dCi	1,5	60	K9K 702, K9K 710	07.2002 ▶	4	C228S	<b>344973</b>
1.9 D 55	1,9	40	F8Q 662	03.1998 ▶	4	C223S	<b>344961</b>
1.9 D 65	1,9	47	F8Q 630	03.1998 ▶	4	C223S	<b>344961</b>
1.9 D 65	1,9	47	F8Q 632	03.1998 ▶	4	C229S	<b>344974</b>
1.9 dCi	1,9	59	F9Q 782, F9Q 790	10.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	62	F9Q 790	10.2003 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	59	F9Q 780	02.2000 ▶	4	C228S	<b>344973</b>
<b>LAGUNA</b>							
1.9 dCi	1,9	68		03.2004 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	79	F9Q 718	09.1999 ▶ 03.2001	4	C228S	<b>344973</b>
1.9 dTi	1,9	72	F9Q 710	10.1997 ▶ 03.2001	4	C228S	<b>344973</b>
1.9 dTi	1,9	72	F9Q 716	10.1997 ▶ 03.2001	4	C213S	<b>344967</b>
2.2 D	2,2	61	G8T 706, G8T 752, G8T 790, G8T 794	09.1994 ▶ 03.2001	4	C210S	<b>344921</b>
2.2 D	2,2	61	G8T 706, G8T 752, G8T 790, G8T 794	11.1993 ▶ 08.1994	4	C210S	<b>344921</b>
2.2 dT	2,2	83	G8T 760	03.1996 ▶ 03.2001	4	C210S	<b>344921</b>
<b>LAGUNA BREAK</b>							
1.9 dCi	1,9	79	F9Q 718	09.1999 ▶ 03.2001	4	C228S	<b>344973</b>
<b>LAGUNA BREAK</b>							
1.9 dTi	1,9	72	F9Q 710	10.1997 ▶ 03.2001	4	C228S	<b>344973</b>
<b>LAGUNA BREAK</b>							
1.9 dTi	1,9	72	F9Q 716	10.1997 ▶ 03.2001	4	C213S	<b>344967</b>
<b>LAGUNA BREAK</b>							
2.2 D	2,2	61	G8T 706, G8T 752, G8T 790, G8T 794	09.1995 ▶ 03.2001	4	C210S	<b>344921</b>
<b>LAGUNA BREAK</b>							
2.2 dT	2,2	83	G8T 760	03.1996 ▶ 03.2001	4	C210S	<b>344921</b>
<b>LAGUNA II</b>							
1.9 dCi	1,9	74		10.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	77		06.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	88	F9Q 750, F9Q 756	03.2001 ▶	4	C228S	<b>344973</b>
2.2 dCi	2,2	110	G9T 702	10.2001 ▶	4	C243S	<b>344993</b>
<b>LAGUNA II BREAK</b>							
1.9 dCi	1,9	68		03.2004 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	74		10.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	77		06.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	88	F9Q 750, F9Q 756	03.2001 ▶	4	C228S	<b>344973</b>
2.2 dCi	2,2	110	G9T 702	10.2001 ▶	4	C243S	<b>344993</b>
<b>MEGANE CLASSIC</b>							
1.9 D	1,9	47	F8Q 620, F8Q 624	09.1996 ▶	4	C211S	<b>344966</b>
1.9 dCi	1,9	75	F9Q 732, F9Q 733	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	75	F9Q 732, F9Q 733	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	79	F9Q 718	09.1999 ▶ 03.2001	4	C228S	<b>344973</b>
1.9 dT	1,9	66	F8Q 784, F8Q 786	09.1996 ▶	4	C212S	<b>344965</b>
1.9 dTi	1,9	59	F9Q 744	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	72	F9Q 716	10.1997 ▶ 03.2001	4	C213S	<b>344967</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW					
<b>RENAULT</b> (.../...)									
<b>MEGANE CLASSIC (.../...)</b>									
1.9 dTi			1,9	<b>72</b>	F9Q 730, F9Q 734	03.1997 ▶ 02.2001	4	C213S	<b>344967</b>
1.9 dTi			1,9	<b>72</b>	F9Q 731, F9Q 736	03.1997 ▶ 02.2001	4	C228S	<b>344973</b>
1.9 dTi			1,9	<b>72</b>	F9Q 731, F9Q 736	03.1997 ▶ 02.2001	4	C228S	<b>344973</b>
1.9 dTi			1,9	<b>72</b>	F9Q 734	03.1997 ▶ 02.2001	4	C213S	<b>344967</b>
1.9 TDI			1,9	<b>69</b>	F8Q 784, F8Q 786	09.1996 ▶	4	C212S	<b>344965</b>
<b>MEGANE BREAK</b>									
1.9 D			1,9	<b>47</b>	F8Q 620	04.1999 ▶	4	C211S	<b>344966</b>
1.9 D			1,9	<b>47</b>	F8Q 788	04.1999 ▶	4	C223S	<b>344961</b>
1.9 D			1,9	<b>47</b>	F8Q-622,-790	04.1999 ▶	4	C229S	<b>344974</b>
1.9 dCi			1,9	<b>75</b>	F9Q 732, F9Q 733	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi			1,9	<b>59</b>	F9Q 744	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi			1,9	<b>72</b>	F9Q 731, F9Q 736	03.1999 ▶ 02.2001	4	C228S	<b>344973</b>
<b>MEGANE I</b>									
1.9 D Eco			1,9	<b>47</b>	F8Q 620, F8Q 624	01.1996 ▶	4	C211S	<b>344966</b>
1.9 dCi			1,9	<b>75</b>	F9Q 732, F9Q 733	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi			1,9	<b>79</b>	F9Q 718	09.1999 ▶ 03.2001	4	C228S	<b>344973</b>
1.9 dT			1,9	<b>66</b>	F8Q 784, F8Q 786	01.1996 ▶	4	C212S	<b>344965</b>
1.9 dTi			1,9	<b>59</b>	F9Q 744	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi			1,9	<b>72</b>	F9Q 716	10.1997 ▶ 03.2001	4	C213S	<b>344967</b>
1.9 dTi			1,9	<b>72</b>	F9Q 730, F9Q 734	03.1997 ▶ 02.2001	4	C213S	<b>344967</b>
1.9 dTi			1,9	<b>72</b>	F9Q 731, F9Q 736	03.1997 ▶ 02.2001	4	C228S	<b>344973</b>
1.9 TDI			1,9	<b>69</b>		09.1996 ▶	4	C212S	<b>344965</b>
<b>MEGANE II</b>									
1.5 dCi			1,5	<b>60</b>	K9K 722	11.2002 ▶	4	C228S	<b>344973</b>
1.5 dCi			1,5	<b>74</b>		10.2003 ▶	4	C228S	<b>344973</b>
1.9 dCi			1,9	<b>68</b>		03.2004 ▶	4	C228S	<b>344973</b>
1.9 dCi			1,9	<b>88</b>	F9Q 800	11.2002 ▶	4	C228S	<b>344973</b>
<b>MEGANE II BREAK</b>									
1.5 dCi			1,5	<b>60</b>	-	09.2003 ▶	4	C228S	<b>344973</b>
1.5 dCi			1,5	<b>74</b>		02.2004 ▶	4	C228S	<b>344973</b>
1.9 dCi			1,9	<b>68</b>		03.2004 ▶	4	C228S	<b>344973</b>
1.9 dCi			1,9	<b>88</b>	-	09.2003 ▶	4	C228S	<b>344973</b>
<b>MEGANE SCENIC</b>									
1.9 D			1,9	<b>47</b>	F8Q 620	03.1997 ▶ 09.1999	4	C211S	<b>344966</b>
1.9 D			1,9	<b>47</b>	F8Q-622,-790	03.1997 ▶ 09.1999	4	C229S	<b>344974</b>
1.9 D			1,9	<b>47</b>	F8Q-788	03.1997 ▶ 09.1999	4	C223S	<b>344961</b>
1.9 dCi			1,9	<b>79</b>	F9Q 718	09.1999 ▶ 03.2001	4	C228S	<b>344973</b>
1.9 dT			1,9	<b>66</b>	F8Q 784, F8Q 786	01.1997 ▶ 09.1999	4	C212S	<b>344965</b>
1.9 dTi			1,9	<b>72</b>	F9Q 716	10.1997 ▶ 03.2001	4	C213S	<b>344967</b>
1.9 dTi			1,9	<b>72</b>	F9Q 730, F9Q 734	04.1997 ▶ 09.1999	4	C213S	<b>344967</b>
<b>MODUS</b>									
1.5 dCi			1,5	<b>50</b>	KA9K	12.2004 ▶	4	C228S	<b>344973</b>
1.5 dCi			1,5	<b>63</b>	KA9K	12.2004 ▶	4	C228S	<b>344973</b>
<b>R 11</b>									
1.6 D			1,6	<b>40</b>	F8M 700, F8M 720, F8M 730	08.1983 ▶ 12.1988	4	C202R	<b>344889</b>
<b>R 18, VARIABLE</b>									
2.1 D			2,1	<b>49</b>	852 710, J8S 711	11.1981 ▶ 07.1986	4	C102S	<b>344878</b>
2.1 TD			2,1	<b>65</b>		11.1981 ▶ 07.1986	4	C102S	<b>344878</b>
<b>R 19 I</b>									
1.9 D			1,9	<b>47</b>	F8Q 706, F8Q 742	03.1991 ▶ 04.1992	4	C202R	<b>344889</b>
1.9 D			1,9	<b>47</b>	F8Q 706, F8Q 742	09.1988 ▶ 02.1991	4	C102S	<b>344878</b>
<b>R 19 I CHAMADE</b>									
1.9 D			1,9	<b>47</b>	F8Q 706, F8Q 742	03.1991 ▶ 04.1992	4	C202R	<b>344889</b>
1.9 D			1,9	<b>47</b>	F8Q 706, F8Q 742	10.1989 ▶ 02.1991	4	C102S	<b>344878</b>
1.9 TD			1,9	<b>68</b>		09.1990 ▶ 04.1992	4	C118S	<b>344920</b>
<b>R 19 II</b>									
1.9 D			1,9	<b>47</b>	F8Q 742	04.1992 ▶ 12.1995	4	C202R	<b>344889</b>
1.9 dT			1,9	<b>66</b>	F8Q 744	04.1992 ▶ 12.1995	4	C118S	<b>344920</b>
<b>R 19 II CHAMADE</b>									
1.9 D			1,9	<b>47</b>	F8Q 742	04.1992 ▶ 12.1995	4	C202R	<b>344889</b>
1.9 dT			1,9	<b>66</b>	F8Q 744	04.1992 ▶ 12.1995	4	C118S	<b>344920</b>
<b>R 21, COMBI</b>									
1.9 D			1,9	<b>47</b>	F8Q 710	09.1989 ▶ 10.1993	4	C202R	<b>344889</b>
2.1 D			2,1	<b>49-65</b>	J8S 600, 604, 704, 714, 740	10.1986 ▶ 12.1995	4	C102S	<b>344878</b>
2.1 D			2,1	<b>49-65</b>	J8S 742, 746, 784, 786, 788	10.1986 ▶ 12.1995	4	C102S	<b>344878</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preriscaldamento

Gloeibougies  
Gloühkerzen  
Swiece zarowe  
Isitma bujisi  
Свечи накаливания


**Valeo**

  	CC	KW					
<b>RENAULT  (.../...)</b>							
<b>R 25</b>							
2.1 D	2,1	<b>46</b>	J8S 706	04.1984 ▶ 05.1989	4	C102S	<b>344878</b>
2.1 D	2,1	<b>51</b>	J8S 736	06.1989 ▶ 12.1992	4	C102S	<b>344878</b>
2.1 TD	2,1	<b>63</b>	J8S 708, J8S 738	04.1984 ▶ 12.1992	4	C102S	<b>344878</b>
<b>R 30</b>							
2.1 TD	2,1	<b>63</b>	J8S 702	02.1982 ▶ 03.1986	4	C102S	<b>344878</b>
<b>R 9</b>							
1.6 D	1,6	<b>40</b>	F8M 700, F8M 720, F8M 730	10.1982 ▶ 12.1988	4	C202R	<b>344889</b>
<b>RAPID</b>							
1.6 D	1,6	<b>40</b>	F8M 720, F8M 730, F8M 736, F8M 760	03.1986 ▶ 08.1998	4	C202R	<b>344889</b>
1.9 D	1,9	<b>40</b>	F8Q 640, F8Q 682	09.1994 ▶ 03.1998	4	C211S	<b>344966</b>
1.9 D	1,9	<b>47</b>	F8Q 722, F8Q 724, F8Q 774, F8Q 776	09.1991 ▶ 03.1998	4	C202R	<b>344889</b>
<b>SAFRANE I</b>							
2.1 dT	2,1	<b>65</b>	J8S 760	11.1993 ▶ 07.1996	4	C102S	<b>344878</b>
2.5 dT	2,5	<b>83</b>	S8U 762, S8U 763	12.1992 ▶ 07.1996	4	C204R	<b>344892</b>
<b>SAFRANE II</b>							
2.2 dT	2,2	<b>83</b>	G8T 740	07.1996 ▶ 12.2000	4	C210S	<b>344921</b>
<b>SCÉNIC</b>							
1.9 dCi	1,9	<b>75</b>	F9Q 732, F9Q 733	11.2000 ▶	4	C228S	<b>344973</b>
1.9 dCi RX4	1,9	<b>75</b>	F9Q 740	11.2000 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	<b>59</b>	F9Q 744	02.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	<b>72</b>	F9Q 731, F9Q 736	09.1999 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	<b>72</b>	F9Q 734	09.1999 ▶	4	C213S	<b>344967</b>
<b>SCÉNIC II</b>							
1.5 dCi	1,5	<b>60</b>		06.2003 ▶	4	C228S	<b>344973</b>
1.5 dCi	1,5	<b>74</b>		11.2003 ▶	4	C228S	<b>344973</b>
1.9 dCi	1,9	<b>88</b>		06.2003 ▶	4	C228S	<b>344973</b>
<b>SUPER 5</b>							
1.6 D	1,6	<b>40</b>	F8M 720, F8M 730	08.1985 ▶ 12.1996	4	C202R	<b>344889</b>
<b>THALIA</b>							
1.5 dCi	1,5	<b>48</b>		04.2002 ▶	4	C228S	<b>344973</b>
<b>VEL SATIS</b>							
2.2 dCi	2,2	<b>110</b>	G9T 702	06.2002 ▶	4	C243S	<b>344993</b>
<b>RENAULT </b>							
<b>EXPRESS, EXTRA, RAPID</b>							
1.6 D	1,6	<b>40</b>	F8M 720, 730, 736, 760	03.1986 ▶ 08.1998	4	C202R	<b>344889</b>
1.9 D	1,9	<b>40</b>	F8Q 640, F8Q 682	09.1994 ▶ 03.1998	4	C211S	<b>344966</b>
1.9 D	1,9	<b>48</b>	F8Q 684, 722, 724, 774, 776	09.1991 ▶ 03.1998	4	C202R	<b>344889</b>
<b>MASTER I</b>							
28-35 2.1 D	2,1	<b>44</b>	J8S 330	01.1986 ▶ 07.1998	4	C102S	<b>344878</b>
28-35 2.4 D	2,4	<b>52</b>	S8U 731, Sofim-8140.61.2300	08.1980 ▶ 08.1989	4	C102S	<b>344878</b>
28-35 2.5 D	2,5	<b>55</b>	S8U 742, Sofim-8140.67.2510	08.1989 ▶ 07.1998	4	C102S	<b>344878</b>
28-35 2.5 TD	2,5	<b>72</b>	S9U 702, Sofim-8140.27.2580	08.1989 ▶ 07.1998	4	C208R	<b>344896</b>
35 2.5 TD	2,5	<b>69</b>	S9U 714, Sofim-8140.27.2500 Sofim-8140.27.2510	08.1989 ▶ 07.1998	4	C203R	<b>344891</b>
<b>MASTER II</b>							
1.9 dCi 80	1,9	<b>60</b>	F9Q 772	11.2001 ▶	4	C228S	<b>344973</b>
1.9 dTi	1,9	<b>59</b>	F9Q 770	09.2000 ▶	4	C228S	<b>344973</b>
2.2 dCi 90	2,2	<b>66</b>	G9T 722	09.2000 ▶	4	C243S	<b>344993</b>
2.5 D	2,5	<b>59</b>	S8U 770	07.1998 ▶ 01.2001	4	C203R	<b>344891</b>
2.5 dCi 120	2,5	<b>84</b>	G9U 720	10.2001 ▶	4	C243S	<b>344993</b>
<b>TRAFIC</b>							
1.9 D	1,9	<b>44</b>	F8Q 606	06.1997 ▶ 03.2001	4	C223S	<b>344961</b>
1.9 dCi 100	1,9	<b>74</b>	F9Q 760	03.2001 ▶	4	C228S	<b>344973</b>
1.9 dCi 80	1,9	<b>60</b>		03.2001 ▶	4	C243S	<b>344993</b>
2.5 D	2,5	<b>99</b>	-	05.2003 ▶	4	C243S	<b>344993</b>
2.1 D	2,1	<b>43</b>	852 720, 852 750	05.1989 ▶ 06.1994	4	C102S	<b>344878</b>
2.1 D	2,1	<b>43</b>	852 750	03.1985 ▶ 04.1989	4	C102S	<b>344878</b>
2.1 D	2,1	<b>47</b>	J8S 620, J8S 758	06.1994 ▶ 10.1997	4	C102S	<b>344878</b>
2.5 D	2,5	<b>55</b>	S8U 750, S8U 752, S8U 758	05.1989 ▶ 03.2001	4	C203R	<b>344891</b>
2.5 D	2,5	<b>55</b>	Sofim-8140.67.2500, 2550, 2580	05.1989 ▶ 03.2001	4	C203R	<b>344891</b>
<b>ROVER </b>							
<b>100</b>							
114 D	1,4	<b>38</b>	TUD 3	10.1992 ▶ 12.1994	4	C108S	<b>344885</b>
115 D	1,5	<b>42</b>	TUD 5	12.1994 ▶ 12.1998	4	C207R	<b>344895</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW					Valeo
<b>ROVER</b> (.../...)									
<b>200</b>									
218 D			1,9	52		09.1991 ▶ 10.1995	4	C100S	344875
218 TD			1,8	65	XUD 7TE	09.1991 ▶ 10.1995	4	C100S	344875
220 D/SD			2,0	63	20 T2R	11.1995 ▶ 03.2000	4	C210S	344921
220 SDi			2,0	77	20 T2N	11.1995 ▶ 03.2000	4	C210S	344921
<b>25</b>									
2.0 iDT			2,0	74		10.1999 ▶	4	C210S	344921
<b>400</b>									
400 TD Tourer			1,8	65	XUD 7TE	09.1993 ▶ 11.1998	4	C100S	344875
418 D			1,9	49		09.1991 ▶ 04.1995	4	C100S	344875
418 TD			1,8	65	XUD 7TE	09.1991 ▶ 04.1995	4	C100S	344875
420 D			2,0	63	20 T2R	11.1995 ▶ 03.2000	4	C210S	344921
420 Di			2,0	77	20 T2N	05.1995 ▶ 03.2000	4	C210S	344921
<b>45</b>									
2.0 iDT			2,0	74		02.2000 ▶	4	C210S	344921
<b>600</b>									
620 Sdi			2,0	77	20 T2N	12.1994 ▶ 02.1999	4	C210S	344921
<b>75</b>									
2.0 CDT			2,0	85	M 47 R	02.1999 ▶	4	C241S	344991
2.0 CDTi			2,0	96		02.2003 ▶	4	C241S	344991
<b>800, COUPÉ</b>									
825 D/SD			2,5	87	425 SL1RR, 492 4 SHIRG	01.1990 ▶ 04.1995	4	C208R	344896
825 D/SD			2,5	87	425 SL1RR, 492 4 SHIRG	05.1995 ▶ 02.1999	4	C214S	344952
<b>MAESTRO</b>									
2.0 D			2,0	44		09.1990 ▶ 10.1992	4	C100S	344875
2.0 TD			2,0	60		09.1990 ▶ 01.1995	4	C100S	344875
<b>MONTEGO</b>									
2.0 D Turbo			2,0	60	BB	10.1988 ▶ 10.1995	4	C100S	344875
<b>SAAB</b>									
<b>9-3</b>									
2.2 TiD			2,2	85	D223L, X 22 DTH	02.1998 ▶ 11.2000	4	C226S	344964
2.2 TiD			2,2	92	-	11.2000 ▶ 09.2002	4	C245S	344995
<b>SEAT</b>									
<b>ALHAMBRA</b>									
1.9 TDI			1,9	66	1Z, AHU, ANU	04.1996 ▶	4	C205R	344893
1.9 TDI			1,9	81	AFN	08.1996 ▶ 06.2000	4	C205R	344893
1.9 TDI			1,9	85	AUY	06.2000 ▶	4	C205R	344893
<b>ALTEA</b>									
1.9 TDI			1,9	77	BKC, BJB	04.2004 ▶	4	C263S	●345018
<b>AROSA</b>									
1.4 TDI			1,4	55	AMF	01.2000 ▶ 10.2001	3	C205R	344893
1.7 SDI			1,7	44	AKU	08.1997 ▶ 10.2001	4	C205R	344893
<b>CORDOBA</b>									
1.7 SDI			1,7	44		07.1997 ▶ 06.1999	4	C205R	344893
1.9 D			1,9	47	1Y	01.1996 ▶ 08.1996	4	C200S	344876
1.9 D			1,9	50	1Y	02.1993 ▶ 08.1996	4	C200S	344876
1.9 SDI			1,9	47	AEY	08.1996 ▶ 06.1999	4	C205R	344893
1.9 SDI			1,9	50	AGP, AQM	06.1999 ▶ 10.2002	4	C205R	344893
1.9 TD			1,9	55	AAZ	02.1993 ▶ 08.1996	4	C200S	344876
1.9 TDI			1,9	66	1Z, AHU	08.1996 ▶ 06.1999	4	C205R	344893
1.9 TDI			1,9	66	AGR, ALH	06.1999 ▶ 10.2002	4	C205R	344893
1.9 TDI			1,9	81	AFN	03.1997 ▶ 06.1999	4	C205R	344893
1.9 TDI			1,9	81	ASK, ASV	06.1999 ▶ 10.2002	4	C205R	344893
<b>IBIZA I</b>									
1.7 D			1,7	40	022 A.5000	06.1984 ▶ 08.1987	4	C111R	344888
1.7 D			1,7	40	022 A.5000	09.1987 ▶ 05.1993	4	C101S	344877
1.7 D			1,7	42	022 A.5000	08.1990 ▶ 05.1993	4	C101S	344877
<b>IBIZA II</b>									
1.7 SDI			1,7	44		07.1997 ▶ 08.1999	4	C205R	344893
1.9 D			1,9	47	1Y	04.1993 ▶ 08.1996	4	C200S	344876
1.9 D			1,9	50	1Y	10.1994 ▶ 08.1996	4	C200S	344876
1.9 SDI			1,9	47	AEY	08.1996 ▶ 08.1999	4	C205R	344893
1.9 TD			1,9	55	AAZ	03.1993 ▶ 08.1996	4	C200S	344876
1.9 TDI			1,9	66	1Z, AHU	08.1996 ▶ 08.1999	4	C205R	344893



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glohnkerzen  
Swiece zarowce  
Isitma bujisi  
Свечи накаливания

**Valeo**


			CC	KW					
<b>SEAT</b> (.../...)									
<b>IBIZA II</b> (.../...)									
1.9 TDI			1,9	81	AFN	02.1997 ▶ 08.1999	4	C205R	<b>344893</b>
<b>IBIZA III</b>									
1.9 SDI			1,9	50	AGP, AQM	08.1999 ▶ 02.2002	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AGR, ALH	08.1999 ▶ 02.2002	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	ASK, ASV	08.1999 ▶ 02.2002	4	C205R	<b>344893</b>
<b>IBIZA IV</b>									
1.9 TDI Cupra R			1,9	118	BPX	03.2004 ▶	4	C263S	<b>●345018</b>
<b>INCA</b>									
1.7 D			1,7	42	AHB	09.1996 ▶	4	C200S	<b>344876</b>
1.9 D			1,9	47	1Y	11.1995 ▶	4	C200S	<b>344876</b>
1.9 SDI			1,9	47	AEY, AYQ	11.1995 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	66		09.1996 ▶	4	C205R	<b>344893</b>
<b>LEON</b>									
1.9 SDI			1,9	50	AQM	11.1999 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	110	ARL	02.2001 ▶ 04.2002	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AGR, ALH	11.1999 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AHF, ASV	11.1999 ▶	4	C205R	<b>344893</b>
<b>MALAGA</b>									
1.7 D			1,7	40	022 A.5000	05.1985 ▶ 08.1987	4	C111R	<b>344888</b>
1.7 D			1,7	40	022 A.5000	09.1987 ▶ 12.1993	4	C101S	<b>344877</b>
1.7 D			1,7	42	022 A.5000	05.1990 ▶ 12.1993	4	C101S	<b>344877</b>
<b>RONDA</b>									
1.7 D			1,7	40	022 A.5000	06.1982 ▶ 12.1986	4	C111R	<b>344888</b>
1.7 D			1,7	41	022 A.5000	06.1982 ▶ 12.1986	4	C111R	<b>344888</b>
<b>TERRA</b>									
1.3 D			1,3	33	MN	03.1990 ▶ 12.1994	4	C200S	<b>344876</b>
1.4 D			1,4	35	1W	10.1990 ▶ 12.1995	4	C200S	<b>344876</b>
<b>TOLEDO I</b>									
1.9 D			1,9	47	1Y	12.1995 ▶ 03.1999	4	C200S	<b>344876</b>
1.9 D			1,9	50	1Y	05.1991 ▶ 03.1999	4	C200S	<b>344876</b>
1.9 SDI			1,9	47	1Y	12.1995 ▶ 03.1999	4	C205R	<b>344893</b>
1.9 TD			1,9	55	AAZ	05.1991 ▶ 03.1999	4	C200S	<b>344876</b>
1.9 TDI			1,9	66	1Z, AHU	08.1995 ▶ 03.1999	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AFN	11.1996 ▶ 03.1999	4	C205R	<b>344893</b>
<b>TOLEDO II</b>									
1.9 TDI			1,9	110	ARL	10.2000 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AGR, ALH	04.1999 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AHF, ASV	04.1999 ▶	4	C205R	<b>344893</b>
<b>TOLEDO III</b>									
1.9 TDI			1,9	77	BKC, BJB	10.2004 ▶	4	C263S	<b>●345018</b>
<b>SKODA</b>									
<b>FABIA, COMBI</b>									
1.9 SDI			1,9	47	ASY	12.1999 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	74	ATD	09.2000 ▶	4	C205R	<b>344893</b>
<b>FELICIA I</b>									
1.9 D			1,9	47	AEF	10.1995 ▶ 03.1998	4	C200S	<b>344876</b>
<b>FELICIA II</b>									
1.9 D			1,9	47	AEF	03.1998 ▶ 06.2001	4	C200S	<b>344876</b>
<b>OCTAVIA, COMBI</b>									
1.9 SDI			1,9	47	AEY	09.1996 ▶	4	C205R	<b>344893</b>
1.9 SDI			1,9	50	AGP, AQM	06.1997 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AGR, ALH	09.1996 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	74	ATD	09.2000 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	77	BJB, BKC	06.2004 ▶	4	C263S	<b>●345018</b>
1.9 TDI			1,9	81	AHF, ASV	08.1997 ▶	4	C205R	<b>344893</b>
<b>SSANGYONG</b>									
<b>KORANDO</b>									
2.2 D			2,2	50	Daewoo DC23	12.1988 ▶ 12.1996	4	C116S	<b>344917</b>
2.3 D			2,3	58	MB-OM 601.940	12.1996 ▶	4	C201S	<b>344881</b>
2.9 D			2,9	72	MB-OM 662	12.1996 ▶	5	C201S	<b>344881</b>
2.9 TD			2,9	88		04.1998 ▶	5	C201S	<b>344881</b>
<b>MUSSO</b>									
2.3 D			2,3	59	MB-OM 601.940, MB-OM 661	10.1995 ▶	4	C201S	<b>344881</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый
















			CC	KW				
<b>SSANGYONG</b> (.../...)								
<b>MUSSO</b> (.../...)								
2.9 D			2,9	73	MB-OM 662	03.1996 ▶	5	C201S <b>344881</b>
2.9 TD			2,9	88		04.1998 ▶	5	C201S <b>344881</b>
<b>REXTON</b>								
2.9			2,9	88		04.2002 ▶	5	C201S <b>344881</b>
<b>SUZUKI</b>								
<b>BALENO, COMBI</b>								
1.9 TD			1,9	55		04.1998 ▶	4	C208R <b>344896</b>
<b>GRAND VITARA</b>								
2.0 HDI 110			2,0	80		07.2001 ▶	4	C218S <b>344956</b>
2.0 TD Intercooler			2,0	64	RF	03.1998 ▶	4	C218S <b>344956</b>
<b>SAMURAI</b>								
1.9 TD			1,9	46	XUD9	11.1998 ▶	4	C215S <b>344953</b>
<b>VITARA</b>								
1.9 D			1,9	50	XUD9A	01.1995 ▶ 03.1998	4	C215S <b>344953</b>
1.9 D			1,9	55		08.1996 ▶ 03.1998	4	C208R <b>344896</b>
2.0 TD			2,0	52	RF	12.1994 ▶ 03.1998	4	C218S <b>344956</b>
2.0 TD Intercooler			2,0	64	RF	12.1995 ▶ 03.1998	4	C218S <b>344956</b>
<b>VITARA CABRIO</b>								
1.9 D			1,9	55		08.1996 ▶ 03.1999	4	C208R <b>344896</b>
<b>TALBOT</b>								
<b>HORIZON</b>								
1.9 D			1,9	47	XUD9	07.1984 ▶ 06.1986	4	C100S <b>344875</b>
1.9 D			1,9	48	XUD9	07.1982 ▶ 06.1986	4	C100S <b>344875</b>
<b>TAGORA</b>								
2.3 TD			2,3	59	XD2S	08.1981 ▶ 06.1983	4	C100S <b>344875</b>
<b>VAUXHALL</b>								
<b>ARENA, COMBI</b>								
1.9 D			1,9	44	F8Q 600, F8Q 606	03.1998 ▶ 08.2001	4	C223S <b>344961</b>
2.5 D			2,5	55	S8U 758, S8U 780, S8U 782	03.1998 ▶ 08.2001	4	C102S <b>344878</b>
<b>ASTRA MK II BELMONT</b>								
1.5 DT			1,5	49	15 DT (T4EC1)	01.1988 ▶ 08.1990	4	C117S <b>344918</b>
1.5 DT			1,5	53	15 DT (T4EC1)	01.1987 ▶ 08.1989	4	C117S <b>344918</b>
1.6 D			1,6	40	16 DA	09.1985 ▶ 08.1991	4	C100S <b>344875</b>
1.7 D			1,7	42	17 D	01.1989 ▶ 12.1991	4	C100S <b>344875</b>
<b>ASTRA MK II, ESTATE</b>								
1.5 DT			1,5	49	15 DT (T4EC1)	01.1988 ▶ 08.1991	4	C117S <b>344918</b>
1.6 D			1,6	40	16 D	02.1982 ▶ 08.1986	4	C100S <b>344875</b>
1.6 D			1,6	40	16 DA	09.1984 ▶ 12.1989	4	C100S <b>344875</b>
1.7 D			1,7	42	17 D	02.1989 ▶ 08.1991	4	C100S <b>344875</b>
<b>ASTRA MK III ESTATE</b>								
1.7 D			1,7	42	17 D	12.1991 ▶ 02.1998	4	C100S <b>344875</b>
1.7 D			1,7	44	17 DR	03.1991 ▶ 12.1994	4	C209S <b>344919</b>
1.7 TD			1,7	50	X 17 DTL	11.1994 ▶ 08.2000	4	C209S <b>344919</b>
1.7 TD			1,7	60	17 DT (TC4EE1) Mot.-Nr. → 731416	12.1991 ▶ 12.1994	4	C115R <b>344916</b>
1.7 TD			1,7	60	17 DT (TC4EE1) Mot.-Nr. 731417 →	12.1991 ▶ 08.1995	4	C117S <b>344918</b>
<b>ASTRA MK IV, ESTATE</b>								
1.7 TD			1,7	50	X 17 DTL	02.1998 ▶ 08.2000	4	C209S <b>344919</b>
2.0 DI			2,0	60	X 20 DTL, Y 20 DTL	02.1998 ▶	4	C226S <b>344964</b>
2.0 DTI 16V			2,0	74	X 20 DTH, Y 20 DTH	08.1999 ▶	4	C226S <b>344964</b>
<b>ASTRAVAN MK III</b>								
1.7 D			1,7	44	17 DR	01.1991 ▶ 08.1994	4	C209S <b>344919</b>
1.7 TD			1,7	50	X 17 DTL	01.1994 ▶ 08.1998	4	C209S <b>344919</b>
<b>ASTRAVAN MK IV</b>								
1.7 TD			1,7	50	X 17 DTL	08.1998 ▶	4	C209S <b>344919</b>
2.0 DI			2,0	60	X 20 DTL	08.1998 ▶	4	C226S <b>344964</b>
<b>CARLTON MK II, ESTATE</b>								
2.3 D			2,3	52	23 D	05.1983 ▶ 08.1986	4	C100S <b>344875</b>
<b>CARLTON MK III, ESTATE</b>								
1.7 D			1,7	44	17 DR	07.1992 ▶ 11.1995	4	C209S <b>344919</b>
2.2 TD			2,2	66	23 YDT	09.1986 ▶ 08.1988	4	C209S <b>344919</b>
2.3 D			2,3	54	23 YD	09.1986 ▶ 03.1994	4	C209S <b>344919</b>
2.3 TD Interc.			2,3	74	23 DTR	03.1992 ▶ 03.1994	4	C100S <b>344875</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preriscaldamento

Gloeibougies  
Gloühkerzen  
Świece żarowe  
Isitma bujisi  
Свечи накаливания


**Valeo**

  	CC	KW					
<b>VAUXHALL  (.../...)</b>							
<b>CAVALIER MK II, ESTATE</b>							
1.6 D	1,6	40	16 D, 16 DA	03.1982 ▶ 08.1988	4	C100S	<b>344875</b>
<b>CAVALIER MK III</b>							
1.7 D	1,7	42	17 D	09.1988 ▶ 09.1992	4	C100S	<b>344875</b>
1.7 D	1,7	44	17 DR	07.1992 ▶ 11.1995	4	C209S	<b>344919</b>
1.7 TD	1,7	60	17 DT (TC4EE1) Mot.-Nr. → 731416	03.1990 ▶ 12.1994	4	C115R	<b>344916</b>
1.7 TD	1,7	60	17 DT (TC4EE1) Mot.-Nr. 731417 →	03.1990 ▶ 11.1995	4	C117S	<b>344918</b>
<b>FRONTERA</b>							
2.3 TD	2,3	74	23 DTR	03.1992 ▶ 10.1998	4	C100S	<b>344875</b>
2.5 TDS	2,5	85	25TDS (VM41B)	09.1996 ▶ 10.1998	4	C214S	<b>344952</b>
<b>FRONTERA MK II</b>							
2.2 DTI	2,2	85	X 22 DTH, Y 22 DTH	10.1998 ▶	4	C226S	<b>344964</b>
<b>NOVA</b>							
1.5 D	1,5	37	15 D (4EC1) Mot.-Nr. 804795 →	09.1987 ▶ 09.1989	4	C116S	<b>344917</b>
1.5 TD	1,5	49	15 DT (T4EC1) Mot.-Nr. → 804794	01.1990 ▶ 02.1993	4	C115R	<b>344916</b>
1.5 TD	1,5	49	15 DT (T4EC1) Mot.-Nr. 804795 →	01.1990 ▶ 02.1993	4	C117S	<b>344918</b>
<b>OMEGA, ESTATE</b>							
2.0 DTI 16V	2,0	74	X 20 DTH	10.1998 ▶ 09.2000	4	C226S	<b>344964</b>
2.2 DTI 16V	2,2	88	Y 22 DTH	09.2000 ▶	4	C245S	<b>344995</b>
2.5 TD	2,5	96	25 DT, X 25 DT	04.1994 ▶ 02.2001	6	C106S	<b>344883</b>
<b>ROYALE</b>							
2.2 TD	2,2	63	23 TD	11.1984 ▶ 08.1987	4	C209S	<b>344919</b>
<b>SINTRA</b>							
2.2 DTI	2,2	85	X 22 DTH	07.1997 ▶ 04.1999	4	C226S	<b>344964</b>
<b>VECTRA MK II</b>							
2.0 DTI 16V	2,0	74		04.2002 ▶	4	C245S	<b>344995</b>
2.2 DTI 16V	2,2	92		04.2002 ▶	4	C245S	<b>344995</b>
<b>VECTRA MK II GTS</b>							
2.2 DTI 16V	2,2	92		04.2002 ▶	4	C245S	<b>344995</b>
<b>VECTRA, ESTATE</b>							
2.0 DI 16V	2,0	60	X 20 DTL	08.1999 ▶	4	C226S	<b>344964</b>
2.0 DI 16V	2,0	60	X 20 DTL	11.1996 ▶ 07.1999	4	C220S	<b>344958</b>
2.0 DTI 16V	2,0	74	X 20 DTH, Y 20 DTH	06.1997 ▶ 08.2000	4	C226S	<b>344964</b>
2.0 DTI 16V	2,0	74	Y 20 DTH	09.2000 ▶	4	C245S	<b>344995</b>
2.2 DTI 16V	2,2	92	Y 22 DTR	09.2000 ▶	4	C245S	<b>344995</b>
<b>ZAFIRA</b>							
2.0 DI 16V	2,0	60	X 20 DTL	10.1999 ▶	4	C226S	<b>344964</b>
2.0 DTI 16V	2,0	74	X 20 DTH	04.1999 ▶	4	C226S	<b>344964</b>
2.2 DTI 16V	2,2	92	Y 22 DTR	01.2002 ▶	4	C245S	<b>344995</b>
<b>VAUXHALL </b>							
<b>BRAVA PICK-UP</b>							
2.2 D	2,2	39	C223	08.1991 ▶ 09.1996	4	C116S	<b>344917</b>
2.5 D	2,5	56	4 JA1	08.1991 ▶ 06.1994	4	C100S	<b>344875</b>
2.5 D	2,5	56	4 JA1T	06.1990 ▶ 06.1994	4	C100S	<b>344875</b>
2.5 TD	2,5	56	4 JA1T	07.1994 ▶	4	C208R	<b>344896</b>
<b>MOVANO</b>							
1.9 DTI	1,9	59	F9Q 770	09.2000 ▶ 10.2001	4	C228S	<b>344973</b>
1.9 DTI	1,9	60		10.2001 ▶	4	C228S	<b>344973</b>
2.2 DTI	2,2	66	G9T 720	09.2000 ▶	4	C243S	<b>344993</b>
2.5 D	2,5	59	SBU 770	07.1998 ▶ 09.2000	4	C203R	<b>344891</b>
2.5 DTI	2,5	84	G9U 720	10.2001 ▶	4	C243S	<b>344993</b>
<b>VIVARO</b>							
1.9 DTI	1,9	74	F9Q 760	08.2001 ▶	4	C228S	<b>344973</b>
<b>VOLKSWAGEN </b>							
<b>BORA, COMBI</b>							
1.9 SDI	1,9	50	AGR, AQM	10.1998 ▶	4	C205R	<b>344893</b>
1.9 TDI	1,9	110	ARL	05.2000 ▶ 09.2001	4	C205R	<b>344893</b>
1.9 TDI	1,9	66	AGR, ALH, ANU	10.1998 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI	1,9	74	ATD, AXR	09.2000 ▶ 10.2001	4	C205R	<b>344893</b>
1.9 TDI	1,9	81	AHF, ASV	10.1998 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI	1,9	85	AJM, AUJ	12.1998 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI	1,9	96	ASZ	11.2000 ▶	4	C205R	<b>344893</b>
<b>GOLF II</b>							
1.6 D	1,6	37		08.1983 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 D	1,6	40	JP, ME	08.1983 ▶ 10.1991	4	C200S	<b>344876</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW					Valeo
<b>VOLKSWAGEN</b> (.../...)									
<b>GOLF II (.../...)</b>									
1.6 TD			1,6	44	1V	08.1989 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 TD			1,6	51	JR, MF	08.1983 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 TD			1,6	59	RA, SB	04.1989 ▶ 10.1991	4	C200S	<b>344876</b>
<b>GOLF III CABRIOLET</b>									
1.9 TDI			1,9	66	1Z, AHU, ALE	09.1993 ▶ 04.1999	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AFN	07.1996 ▶ 05.1998	4	C205R	<b>344893</b>
<b>GOLF III, VARIANT</b>									
1.9 D			1,9	48	1Y	11.1991 ▶ 08.1997	4	C200S	<b>344876</b>
1.9 SDI			1,9	47	AEY	04.1997 ▶ 08.1997	4	C205R	<b>344893</b>
1.9 TD.GTD			1,9	55	AAZ	11.1991 ▶ 08.1997	4	C200S	<b>344876</b>
1.9 TDI			1,9	66	1Z, AHU, ALE	09.1993 ▶ 04.1999	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AFN	04.1996 ▶ 04.1999	4	C205R	<b>344893</b>
<b>GOLF IV CABRIOLET</b>									
1.9 TDI			1,9	66	AHU, ALE	06.1998 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AFN, AVG	06.1998 ▶	4	C205R	<b>344893</b>
<b>GOLF IV, VARIANT</b>									
1.9 SDI			1,9	50	AGP, AQM	08.1997 ▶	4	C205R	<b>344893</b>
1.9 TDI			1,9	110	ARL	05.2000 ▶ 10.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AGR, ALH	08.1997 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	74	ATD, AXR	09.2000 ▶ 10.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AHF, ASV	08.1997 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	85	AJM, AUJ	12.1998 ▶ 06.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	96	ASZ	11.2000 ▶ 10.2001	4	C205R	<b>344893</b>
<b>GOLF V</b>									
1.9 TDI			1,9	66	BRU	05.2004 ▶	4	C263S	<b>•345018</b>
1.9 TDI			1,9	77	BJB, BKC	10.2003 ▶	4	C263S	<b>•345018</b>
<b>GOLF V PLUS</b>									
1.9 TDI			1,9	77	BKC	01.2005 ▶	4	C263S	<b>•345018</b>
<b>ILTIS</b>									
1.6 TD			1,6	51	1C	08.1987 ▶ 12.1988	4	C200S	<b>344876</b>
<b>JETTA</b>									
1.9 TDI			1,9	77	BKC, BJB	08.2005 ▶	4	C263S	<b>•345018</b>
<b>JETTA II</b>									
1.6 D			1,6	40	JP, ME	01.1984 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 TD			1,6	44	1V	01.1990 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 TD			1,6	51	JR, MF	01.1984 ▶ 10.1991	4	C200S	<b>344876</b>
1.6 TD			1,6	59	RA, SB	04.1989 ▶ 10.1991	4	C200S	<b>344876</b>
<b>LUPO</b>									
1.2 TDI			1,2	45	ANY, AYZ	07.1999 ▶ 10.2001	3	C205R	<b>344893</b>
1.4 TDI			1,4	55	AMF	01.1999 ▶ 10.2001	3	C205R	<b>344893</b>
1.7 SDI			1,7	44	AKU	09.1998 ▶ 10.2001	4	C205R	<b>344893</b>
<b>NEW BEETLE</b>									
1.9 TDI			1,9	66	ALH	01.1998 ▶ 02.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	74	ATD	02.2001 ▶ 10.2001	4	C205R	<b>344893</b>
<b>PASSAT, VARIANT</b>									
1.6 D			1,6	40	CR, JK	08.1980 ▶ 03.1988	4	C200S	<b>344876</b>
1.6 TD			1,6	51	CY	04.1982 ▶ 03.1988	4	C200S	<b>344876</b>
1.6 TD			1,6	59	RA	05.1986 ▶ 03.1988	4	C200S	<b>344876</b>
1.6 TD			1,6	59	RA, SB	08.1988 ▶ 09.1993	4	C200S	<b>344876</b>
1.9 D			1,9	50	1Y	05.1989 ▶ 10.1993	4	C200S	<b>344876</b>
1.9 TD			1,9	55	AAZ	03.1991 ▶ 08.1996	4	C200S	<b>344876</b>
1.9 TDI			1,9	66	1Z	10.1993 ▶ 08.1996	4	C205R	<b>344893</b>
1.9 TDI			1,9	66	AHH, AHU	10.1996 ▶ 11.2000	4	C205R	<b>344893</b>
1.9 TDI			1,9	74	AVB	02.2000 ▶ 10.2001	4	C205R	<b>344893</b>
1.9 TDI			1,9	77	BKC	03.2005 ▶	4	C263S	<b>•345018</b>
1.9 TDI			1,9	81	AFN	03.1996 ▶ 08.1996	4	C205R	<b>344893</b>
1.9 TDI			1,9	81	AFN, AVG	10.1996 ▶ 11.2000	4	C205R	<b>344893</b>
1.9 TDI			1,9	85	AJM, ATJ	08.1998 ▶ 11.2000	4	C205R	<b>344893</b>
1.9 TDI			1,9	96	AVF, AWX	11.2000 ▶ 10.2001	4	C205R	<b>344893</b>
<b>POLO</b>									
1.3 D			1,3	33	MN	08.1986 ▶ 07.1990	4	C200S	<b>344876</b>
1.4 D			1,4	35	1W	10.1990 ▶ 09.1994	4	C200S	<b>344876</b>
1.4 TDI			1,4	55	AMF	10.1999 ▶ 09.2001	3	C205R	<b>344893</b>
1.7 SDI			1,7	42	AHG	04.1997 ▶ 10.1999	4	C205R	<b>344893</b>
1.7 SDI			1,7	44	AKU	08.1997 ▶ 09.2001	4	C205R	<b>344893</b>



Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preriscaldamento

Gloeibougies  
Glühkerzen  
Świece żarowe  
Isitma bujisi  
Свечи накаливания

**Valeo**

	CC	KW					
<b>VOLKSWAGEN  (.../...)</b>							
<b>POLO (.../...)</b>							
1.9 D	1,9	47	AEF	10.1994 ▶ 09.2001	4	C200S	344876
1.9 SDI	1,9	47	AGD, ASX	07.1996 ▶ 09.2001	4	C205R	344893
1.9 TDI	1,9	96	ASZ, BLT	11.2003 ▶	4	C263S	●345018
<b>POLO CLASSIC</b>							
1.3 D	1,3	33	MN	08.1986 ▶ 12.1988	4	C200S	344876
1.4 D	1,4	35	1W	10.1990 ▶ 09.1994	4	C200S	344876
1.7 SDI	1,7	42	AKW	07.1997 ▶ 09.2001	4	C205R	344893
1.9 SDI	1,9	47	1Y, AEY	12.1995 ▶ 09.2001	4	C205R	344893
1.9 SDI	1,9	50	AGP, AQM	08.1999 ▶ 09.2001	4	C205R	344893
1.9 TDI 110	1,9	81	AFN, ASV	06.1998 ▶ 09.2001	4	C205R	344893
1.9 TDI 90	1,9	66	AGR, AHU, ALE, ALH	09.1996 ▶ 09.2001	4	C205R	344893
<b>POLO COUPE</b>							
1.3 D	1,3	33	MN	08.1986 ▶ 08.1990	4	C200S	344876
1.4 D	1,4	35	1W	08.1990 ▶ 09.1994	4	C200S	344876
<b>POLO VARIANT</b>							
1.7 SDI	1,7	42	AKW	08.1997 ▶ 09.2001	4	C205R	344893
1.9 SDI	1,9	47	AEY	06.1997 ▶ 09.2001	4	C205R	344893
1.9 SDI	1,9	50	AGP, AQM	08.1999 ▶ 09.2001	4	C205R	344893
1.9 TDI	1,9	66	AGR, AHU, ALE, ALH	05.1997 ▶ 09.2001	4	C205R	344893
1.9 TDI	1,9	81	AFN, ASV	06.1998 ▶ 09.2001	4	C205R	344893
<b>SHARAN</b>							
1.9 TDI	1,9	66	1Z, AHU, ANU	09.1995 ▶ 02.2000	4	C205R	344893
1.9 TDI	1,9	81	AFN, AVG	09.1996 ▶ 04.2000	4	C205R	344893
1.9 TDI	1,9	85	AUY	04.2000 ▶ 10.2001	4	C205R	344893
<b>TOURAN</b>							
1.9 TDI	1,9	74	AVQ	02.2003 ▶	4	C263S	●345018
1.9 TDI	1,9	77	BKC	08.2003 ▶	4	C263S	●345018
<b>VENTO</b>							
1.9 D	1,9	48	1Y	11.1991 ▶ 09.1998	4	C200S	344876
1.9 SDI	1,9	47	AEY	04.1997 ▶ 09.1998	4	C205R	344893
1.9 TD	1,9	55	AAZ	11.1991 ▶ 09.1998	4	C200S	344876
1.9 TDI	1,9	66	1Z, AHU, ALE	09.1993 ▶ 09.1998	4	C205R	344893
1.9 TDI	1,9	81	AFN	04.1996 ▶ 09.1998	4	C205R	344893
<b>VOLKSWAGEN </b>							
<b>BUS T3</b>							
1.6 D	1,6	37	CS	01.1981 ▶ 07.1987	4	C200S	344876
1.6 TD	1,6	51	JX	08.1984 ▶ 07.1992	4	C200S	344876
1.7 D	1,7	42	KY	10.1986 ▶ 07.1992	4	C200S	344876
<b>BUS T4</b>							
1.9 D	1,9	44	1X	09.1990 ▶	4	C200S	344876
1.9 TD	1,9	50	ABL	10.1992 ▶	4	C200S	344876
2.4 D	2,4	55	AJA	08.1997 ▶	5	C200S	344876
2.4 D	2,4	57	AAB	09.1990 ▶ 07.1991	5	C200S	344876
2.5 TDI	2,5	111	AHY, AXG	05.1998 ▶	5	C205R	344893
2.5 TDI	2,5	65	AJT, AYY	05.1998 ▶	5	C205R	344893
2.5 TDI	2,5	75	ACV, AUF, AYC	09.1995 ▶	5	C205R	344893
<b>CADDY I</b>							
1.6 D	1,6	40	JK, ME	08.1982 ▶ 07.1992	4	C200S	344876
<b>CADDY II</b>							
1.7 SDI	1,7	42	AHB	07.1996 ▶	4	C205R	344893
1.9 D	1,9	47	1Y	11.1995 ▶	4	C200S	344876
1.9 D	1,9	47	AEF	10.1997 ▶	4	C200S	344876
1.9 SDI	1,9	47	AEY, AYQ	11.1995 ▶	4	C205R	344893
1.9 TDI	1,9	66	1Z, AHU, ALE, ALH	09.1996 ▶	4	C205R	344893
<b>CADDY III</b>							
1.9 TDI	1,9	77	BJB	04.2004 ▶	4	C263S	●345018
<b>CADDY LIFE III</b>							
1.9 TDI	1,9	77	BJB	04.2004 ▶	4	C263S	●345018
<b>LT 28 I</b>							
2.4 D	2,4	51	1S, ACT	08.1989 ▶ 06.1996	6	C200S	344876
2.4 D	2,4	55	CP, DW	01.1979 ▶ 07.1992	6	C200S	344876
2.4 TD	2,4	68	1G	08.1989 ▶ 08.1992	6	C200S	344876
2.4 TD	2,4	70	ACL	09.1992 ▶ 06.1996	6	C200S	344876
2.4 TD	2,4	75	DV	12.1982 ▶ 07.1989	6	C200S	344876

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



			CC	KW				
<b>VOLKSWAGEN</b> (.../...)								
<b>LT 28-35 I</b>								
2.4 D			2,4	51	1S, ACT	08.1989 ▶ 06.1996	6	C200S <b>344876</b>
2.4 D			2,4	55	CP, DW	01.1979 ▶ 07.1992	6	C200S <b>344876</b>
2.4 TD			2,4	68	1G	08.1989 ▶ 08.1992	6	C200S <b>344876</b>
2.4 TD			2,4	70	ACL	09.1992 ▶ 06.1996	6	C200S <b>344876</b>
2.4 TD			2,4	75	DV	12.1982 ▶ 07.1989	6	C200S <b>344876</b>
<b>LT 28-35 II</b>								
2.5 SDI			2,5	55	AGX	07.1996 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	61	BBE	05.2001 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	66	APA	05.1999 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	75	AHD	05.1996 ▶ 08.1999	5	C205R <b>344893</b>
2.5 TDI			2,5	80	ANJ, AVR	05.1999 ▶	5	C205R <b>344893</b>
<b>LT 28-46 II</b>								
2.5 SDI			2,5	55	AGX	09.1996 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	61	BBE	05.2001 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	66	APA	05.1999 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	75	AHD	05.1996 ▶ 08.1999	5	C205R <b>344893</b>
2.5 TDI			2,5	80	ANJ, AVR	05.1999 ▶	5	C205R <b>344893</b>
<b>LT 40-55 I</b>								
2.4 D			2,4	51	1S, ACT	07.1990 ▶ 05.1996	6	C200S <b>344876</b>
2.4 D			2,4	55	CP, DW	01.1979 ▶ 07.1992	6	C200S <b>344876</b>
2.4 TD			2,4	68	1G	08.1989 ▶ 08.1992	6	C200S <b>344876</b>
2.4 TD			2,4	70	ACL	06.1992 ▶ 05.1996	6	C200S <b>344876</b>
2.4 TD			2,4	75	DV	02.1986 ▶ 08.1992	6	C200S <b>344876</b>
<b>TRANSPORTER T3</b>								
1.6 D			1,6	37	CS	01.1981 ▶ 07.1987	4	C200S <b>344876</b>
1.6 TD			1,6	51	JX	10.1984 ▶ 07.1992	4	C200S <b>344876</b>
1.7 D			1,7	42	KY	07.1989 ▶ 07.1992	4	C200S <b>344876</b>
<b>TRANSPORTER T4</b>								
1.9 D			1,9	45	1X	07.1990 ▶	4	C200S <b>344876</b>
1.9 TD			1,9	50	ABL	10.1992 ▶	4	C200S <b>344876</b>
2.4 D			2,4	55	AJA	08.1997 ▶	5	C200S <b>344876</b>
2.4 D			2,4	57	AAB	07.1990 ▶	5	C200S <b>344876</b>
2.5 TDI			2,5	111	AHY, AXG	05.1998 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	65	AJT, AYY	12.1998 ▶	5	C205R <b>344893</b>
2.5 TDI			2,5	75	ACV, AUF, AYC	09.1995 ▶	5	C205R <b>344893</b>
<b>VOLVO</b>								
<b>240, COMBI</b>								
2.4 D			2,4	58	D 24	08.1987 ▶ 08.1993	6	C200S <b>344876</b>
2.4 D			2,4	60	D 24	04.1979 ▶ 08.1993	6	C200S <b>344876</b>
<b>340-360</b>								
1.6 D			1,6	40	D 16	08.1984 ▶ 07.1991	4	C202R <b>344889</b>
<b>440 K</b>								
1.9 TD			1,9	66	D 19 T	07.1994 ▶ 12.1996	4	C118S <b>344920</b>
<b>460 L</b>								
1.9 TD			1,9	66	D 19 T	07.1994 ▶ 07.1996	4	C118S <b>344920</b>
<b>740, COMBI</b>								
2.4 D			2,4	60	D 24	08.1985 ▶ 07.1988	6	C200S <b>344876</b>
2.4 TD			2,4	80	D 24 T	09.1985 ▶ 07.1992	6	C200S <b>344876</b>
2.4 TD			2,4	83		08.1984 ▶ 07.1990	6	C200S <b>344876</b>
2.4 TD Interc.			2,4	90	D 24 TIC	08.1986 ▶ 07.1988	6	C200S <b>344876</b>
<b>760, COMBI</b>								
2.4 D			2,4	60	D 24	01.1982 ▶ 07.1992	6	C200S <b>344876</b>
2.4 TD			2,4	80	D 24 T	04.1987 ▶ 07.1992	6	C200S <b>344876</b>
2.4 TD			2,4	82	D 24 T	08.1982 ▶ 07.1987	6	C200S <b>344876</b>
2.4 TD Interc.			2,4	85	D 24 TIC	08.1987 ▶ 07.1992	6	C200S <b>344876</b>
<b>850, COMBI</b>								
2.5 TDI			2,5	103	D 5252 T	08.1995 ▶ 12.1996	5	C205R <b>344893</b>
<b>940 II, COMBI</b>								
2.4 TD Interc.			2,4	85	D 24 TIC	09.1991 ▶ 07.1994	6	C200S <b>344876</b>
2.4 TD Interc.			2,4	90	D 24 TIC	08.1994 ▶ 10.1998	6	C200S <b>344876</b>
<b>940, COMBI</b>								
2.4 D			2,4	60	D 24	08.1990 ▶ 12.1994	6	C200S <b>344876</b>
2.4 TD			2,4	80	D 24 T	08.1990 ▶ 08.1993	6	C200S <b>344876</b>
2.4 TD Intercooler			2,4	90	D 24 TIC	08.1990 ▶ 12.1994	6	C200S <b>344876</b>














Glow plugs  
Bougies de préchauffage  
Bujías de precalentamiento  
Velas de pré-aquecimento  
Candele di preiscaldamento

Gloeibougies  
Glühkerzen  
Swiece żarowe  
Isitma bujisi  
Свечи накаливания



  	CC	KW					
<b>VOLVO</b>  (.../...)							
<b>960, COMBI</b>							
2.4 TD Interc.	2,4	<b>85</b>	D 24 TIC	09.1991 ▶ 07.1994	6	C200S	<b>344876</b>
<b>S 40 II</b>							
2.0 D	2,0	<b>100</b>	DW 10BTED4	01.2004 ▶	4	C261S	<b>●345016</b>
<b>S40 I</b>							
1.9 DI	1,9	<b>70</b>	D 4192 T2	03.1999 ▶ 07.2000	4	C213S	<b>344967</b>
1.9 DI	1,9	<b>75</b>	D 4192 T3	07.2000 ▶ 12.2003	4	C228S	<b>344973</b>
1.9 DI	1,9	<b>85</b>	D 4192 T4	07.2000 ▶ 12.2003	4	C228S	<b>344973</b>
1.9 TD	1,9	<b>66</b>	D 4192 T	07.1995 ▶ 08.1999	4	C212S	<b>344965</b>
<b>S60</b>							
2.4 D5	2,4	<b>120</b>	D 5244 T	07.2001 ▶	5	C262S	<b>●345017</b>
<b>S70</b>							
2.5 TDI	2,5	<b>103</b>	D 5252 T	01.1997 ▶ 11.2000	5	C205R	<b>344893</b>
<b>S80</b>							
2.4 D	2,4	<b>96</b>	D 5244 T2	10.2001 ▶	5	C262S	<b>●345017</b>
2.4 D5	2,4	<b>120</b>	D 5244 T	08.2001 ▶	5	C262S	<b>●345017</b>
2.5 TDI	2,5	<b>103</b>	D 5252 T	01.1999 ▶	5	C205R	<b>344893</b>
<b>V40</b>							
1.9 DI	1,9	<b>70</b>	D 4192 T2	03.1999 ▶ 07.2000	4	C213S	<b>344967</b>
1.9 DI	1,9	<b>75</b>	D 4192 T3	07.2000 ▶ 12.2003	4	C228S	<b>344973</b>
1.9 DI	1,9	<b>85</b>	D 4192 T4	07.2000 ▶ 12.2003	4	C228S	<b>344973</b>
1.9 TD	1,9	<b>66</b>	D 4192 T	07.1995 ▶ 08.1999	4	C212S	<b>344965</b>
<b>V50</b>							
2.0 D	2,0	<b>100</b>	D 4204 T, T2	04.2004 ▶	4	C261S	<b>●345016</b>
<b>V70 I</b>							
2.5 TDI	2,5	<b>103</b>	D 5252 T	01.1997 ▶ 03.2000	5	C205R	<b>344893</b>
<b>V70 II</b>							
2.4 D	2,4	<b>96</b>	D 5244 T2	12.2001 ▶	5	C262S	<b>●345017</b>
2.4 D5	2,4	<b>120</b>	D 5244 T	08.2001 ▶	5	C262S	<b>●345017</b>
2.5 TDI	2,5	<b>103</b>	D 5252 T	03.2000 ▶	5	C205R	<b>344893</b>
<b>XC 90</b>							
2.4 D5	2,4	<b>120</b>	D 5244 T	10.2002 ▶	5	C262S	<b>●345017</b>

• New Nouveau Nuevo Novo Nuovo Nieuw Neu Nowi Yeni Новый



2.3

Glow plugs

Bougies de préchauffage

Bujías de precalentamiento

Velas de pré-aquecimento

Candele di preriscaldamento

Gloeibougies

Glühkerzen

Świece żarowe

Isitma bujisi


Свечи накаливания





**Valeo**


**Valeo**





 <b>OE</b>	<b>Valeo</b>
<b>ALFA ROMEO</b>	
116 61 05 358 00/00	<b>C103S</b>
116 76 05 358 01/00	<b>C103S</b>
605 07 123	<b>C103S</b>
605 96 245	<b>C206R</b>
606 17 002	<b>C214S</b>
608 16 139	<b>C227S</b>
<b>BMW</b>	
12 12 1 286 059	<b>C100S</b>
12 12 1 288 161	<b>C100S</b>
12 23 1 288 245	<b>C100S</b>
12 23 2 240 255	<b>C100S</b>
12 23 2 241 387	<b>C106S</b>
12 23 2 241 389	<b>C106S</b>
12 23 2 248 059	<b>C241S</b>
12 23 9 061 353	<b>C100S</b>
12 23 9 061 354	<b>C106S</b>
<b>CITROEN</b>	
5962 008	<b>C100S</b>
5962 1P	<b>C224S</b>
5962 1Q	<b>C224S</b>
5962 1R	<b>C107S</b>
5962 1S	<b>C104S</b>
5962 1T	<b>C102S</b>
5962 1V	<b>C101S</b>
5962 1W	<b>C105S</b>
5962 1X	<b>C118S</b>
5962 1Y	<b>C202R</b>
5962 1Z	<b>C200S</b>
5962 2Z	<b>C216S</b>
5962 3E	<b>C218S</b>
5962 3J	<b>C215S</b>
5962 7F	<b>C218S</b>
5962 7G	<b>C218S</b>
5962 58	<b>C208R</b>
5962 S8	<b>C208R</b>
5962 T1	<b>C202R</b>
5962 T2	<b>C118S</b>
5962 W2	<b>C207R</b>
5962 W8	<b>C100S</b>
5962 X1	<b>C111R</b>
90 041 002 80	<b>C108S</b>
91 536 646	<b>C100S</b>
91 538 910 99	<b>C108S</b>
95 493 206	<b>C111R</b>
95 534 788	<b>C111R</b>
95 534 788	<b>C111R</b>
96 070 388 80	<b>C108S</b>
96 076 258	<b>C108S</b>
96 141 678	<b>C208R</b>
96 236 383	<b>C218S</b>
96 316 589 80	<b>C207R</b>
96 389 858	<b>C218S</b>
MKP 000 71	<b>C200S</b>
<b>FIAT</b>	
07029585	<b>C111R</b>
4393814	<b>C111R</b>
4474413	<b>C102S</b>
46447610	<b>C225S</b>
46451951	<b>C227S</b>
46754154	<b>C247S</b>
4714294	<b>C111R</b>
4729585	<b>C111R</b>
4754011	<b>C111R</b>
4774412	<b>C111R</b>
4774413	<b>C102S</b>
4781356	<b>C102S</b>
4849406	<b>C110S</b>
5493206	<b>C111R</b>
5950464	<b>C111R</b>
5951861	<b>C111R</b>
5951879	<b>C111R</b>
5951881	<b>C101S</b>
5951882	<b>C102S</b>
5973752	<b>C101S</b>
5973753	<b>C101S</b>
60507123	<b>C103S</b>
60596245	<b>C208R</b>
60617002	<b>C214S</b>
60812292	<b>C206R</b>
60814613	<b>C227S</b>
76226740	<b>C101S</b>
7632587	<b>C109S</b>
7702960	<b>C101S</b>
7735920	<b>C206R</b>
7777837	<b>C203R</b>
9616572480	<b>C215S</b>



 <b>OE</b>	<b>Valeo</b>
<b>FIAT</b> (.../...)	
9623638380	<b>C218S</b>
9631658980	<b>C216S</b>
9633214380	<b>C215S</b>
9638985980	<b>C218S</b>
98462490	<b>C204R</b>
98498630	<b>C203R</b>
F 2 VB	<b>C111R</b>
F 4 VB	<b>C111R</b>
FU 2 A	<b>C101S</b>
FU 4 A	<b>C102S</b>
<b>FORD</b>	
1 008 792	<b>C217S</b>
1 056 857	<b>C217S</b>
1 079 401	<b>C255S</b>
1 148 105	<b>C258S</b>
1 587 444	<b>C111R</b>
1 690 048	<b>C214S</b>
6 063 505	<b>C111R</b>
6 132 244	<b>C104S</b>
6 132 246	<b>C104S</b>
6 154 593	<b>C100S</b>
7 072 673	<b>C208R</b>
7 088 988	<b>C105S</b>
78 GB 6 M 090 CA	<b>C111R</b>
785 F 6M090 BA	<b>C111R</b>
785 F 6M090 CB	<b>C111R</b>
786 B 6M090 CA	<b>C111R</b>
83 BB 6M090 A1A	<b>C100S</b>
83 BB 6M090 A2A	<b>C100S</b>
84 BB 6M090 AA	<b>C100S</b>
84 FF 6M090 B1A	<b>C104S</b>
84 FF 6M090 B2A	<b>C104S</b>
89 FF 6M090 AA	<b>C105S</b>
910 X 6M090 AA	<b>C202R</b>
910 X 6M090 AA	<b>C202R</b>
910 X 6M090 BA	<b>C111R</b>
910 X 6M090 BA	<b>C111R</b>
93 FF 6M090 AA	<b>C105S</b>
95 DD 6M 090 AA	<b>C214S</b>
96 FF 6M090 AA	<b>C217S</b>
96 FF 6M090 AB	<b>C217S</b>
96 FF 6M090 BA	<b>C217S</b>
96 FF 6M090 BB	<b>C217S</b>
V 94 DX 6M090 AA	<b>C208R</b>
XS 4U 6M090 AB	<b>C255S</b>
XS 7U 6M090 BA	<b>C252S</b>
<b>ISUZU</b>	
8-94221-719-3	<b>C114R</b>
8-94221-719-3	<b>C114R</b>
8-94241-449-0	<b>C114R</b>
8-94241-449-1	<b>C114R</b>
8-94241-490	<b>C114R</b>
8-94249-692-1	<b>C114R</b>
8-94255-588-0	<b>C114R</b>
8-94319-700-1	<b>C116S</b>
8-94319-700-2	<b>C116S</b>
8-94402-303-1	<b>C115R</b>
8-94439-218-0	<b>C114R</b>
8-94481-972-0	<b>C117S</b>
<b>IVECO</b>	
4841294	<b>C102S</b>
4849406	<b>C110S</b>
98459883	<b>C203R</b>
98462490	<b>C204R</b>
98498630	<b>C203R</b>
<b>JAGUAR</b>	
02 JD 61164	<b>C252S</b>
<b>MERCEDES</b>	
000 159 75 01	<b>C107S</b>
000 159 77 01	<b>C100S</b>
000 159 81 01	<b>C107S</b>
000 159 83 01	<b>C107S</b>
001 152 26 01	<b>C222S</b>
001 159 00 01	<b>C201S</b>
001 159 15 01	<b>C219S</b>
001 159 16 01	<b>C219S</b>
001 159 17 01	<b>C201S</b>
001 159 20 01	<b>C221S</b>
001 159 21 01	<b>C221S</b>
001 159 22 01	<b>C208R</b>
001 159 27 01	<b>C238S</b>
001 159 28 01	<b>C236S</b>
001 159 35 01	<b>C208R</b>
001 159 36 01	<b>C201S</b>
001 159 37 01	<b>C236S</b>
001 159 38 01	<b>C236S</b>
001 159 42 01	<b>C236S</b>



 <b>OE</b>	<b>Valeo</b>
<b>MERCEDES</b> (.../...)	
001 159 48 01	<b>C236S</b>
001 159 49 01	<b>C236S</b>
661 159 30 01	<b>C201S</b>
661 159 31 01	<b>C201S</b>
A 001 159 49 01	<b>C236S</b>
<b>MOTORCRAFT</b>	
EZD 2	<b>C111R</b>
EZD 5	<b>C100S</b>
EZD 6	<b>C104S</b>
EZD 8	<b>C105S</b>
EZD 10	<b>C200S</b>
EZD 11	<b>C107S</b>
EZD 13	<b>C103S</b>
EZD 14	<b>C101S</b>
EZD 15	<b>C111R</b>
EZD 16	<b>C102S</b>
EZD 23	<b>C201S</b>
EZD 24	<b>C114R</b>
EZD 27	<b>C200S</b>
EZD 28	<b>C111R</b>
EZD 29	<b>C202R</b>
EZD 30	<b>C208R</b>
EZD 33	<b>C205R</b>
EZD 36	<b>C214S</b>
EZD 37	<b>C255S</b>
EZD 38	<b>C252S</b>
EZD 39	<b>C217S</b>
EZD 40	<b>C258S</b>
<b>OPEL</b>	
09 110 945	<b>C223S</b>
12 14 304	<b>C111R</b>
12 14 305	<b>C245S</b>
12 14 306	<b>C100S</b>
12 14 307	<b>C100S</b>
12 14 308	<b>C114R</b>
12 14 309	<b>C115R</b>
12 14 310	<b>C117S</b>
12 14 311	<b>C116S</b>
12 14 312	<b>C116S</b>
12 14 315	<b>C117S</b>
12 14 317	<b>C106S</b>
12 14 319	<b>C209S</b>
12 14 322	<b>C220S</b>
12 14 324	<b>C106S</b>
12 14 427	<b>C214S</b>
12 14 457	<b>C226S</b>
44 02 945	<b>C223S</b>
44 03 145	<b>C203R</b>
56 14 216	<b>C200S</b>
56 14 218	<b>C107S</b>
56 14 219	<b>C200S</b>
56 14 221	<b>C114R</b>
88 900 715	<b>C236S</b>
88 900 716	<b>C214S</b>
88 900 718	<b>C238S</b>
88 900 720	<b>C217S</b>
88 900 721	<b>C241S</b>
88 900 722	<b>C205R</b>
88 900 723	<b>C200S</b>
88 900 724	<b>C219S</b>
88 900 725	<b>C208R</b>
88 900 726	<b>C207R</b>
88 900 727	<b>C221S</b>
88 900 728	<b>C209S</b>
88 900 729	<b>C225S</b>
88 900 730	<b>C111R</b>
88 900 731	<b>C107S</b>
88 900 732	<b>C104S</b>
88 900 733	<b>C100S</b>
88 900 734	<b>C102S</b>
88 900 735	<b>C108S</b>
88 900 736	<b>C101S</b>
88 900 737	<b>C105S</b>
88 900 738	<b>C106S</b>
88 900 740	<b>C202R</b>
88 900 741	<b>C201S</b>
88 900 742	<b>C206R</b>
88 900 743	<b>C116S</b>
90 040 991	<b>C104S</b>
90 051 950	<b>C111R</b>
90 093 897	<b>C111R</b>
90 166 155	<b>C100S</b>
90 210 824	<b>C100S</b>
90 464 737	<b>C220S</b>
90 487 858	<b>C106S</b>
90 510 924	<b>C209S</b>
90 540 864	<b>C106S</b>



 <b>OE</b>	<b>Valeo</b>
<b>OPEL</b> (.../...)	
90 569 338	<b>C226S</b>
91 109 45	<b>C223S</b>
<b>OPEL</b>	
91 111 45	<b>C203R</b>
<b>OPEL</b>	
91 153 919	<b>C214S</b>
91 182 01	<b>C226S</b>
91 966 69	<b>C245S</b>
94 402 303	<b>C115R</b>
94 439 218	<b>C114R</b>
94 481 972	<b>C117S</b>
97 464 737	<b>C245S</b>
<b>PEUGEOT</b>	
5960 12	<b>C258S</b>
5961 39	<b>C100S</b>
5961 40	<b>C111R</b>
5961 53	<b>C100S</b>
5961 54	<b>C111R</b>
5961 57	<b>C100S</b>
5961 58	<b>C111R</b>
5962 35	<b>C107S</b>
5962 1P	<b>C224S</b>
5962 1Q	<b>C224S</b>
5962 2Y	<b>C207R</b>
5962 3C	<b>C218S</b>
5962 3H	<b>C215S</b>
5962 7F	<b>C218S</b>
5962 7G	<b>C218S</b>
5962 74	<b>C100S</b>
5962 J2	<b>C202R</b>
5962 J3	<b>C108S</b>
5962 J4	<b>C102S</b>
5962 J5	<b>C107S</b>
5962 J6	<b>C101S</b>
5962 J7	<b>C200S</b>
5962 K5	<b>C100S</b>
5962 R8	<b>C208R</b>
5962 S8	<b>C208R</b>
5962 T1	<b>C202R</b>
5962 T2	<b>C118S</b>
5962 T7	<b>C105S</b>
5962 W3	<b>C207R</b>
7932 567 718	<b>C111R</b>
9150 860 280	<b>C100S</b>
9150 861 080	<b>C100S</b>
9152 184 980	<b>C100S</b>
9153 664 680	<b>C100S</b>
9553 478 8	<b>C111R</b>
9616 572 480	<b>C208R</b>
9623 638 3	<b>C218S</b>
9631 658 980	<b>C207R</b>
9633 214 380	<b>C215S</b>
9638 985 8	<b>C218S</b>
<b>RENAULT</b>	
50 01 001 587	<b>C111R</b>
77 00 100 558	<b>C223S</b>
77 00 100 586	<b>C213S</b>
77 00 100 635	<b>C229S</b>
77 00 103 674	<b>C243S</b>
77 00 105 290	<b>C211S</b>
77 00 111 323	<b>C228S</b>
77 00 111 940	<b>C229S</b>
77 00 662 199	<b>C111R</b>
77 00 673 874	<b>C111R</b>
77 00 701 130	<b>C102S</b>
77 00 715 768	<b>C102S</b>
77 00 733 076	<b>C102S</b>
77 00 741 144	<b>C102S</b>
77 00 854	



	
<b>RENAULT (.../...)</b>	
77 01 414 077	<b>C200S</b>
77 01 414 078	<b>C104S</b>
77 01 414 079	<b>C107S</b>
77 01 414 080	<b>C101S</b>
77 01 414 081	<b>C105S</b>
77 01 414 083	<b>C108S</b>
77 01 414 084	<b>C103S</b>
77 01 414 086	<b>C100S</b>
77 01 414 088	<b>C200S</b>
77 01 414 089	<b>C108S</b>
77 01 414 107	<b>C201S</b>
77 01 414 108	<b>C106S</b>
77 01 414 123	<b>C208R</b>
77 01 414 157	<b>C201S</b>
82 00 012 099	<b>C243S</b>
<b>ROVER</b>	
ERC 8450	<b>C111R</b>
ETC 8847	<b>C257S</b>
NCC 100050	<b>C210S</b>
<b>TALBOT</b>	
91 507 715 80	<b>C100S</b>
91 507 719 80	<b>C100S</b>
<b>UNIC-IVECO</b>	
004 729 585	<b>C111R</b>
<b>VAUXHALL</b>	
900 33357	<b>C111R</b>
900 93897	<b>C111R</b>
902 10824	<b>C100S</b>
<b>V.A.G.</b>	
068 905 061	<b>C200S</b>
N 019 081 1	<b>C200S</b>
N 019 081 2	<b>C200S</b>
N 019 081 4	<b>C200S</b>
N 019 097 1	<b>C200S</b>
N 101 401 01	<b>C205R</b>
N 101 401 02	<b>C205R</b>
N 101 401 03	<b>C205R</b>
N 101 401 04	<b>C205R</b>
N 101 401 05	<b>C205R</b>
N 102 130 01	<b>C200S</b>
N 102 130 02	<b>C200S</b>
<b>VOLVO</b>	
1542319	<b>C103S</b>
840643	<b>C111R</b>



# 2.4

Glow plugs

Bougies de préchauffage

Bujías de precalentamiento

Velas de pré-aquecimento

Candele di preriscaldamento

Gloeibougies

Glühkerzen

Świece żarowe

Isitma bujisi

Свечи накаливания



Назначение и рекомендации по эксплуатации продукции, содержащиеся в наших каталогах, указываются с учетом состояния автомобильного парка на день ее появления. Компания «Valeo Service Eastern Europe Sp.zo.o» не несет ответственности в случае внесения изменений в рекомендации по эксплуатации продукции или их устранения, произошедших, в частности, по инициативе производителей автомобилей.

Технические характеристики нашей продукции могут претерпевать изменения в любой момент, с учетом усовершенствования технических и технологических процессов.



Некоторые виды продукции могут не иметься в наличии в отдельных странах.



Заказы осуществляются согласно общим правилам торговли, применяемым в компании «Valeo Service Eastern Europe Sp.zo.o».



Фотографии и изображения продукции могут не в полной мере соответствовать оригиналам. Воспроизведение всей или части настоящей публикации запрещено без специального письменного согласия компании «Valeo Service Eastern Europe Sp.zo.o».









	
<b>AC-DELCO</b>	
104G	<b>C238S</b>
106G	<b>C217S</b>
109G	<b>C241S</b>
110G	<b>C205R</b>
114G	<b>C219S</b>
116G	<b>C208R</b>
117G	<b>C207R</b>
118G	<b>C221S</b>
120G	<b>C209S</b>
128G	<b>C200S</b>
138G	<b>C225S</b>
148G	<b>C201S</b>
149G	<b>C206R</b>
230G	<b>C107S</b>
233G	<b>C114R</b>
239G	<b>C111R</b>
240G	<b>C104S</b>
241G	<b>C100S</b>
242G	<b>C102S</b>
243G	<b>C108S</b>
244G	<b>C101S</b>
245G	<b>C105S</b>
246G	<b>C106S</b>
247G	<b>C202R</b>
250G	<b>C116S</b>
28G	<b>C200S</b>
30G	<b>C107S</b>
41G	<b>C100S</b>
48G	<b>C201S</b>
500 GG/93893040	<b>C200S</b>
503 GG/93893043	<b>C111R</b>
507 GG/93893047	<b>C100S</b>
508 GG/93893048	<b>C200S</b>
509 GG/93893049	<b>C103S</b>
510 GG/93893050	<b>C104S</b>
511 GG/93893051	<b>C111R</b>
512 GG/93893052	<b>C102S</b>
517 GG/93893057	<b>C114R</b>
518 GG/93893058	<b>C264S</b>
525 GG/93893065	<b>C106S</b>
526 GG/93893066	<b>C101S</b>
<b>AUTOLITE</b>	
1101	<b>C200S</b>
1103	<b>C107S</b>
B 17 N	<b>C200S</b>
B 19 N	<b>C111R</b>
B 20 N	<b>C111R</b>
B 22 N	<b>C111R</b>
B 23 R	<b>C102S</b>
B 24 SR	<b>C103S</b>
B 27 SR	<b>C105S</b>
B 28 SR	<b>C104S</b>
B 29 SR	<b>C101S</b>
B 30 SR	<b>C110S</b>
B 31 SR	<b>C107S</b>
B 32 R	<b>C102S</b>
B 41 SR	<b>C201S</b>
B 42 SR	<b>C108S</b>
B 43 SR	<b>C200S</b>
B 44 SR	<b>C106S</b>
B 48 R	<b>C202R</b>
<b>BERU</b>	
GE 100	<b>C263S</b>
GE 102	<b>C259S</b>
GE 105	<b>C260S</b>
GN 003	<b>C236S</b>
GN 007	<b>C214S</b>
GN 010	<b>C238S</b>
GN 013	<b>C215S</b>
GN 016	<b>C216S</b>
GN 017	<b>C227S</b>
GN 018	<b>C228S</b>
GN 019	<b>C229S</b>
GN 022	<b>C217S</b>
GN 024	<b>C241S</b>
GN 026	<b>C243S</b>
GN 027	<b>C218S</b>
GN 033	<b>C245S</b>
GN 041	<b>C247S</b>
GN 045	<b>C262S</b>
GN 047	<b>C258S</b>
GN 054	<b>C261S</b>
GN 855	<b>C205R</b>
GN 857	<b>C200S</b>
GN 858	<b>C201S</b>
GN 860	<b>C219S</b>
GN 905	<b>C210S</b>



	
<b>BERU (...)</b>	
GN 908	<b>C206R</b>
GN 909	<b>C208R</b>
GN 912	<b>C207R</b>
GN 917	<b>C204R</b>
GN 927	<b>C203R</b>
GN 939	<b>C252S</b>
GN 944	<b>C220S</b>
GN 948	<b>C221S</b>
GN 954	<b>C209S</b>
GN 959	<b>C212S</b>
GN 961	<b>C222S</b>
GN 963	<b>C223S</b>
GN 964	<b>C224S</b>
GN 970	<b>C225S</b>
GN 971	<b>C211S</b>
GN 992	<b>C226S</b>
GN 993	<b>C255S</b>
GN 994	<b>C256S</b>
GN 999	<b>C213S</b>
GV 602	<b>C111R</b>
GV 603	<b>C107S</b>
GV 631	<b>C104S</b>
GV 636	<b>C100S</b>
GV 642	<b>C102S</b>
GV 657	<b>C103S</b>
GV 661	<b>C108S</b>
GV 663	<b>C101S</b>
GV 666	<b>C105S</b>
GV 673	<b>C264S</b>
GV 719	<b>C106S</b>
GV 727	<b>C110S</b>
GV 728	<b>C113S</b>
GV 730	<b>C109S</b>
GV 749	<b>C114R</b>
GV 783	<b>C257S</b>
GV 844	<b>C118S</b>
GV 852	<b>C202R</b>
GV 945	<b>C115R</b>
GV 946	<b>C116S</b>
GV 947	<b>C117S</b>
<b>BOSCH</b>	
0 250 200 053	<b>C103S</b>
0 250 200 054	<b>C111R</b>
0 250 200 056	<b>C111R</b>
0 250 200 057	<b>C100S</b>
0 250 200 058	<b>C104S</b>
0 250 200 059	<b>C102S</b>
0 250 200 060	<b>C111R</b>
0 250 200 061	<b>C100S</b>
0 250 200 065	<b>C111R</b>
0 250 200 066	<b>C104S</b>
0 250 200 068	<b>C111R</b>
0 250 200 069	<b>C102S</b>
0 250 200 454	<b>C111R</b>
0 250 200 456	<b>C111R</b>
0 250 200 465	<b>C111R</b>
0 250 200 468	<b>C111R</b>
0 250 200 469	<b>C102S</b>
0 250 201 001	<b>C107S</b>
0 250 201 004	<b>C200S</b>
0 250 201 005	<b>C100S</b>
0 250 201 006	<b>C102S</b>
0 250 201 008	<b>C100S</b>
0 250 201 009	<b>C100S</b>
0 250 201 011	<b>C200S</b>
0 250 201 012	<b>C103S</b>
0 250 201 017	<b>C104S</b>
0 250 201 019	<b>C100S</b>
0 250 201 026	<b>C201S</b>
0 250 201 027	<b>C106S</b>
0 250 201 029	<b>C202R</b>
0 250 201 030	<b>C100S</b>
0 250 201 031	<b>C118S</b>
0 250 201 032	<b>C200S</b>
0 250 201 033	<b>C206R</b>
0 250 201 034	<b>C103S</b>
0 250 201 035	<b>C219S</b>
0 250 201 037	<b>C208R</b>
0 250 201 038	<b>C221S</b>
0 250 201 039	<b>C209S</b>
0 250 201 040	<b>C200S</b>
0 250 201 041	<b>C201S</b>
0 250 201 042	<b>C215S</b>
0 250 201 043	<b>C209S</b>
0 250 201 045	<b>C208R</b>
0 250 201 046	<b>C200S</b>
0 250 201 047	<b>C201S</b>



	
<b>BOSCH (...)</b>	
0 250 201 048	<b>C221S</b>
0 250 201 049	<b>C217S</b>
0 250 201 050	<b>C212S</b>
0 250 201 405	<b>C101S</b>
0 250 201 927 (SB)	<b>C100S</b>
0 250 201 929 (SB)	<b>C102S</b>
0 250 201 930 (SB)	<b>C200S</b>
0 250 201 932 (SB)	<b>C107S</b>
0 250 201 934 (SB)	<b>C104S</b>
0 250 201 935 (SB)	<b>C202R</b>
0 250 201 936 (SB)	<b>C206R</b>
0 250 201 937 (SB)	<b>C106S</b>
0 250 201 938 (SB)	<b>C118S</b>
0 250 201 939 (SB)	<b>C208R</b>
0 250 201 940 (SB)	<b>C201S</b>
0 250 202 001	<b>C203R</b>
0 250 202 002	<b>C109S</b>
0 250 202 003	<b>C264S</b>
0 250 202 008	<b>C114R</b>
0 250 202 009	<b>C205R</b>
0 250 202 018	<b>C105S</b>
0 250 202 020	<b>C207R</b>
0 250 202 021	<b>C211S</b>
0 250 202 022	<b>C205R</b>
0 250 202 023	<b>C214S</b>
0 250 202 024	<b>C211S</b>
0 250 202 025	<b>C210S</b>
0 250 202 026	<b>C222S</b>
0 250 202 027	<b>C220S</b>
0 250 202 028	<b>C227S</b>
0 250 202 029	<b>C236S</b>
0 250 202 032	<b>C218S</b>
0 250 202 033	<b>C203R</b>
0 250 202 034	<b>C225S</b>
0 250 202 035	<b>C223S</b>
0 250 202 036	<b>C247S</b>
0 250 202 039	<b>C236S</b>
0 250 202 040	<b>C257S</b>
0 250 202 041	<b>C238S</b>
0 250 202 042	<b>C226S</b>
0 250 202 043	<b>C245S</b>
0 250 202 045	<b>C236S</b>
0 250 202 085	<b>C116S</b>
0 250 202 086	<b>C115R</b>
0 250 202 087	<b>C117S</b>
0 250 202 103	<b>C241S</b>
0 250 202 901 (SB)	<b>C203R</b>
0 250 202 902 (SB)	<b>C205R</b>
0 250 251 471	<b>C225S</b>
<b>BRISK</b>	
21 N 01	<b>C200S</b>
21 N 21	<b>C111R</b>
21 N 22	<b>C111R</b>
21 N 51	<b>C103S</b>
21 R 02	<b>C104S</b>
21 R 06	<b>C200S</b>
21 R 21	<b>C100S</b>
21 R 21	<b>C101S</b>
21 R 21	<b>C107S</b>
21 R 22	<b>C102S</b>
21 R 26	<b>C202R</b>
21 R 51	<b>C103S</b>
21 R 71	<b>C105S</b>
21 R 71	<b>C108S</b>
<b>CHAMPION</b>	
CH 110	<b>C114R</b>
CH 137	<b>C102S</b>
CH 137	<b>C110S</b>
CH 147	<b>C105S</b>
CH 147	<b>C108S</b>
CH 155	<b>C202R</b>
CH 156	<b>C201S</b>
CH 157	<b>C116S</b>
CH 158	<b>C117S</b>
CH 159	<b>C106S</b>
CH 160	<b>C200S</b>
CH 163	<b>C206R</b>
CH 163	<b>C208R</b>
CH 166	<b>C221S</b>
CH 167	<b>C209S</b>
CH 169	<b>C200S</b>
CH 171	<b>C201S</b>
CH 172	<b>C215S</b>
CH 175	<b>C209S</b>
CH 176	<b>C208R</b>
CH 177	<b>C200S</b>
CH 184	<b>C201S</b>



	
<b>CHAMPION (...)</b>	
CH 185	<b>C207R</b>
CH 188	<b>C115R</b>
CH 189	<b>C215S</b>
CH 190	<b>C220S</b>
CH 196	<b>C255S</b>
CH 203	<b>C241S</b>
CH 205	<b>C217S</b>
CH 207	<b>C226S</b>
CH 217	<b>C223S</b>
CH 218	<b>C236S</b>
CH 232	<b>C243S</b>
CH 62	<b>C103S</b>
CH 68	<b>C100S</b>
CH 68	<b>C101S</b>
CH 68	<b>C107S</b>
CH 68	<b>C110S</b>
CH 69	<b>C200S</b>
CH 70	<b>C103S</b>
CH 79	<b>C104S</b>
CH 87	<b>C111R</b>
CH 88	<b>C100S</b>
CH 88	<b>C102S</b>
CH 90	<b>C109S</b>
CH 94	<b>C264S</b>
X 510	<b>C110S</b>
XCH 512	<b>C109S</b>
<b>HELLA</b>	
8EG 008 497-491	<b>C236S</b>
8EG 008 497-511	<b>C238S</b>
8EG 008 497-541	<b>C227S</b>
8EG 008 497-551	<b>C228S</b>
8EG 008 497-561	<b>C229S</b>
8EG 008 497-571	<b>C241S</b>
8EG 008 497-591	<b>C247S</b>
8EG 008 497-601	<b>C244S</b>
8EG 008 497-611	<b>C255S</b>
PO 749	<b>C236S</b>
PO 751	<b>C238S</b>
PO 754	<b>C227S</b>
PO 755	<b>C228S</b>
PO 756	<b>C229S</b>
PO 757	<b>C241S</b>
PO 759	<b>C247S</b>
PO 760	<b>C224S</b>
PO 761	<b>C255S</b>
<b>INTERMOTOR</b>	
80000	<b>C111R</b>
80011	<b>C103S</b>
80015	<b>C106S</b>
80020	<b>C200S</b>
80021	<b>C200S</b>
80024	<b>C205R</b>
80026	<b>C200S</b>
80031	<b>C100S</b>
80034	<b>C101S</b>
80036	<b>C201S</b>
80041	<b>C104S</b>
80044	<b>C105S</b>
80050	<b>C202R</b>
80060	<b>C202R</b>
80100	<b>C264S</b>
80124	<b>C114R</b>
80134	<b>C116S</b>
80135	<b>C115R</b>
80136	<b>C117S</b>
80140	<b>C208R</b>
80142	<b>C257S</b>
80144	<b>C108S</b>
80151	<b>C103S</b>
80152	<b>C200S</b>
80155	<b>C107S</b>
80156	<b>C103S</b>
80157	<b>C225S</b>
80158	<b>C210S</b>
<b>LUCAS</b>	
6415-3	<b>C200S</b>
6415-4	<b>C100S</b>
DS 001	<b>C107S</b>
DS 003	<b>C100S</b>
DS 003	<b>C102S</b>
DS 006	<b>C111R</b>
DS 017	<b>C264S</b>
DS 032	<b>C114R</b>
DS 040	<b>C100S</b>
DS 052	<b>C103S</b>
DS 056	<b>C104S</b>



	
<b>LUCAS (.../...)</b>	
DS 058	<b>C105S</b>
DS 122	<b>C100S</b>
DS 850	<b>C105S</b>
HDS 216	<b>C107S</b>
HDS 218	<b>C100S</b>
HDS 221	<b>C111R</b>
HDS 232	<b>C264S</b>
HDS 247	<b>C114R</b>
HDS 255	<b>C102S</b>
HDS 266	<b>C103S</b>
HDS 267	<b>C103S</b>
HDS 271	<b>C104S</b>
HDS 273	<b>C105S</b>
HDS 274	<b>C106S</b>
HDS 295	<b>C101S</b>
HDS 297	<b>C201S</b>
HDS 299	<b>C110S</b>
HDS 302	<b>C114R</b>
HDS 303	<b>C257S</b>
HDS 337	<b>C100S</b>
HDS 338	<b>C115R</b>
HDS 339	<b>C108S</b>
HDS 341	<b>C118S</b>
HDS 342	<b>C205R</b>
HDS 343	<b>C200S</b>
HDS 346	<b>C117S</b>
HDS 347	<b>C202R</b>
HDS 348	<b>C208R</b>
HDS 349	<b>C209S</b>
HDS 350	<b>C207R</b>
HDS 351	<b>C206R</b>
HDS 352	<b>C201S</b>
HDS 353	<b>C204R</b>
HDS 354	<b>C221S</b>
HDS 355	<b>C210S</b>
HDS 356	<b>C225S</b>
HDS 357	<b>C109S</b>
HDS 360	<b>C226S</b>
HDS 361	<b>C214S</b>
HDS 362	<b>C217S</b>
HDS 363	<b>C219S</b>
HDS 364	<b>C227S</b>
HDS 365	<b>C224S</b>
HDS 366	<b>C211S</b>
HDS 367	<b>C218S</b>
HDS 368	<b>C228S</b>
HDS 369	<b>C216S</b>
HDS 370	<b>C213S</b>
HDS 371	<b>C215S</b>
HDS 372	<b>C241S</b>
HDS 373	<b>C222S</b>
HDS 376	<b>C223S</b>
HDS 379	<b>C255S</b>
<b>MAGNETI MARELLI</b>	
TIX 2 A	<b>C111R</b>
TIX 4 A	<b>C111R</b>
TIX 6 A	<b>C111R</b>
TIX 7 A	<b>C103S</b>
TLX 2 A	<b>C111R</b>
UC 10 A	<b>C116S</b>
UC 11 A	<b>C227S</b>
UC 12 A	<b>C218S</b>
UC 13 A	<b>C223S</b>
UC 14 A	<b>C214S</b>
UC 15 A	<b>C216S</b>
UC 16 A	<b>C226S</b>
UC 17 A	<b>C236S</b>
UC 18 A	<b>C238S</b>
UC 2 A	<b>C109S</b>
UC 3 A	<b>C205R</b>
UC 4 A	<b>C225S</b>
UC 7 A	<b>C207R</b>
UC 8 A	<b>C210S</b>
UX 11 A	<b>C105S</b>
UX 12 A	<b>C104S</b>
UX 13 A	<b>C201S</b>
UX 14 A	<b>C202R</b>
UX 15 A	<b>C106S</b>
UX 2 A	<b>C107S</b>
UX 4 A	<b>C102S</b>
UX 7 A	<b>C103S</b>
UX 8 A	<b>C200S</b>
<b>NGK</b>	
Y 103-1	<b>C202R</b>
Y 104 R	<b>C114R</b>
Y 115 T	<b>C264S</b>
Y 115 T-1	<b>C264S</b>

	
<b>NGK (.../...)</b>	
Y 206 T	<b>C111R</b>
Y 207 TS	<b>C200S</b>
Y 208 T	<b>C111R</b>
Y 503 R	<b>C216S</b>
Y 504 R	<b>C218S</b>
Y 506 R	<b>C223S</b>
Y 507 R	<b>C241S</b>
Y 515 J	<b>C228S</b>
Y 516 J	<b>C229S</b>
Y 517 J	<b>C243S</b>
Y 710 R	<b>C116S</b>
Y 711 RS	<b>C117S</b>
Y 719 RS	<b>C117S</b>
Y 729 U	<b>C257S</b>
Y 730 U	<b>C210S</b>
Y 731 U	<b>C207R</b>
Y 732 U	<b>C205R</b>
Y 739 R	<b>C109S</b>
Y 741 U	<b>C214S</b>
Y 745 U	<b>C236S</b>
Y 746 R	<b>C238S</b>
Y 747 U	<b>C247S</b>
Y 748 U	<b>C226S</b>
Y 752 M	<b>C215S</b>
Y 902 R	<b>C100S</b>
Y 907 R	<b>C104S</b>
Y 908 R	<b>C102S</b>
Y 909 R	<b>C103S</b>
Y 910 R	<b>C105S</b>
Y 911 R	<b>C108S</b>
Y 912 M	<b>C202R</b>
Y 913 M	<b>C202R</b>
Y 914 U	<b>C204R</b>
Y 916 R	<b>C201S</b>
Y 917 U	<b>C106S</b>
Y 918 R	<b>C200S</b>
Y 920 R	<b>C101S</b>
Y 922 R	<b>C206R</b>
Y 923 U	<b>C208R</b>
Y 924 U	<b>C209S</b>
Y 925 R	<b>C221S</b>
Y 930 U	<b>C219S</b>
Y 937 R	<b>C217S</b>
Y 938 R	<b>C215S</b>

## EUROPE

### FRANCE

#### VALEO SERVICE FRANCE

15, RUE DES ROSIERS  
93582 SAINT-OUEN CEDEX - FRANCE  
TEL.: (+33) 1 49 45 32 32  
FAX: (+33) 1 49 45 37 36  
S.A.S. au capital de 17 623 995 €  
RCS Bobigny B 306 486 408

### SPAIN, PORTUGAL

#### VALEO SERVICE ESPAÑA, S.A.

AREA EMPRESARIAL ANDALUCIA  
CARRETERA DE ANDALUCIA, KM 16.5- SECTORES 7 Y 8  
28906 GETAFE (MADRID) - ESPAÑA  
TEL.: (+34) 91 495 85 00  
FAX: (+34) 91 495 86 99  
TEL. ATENCIÓN TÉCNICA :  
902 011 799  
TEL. ATENCIÓN AL CLIENTE :  
900 122 657

Valeo Service España Sociedad Anónima  
inscrita en el Registro Mercantil de Madrid,  
Tomo 972 - Libro 941 de la sección 8ª,  
Folio 25 - Hoja 65435 - Inscrpción 1ª NIF. A-28772978

### ITALY

#### VALEO SERVICE ITALIA SPA

VIA ASTI 89  
10026 SANTENA (TO) - ITALIA  
TEL.: (+39) 011 94 95 1  
FAX: (+39) 011 94 94 116  
TEL. LINEA TECNICA : 800 805 046  
N. iscrizione al Tribunale di Torino 2009/88 reg. soc.  
C.C.I.A.A. 715107 - Capitale sociale € 2.600.000

### UNITED KINGDOM

#### VALEO SERVICE UK LTD

HEMING ROAD - WASHFORD  
REDDITCH - WORCS B98 0DZ - ENGLAND  
TEL.: (+44) 1527 838 300  
FAX: (+44) 1527 523 732  
Registration Number : 956685

### GERMANY

#### VALEO SERVICE DEUTSCHLAND GMBH

BRANDENBURGER STRASSE 46  
40880 RATINGEN - DEUTSCHLAND  
TEL.: (+49) 21 02 865 0  
FAX: (+49) 21 02 865 142  
Handelsregister Ratingen - HRB 3340

### BENELUX

#### VALEO SERVICE BENELUX B.V.

HEIBLOEMWEG 1  
5704 BS HELMOND - THE NETHERLANDS  
TEL. BELGIUM (NL) : (+32) 2 366 99 17  
TEL. BELGIUM (FR) : (+32) 2 355 14 46  
TEL. NETHERLANDS : (+31) 492 580 894  
FAX BELGIUM : (+32) 2 366 04 47  
FAX NETHERLANDS : (+31) 492 580 828  
K.v.K. Eindhoven 33113859

## TURKEY

#### VALEO OTOMOTIV DAGITIM A.S.

AYDINEVLER SANAYI CADDESI  
CENTRUM IS MERKEZI N°3  
KAT: 3, DAIRE N°302-303 KÜÇÜKYALI - MALTEPE  
34854 ISTANBUL - TURKEY  
TEL.: (+90) 216 518 75 75  
FAX: (+90) 216 519 93 14

### POLAND, LITHUANIA, LATVIA, ESTONIA

#### VALEO SERVICE EASTERN EUROPE SP. ZO.O.

UL. POSTĘPU 13  
02-676 WARSZAWA - POLSKA  
TEL.: (+48) 22 543 43 00  
FAX: (+48) 22 543 43 05  
SP. Z O.O. O KAPITALE 4.637.000 PLN  
KRS 56793  
Sąd Rejonowy dla m.St. Warszawy

### RUSSIA, BELARUS, UKRAINE

#### VALEO SERVICE EASTERN EUROPE SP. ZO.O.

(LIAISON OFFICE IN MOSCOW)  
IBRAGIMOVA STR. 31/50 OFFICE 417  
105318 MOSCOW - RUSSIA  
TEL.: (+7) 495 981 06 96

### SWITZERLAND, AUSTRIA, SWEDEN, FINLAND, NORWAY, DENMARK, ICELAND, GREECE, EASTERN EUROPE OTHERS

#### VALEO SERVICE EXPORT

15, RUE DES ROSIERS  
93582 SAINT-OUEN CEDEX - FRANCE  
TEL.: (+33) 01 49 45 32 32  
FAX: (+33) 01 49 45 36 59  
S.A.S. au capital de 17 623 995 €  
RCS Bobigny B 306 486 408

#### LIAISON OFFICE IN AUSTRIA

MÜHLGASSE 7  
2380 PERCHTOLDSDORF - AUSTRIA  
TEL.: (+43) 1 480 42 46  
FAX.: (+43) 1 480 42 34

#### LIAISON OFFICE IN GREECE

117 NOTARA STREET  
185 35 PIRAEUS - GREECE  
TEL.: (+30) 210 45 27 447-8  
FAX.: (+30) 210 45 27 449

#### LIAISON OFFICE IN CZECH REPUBLIC

RADISTU 620/6  
16100 PRAGUE 6 - CZECH REPUBLIC  
TEL.: (+420) 233 313 300  
FAX.: (+420) 233 313 301

## LIAISON OFFICE IN HUNGARY

KOSSUTH UTCA 33  
8581 BAKONYJAKO - HUNGARY  
TEL.: (+36) 89 350 156  
FAX : (+36) 89 350 156

## AMERICAS

### LATIN AMERICA

#### VALEO CIBIE SERVICE LTDA

RUA SADAÉ TAKAGI, 2000  
BAIRRO COOPERATIVA  
09852-070 - SÃO BERNARDO DO CAMPO  
SÃO PAULO - BRASIL  
TEL.: (+55) 11 43 93 33 54  
FAX: (+55) 11 43 93 33 55  
C.N.P.J.: 57.010.662/0008-36  
Inscrição Estadual: 635.331.124.114

## ASIA, AUSTRALIA NEW-ZEALAND

#### VALEO SERVICE EXPORT

15, RUE DES ROSIERS  
93582 SAINT-OUEN CEDEX - FRANCE  
TEL.: (+33) 01 49 45 32 32  
FAX: (+33) 01 49 45 36 59

#### LIAISON OFFICE IN CHINA

501, KE YUAN ROAD  
ZHANG JIANG HI TECH PARK  
PUDONG SHANGHAI  
201203 CHINA  
TEL.: (+86) 21 5080 0581  
FAX: (+86) 21 5080 0581

## AFRICA, MIDDLE EAST, DOM-TOM

#### VALEO SERVICE EXPORT

15, RUE DES ROSIERS  
93582 SAINT-OUEN CEDEX - FRANCE  
TEL.: (+33) 01 49 45 32 32  
FAX: (+33) 01 49 45 36 59  
S.A.S. au capital de 17 623 995 €  
RCS Bobigny B 306 486 408

#### LIAISON OFFICE IN TUNISIA

34, RUE ALI-DARGOUTH  
1000 TUNIS - TUNISIA  
TEL.: (216) 71 241 327  
FAX : (216) 71 240 675

